
# Agilent U1241A/U1242A Handheld Digital Multimeter Quick Start Guide




Measurement Functions	Input terminal		Overload Protection	
Voltage			1000 V R.M.S.	
Diode	<b>→</b> ⊢ VΩ + <b>⊢</b>	СОМ	1000 V R.M.S	
Resistance			< 0.3 A short circuit current	
Capacitance	7			
μ <b>A</b> & m <b>A</b>	μ <b>A mA</b>	COM	440 mA/1000 V 30 kA/fast-acting fuse	
А	A	COM	11A/1000 V 30 kA/fast-acting fuse	
Temperature	+T1	-T1	1000 V R.M.S.	
Temperature (for U1242A)	+T2	−T2	440 mA/1000 V 30 kA/fast-acting fuse	

WARNING

To avoid damaging this device, do not exceed the input limit.




## **Annunciator Display**



No.	Descriptions	No.	Descriptions
1	21-segment analog bar graph display	12	MINMAX Recording mode
2	Capacitor discharge indicator	13	Harmonic Ratio mode (for U1242A)
3	Cold junction of ambient temperature	14	Data logging mode (for U1242A)
4	Audible continuity for resistance and diode function	15	Data logging viewing mode (for U1242A)
5	Primary display -18888	16	Auto or manual data logging mode and datalog viewing mode
6	AC or DC measurement mode	17	Secondary display (temperature display)
7	Auto range	18	Null math function
8	Diode / Audible continuity	19	Thermocouple type for temperature measurement
9	T1, T2 and T1 – T2 temperature measurements scan (for U1242A)	20	Primary measurement units
		21	Measurement range
10	Data hold	22	Low battery indicator
11	T1, T2* and T1 – T2* temperature measurements	23	Auto power off indicator

<sup>\*</sup>T2 temperature measurement and delta (T1 - T2) are only available for U1242A.

## **Features and Functions**





## Keypad


Function	First level functions	Range	Second level functions (press SHIFT)	Range
OFF	Turn off the meter			
H.RATIO	DCV measurement	0.1 mV to 1000 V	ACV measurement	0.1 mV to 1000 V
			Harmonic ratio (for U1242A)	0.0% to 99.9%
sw-c	Diode measurement		Switch counter measurement	
<b>4))</b> Ω	Resistance measurement	0.1 Ω to 100 MΩ	Audible continuity measurement	
<b>→</b> ⊢	Capacitance measurement	0.1 nF to 10 mF		
$\mu A \overline{\sim}$	DCμA	0.1 μA to 10 mA	ACμA measurement	0.1 μA to 10 mA
mA $\sim$	DCmA	0.01 mA to 440 mA	ACmA measurement	0.01 mA to 440 mA
			mA% scale	
$A \overline{\sim}$	DCA	0.001 A to 10 A	ACA measurement	0.001 A to 10 A
T1	T1 temperature	–40 °C to 1000 °C	T2 and T1–T2 temperature measurements (for U1242A)	-40 °C to 1000 °C

Actions	Steps	
Turns ON backlight	Press 🔯	
Checks battery capacity	Press and hold  for > 1 second	
Freezes the measured value	Press HOLD	
Starts MIN/MAX/AVG recording	Press and hold HOLD for > 1 second	
Offsets the measured value	Press NULL	
Scan the measured temperature (for U1242A only)	Press and hold NULL for > 1 second	
Changes the measuring range	Press (RANGE)	
Turns on auto range	Press and hold RANGE for > 1 second	
Measures frequency for AC signal	Press (Hz)	
Starts manual data logging	Press and hold (Hz) for > 1 second	

## **Tilt Stand**



Tilt stand at 60°



Tilt stand at 30°

## **Safety Information**

The Agilent U1241A and U1242A are safety-certified in compliance with the following safety and EMC requirements:

- IEC 61010-1:2001 / EN61010-1:2001
- · USA: UL 61010-1:2004
- · Canada: CSA C22.2 No. 61010-1:2004
- IEC 61326-1:2005/ EN 61326-1:2006
- Canada: ICES-001:2004
- Australia/New Zealand: AS/NZS CISPR11:2004

#### **Safety Notices**

### CAUTION

A **CAUTION** notice denotes a hazard. It calls attention to an operating procedure, practice, or the like that, if not correctly performed or adhered to, could result in damage to the product or loss of important data. Do not proceed beyond a **CAUTION** notice until the indicated conditions are fully understood and met.

## WARNING

WARNING notice denotes a hazard. It calls attention to an operating procedure, practice, or the like that, if not correctly performed or adhered to, could result in personal injury or death. Do not proceed beyond a WARN-ING notice until the indicated conditions are fully understood and met.

### **Safety Symbols**



Caution, risk of danger (refer to this manual for specific Warning or Caution information)



Caution, risk of electric shock



Earth (ground) terminal

CAT III 1000 V

Category III 1000 V Overvoltage Protection

CAT IV 600 V

Category IV 600 V Overvoltage Protection

For further safety information details, refer to the Agilent U1241A and U1242A Handheld Digital Multimeter User's and Service Guide.

© Agilent Technologies, Inc. 2007-2009 Second Edition, April 01, 2009

Printed in Malaysia

U1241-90024

