

# Keysight EXF Wireless Test Set for Femtocell E6650A

[Software version F.16.08 Released 6 - October 2015](#)

[Software version F.16.06 Released 22 July 2015](#) - Microsoft .Net 4.5 is required for this release. (.Net 4.5 needs to be manually uninstalled before you can load an older release / previous version.)

[Software version F.14.69 Released 8 - February 2015](#)

[Software version F.14.56 Released 22 - November 2014](#)

## Software version F.16.08

|  |  |
|--|--|
| Released Date:   | Oct 6th 2015   |
| Requirements category (e.g., operating system):            | Microsoft Windows 7  |
| Requirements category (e.g., instrument software version): | Core™ i7-4700EQ quad-core, 2.4 GHz processor<br>Windows Embedded Standard 7 (WES7) 32-bit or 64-bit Operating System |
| Requirements category (other):                             | Microsoft .Netframe work 4.5   |
| File Name:   | XSA_Installer_F.16.08_Self-extractor_x64.exe   |

## Software F.16.08 Enhancements

| Model  | Option              | Description   |
|--------|---------------------|---|
| E6650A | V9081B<br>Bluetooth | Added new test results DeltaF1F0 and Max Frequency Offset for Bluetooth LE measurement according to standards |

**Software F.16.08 Issues Resolved**

| <b>Model</b> | <b>Option</b>                     | <b>Description</b>   |
|--------------|-----------------------------------|--|
| E6650A       |                                   | <p>Fixed a defect: random crashes occurred when editing a source ARB sequence file.</p> <p>Fixed a defect: license-checking errors occurred with Signal Studio waveform MEU licenses</p> <p>Fixed a defect: Loading Signal Studio waveforms into ARB memory sometimes caused a crash.</p> <p>Fixed a defect: Application can't recognize old config file after upgrade to new revision.</p>                                    |
| E6650A       | V9077B<br>WLAN                    | <p>Fixed a defect: FFT SEM trace provided with WLAN MIMO Mod Analysis was incorrect.</p> <p>Fixed a defect: could not release remote analyzers when deleting all remote analyzers for MIMO.</p> <p>Fixed a defect: WLAN 11af EVM could not be demodulated successfully.</p>  |
| E6650A       | V9065B<br>Sequence Analyzer       | <p>Fixed a defect: LSEQ Edge EVM returned similar results of different acquisitions in some cases.</p> <p>Fixed a defect: could not recall sequencer analyzer sequence file and source list sequence file by means of user interface.</p> <p>Fixed a defect: random crashes occurred when exiting sequence analyzer mode.</p> <p>Fixed a defect: Demodulation of LTE FDD EVM sometimes occurred in sequence analyzer mode.</p> |
| E6650A       | V9080B<br>LTE FDD<br>/LTE-Adv FDD | <p>Fixed a defect: Performing auto range for LTE measurement was causing crashes.</p> <p>Fixed a defect: LTE CCDF measurement cannot be enabled.</p> <p>Fixed a defect: LTE/LTE-A mode could not be pre-loaded at startup.</p>   |

## Software version F.16.06

|  |   |
|--|---|
| Released Date:   | 22 July 2015  |
| Requirements category (e.g., operating system):            | Microsoft Windows 7   |
| Requirements category (e.g., instrument software version): | CoreTM i7-4700EQ quad-core, 2.4 GHz processor<br>Windows Embedded Standard 7 (WES7) 32-bit or 64-bit Operating System |
| Requirements category (other):                             | Microsoft .Netframework 4.5   |
| File Name:   | XSA_Installer_F.16.06_Self-extractor_x64.exe  |

## Software F.16.06 Enhancements

| Model  | Option                             | Description  |
|--------|------------------------------------|--|
| E6650A |                                    | Microsoft .Net 4.5 is required for this release. (.Net 4.5 should be manually uninstalled if you want to downgrade to an older release / previous version.)<br><br>Adds support for EXF and 89600 connectivity<br><br>Added a trigger polarity to the source external trigger. |
| E6650A |                                    | Added weekly alignments buttons: RF, IF and Source the user interface  |
| E6650A | V9065B<br>Sequence Analyzer        | Sequence Analyzer mode, reduced minimum transition time between acquisition steps for some configurations.<br><br>Added a new feature to query Complex IQ Origin Offset.<br><br>Add Support to LTE band 30   |
| E6650A | V9080B LTE<br>FDD/LTE-Adv<br>FDD   | Added new feature to support LTE-Advanced FDD.<br>Added new feature to support LTE CCDF  |
| E6650A | V9082B<br>LTE TDD/ LTE-<br>Adv TDD | Added new feature to support LTE-Advanced TDD.<br>Added new feature to support LTE CCDF  |

|        |   |   |
|--------|---|---|
| E6650A | V9080B LTE FDD, V9082B LTE-TDD, and V9073B W-CDMA | Added a new feature to query Complex IQ Origin Offset.  |
| E6650A | V9077B WLAN                                       | Added new feature to support 802.11p and 802.11j.<br>Added new feature to support 1024QAM for 802.11ac.<br>Added new SCPI command for “Frequency Sync” to improve EVM results.<br>[:SENSE]:EVM:FREQUENCY:SYNC PPILot   PPData   PREAMBLE<br>Added new softkey “User Select Field” for EVM |
| E6650A | E6650A-AW1  | Added new feature to support Real Time AWGN Source  |

### Software F.16.06 Issues Resolved

| Model  | Option                   | Description  |
|--------|--------------------------|--|
| E6650A |                          | Fixed a defect: External trigger level range is not correct.<br>Fixed a defect: Source sync operation occasionally causes inconsistency status.  |
| E6650A | V9065B Sequence Analyzer | Fixed a defect: Some 802.11 results are not displayed occasionally.<br>Fixed an application crash when Basic IQ is queried in an unsupported mode<br>Fixed a defect: correct help link of WCDMA Band 19 and LTE Band 30<br>Fixed a defect: added WLAN EVM “Track Timing” in Sequence Analyzer<br>Fixed a defect: LTE EVM reports error in Sequence mode when signal has large IQ offsets |

|        |                   |   |
|--------|-------------------|---|
| E6650A | V9077B<br>WLAN    | Fixed a defect: EXM WLAN supports negative Gate Delay<br><br>Fixed a defect: WLAN FFT SEM Detector should be Average                    |
| E6650A | V9082B<br>LTE TDD | Fixed a defect: When no RF burst signal presents, application completes measurements immediately without showing “Waiting for Trigger”. |

### Software Version F.14.69

|  |  |
|--|--|
| Released Date:   | 8 February 2015  |
| Requirements category (e.g., operating system):            | Microsoft Windows 7  |
| Requirements category (e.g., instrument software version): | Core™ i7-4700EQ quad-core, 2.4 GHz processor<br>Windows Embedded Standard 7 (WES7) 32-bit or 64-bit Operating System |
| Requirements category (other):                             | none   |
| File Name:   | XSA_Installer_F.14.69_Self-extractor_x64.exe   |

### Software F.14.69 Enhancements

| Model  | Option  | Description   |
|--------|---|---|
| E6650A | V9065B<br>Sequence Analyzer                       | In Sequence Analyzer mode, reduced minimum transition time between acquisition steps for some configurations.<br><br>Added a new feature to query Complex IQ Origin Offset. |
| E6650A | V9080B LTE FDD, V9082B LTE TDD, and V9073B W-CDMA | Added a new feature to query Complex IQ Origin Offset.  |

### Software F.14.69 Issues Resolved

| Model | Option | Description |
|-------|--------|-------------|
|-------|--------|-------------|

|        |                             |   |
|--------|-----------------------------|---|
| E6650A |                             | <p>Fixed a defect: LAN ports IP addresses incorrectly reported in system display.</p> <p>Fixed a defect: Source sequence initialization occasionally causes operation time-out.</p> <p>Fixed a defect: Source sync operation occasionally times out.</p> <p>Fixed a defect: TRX Configurator launch failed occasionally.</p> <p>Fixed a defect: Intermittent “Source Synthesizer Unlocked – DETECTED” errors when executing a source list sequence.</p> |
| E6650A | V9065B<br>Sequence Analyzer | Fixed a defect: Intermittent timeout errors during sequence execution or when fetching sequence results.  |

## Software Version F.14.56

|  |   |
|--|---|
| Released Date:   | 20 November 2014  |
| Requirements category (e.g., operating system):            | Microsoft Windows 7   |
| Requirements category (e.g., instrument software version): | CoreTM i7-4700EQ quad-core, 2.4 GHz processor<br>Windows Embedded Standard 7 (WES7) 32-bit or 64-bit Operating System |
| Requirements category (other):                             | none  |
| File Name:   | XSA_Installer_F.14.56_Self-extractor_x64.exe  |

## Software F.14.56 Enhancements

| Model  | Option | Description   |
|--------|--------|---|
| E6650A |        | Added Supports external trigger delay for source input trigger. |

## Software F.14.56 Issues Resolved

| Model | Option | Description |
|-------|--------|-------------|
|-------|--------|-------------|

|        |                                 |   |
|--------|---------------------------------|---|
| E6650A |                                 | Fixed a defect: waveform multi-pack licenses                              |
| E6650A | V9065B,<br>Sequence<br>Analyzer | Fixed a defect: issue where recalling a sequence file may not be recalled |

### Software Version F.14.54

|  |   |
|--|---|
| Released Date:   | 15 October 2014   |
| Requirements category (e.g., operating system):            | Microsoft Windows 7   |
| Requirements category (e.g., instrument software version): | CoreTM i7-4700EQ quad-core, 2.4 GHz processor<br>Windows Embedded Standard 7 (WES7) 32-bit or 64-bit Operating System |
| Requirements category (other):                             | None  |
| File Name:   | XSA_Installer_F.14.54_Self-extractor_x64.exe  |

Initial Release for E6650A, Keysight EXF Wireless Test Set for Femtocell

© Keysight Technologies 2000-2014