## **Release Notes**

# Keysight M960xA PXIe Precision Source/Measure Unit Software

## Version 3.5.1755.0

| Released Date: | 16 Apr. 2021                   |
|----------------|--------------------------------|
| File Name:     | Keysight.M960xA_3.5.1755.0.zip |

#### Note

The firmware update is required after the installation of the M960x PXIe Precision
 Source/Measure Unit Instrument Drivers by following the installation instruction available in the same download page.

#### **New Features**

- Supported PX0107A Low noise filter adapter for M9614A and M9615A PXIe 5-Channel Precision Source/Measure Units, which enables you to evaluate noise sensitive devices and circuits such as quantum computing and many types of analog and RF ICs.
- Supported Laser Diode Mode for M9602A and M9603A PXIe Precision Source/Measure Units, which is effective in applying pulse currents with fast rise time and measuring devices such as a laser diode or VCSEL.

#### **Enhancements**

- Enlarged the voltage range to 17 V for 5 A pulsed range of M9602A and M9603A PXIe Precision Source/Measure Units.
- Supported Trigger I/O configuration dialog on SFP.

## **Bug Fixes**

Fixed: SFP may not connect more than 20 modules. (#1301)

## Version 3.0.1661.0

| Released Date: | 04 Feb. 2021                   |
|----------------|--------------------------------|
| File Name:     | Keysight.M960xA_3.0.1661.0.zip |

#### Note

The firmware update is required after the installation of the M960x PXIe Precision
 Source/Measure Unit Instrument Drivers by following the installation instruction available in the same download page.

# **Bug Fixes**

- Fixed: The Model option doesn't work on simulation mode. (#1159)
- Fixed: Unexpected current range is selected for pulsed current list sweep on M9602A/03A.
  (#1160)
- Fixed: The software may hang-up by an emergency event. (#1173, 1179)
- Fixed: The status may not be set correctly when using seamless current measurement ranging on M9614/15A. (#1190, 1241)

## Version 3.0.1510.0

| Released Date: | 30 Oct. 2020                   |
|----------------|--------------------------------|
| File Name:     | Keysight.M960xA_3.0.1510.0.zip |

#### Note

The firmware update is required after the installation of the M960x PXIe Precision
 Source/Measure Unit Instrument Drivers by following the installation instruction available in the same download page.

#### **New Features**

Supported M9602A and M9603A PXIe Precision Source/Measure Units.

## **Bug Fixes**

- Fixed: The M9601A may fail at power-on self-test. (#334)
- Fixed: The M9601A is reset by interlock failure error. (#869)

- Fixed: An unexpected error occurs when the seamless current ranging turns on. (#915)
- Fixed: Inappropriate characters are output to csv when the measurement results are infinity on SFP. (#1010)
- Fixed: The software may hang-up by an emergency event. (#1061)
- Fixed: The M9601/14/15A may hang-up at power-on self-test. (#1092)

## Version 2.0.1263.0

| Released Date: | 14 Aug. 2020                   |
|----------------|--------------------------------|
| File Name:     | Keysight.M960xA_2.0.1263.0.zip |

#### **New Features**

Supported M9614A and M9615A PXIe 5-Channel Precision Source/Measure Units.

### **Enhancements**

Supported Save/Load Settings on SFP. (#160)

## **Bug Fixes**

- Fixed: The value may not be set or returned correctly on IVI-C driver. (#595, #716, #734)
- Fixed: The aperture time may be slightly shorter than the specified value. (#643, #646)
- Fixed: The source value returned by KtM960x\_MeasurementFetchArrayData may not be correct.
  (#729, #743)
- Fixed: The voltage output may not be correct for list sweep with digitizer mode. (#748)
- Fixed: The program may hang up when an interlock failure occurs. (#862, 880)
- Fixed: The interlock value may not be set for multiple modules. (#900)

## Version 1.0.31.0

| Released Date: | 13 March. 2020               |
|----------------|------------------------------|
| File Name:     | Keysight.M9601A_1.0.31.0.zip |

## **Bug Fixes**

Fixed: The wait time after changing voltage/current may not be correct. (#410, #411, #468)

- Fixed: The voltage output may not be correct when continuous trigger output is enabled. (#463, #464)
- Fixed: The session may not be opened for large number of modules. (#472, #480)
- Fixed: The unexpected error may occur when controlling modules in multiple chassis. (#450, #477)
- Fixed: The unexpected interlock error may occur. (#492, #493, #494)
- Fixed: The trigger may not be aborted. (#386, #414)
- Fixed: The invalid commands may be logged on Monitor Driver Calls on Soft Front Panel. (#534)
- Fixed: Operation mode may not be set correctly. (#547)

# Version 1.0.9.0

| Released Date: | 30 November. 2019           |
|----------------|-----------------------------|
| File Name:     | Keysight.M9601A_1.0.9.0.zip |

#### Initial Release

© Keysight Technologies 2016-2020