

# E9901G/E9902G/E9903G /E9905G i3070 In-Circuit Test System

## i3070 10.20pa Software Release

Release Version:	10.20pa
Released Date:	December, 2021
Operating System:	Windows 10 Pro, Windows 10 Enterprise
System Requirements:	i3070 In-Circuit Test System with i3070 10.20p software release
Release Type:	Minor Update Release

This software revision should only be installed on systems with i3070 10.20p software release. It can be installed on both i3070 test systems and i3070 test development workstations. No new licenses are needed.

## Resolved Issues

- ICT-102 Fixed: i3070 unmux board file will be modified after "config" compile error.
- ICT-100 Fixed: In BTI, adding a receiver to a node in digital test results in error "driver already exists".
- ICT-105 Fixed: Full diagnostics passes, but running diagnostics on ASRU-N card results in relay failure at Test 2714.
- ICT-216 Fixed: T3601 intermittent DGN failures on Heron P3 and P5 pin cards.
- ICT-225 Fixed: DGN XTPB firmware update fails if i3070 software is not installed to "C:\i3070\_ICT".
- ICT-233 Fixed: Fixture Consultant crashes while finding some nodes (bead probes).
- ICT-234 Fixed: RestAPI.dll issue when parsing short test open.
- ICT-238 Fixed: BT-Basic only copies i3070 files to AE project folder once.
- ICT-243 Fixed: PMA CAD file parse issue leading to no heatmap display.



This information is subject to change without notice.

© Keysight Technologies 2000-2021  
Printed in Malaysia



E9901-90047

[www.keysight.com](http://www.keysight.com)