



## **E6651A Mobile WiMAX™ Test Set - Revision History for Internal Drivers**

---

epsg1137851

### **Internal RF Driver Revision 6.3.0 – March 11<sup>th</sup> 2009**

#### **Status**

An update is available for E6651A instruments with Internal RF Driver versions prior to 3.3.0.0.

#### **E6651A Test Set Check**

To check the current Internal RF Driver version:

- Press the "SYSTEM" button, "MORE", followed by the "SERVICE" softkey.
- Check the current Internal RF Driver versions displayed for each of the "3010 / 3011", "3020 / 3025" and "3030 / 3035" modules.

If any of these versions is less than 3.3.0.0, Agilent recommends that you upgrade the internal RF Drivers.

#### **Update**

The Internal RF Drivers patch is installed in the same way as a firmware release. Download the appropriate patch for the hardware version of your E6651A:

- setup-E6651A\_A.1-RF\_drivers-6.3.0.zip for Hardware version A.1 instruments running firmware version 5.x.x.x
- setup-E6651A\_A.2-RF\_drivers-6.3.0.zip for Hardware version A.2 instruments running firmware version 6.x.x.x

#### **Additional Help and Information**

Consult the E6651A Firmware Upgrade instructions at

[http://www.home.agilent.com/agilent/redirector.jsp?action=ref&lc=eng&cc=US&nfr=-35061.603614&ckey=1208326&cname=AGILENT\\_EDITORIAL](http://www.home.agilent.com/agilent/redirector.jsp?action=ref&lc=eng&cc=US&nfr=-35061.603614&ckey=1208326&cname=AGILENT_EDITORIAL) for further details on how to install the update.

When released, updates are available for download from <http://www.agilent.com/find/E6651A>. To receive notification of updates, please subscribe to the Agilent e-mail update service at

<http://www.agilent.com/find/emailupdates>