



E5100A Network Analyzer Firmware Revision History

Note:

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Agilent representative.

Revision 3.31 ... Released Jul. 2001

1. Fix SMOOTHING APERTURE problem.

Revision 3.30 ... Released Mar. 2001

1. Interpolation of measured value in special setting was incorrect.

Revision 3.21 ... Released Feb. 2000

1. Change brand HP to Agilent.

Revision 3.20 ... Released Sep. 1999

1. New printer support at present.
2. Menu2 of Front panel key data can not be saved.

Revision 3.14 ... Released Nov. 1998

1. Submit your query to Service from Contact Us page.

Revision 3.13 ... Released Oct. 1998

1. Submit your query to Service from Contact Us page.

Revision 3.12 ... Released Aug. 1998

1. Submit your query to Service from Contact Us page.

Revision 3.11 ... Released Jul. 1998

1. Add option 180MHz.

Revision 3.10 ... Released May. 1998

1. Add option 024.

Revision 3.00 ... Released Dec. 1997

1. Enhancement (All E5100A/B is color LCD display).

Revision 2.13 ... Released Jul. 1997

1. Submit your query to Service from Contact Us page.

Revision 2.12 ... Released Nov. 1996

1. Submit your query to Service from Contact Us page.

Revision 2.11 ... Released Aug. 1996

1. Submit your query to Service from Contact Us page.

Revision 2.10 ... Released Mar. 1996

1. Submit your query to Service from Contact Us page.

Revision 2.02 ... Released Jan. 1996

1. Submit your query to Service from Contact Us page.

Revision 2.01 ... Released Dec. 1995

1. Submit your query to Service from Contact Us page.

Revision 2.00 ... Released Dec. 1995

1. Submit your query to Service from Contact Us page.

Revision 1.01 ... Released Nov. 1995

1. Submit your query to Service from Contact Us page.

Revision 1.00 ... Released Feb. 1995

1. Initial Release.