

Software Release Date: Nov, 2018

System Requirements: Keysight i3070 test system or test development workstation

Controller Requirements: Windows PC

Operating System: Microsoft Windows 7 or Windows 10

Software Requirement: Keysight i3070 09.20p

This software patch should only be installed on systems with i3070 09.20p software release. It can be installed on i3070 test system or i3070 test development workstation.

The 09.20pc software patch addresses following change requests.

Change Request	Description
205134	08.40p: To display failed subtest only when "execute to fail; display failure" for 6 subtests or more.
311951	09.00p: BTI: Fixed capacitor compensation takes long time to execute.
381862	09.00p: BTI: Enhanced layout for operator login with freezes feature.
381897	09.00p: BTI: Enhanced board browser display for failed devices.
457944	09.00p: Enhanced IPG to consider jumpers for safeguard.
464300	09.00p: BTI: Enhanced layout with User Control Button.
484444	09.00p: Enhanced IPG to place 75Mil, 50Mil and 39Mil LONG probes.
491364	09.00p: Fixed Coverage Analyst data is incorrect for panel.
506083	09.01p: Inline: Fixed cannot re-compile the modified XL board fixture file.
540846	09.10p: BTI: Added pop-up message for fixture Lock or Unlock.
541611	09.10p: BTI: Fixed version test still runs if commented.
542223	09.10p: BTI: Added custom buttons in Main tool bar.

542229	09.10p: BTI: Added test time to dashboard for each component category.
542231	09.10p: BTI: Display the executing line in Command window.
542245	09.10p: BTI: Enhanced right button click menus in Test and Marco Explorer.
542988	09.10p: Enhanced error message for volt/current compliance test failures.
545997	09.10p: PBD: Enhanced screen refresh for missing test-source.
548451	09.10p: Enhanced XVision security with default Host Access Control is ticked
549837	09.00p: LED: Fixed DLL that may cause tests to hang-up.
552881	09.00p: BTI: Fixed debug mode for board versions loaded incorrectly.
553280	09.10p: Fixed Board Grader Macros prompt Segmentation Violation for non-version board
553556	09.01p Fixed Xvision may fail to start and pop-up message "Console server failed to initialize".
555985	09.00p: Inline: Included tower light control command for Inline Testmain.


The software patch must be installed using the administrator login (or a login with administrator privileges).

Installing the 09.20pc software patch

1. Save the **Keysighti3070_0920pc.zip** file to your hard disk.
2. Unzip it. Choose either Win7 or Win10 folder based on the Operating System
3. Close all open programs.
4. Double-click **Keysighti3070_0920pc.exe**
5. Follow the on-screen instructions for installation.
6. To validate that the software was installed correctly:
 - a. On the **Start** menu, select **All Programs > Keysight ICT > Korn Shell**
 - b. In the Korn Shell window, type **version** and press **Enter**.
The following software revision should be displayed:
Keysight i3070 09.20pc 0418 WN.

© Keysight Technologies, Inc. 2018

Printed in Malaysia 10/2018



E9901-90042

