

Instrument Software Revision History

Keysight CXA-m PXIe Signal Analyzer

Version M.19.05 (Release Date May, 2017)

Enhancements:

- Support Bluetooth 5.0 measurement application, N9081A-3FP
- Support WLAN 802.11ax measurement application, N9077A-8FP
- Support NB-IoT & eMTC measurement application, N9080B-3FP

Issues Resolved:

- Intermittent alignment failure caused by the attenuator control

Version M.18.11 (Release Date Sep, 2016)

Issues Resolved:

- Burst Trigger Alignment failure
- Preamp display issue in measurement bar
- Mode/Meas key doesn't work for initial mode switch from VSA to XSA
- LO update issue in Noise Figure measurement mode
- Selected marker is unexpectedly changed when marker mode is changed
- AC/DC switching is not available in the menu

Version M.16.16 (Release Date Jan, 2016)

Issues Resolved:

- IVI driver cannot get the correct HiSLIP number during IVI initialization
- 89601X license recognition issue
- AC/DC coupling can only be enabled in option 526

- Optimized test code for NF DUT tests
 - Initialization of font and culture information occasionally fails.
-

Version M.16.05 (Release Date July, 2015)

Enhancements:

- Support T03/T07/T13/T26 Tracking Generator Option
- Support 89601B, VSA software
- N9064A Vector Signal Analysis Application

Issues Resolved:

- *RST does not work in IQ mode sometimes
 - SA crash in IQ mode when sending “:SPEC:BAND:IF:SIZE” command
 - Misc/System Alignment Fail error in some settings
 - RF burst trigger doesn't apply to settings
-

Version M.14.79 (Release Date Nov, 2014)

Initial M9290A, CXA-m PXIe Signal Analyzer release