Keysight RP7930 and RP7940 Series Regenerative Power System

B.06.05.1053 Version Information

Released Date:	7 Feb 2024
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_06_05_1053.upd

Enhancements

- Implemented HighZ LowZ functionality for RP793xA and RP794xA models

B.06.05.1049 Version Information

Released Date:	18 Jan 2024
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_06_05_1049.upd

Enhancements

- Added workaround to reboot unit if clock_sync_check fails during boot up

B.06.04.10 Version Information

Released Date:	11 April 2023
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_06_04_1018.upd

Enhancements

- AC processor version 254

B.06.01.953 Version Information

Released Date:	26 Aug 2021
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_06_01_953.upd

Features

- Fixed the Web Control Instrument tab issue where the web interface is no longer responsive

B.05.04.880 Version Information

Released Date:	14 June 2021
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_05_04_880

Features and Enhancement

- The following features are added to primary/secondary (formerly master/slave) operation. (Must work with Serial Number MY63000xxx and above)

    - CD arbs
    - Elog measurements except for current min/max
    - Current min/max and high/low measurements
    - Power min/max measurements
    - Current level trigger source

B.05.03.838 Version Information

Released Date:	2 Feb 2021
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_05_03_838

Bug Fixed

- An error is now reported to notify if the elog buffer is overrun
- Fixed primary/secondary unit elog time limit
- Fixed issue where elog was aborted when a trigger was sent when running on a single unit

B.03.06.483 Version Information

Released Date:	30 Mar 2020
Requirements category (e.g., operating system):	Microsoft Windows 7, Microsoft Windows 8, Microsoft Windows 10
Requirements category (e.g., instrument software version):	None
Requirements category (other):	None
File Name:	RP79XX-B_03_06_483.upd

Bugs Fixed

- Certified to LXI version 1.5
- Resolved LAN disconnect issue