E5072A ENA Network Analyzer Firmware Revision History

Rev. 20200331

Note:
The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

Revision B.02.50 … Released March 2020
Support U2065xA Power Sensor.

Revision B.02.48 … Released January 2019
Bug Fix. Trace is not shown as straight 0 dB line, when calibration is done.

Revision B.02.44 … Released October 2018
Support user ID 6 to ID 12 for ECal User Characterization
Bug Fix. Unnatural reading of -200dB in high IFBW setting

Revision B.02.39 … Released March 2017
Bug fixes. Potential failure of User Characterization by N7554A/N7555A
Incorrect Calibration Kit Definitions for 85032F
*IDN?="Keysight" is not recognized with USB Power Sensor

Revision B.02.30 … Released June 2016
Add New ECal (N7554A, N7555A)

Revision B.02.20 … Released July 2015
Support Option-006 Wireless Power Transfer Analysis

Revision B.02.11 … Released July 2015
Changed Power On Test limits and Diag Test limits

Revision B.02.02 … Released April 2015
Bug Fixes. Analysis > Transform cannot be set to "ON"
FW crash when Rotate Adapter soft key is pressed

Revision B.02.00 … Released December 2014
Rebranded to Keysight
- Company name and its logo
- Manufacturer name in the product information via IDN? changed to Keysight Technologies from Agilent Technologies
Changed OS to Win-7

Revision A.01.14   … Released October 2014
   Minor Enhancement.
   Bug fixes.

Revision A.01.13   … Released March 2014
   Bug fixes. Receiver Levelling doesn't work properly on Ch2 and above.

Revision A.01.11   … Released February 2014
   Bug fixes. The previous reading of marker is output after format change. This occurs only when
   Display update is off.

Revision A.01.06   … Released February 2013
   Fixed minor bugs.

Revision A.01.03   … Released June 2012
   Fixed minor bugs on system recovery issues.

Revision A.01.03   … Released October 2011
   Fixed minor bugs.

Revision A.01.00   … Released June 2011
   Initial revision