Follow this process to install your N443xD ECal module.

1. Unpack & Inspect

2. Verify Shipment Using Box Contents List

Box Contents List

- ☑ _____
- ☑ _____
- ☑ _____
- ☑ _____
- ☑ _____

For installation instructions refer to the enclosed Quick Start Poster.

3. Remove:

– Certificate of Calibration and save for reference.
Inspect items in product case:
– Top layer: ECal, Certificate of Calibration, and accessories
– Bottom layer: Torque wrenches (i.e, varies with options)

4. Attach ECal USB to instrument

For complete product information visit http://www.keysight.com/find/ecal or scan the codebelow.

ECal

KEYSIGHT TECHNOLOGIES

N443xD ECal Module