

Release Notes

Keysight CX3300 Series Device Current Waveform Analyzer Firmware

Version 1.2.1641.10427

Released Date:	11 Oct. 2016
File Name:	Keysight.Cx3300.Setup_1.2.1641.10427.exe

New Features

- Supported Invert Colors option for saving Screen Capture (#471403)
- Added the measurement range setup field on the channel setup mini dialog box which is opened by clicking the channel summary on the summary bar (#464676)
- Added the right-click menu to edit or delete the selected marker or annotation. (#471529)

Enhancements

- Improved the usability to select area of "Anywhere" zoom. (#471531)
- Improved the usability to keep the scale when changing the sampling rate or the measurement range. (#471369, 464672)
- Improved the waveform loading from a Composite File. (#477978)

Bug Fixes

- Fixed: Known Issue of 1.1.1631.12302: Sorting of the table of Automatic Power and Current Profiler may not work correctly (#481519, #481689)
- Fixed: Must report the incorrect single channel connection of the CX1102A. Both primary and secondary channels must be connected. (#484091)

Known Issues

- A-B marker may not work correctly by applying the marker when the acquisition is stopped (#489721)

Version 1.1.1631.12302

Released Date:	8 Aug. 2016
File Name:	Keysight.Cx3300.Setup_1.1.1631.12302.exe

New Features

- Support XY zoom when selecting a corner of “Anywhere” zoom. (#471530)

Enhancements

- Improved the performance of displaying a large amount of data. (#459357, #471363)

Bug Fixes

- Fixed: Known Issue of 1.0.1621.18649: Automatic Power and Current Profiler may not work correctly for a waveform measured with a CX1102A. (#478092)
- Fixed: Known Issue of 1.0.1621.18649: The waveform on CX3300 is not displayed occasionally when changing the display mode using an external display. (#469790)
- Fixed: Known Issue of 1.0.1621.18649: After forcing quit the CX3300 firmware for any reasons, power-cycle the CX3300. (#471540)
- Fixed: User calibration doesn't work correctly for two CX1102A configuration (#482475)
- Fixed: Automatic Power and Current Profiler occasionally hangs up by file saving (#481068, #481072)
- Fixed: The bandwidth display on the summary bar is not correct for some ranges of CX1102A and CX1103A (#482707)

Known Issues

- Sorting of the table of Automatic Power and Current Profiler may not work correctly (#481519, #481689)

Version 1.0.1621.18649

Released Date:	15 June 2016
File Name:	Keysight.Cx3300.Setup_1.0.1621.18649.exe

Initial Release

Known Issues

- Automatic Power and Current Profiler may not work correctly for a waveform measured with a CX1102A. (#478092)
- The file operation such as loading, saving or recording occasionally stops if you attach or detach a current sensor during the file operation. (#471347)
- The waveform on CX3300 is not displayed occasionally when changing the display mode using an external display. (#469790)
- After forcing quit the CX3300 firmware for any reasons, power-cycle the CX3300. (#471540)

© Keysight Technologies 2016