Release Notes

# PAM-4 Measurement SDK

This document contains latest information on the PAM-4 Measurement SDK.

- Release 1.1.5.0
- Release 1.1
- Release 1.0
- Licensing Setup
- Installation Steps
- Getting Started with the PAM-4 Measurement SDK
- Related Documents
- Known Issues



# Release 1.1.5.0

Release Date:	April 08, 2022	
Operating System:	Microsoft Windows 10 (64 bit) 1607 or newer	
	Microsoft Windows Server 2012 R2 (64 bit)	
File Name:	PAM-4_MeasurementSDK_1.1.5.0.exe	
N1010A FlexDCA	Must not be installed. This SDK is intended to separate the Analysis from the Acquisition. As such it needs to be	
	installed on a different physical or virtual machine than the	
	N1010A FlexDCA that is required for doing Waveform	
	Acquisition.	

## Enhancements

- Added support for the following new measurement:
  - o Eye Levels

## Release 1.1

Release Date:	October 27, 2021
Operating System:	Microsoft Windows 10 (64 bit) 1607 or newer
	Microsoft Windows Server 2012 R2 (64 bit)
File Name:	PAM-4_MeasurementSDK_1.1.3.0.exe
N1010A FlexDCA	Must not be installed. This SDK is intended to separate the Analysis from the Acquisition. As such it needs to be
	installed on a different physical or virtual machine than the
	N1010A FlexDCA that is required for doing Waveform
	Acquisition.

## Enhancements

- Added support for the following new measurements:
  - o CEQ Noise Gain
  - o Partial TDECQ
- Added the capability to save the equalized waveforms

# Release 1.0

Release Date:

March 26, 2020

Operating System:	Microsoft Windows 10 (64 bit) 1607 or newer	
	Microsoft Windows Server 2012 R2 (64 bit)	
File Name:	PAM-4_MeasurementSDK_1.0.2.exe	
N1010A FlexDCA	Must not be installed. This SDK is intended to separate th	
	Analysis from the Acquisition. As such it needs to be	
	installed on a different physical or virtual machine than the	
	N1010A FlexDCA that is required for doing Waveform	
	Acquisition.	

This SDK enables you to perform the following PAM-4 measurements on waveforms captured with a Keysight Digital Communication Analyzer (DCA) oscilloscope:

- TDECQ
- Outer OMA and OER
- Eye Width
- Eye Linearity
- Eye Skew


# Licensing Setup

#### Setting up the license server


You are required to set up a license server on a physical machine. To install the license file, perform the following steps on this physical machine:

1. Install the Keysight License Manager 6 from here.

2. Click "Add/remove a license on your local machine".




3. Click "Add a license to this floating license server to be used by other machines".



4. Click OK.

5. Specify the license file and proceed with the license installation.



#### Setting up the client machine

 To connect to the license server in another OS on same network (Physical or Virtual Machine), add the enviornment variable with the Key as the license name (KS9000\_LICENSE\_FILE) and @Server name as the value.

Edit System Variable		×
Variable name:	KS9000_LICENSE_FILE	7
Variable value:	@XXXYYY.com	] ]
variable value:		]
Browse Directory	Browse File OK Cancel	

# Installation Steps

The PAM-4 Measurement SDK installer is for installation on 64-bit Windows 10 Operating Systems (OS version 1607 or newer) and Windows Server 2012 R2 64-bit. It must not be installed on a machine that already has the FlexDCA N1010A Software installed.

Perform the following steps to install the PAM-4 Measurement SDK:

- 1. Launch the installer file to run the setup. The User needs to be in the Administrator group to successfully install the software.
- 2. The installer will install the prerequisites one by one. One of the prerequisites is .NET Framework 3.5 which can fail if no internet connection is available. Refer to the Known Issues section for a workaround.
- It is likely that the installation of prerequisites will prompt for reboot twice. Once after the installation of .NET Framework 4.7.1 and another after the installation of Keysight IO Libraries. Please do the reboot. After the reboot, installation will be invoked automatically. Proceed with the installation by clicking Ok.
- 4. After the installation of prerequisites, you will get "Welcome" screen. Click Next.
- 5. Check the *Keysight Software End User License Agreement* and select "I accept the terms of the license agreement" option.
- 6. Click Next to accept the terms of the license agreement.
- 7. In the Setup Type, select "Complete". It will now install the required files.
- 8. Click Finish.

Getting Started with the PAM-4 Measurement SDK

1. In the Start menu, locate the Keysight KMF 1.40 folder.

	К		
	0	Keysight Connection Expert New	
		Keysight KMF New	~
		Keysight KMF 1.40 New	^
		KMF Examples Folder	
	C	KMF Programmer's Guide	
R		KMF Sample Browser New	
		Keysight License Manager New	~
۲ì			

- Open the KMF Examples Folder to verify that the installation works. Navigate to Keysight\KMF\Examples\Product\Pam4AnalysisExample.1.40.XX.0\Pam4AnalysisExample. exe. This is an application depicting a usage scenario of API. You can navigate to its source code as well at Keysight\KMF\Examples\Product\Pam4AnalysisExample.1.40.XX.0\src.
- 3. If you get the following error message related to the license, ensure that you have completed the licensing setup. For more information see the section Licensing Setup. Also ensure that when you set up the client machine by adding the environment variable, you must close the Windows File Explorer and reopen it and then try. If you still get this error again then try after rebooting.

E C:\Program Files\Keysight\KMF\Examples\Product\Pam4AnalysisExample.1.40.90.0\Pam4AnalysisExample.exe	-	-		×
Pam4Analysis plugin Example				^
Variant 1: process a byte array directly, as received from Analysis process				
Create the KMF session				
ERROR: License for plugin Keysight.Kmf.Dca.Pam4Analysis not found. Plugin can not be created. See	event	log f	or deta	ail
5.				
Press any key to exit.				

# Related Documents

For detailed information, refer to the following document for this application:

- "KMF Programmers Guide". This can be found in the Start menu. Refer to the following sections in this document.
  - Programmers Guide > Plugin Reference > Processing Plugin Reference > Keysight.Kmf.Dca.Pam4 Assembly

🛄 Plugin Reference
Drocessing Plugin Reference
Keysight.Kmf.Analysis.Modulation.Digital Assembly
Keysight.Kmf.Dca.Pam4 Assembly [PreCon]
Keysight.Kmf.Dca.Pam4Analysis Plugin
PAM4 Analysis Example Program
PAM4 Analysis Sample
<ul> <li>API Reference &gt; Keysight.Kmf.Dca Namespace</li> </ul>
🛄 API Reference
Keysight.Kmf Assembly
Keysight.Kmf.Analysis.Modulation.Digital Assembly
Keysight.Kmf.Dca.Pam4 Assembly
🛄 Keysight.Kmf.Dca Namespace
💭 Pam4Analysis Class
Properties
Methods
Classes
Enumerations
Kevsiaht.Kmf.Dsp.Converters Assembly

## Known Issues

.NET 3.5 Framework installation

- Error code 0x800F081F might be received during the installation of .NET 3.5 framework. That could be because installation media of Windows 10 is absent. If installation media is absent, installer tries to install .Net Framework 3.5 from windows update. So, internet is required to get this one installed from windows update.
- Alternatively, user can also switch on .NET Framework 3.5 as it is a part of Windows 10 standard installation. In the Control Panel's Programs and Features window, click the "Turn Windows features on or off" link. Again, the installation media is needed or the internet connection so that it can be installed from Windows update.

Programs and Features					
÷	- 🔶 👻 🛧 🛐 > Control Pa	nel > All Control Panel Items > Programs and Features			
	Control Panel Home	Uninstall or change a program			
	View installed updates	To uninstall a program, select it from the list and then			
•	Turn Windows features on or off	Organize 🔻			

And turn on the .NET Framework 3.5, on. If no Windows installation media is present, you need a working internet connection as it will install from the Windows update.

💽 Windo	ows Features	—		$\times$
Turn W	indows features on or off			?
To turn a feature on, select its check box. To turn a feature off, clear its check box. A filled box means that only part of the feature is turned on.				
· ·	.NET Framework 3.5 (includes .NET 2.0 ar	nd 3.0)		^
🕀 🗖 🚽	.NET Framework 4.6 Advanced Services			
	Active Directory Lightweight Directory Se	rvices		
	Containers			
	Data Center Bridging			
• • •	Device Lockdown			
• 🗹 🚽	Hyper-V			
	Internet Explorer 11			
• • •	Internet Information Services			
	Internet Information Services Hostable W	eb Co	re	
• • •	Legacy Components			
	Media Features			$\sim$
	0	К	Cance	I

- You can troubleshoot from here.
- After that, proceed with the installation.

Invalid waveform file. Only files generated by Keysight DCA are valid.

If you get this message, then the provided waveform is either not from a Keysight DCA or the Keysight DCA is needing maintenance. Contact Keysight support.

Keysight N1000 Measurement science license missing. Please verify Keysight KMF Pam4 is installed properly.

If you get this message, then probably your executable process is not linked against Keysight.Kmf and Keysight.Kmf.Dca.Pam4 assembly. This might happen with dynamic assembly loading scenarios, which are currently not supported.

## KMF Sample Browser PAM 4 Analysis not working

Only use the Console Example, as described in step 2 of Getting Started with the PAM-4 Measurement SDK.