

## Release Notes

# Keysight M9601A PXIe Precision Source/Measure Unit Software

## Version 1.0.31.0

Released Date:	13 March. 2020
File Name:	Keysight.M9601A_1.0.31.0.zip

### Bug Fixes

- Fixed: The wait time after changing voltage/current may not be correct. (#410, #411, #468)
- Fixed: The voltage output may not be correct when continuous trigger output is enabled. (#463, #464)
- Fixed: The session may not be opened for large number of modules. (#472, #480)
- Fixed: The unexpected error may occur when controlling modules in multiple chassis. (#450, #477)
- Fixed: The unexpected interlock error may occur. (#492, #493, #494)
- Fixed: The trigger may not be aborted. (#386, #414)
- Fixed: The invalid commands may be logged on Monitor Driver Calls on Soft Front Panel. (#534)
- Fixed: Operation mode may not be set correctly. (#547)

## Version 1.0.9.0

Released Date:	30 November. 2019
File Name:	Keysight.M9601A_1.0.9.0.zip

### Initial Release