



E4991A RF Impedance/Material Analyzer Firmware Revision History

Note:

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Agilent representative.

E4991A S/N MY43300481 and above (For Windows 2000)

Revision 2.01 ... Released Nov. 2005

1. DC bias test in the External Test program always fails even if the performance test passes.
2. "System Error" is displayed when DUT is connected or disconnected.

Revision 2.00 ... Released Jan. 2005

1. Change the Operating System from Windows 98 to Windows 2000.

E4991A S/N JPxxxxxxxx - MY432000230 (For Windows 98)

Revision 1.01 ... Released Mar. 2003

1. Adapt E4991A-007 Temperature Characteristic Test Kit.
2. FW Ver 1.00 bug fix.
 - CALC:DATA? with segment sweep only return the data up to NOP of linear sweep
 - A VBA program causes error with complex-trace in polar chart format

Revision 1.00 ... Released Apr. 2001

1. Initial Release.