



## E4981A Capacitance Meter, 120 Hz/ 1 kHz/ 1 MHz Firmware Revision History

Rev. 20160318

---

### Note:

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

---

### Revision A.03.15 ... Released Mar. 2016

1. For FW A.3.13
2. Fixed Turn ON error due to DSP response

### Revision A.03.13 ... Released Sep. 2015

1. For FW A.3.11
2. Fixed minor security hole in VxWorks

### Revision A.03.12 ... Released Sep. 2015

1. For FW A.3.10 or below
2. Fixed minor security hole in VxWorks

### Revision A.03.11 ... Released Apr. 2015

1. Initial for FW A.03.11
2. Support new LCD/FPGA

### Revision A.03.10 ... Released Apr. 2015

1. For FW A.3.00 or below
2. Support old LCD/FPGA

### Revision 1.10 ... Released Oct. 2009

1. Fixed bug on I/O error through device using USB control

Note: For MY48100471 and above, the firmware revision 1.10 and later can be only installed. Do NOT attempt to install the older firmware revisions.

### Revision 1.01 ... Released Dec. 2008

1. Revised digital I/F program revision check.

### Revision 1.00 ... Released Oct. 2008

1. Initial Release