



## **E5061A/62A Network Analyzer Firmware Revision History**

---

**Note:**

The purpose of this document is to provide an overview of the important changes that would affect the majority of customers. If you concern about a specific issue, contact your local Agilent representative.

---

**Revision A.03.01** ... Released Jul 2007

- Bug Fixes

**Revision A.03.00** ... Released Mar 2007

- LXI-C Compliant \*1

\*1. This function is available when the volume label on the hard disk is AL300 or higher.

**Revision A.02.12** ... Released Nov 2006

- Fixed bug of user calibration data

**Revision A.02.11** ... Released Jul 2006

- Added VBA program to the installer

**Revision A.02.10** ... Released Jun 2006

- Ripple limit test function
- Bandwidth limit test function
- Offset limit line function

**Revision A.02.00** ... Released Sep 2005

- User preset function
- Notch search function
- Function to all the marker values are displayed
- Function to change display position where marker value are displayed
- Function to align the marker value
- Display the overlap limit lines
- Reference tracking function
- Function to change display value where Y axis are displayed
- Frequency information appearing as asterisks
- User recovery function \*1
- Remote control using HTTP \*1

\*1. This function is available when the volume label on the hard disk is AL200 or higher.

**Revision A.01.00** ... Released Jan 2004

- Initial revision