


Agilent Test & Measurement Discontinued Products



Technical Support Status

(last updated May 1, 2004)

The following list contains Agilent Technologies products that are no longer sold and do not have specific information on the Agilent web site. The list provides the following information:

- **Model number**
- **Brief Product description**
- **Replacement information.** If replacement information is available, it's listed here. You will typically find information on replacement products by searching for the listed model number on the Agilent Test & Measurements website at www.agilent.com/find/t&m. Some replacement listings on this page are jumpstations that will take you directly to the replacement family.
- **Technical support status** as of May 1, 2004. "Currently supported" means that, if your instrument is under warranty, or if you have a valid support contract with Agilent, you can receive technical product support and service through the Agilent support network. "No longer supported" means that the Agilent website is the sole source of application support for this product. For many older products, "no longer supported" may mean no further information is available.

You can find information on many recently discontinued products on the Agilent website at www.agilent.com/find/discontinued.



Product	Description	Support Status	Replacement Information
83A	PERSONAL COMPUTE	No longer supported	no replacement
83F	HP83+GPIB IO SYS	No longer supported	no replacement
85A	BASIC PROGRAMMAB	No longer supported	no replacement
85B	PERS COMPUTER	No longer supported	no replacement
86A	86A PERS COMPUTR	No longer supported	no replacement
86B	PERS COMPUTER	No longer supported	no replacement
87A	PERSONAL COMPUTE	No longer supported	no replacement
87XM	87XM PERS COMPTR	No longer supported	no replacement
105A	CRYSTAL OSC	No longer supported	no replacement
105B	Crystal Oscillator	product family sold	http://www.agilent.com/find/symmetricom
107A	QUARTZ OSCILLATO	No longer supported	no replacement
107B	QUARTZ OSCILLATO	No longer supported	no replacement
117A	VLF COMPARATOR	No longer supported	no replacement
120B	OSCILLOSCOPE	No longer supported	
123A	RTD TEST	No longer supported	no replacement
124A	OSCIL. CAMERA	No longer supported	no replacement
130C	OSCILLOSCOPE	No longer supported	
140A	OSCILLOSCOPE	No longer supported	
140B	OSCILLOSCOPE	No longer supported	
140T	SPEC AN -MAINFRM	No longer supported	141T
141B	OSCILLOSCOPE	No longer supported	
141T	SPEC AN -MAINFRM	No longer supported	
143A	OSCILLOSCOPE	No longer supported	no replacement
143S	SPEC AN -MAINFRM	No longer supported	
180A	OSCILLOSCOPE	No longer supported	
180AR	NOT FOR SALE PRODUCT	No longer supported	no replacement
180C	SCOPE MAINFRAME	No longer supported	no replacement
180D	SCOPE MAINFRAME	No longer supported	no replacement
180ER	SCOPE MAINFRAME	No longer supported	
180F	RUGGEDIZED SCOPE	No longer supported	
180TR	MAIN FRAME	No longer supported	
181A	SCOPE MAINFRAME	No longer supported	
181AR	SCOPE MAINFRAME	No longer supported	no replacement
181T	MAIN FRAME	No longer supported	853A, 182T
181TR	MAIN FRAME	No longer supported	853A, 182T
182A	OSCILLOSCOPE	No longer supported	
182C	SCOPE MAINFRAME	No longer supported	
182T	MAIN FRAME	No longer supported	
183A	OSCILLOSCOPE	No longer supported	
183B	OSCILLOSCOPE	No longer supported	
183C	OSCILLOSCOPE	No longer supported	
183D	OSCILLOSCOPE	No longer supported	
184A	SCOPE MAINFRAME	No longer supported	
184B	OSCILLOSCOPE	No longer supported	
191A	OSCILLOSCOPE	No longer supported	
193A	OSCILLOSCOPE	No longer supported	
195A	OSCILLOSCOPE CAM	No longer supported	no replacement
197A	OSCILLOSCOPE CAM	No longer supported	no replacement
197B	CAMERA FOR CATHODE RAY TUBE RECORDING	No longer supported	no replacement
198A	CAMERA	No longer supported	no replacement
200CD	OSCILLATOR	No longer supported	http://www.agilent.com/find/esg
202H	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
202J	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
203A	FUNCTION GENERAT	No longer supported	
211B	GENERATOR	No longer supported	81101A
214A	PULSE GENERATOR	No longer supported	8114A
214B	100 V, 10MHz PULSE GENERATOR	No longer supported	8114A
221A	GENERATOR	No longer supported	81101A
222A	GENERATOR	No longer supported	81101A
226A	TIME MARK GEN	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
232A	OBSOLETE SIG GEN	No longer supported	http://www.agilent.com/find/signal_sources
239A	OSC LOW DISTORT	No longer supported	no replacement
250B	RX METER	No longer supported	
297A	SWEEP DRIVE	No longer supported	no replacement
302A	WAVE ANALYZER	No longer supported	
310A	WAVE ANALYZER	No longer supported	
312A	WAVE ANALYZER	No longer supported	
312B	SELECTIVE VOLT	No longer supported	
312C	SELECT LEVEL MET	No longer supported	
312D	SELECT LEVEL MET	No longer supported	
313A	OSCILLATOR	No longer supported	
331A	DISTORTION ANALY	No longer supported	
332A	DISTORTION ANALY	No longer supported	
333A	DISTORTION ANALY	No longer supported	
334A	Distortion Analyzer	No longer supported	
339A	Distortion Measurement Set	No longer supported	
340B	NOISE FIGURE MET	No longer supported	Noise Figure Analyzers
340BR	NOISE FIGURE MET	No longer supported	Noise Figure Analyzers
342A	NOISE FIGURE MTR	No longer supported	Noise Figure Analyzers
342AR	NOISE FIGURE MTR	No longer supported	Noise Figure Analyzers
343A	VHF NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
345B	IF NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
349A	NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
350D	ATTENUATOR	No longer supported	4437A
353A	PATCH PANEL	No longer supported	no replacement
354A	ATTENUATOR	No longer supported	no replacement
355CR	VHF coaxial step attenuator, 0 to 12 dB	No longer supported	
355DR	VHF coaxial step attenuator, 0-120 dB	Currently supported	
355ER	Programmable VHF attenuator	Currently supported	
360A	Low Pass Filter	No longer supported	no replacement
360B	Low Pass Filter	No longer supported	no replacement
360C	Low Pass Filter	No longer supported	no replacement
360D	Low Pass Filter	No longer supported	no replacement
393A	VAR COAX ATTN	No longer supported	no replacement
394A	VAR COAX ATTN	No longer supported	no replacement
400D	VOLTMETER	No longer supported	3458A
400DR	VOLTMETER	No longer supported	3458A
400E	AC VOLTMETER	No longer supported	3458A
400EL	AC VOLTMETER	No longer supported	3458A
400F	AC VOLTMETER	No longer supported	3458A
400FL	AC VOLTMETER	No longer supported	3458A
400GL	AC VOLTMETER	No longer supported	3458A
400H	VOLTMETER	No longer supported	3458A
400LR	VOLTMETER	No longer supported	3458A
403A	AC VOLTMETER	No longer supported	3458A
403B	AC VOLTMETER	No longer supported	3458A
410C	MULTI FUNC METER	No longer supported	34401A
411A	RF MILLIVOLTMETE	No longer supported	no replacement
411AR	RF MILLIVOLTMETE	No longer supported	no replacement
412A	DC VOLTMETER	No longer supported	34401A
412AR	DC VOLTMETER	No longer supported	34401A
415B	Description Not Available (Corp)	No longer supported	
415BR	WAVE INDICATOR	No longer supported	
415E	SWR Meter	No longer supported	
416B	RATIO METER	No longer supported	
416BR	RATIO METER	No longer supported	
419A	DC NULL VOLTMETE	No longer supported	34420A
420A	CRYSTAL DETECTOR	No longer supported	no replacement
420B	CRYSTAL MOUNT	No longer supported	no replacement
420C	Coaxial Crystal Detector	No longer supported	no replacement
423A	Coaxial crystal detector	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
427A	MULTI-FUNC METER	No longer supported	34401A, 3458A
428B	MILLIAMMETER	No longer supported	34134A
428BR	MILLIAMMETER	No longer supported	no replacement
430C	Description Not Available (Corp)	No longer supported	no replacement
430CR	POWER METER	No longer supported	no replacement
431C	POWER METER	No longer supported	
432AR	Thermistor power meter	Currently supported	
432B	Digital Thermistor Power Meter	No longer supported	432A
432C	PROG DIG PUR MTR	No longer supported	no replacement
434A	Description Not Available (Corp)	No longer supported	no replacement
434AR	POWER METER	No longer supported	no replacement
435A	POWER METER	No longer supported	no replacement
436AR	Digital Power Meter	Currently supported	
440A	DETECTOR MOUNT	No longer supported	no replacement
442B	Slotted Line RF Probe	No longer supported	no replacement
446B	UNTUNED PROBE	No longer supported	no replacement
448A	SWEEP ADAPTER	No longer supported	no replacement
448B	SLOTTED LINE SWE	No longer supported	no replacement
456A	CURRENT PROBE	No longer supported	34134A
461A	AMPLIFIER	No longer supported	
462A	AMPLIFIER	No longer supported	
465A	AMPLIFIER	No longer supported	
467A	POWER AMP	No longer supported	
477B	THERMISTOR MOUNT	No longer supported	no replacement
478AR	Coaxial thermistor mount	Currently supported	
489A	TWT AMPLIFIER	No longer supported	no replacement
491C	TWT AMPLIFIER	No longer supported	no replacement
493A	TWT AMPLIFIER	No longer supported	no replacement
495A	TWT AMPLIFIER	No longer supported	no replacement
508A	TACHOMETER GENER	No longer supported	no replacement
508B	TACHOMETER GENER	No longer supported	no replacement
508C	TACHOMETER GENER	No longer supported	no replacement
508D	TACHOMETER GENER	No longer supported	no replacement
513A	POWER SUPPLY	No longer supported	
536A	Frequency Meter	No longer supported	no replacement
580A	CONVERTER	No longer supported	no replacement
581A	CONVERTER	No longer supported	no replacement
606A	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
606AR	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
606B	SIGNAL GENERATOR	No longer supported	
606BR	SIGNAL GENERATOR	No longer supported	
608E	SIGNAL GENERATOR	No longer supported	
608ER	SIGNAL GENERATOR	No longer supported	
608F	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
608FR	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
612A	SIGNAL GENERATOR	No longer supported	
612AR	SIGNAL GENERATOR	No longer supported	
614A	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
614AR	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
616B	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
616BR	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
618C	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
618CR	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
620B	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
620BR	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
626A	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
626AR	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
628A	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
628AR	KLY SIG. GEN.	No longer supported	http://www.agilent.com/find/psg
653A	TEST OSCILLATOR	No longer supported	no replacement
675A	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/esg

Product	Description	Support Status as of 1 May	Replacement Information
676A	TRACKING DETECTO	No longer supported	no replacement
712C	DC POWER SUPPLY	No longer supported	
716B	POWER SUPPLY	No longer supported	
721A	DC POWER SUPPLY	No longer supported	
735A	DC TRANSFER STAN	No longer supported	no replacement
738BR	CALIBRATOR	No longer supported	no replacement
740B	VOLTMETER	No longer supported	no replacement
741B	VOLTMETER	No longer supported	no replacement
745A	AC CALIBRATOR	No longer supported	no replacement
746A	AMPLIFIER	No longer supported	no replacement
772DR	Coupler,dual directional,0.1 to 18 GHz	Currently supported	
773DR	Coupler, directional, 0.1 to 18 GHz	Currently supported	
774DR	Coaxial Dual Directional Coupler	No longer supported	
775DR	Dual-directional coupler,0.45-0.95 GHz	Currently supported	
776DR	Dual-directional coupler,0.94-1.90 GHz	No longer supported	
777DR	Dual-directional coupler,1.90-4.0GHz	Currently supported	
779DR	Directional coupler, 1.7 to 12.4 GHz	Currently supported	
784A	DIRECTIONAL DETE	No longer supported	
784B	COM BAND DR DETE	No longer supported	784C
784C	Directional detector, 1.7 to 12.4 GHz	No longer supported	no replacement
786D	Coaxial Directional Detector	No longer supported	no replacement
787D	Directional Detector	No longer supported	no replacement
788C	Directional Detector	No longer supported	no replacement
789C	Directional Detector	No longer supported	no replacement
796D	Coaxial Directional Coupler	No longer supported	no replacement
797D	Coaxial Directional coupler	No longer supported	no replacement
798C	Coaxial Directional Coupler	No longer supported	no replacement
805C	SLOTTED LINE	No longer supported	no replacement
809C	Slotted Line Carriage	No longer supported	no replacement
814B	PROBE CARRIAGE	No longer supported	no replacement
817A	SLOTTED LINE SYS	No longer supported	no replacement
817B	SLOTTED LINE SYS	No longer supported	no replacement
851B	SPECTRUM ANALYZE	No longer supported	
853A	PORT SPEC AN DSP	No longer supported	
890A	DC POWER SUPPLY	No longer supported	
895A	DC POWER SUPPLY	No longer supported	no replacement
905A	Sliding Load	No longer supported	
907A	SLIDING LOAD	No longer supported	no replacement
909AR	Coaxial termination, APC-7, dc-18 GHz	Currently supported	
911A	Sliding Load	No longer supported	no replacement
911C	Sliding Load	No longer supported	911D/E
911F	Sliding Mismatch, 3.5mm Female	No longer supported	no replacement
911G	Sliding Mismatch, 3.5mm Male	No longer supported	no replacement
934A	MIXER	No longer supported	no replacement
938A	Frequency Doubler Set	No longer supported	no replacement
940A	Frequency Doubler Set	No longer supported	no replacement
970A	PROBE MULTIMETER	No longer supported	no replacement
1000A	TESTMOBILE	No longer supported	1183A
1001A	TESTMOBILE	No longer supported	1183A
1001B	TESTMOBILE	No longer supported	1183A
1002A	DELUX TESTMOBILE	No longer supported	1183A
1002B	TESTMOBILE	No longer supported	1183A
1003A	TESTMOBILE	No longer supported	1183A
1004A	TESTMOBILE	No longer supported	1183A
1006A	TESTMOBILE FOR INSTRUMENTS 31.5 cm WIDE	No longer supported	
1007A	TESTMOBILE FOR INSTRUMENTS 31.5 cm WIDE	No longer supported	
1008A	TESTMOBILE FOR RACK MOUNT INSTRUMENTS	No longer supported	
1104A	COUNTDOWN SUPPLY	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
1105A	PULSE GENERATOR	No longer supported	
1106A	PROBE	No longer supported	
1106B	TUNNEL DIODE MNT	No longer supported	
1108A	TUNNEL DIODE MNT	No longer supported	
1109B	HIGH PASS FILTER	No longer supported	
1110A	AC CURRENT PROBE	No longer supported	
1110B	CURRENT PROBE	No longer supported	
1111A	PROBE AMPLIFIER	No longer supported	
1112A	POWER SUPPLY	No longer supported	
1114A	TESTMOBILE	No longer supported	
1116A	TESTMOBILE	No longer supported	1183A
1117B	TESTMOBILE	No longer supported	
1118A	TESTMOBILE	No longer supported	1183A
1119A	TESTMOBILE	No longer supported	1183A
1119B	TESTMOBILE	No longer supported	1183A
1119C	TESTMOBILE	No longer supported	1183A
1119D	TESTMOBILE	No longer supported	1183A
1120A	500 MHZ PROBE	No longer supported	
1121A	500 MHz AC Probe	No longer supported	85024A
1122A	PROBE POWER SUPPLY	No longer supported	
1124A	100 MHz ACTIVE DIVIDER PROBE	No longer supported	
1125A	IMPEDANCE CONVER	No longer supported	no replacement
1133A	TV/VIDEO SYNC POD	No longer supported	
1141AR	IX FET differential probe, 200 MHz BW	Currently supported	
1142AR	Probe control & power module for 1141A	No longer supported	
1143AR	Probe offset control and power module	Currently supported	
1150A	WAVEFORM PROCESS	No longer supported	no replacement
1152AR	2.5 GHz, 0.6 pF, Active Probe	Currently supported	
1153AR	200MHz Differential Probe	Currently supported	
1200A	500 KHZ SCOPE	No longer supported	
1200B	500 KHZ SCOPE	No longer supported	
1201A	OSCILLOSCOPE	No longer supported	
1201B	STORAGE SCOPE	No longer supported	
1202A	OSCILLOSCOPE	No longer supported	
1202B	OSCILLOSCOPE	No longer supported	
1205A	OSCILLOSCOPE	No longer supported	
1205B	500 KHZ SCOPE	No longer supported	
1206A	OSCILLOSCOPE	No longer supported	
1206B	OSCILLOSCOPE	No longer supported	
1208A	X-Y DISPLAY	No longer supported	
1208B	X-Y DISPLAY	No longer supported	
1217A	OSCILLOSCOPE	No longer supported	
1217B	OSCILLOSCOPE	No longer supported	
1220A	15 MHZ SCOPE	No longer supported	
1221A	OSCILLOSCOPE	No longer supported	
1222A	15 MHZ SCOPE	No longer supported	
1223A	STORAGE SCOPE	No longer supported	
1230A	LOGIC TRIGGER	No longer supported	no replacement
1300A	X-Y DISPLAY	No longer supported	
1304A	14 INCH XYZ DISP	No longer supported	
1309A	MONITOR SCOPE	No longer supported	
1310A	19" XYZ DISPLAY	No longer supported	
1310B	GRAPHICS DISPLAY	No longer supported	no replacement
1311A	14" XYZ DISPLAY	No longer supported	
1311B	14" XYZ DISPLAY	No longer supported	
1317A	17" XYZ DISPLAY	No longer supported	
1317B	17" XYZ CRT DISP	No longer supported	
1321A	21" XYZ DISPLAY	No longer supported	
1321B	21" CRT DISPLAY	No longer supported	
1330A	X-Y DISPLAY	No longer supported	
1331A	X-Y DISPLAY	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
1331B	X-Y DISPLAY	No longer supported	
1331C	X-Y DISPLAY	No longer supported	
1331D	X-Y DISPLAY	No longer supported	
1332A	6", HIGH RESOLUTION, XYZ DISPALY	No longer supported	
1333A	5" XYZ DISPLAY	No longer supported	
1335A	XY STORAGE DISPL	No longer supported	no replacement
1336A	DISPLAY	No longer supported	
1336P	POWER SUPPLY	No longer supported	
1336S	X/Y CRT DISPLAY	No longer supported	
1338A	TRI-COLOR DISPL	No longer supported	
1340A	6 INCH, HIGH RESOLUTION, XYZ DISPLAY	No longer supported	
1345A	6 INCH DIGITAL DISPLAY	No longer supported	
1346A	HP-IB DISP MOD	No longer supported	
1347A	HP-IB DISPLAY	No longer supported	
1350A	GRAPHICS TRANSLA	No longer supported	no replacement
1350S	DISPLAY SYSTEM	No longer supported	
1351A	GRAPHIC GEN	No longer supported	no replacement
1351S	GRAPHICS SYSTEM	No longer supported	
1360S	GRAPHIC DISP SYS	No longer supported	
1402A	AMPLIFIER	No longer supported	no replacement
1404A	AMPLIFIER	No longer supported	
1405A	AMPLIFIER	No longer supported	
1408A	AMPLIFIER	No longer supported	
1410A	AMPLIFIER	No longer supported	no replacement
1411A	AMPLIFIER	No longer supported	no replacement
1415A	REFLECTOMETER	No longer supported	
1416A	FREQ INDICATOR	No longer supported	
1421A	TIME BASE	No longer supported	no replacement
1423A	TIME BASE	No longer supported	
1424A	TIME BASE	No longer supported	
1425A	TIME BASE	No longer supported	
1430C	SAMPLER	No longer supported	no replacement
1432A	SAMPLER	No longer supported	
1551A	OSCILLOSCOPE	No longer supported	
1551B	OSCILLOSCOPE	No longer supported	
1600A	LOGIC ANALYZER	No longer supported	
1600S	LOGIC ANALYZER	No longer supported	
1601A	LOGIC ANALYZER	No longer supported	
1601L	LOGIC ANALYZER S	No longer supported	
1602A	LOGIC ANALYZER	No longer supported	
1607A	LOGIC ANALYZER	No longer supported	
1610A	LOGIC ST ANALYZR	No longer supported	
1610B	LOGIC ANALYZER	No longer supported	
1611A	LOGIC ANALYZER	No longer supported	
1615A	LOGIC ANALYZER	No longer supported	
1620A	PATTERN ANALYZER	No longer supported	
1630A	LOGIC ANALYZER WITH 35 CHANNELS	No longer supported	
1630D	LOGIC ANALYZER WITH 43 CHANNELS	No longer supported	
1630G	LOGIC ANALYZER WITH 65 CHANNELS	No longer supported	
1630S	LOGIC ANALYSIS SYSTEM REFERENCE	No longer supported	
1631A	LOGIC ANALYZER/DIGITIZING OSCILLOSCOPE	No longer supported	
1631D	LOGIC ANALYZER/DIGITIZING OCSILLOSCOPE	No longer supported	
1631DR	Remarketed Logic Analyzer/Digitizing Oc	No longer supported	no replacement
1631S	SYSTEM REFERENCE	No longer supported	
1640A	SERIAL ANALYZER	No longer supported	
1640B	LOGIC ANALYZER	No longer supported	
1645A	Data Error Analyzer.	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
1650A	80 CHANNEL LOGIC ANALYZER	No longer supported	
1650B	80 CHANNEL LOGIC ANALYZER	No longer supported	
1650BBSK	80 CHANNEL LOGIC ANALYZER	No longer supported	
1650BISK	80 Channel Logic Analyzer	No longer supported	
1650BR	Remarketed 80 Channel Logic Analyzer	No longer supported	
1651A	32 CHANNEL LOGIC ANALYZER	No longer supported	
1651B	32 CHANNEL LOGIC ANALYZER	No longer supported	
1651BBSK	32 CHANNEL LOGIC ANALYZER	No longer supported	
1651BK	32 Channel Logic Analyzer	No longer supported	
1651BR	32 channel Logic Analyzer	No longer supported	
1652B	80 CH LOGIC ANALYZER/2 CH DIG. SCOPE	No longer supported	
1652BR	Rmkt 80 Ch Logic Analyzer/2 Ch Dig Scope	No longer supported	
1653B	32 CH LOGIC ANAL W/ 2 CH DIG. SCOPE	No longer supported	
1654B	64 CHANNEL LOGIC ANALYZER	No longer supported	
1654BK	64 CHANNEL LOGIC ANALYZER	No longer supported	
1660A	136-CHANNEL PORTABLE LOGIC ANALYZER	No longer supported	1660C Series
1660AR	Refurbished 136-Ch Port Logic Analyzer	No longer supported	
1660AS	136-CH LOGIC ANALYZER W/ OSCILLOSCOPE	No longer supported	1660CS Series
1660C	136 Channel Benchtop Logic Analyzer	No longer supported	
1661A	102-CHANNEL PORTABLE LOGIC ANALYZER	No longer supported	1660C Series
1661AR	102-Channel Portable Logic Analyzer	No longer supported	
1661AS	102-CH LOGIC ANALYZER WITH OSCILLOSCOPE	No longer supported	1661CS Series
1661E	102 Channel Color Logic Analyzer	Currently supported	
1662A	68-CHANNEL PORTABLE LOGIC ANALYZER	No longer supported	1662C Series
1662AK	68-CH LOGIC ANALYZER KIT FOR CHINA	No longer supported	1662C Series
1662AR	68-Channel Portable Logic Analyzer	No longer supported	
1662AS	68-CH LOGIC ANALYZER WITH OSCILLOSCOPE	No longer supported	1662CS Series
1662EP	68 Channel Color LA w/32 Ch. Pat. Gen.	Currently supported	
1663A	34-CHANNEL PORTABLE LOGIC ANALYZER	No longer supported	1663C Series
1663AR	34-Channel Portable Logic Analyzer	No longer supported	
1663AS	34-CH LOGIC ANALYZER WITH OSCILLOSCOPE	No longer supported	1663CS Series
1664AR	Value-Priced 34-Channel Logic Analyzer	No longer supported	
1670AR	136-Ch Bnchtp Log Analy w/64K Acq Memory	No longer supported	
1671AR	102-Ch Bnchtp Log Analy w/64K Acq Memory	No longer supported	
1672AR	68-Ch Bnchtp Log analy w/64K Acq Memory	No longer supported	
1700B	OSCILLOSCOPE	No longer supported	
1702A	OSCILLOSCOPE	No longer supported	
1703A	OSCILLOSCOPE	No longer supported	
1707B	OSCILLOSCOPE	No longer supported	
1710A	OSCILLOSCOPE	No longer supported	
1710B	OSCILLOSCOPE	No longer supported	
1712A	OSCILLOSCOPE	No longer supported	
1715A	200 MHZ SCOPE	No longer supported	
1720A	OSCILLOSCOPE	No longer supported	
1720AF	250MHZ SCOPE	No longer supported	
1722A	OSCILLOSCOPE	No longer supported	

Product	Description	Support Status	Replacement Information
1722B	275MHZ SCOPE	No longer supported	
1725A	275MHZ SCOPE	No longer supported	
1726A	TIME INTVL SCOPE	No longer supported	
1727A	HF STORAGE SCOPE	No longer supported	
1731A	PMW 3rd Edition MS Library Upgrade	No longer supported	
1740A	100MHZ SCOPE	No longer supported	
1740AF	100 MHZ SCOPE	No longer supported	
1740S	DATA/TIME ANALYZ	No longer supported	
1741A	100 MHz DUAL CHANNEL STORAGE SCOPE	No longer supported	54600 Family Scopes
1742A	100MHZ SCOPE	No longer supported	
1743A	100MHZ SCOPE	No longer supported	
1744A	100MHZ SCOPE	No longer supported	
1745A	100 MHZ SCOPE	No longer supported	
1746A	100 MHZ SCOPE	No longer supported	
1801A	50 MHZ AMPLIFIER	No longer supported	no replacement
1801F	50 MHZ AMPLIFIER	No longer supported	
1803A	AMPLIFIER	No longer supported	no replacement
1804A	50MHZ AMPLIFIER	No longer supported	
1805A	100MHZ AMPLIFIER	No longer supported	no replacement
1806A	AMPLIFIER	No longer supported	no replacement
1807A	AMPLIFIER	No longer supported	
1808A	AMPLIFIER	No longer supported	no replacement
1809A	100MHZ AMPLIFIER	No longer supported	no replacement
1810A	SAMPLING PLUG-IN	No longer supported	
1811A	SAMPLING PLUG-IN	No longer supported	no replacement
1815A	TDR PLUG-IN	No longer supported	no replacement
1815B	TDR PLUG-IN	No longer supported	
1816A	LADDER BRACKET	No longer supported	no replacement
1817A	SAMPLING HEAD	No longer supported	
1818A	REFLECTOMETER	No longer supported	no replacement
1820A	TIME BASE	No longer supported	
1820B	TIME BASE	No longer supported	
1820C	TIME BASE	No longer supported	
1821A	TIME BASE	No longer supported	no replacement
1821F	TIME BASE	No longer supported	
1824A	TIME BASE	No longer supported	
1825A	TIME BASE	No longer supported	no replacement
1830A	AMPLIFIER	No longer supported	
1831A	DIRECT ACCESS	No longer supported	
1831B	DIRECT ACCESS	No longer supported	
1834A	AMPLIFIER	No longer supported	
1835A	PLUG-IN	No longer supported	
1840A	TIME BASE	No longer supported	
1841A	TIME BASE	No longer supported	
1900A	PLUG-IN MAINFRAM	No longer supported	
1901A	PLUG-IN MAINFRAM	No longer supported	
1905A	RATE GENERATOR	No longer supported	
1906A	RATE GENERATOR	No longer supported	
1908A	DELAY GENERATOR	No longer supported	
1909A	DELAY GENERATOR	No longer supported	
1910A	DELAY GENERATOR	No longer supported	
1915A	RISE AND FALL OU	No longer supported	
1916A	VARIABLE OUTPUT	No longer supported	no replacement
1917A	TRANS TIME OUTPU	No longer supported	
1920A	TRANS TIME OUTPU	No longer supported	
1921A	OUTPUT PLUG-IN	No longer supported	
1922A	OUTPUT PLUG-IN	No longer supported	
1925A	WORD GENERATOR	No longer supported	
1927A	FAN-IN AMPLIFIER	No longer supported	
1928A	FAN-OUT AMPLIFIE	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
1930A	SEQUENCE GENERAT	No longer supported	
1934A	MULTIPHASE CLOCK	No longer supported	
1950A	2 CHANNEL PLUG-IN MODULE FOR 1980A/B	No longer supported	no replacement
1965A	COUNTER EXPANSION MODULE FOR 1980A/B	No longer supported	no replacement
1980A	OSCILLOSCOPE	No longer supported	no replacement
1980B	100 MHz OSCILLOSCOPE MEASUREMENT SYSTEM	No longer supported	no replacement
1980BR	Remarketed 100 MHz oscilloscope	No longer supported	no replacement
1980S	SYSTEM REFERENCE	No longer supported	no replacement
2019A	COUPLER/CONTROLL	No longer supported	no replacement
2070A	DATA LOGGER	No longer supported	34970A
2104AN	M&C PRC.UNIT/PNL	No longer supported	34970A, 3499A, E1419A
2104AR	M&C PRC.UNIT/RAC	No longer supported	34970A, 3499A, E1419A
2212B	V-TO-F CONVERTER	No longer supported	no replacement
2250A	INDUST MEAS CNTL	No longer supported	no replacement
2250H	MEAS CONTROL SYS	No longer supported	no replacement
2250L	MEAS CONTROL SYS	No longer supported	no replacement
2250M	M&C PRCSR MOBILE	No longer supported	no replacement
2250N	M&C PROCSOR NEMA	No longer supported	no replacement
2250R	M&C PROCSOR 56"	No longer supported	no replacement
2250S	MEAS CONTROL SYS	No longer supported	no replacement
2251AN	M&C UNIT PNL MNT	No longer supported	no replacement
2251AR	M&C UNIT RACK MT	No longer supported	no replacement
2255H	MEAS CNTL SUBSYS	No longer supported	no replacement
2300E	RTE SOFTWARE	No longer supported	no replacement
2401C	DIGITAL VOLTMETE	No longer supported	34401A & 3458A
2470B	DATA AMPLIFIER	No longer supported	no replacement
2804A	Quartz Thermometer	No longer supported	no replacement
2811B	QTZ PRESSURE GAU	No longer supported	no replacement
2813B	Quartz Pressure Probe	No longer supported	no replacement
2813C	Quartz Pressure Probe	No longer supported	no replacement
2813D	Quartz Pressure Probe Set	No longer supported	no replacement
2813E	Quartz Pressure Probe	No longer supported	no replacement
2816A	Pressure Signal Processor	No longer supported	no replacement
2820A	PRESS RECORD SYS	No longer supported	no replacement
2830A	SENSOR OSCILLATO	No longer supported	no replacement
3040A	NETWORK ANALYZER	No longer supported	
3041A	NETWORK ANALYZER	No longer supported	
3042A	AUTO NET ANALYZE	No longer supported	
3043A	NETWORK ANALYZER	No longer supported	
3044A	SPECTRUM ANALYZE	No longer supported	3585A
3045A	AUTO SPEC ANALYZ	No longer supported	
3046A	Selective Level Measurement System	No longer supported	
3046B	Auto Selective Level Measurement System	No longer supported	
3046S	Auto Selective Level Measuring System	No longer supported	
3047A	Phase noise measurement system	No longer supported	E5505C
3047S	Phase Noise Measurement System	No longer supported	E5505C
3048A	Phase noise measurement system	No longer supported	3048AR
3048AR	Phase noise measurement system	No longer supported	no replacement
3048MS	Phase Noise Measurement System	No longer supported	E5505C
3048S	Phase noise measurement sys, coordinated	No longer supported	no replacement
3050A	AUTO DATA ACQ SY	No longer supported	34970A
3050B	DATA ACQ SYSTEM	No longer supported	34970A & VXI
3051A	PROG.DATA LOGGER	No longer supported	34970A
3052A	DATA ACQ.SYSTEM	No longer supported	34970A, 3499A
3054A	AUTO DA/C SYSTEM	No longer supported	34970A, 3499A
3054C	AUTO DA/C SYSTEM	No longer supported	34970A, 3499A

Product	Description	Support Status	Replacement Information
3054DL	DATA LOGGER	No longer supported	34970A, 3499A
3054S	AUTO DA/C SYSTEM	No longer supported	34970A, 3499A, E1419A
3055S	PC DA/C SYSTEM	No longer supported	34970A, 3499A
3056DL	DATA LOGGER	No longer supported	34970A, 3499A
3056S	DATA LOGGING SYS	No longer supported	34970A
3057A	DA&C INSTRUMENT, CONTROLLER & SOFTWARE	No longer supported	no replacement
3058A	DA&C INSTRUMENT, CONTROLLER & SOFTWARE	No longer supported	http://www.agilent.com/find/vxi
3059A	DA&C INSTRUMENT, CONTROLLER & SOFTWARE	No longer supported	http://www.agilent.com/find/vxi
3200B	VHF OSCILLATOR	No longer supported	http://www.agilent.com/find/signal_sources
3205A	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
3235A	SWITCH/TEST UNIT	No longer supported	http://www.agilent.com/find/vxi
3235AR	Switch/Test Unit	No longer supported	
3235E	EXTENDER	No longer supported	no replacement
3235PS	POWER SUPPLY 3235	No longer supported	no replacement
3245A	Universal source	Currently supported	33250A
3260A	MARKED CARD PRGM	No longer supported	no replacement
3300A	FUNC GENERATOR	No longer supported	33220A
3302A	PHASE PLUG-IN	No longer supported	no replacement
3304A	OFFSET PLUG-IN	No longer supported	no replacement
3310A	FUNCTION GENERATOR	No longer supported	http://www.agilent.com/find/esg
3310B	FUNCTION GENERAT	No longer supported	http://www.agilent.com/find/esg
3311A	FUNCTION GENERATOR	No longer supported	http://www.agilent.com/find/esg
3312A	Function Generator	No longer supported	33220A
3314A	Programmable Function Generator	No longer supported	33220A
3314AR	Programmable function generator	No longer supported	
3320A	FREQ SYNTHESIZER	No longer supported	http://www.agilent.com/find/esg
3320B	FREQ SYNTHESIZER	No longer supported	http://www.agilent.com/find/esg
3320C	LEVEL GENERATOR	No longer supported	http://www.agilent.com/find/esg
3325A	Synthesizer/Function Generator	No longer supported	http://www.agilent.com/find/esg
3325AR	Synthesizer Frequency Sweeper	No longer supported	
3326A	Two-Channel Synthesizer	No longer supported	
3330A	AUTO SYNTHESIZER	No longer supported	
3330B	AUTO SYNTHESIZER	No longer supported	
3335A	Synthesizer/Level Generator	No longer supported	http://www.agilent.com/find/esg
3335AR	Synthesizer/Level Generator	No longer supported	no replacement
3336A	Synthesis/Level Generator	No longer supported	
3336B	Synthesizer/Level Generator	No longer supported	
3336C	Synthesizer/Level Generator	No longer supported	http://www.agilent.com/find/esg
3400A	RMS VOLTMETER	No longer supported	no replacement
3400B	RMS analog meter	No longer supported	no replacement
3400BR	RMS analog meter	Currently supported	
3403C	RMS VOLTMETER	No longer supported	no replacement
3406A	RF VOLTMETER	No longer supported	no replacement
3410A	MICROVOLTMETER	No longer supported	no replacement
3420B	VOLTMETER/RATIO	No longer supported	34401A , 3458A
3421A	DATA ACQ. UNIT	No longer supported	34970A
3435A	3-1/2 DMM AUTORG	No longer supported	34401A
3437A	SYSTEM VOLTMETER	No longer supported	3458A
3437AR	System voltmeter	No longer supported	
3438A	3-1/2 DMM AUTORG	No longer supported	34401A
3440A	VOLTMETER	No longer supported	34401A
3443A	DC RANGE SELECTO	No longer supported	34401A , 3458A
3444A	MULTI-FUNCTION U	No longer supported	34401A
3445A	AC/DC RANGE UNIT	No longer supported	34401A
3450A	DIGIAL VOLTMETER	No longer supported	34401A , 3458A
3450B	MULTI-METER	No longer supported	34401A, 3458A
3455A	5 OR 6 DIGIT DMM	No longer supported	34401A
3456A	6 1/2 DIGIT DMM	No longer supported	34401A, 3458A

Product	Description	Support Status	Replacement Information
		as of 1 May	
3456AR	6 1/2 Digit DMM *** NOT FOR SALE ***	No longer supported	no replacement
3457A	Digital multimeter	No longer supported	34401A, 3458A, 34970A
3460B	DIGITAL VOLTMETE	No longer supported	34401A & 3458A
3462A	VOLTMETER	No longer supported	34401A & 3458A
3465A	4-1/2 DIGIT DMM	No longer supported	34401A
3465B	4-1/2 DIGIT DMM	No longer supported	34401A
3466A	4 1/2 DIGIT DMM	No longer supported	34401A
3467A	MULTIMETER	No longer supported	34401A
3468A	5.5 digit DMM with HP-IL interface	No longer supported	34401A
3468B	5.5 digit DMM w/ HP-IL, rack/stack case	No longer supported	34401A
3469B	DIGITAL MULTIMET	No longer supported	34401A
3476A	3-1/2 DMM AUTORG	No longer supported	34401A
3476B	3-1/2 DIGIT DMM	No longer supported	34401A
3478A	5.5 digit DMM with HP-IB interface	No longer supported	34401A
3478AR	5.5 Digit DMM w/HP-IB Interface	No longer supported	
3480A	DIGITAL VOLTMETE	No longer supported	34401A
3480B	DIGITAL VOLTMETE	No longer supported	34401A
3480C	DIGITAL VOLTMETE	No longer supported	34401A , 3458A
3480D	DIGITAL VOLTMETE	No longer supported	34401A
3482A	DC RANGE UNIT	No longer supported	34401A , 3458A
3484A	MULTIFUNCTION UN	No longer supported	34401A
3485A	SCANNING UNIT	No longer supported	34970A
3489A	DATA PUNCH	No longer supported	no replacement
3490A	5-1/2 DMM AUTORG	No longer supported	34401A
3495A	SCANNER	No longer supported	34970A, 3499A, E1419A
3497A	ACQ/CONTROL UNIT	No longer supported	34970A
3497AR	ACQ/Control Unit	No longer supported	
3497S	DATA ACQ/CNT SYS	Currently supported	34970A
3498A	EXTENDER	No longer supported	no replacement
3498AR	Extender	No longer supported	
3529A	M.METER PROBE	No longer supported	no replacement
3550B	TEST SET	No longer supported	
3551A	TRANSMISSION TEST SET	No longer supported	no replacement
3552A	Transmission Test Set CCITT	No longer supported	no replacement
3555B	MEASURING SET	No longer supported	no replacement
3556A	PSOPHOMETER	No longer supported	no replacement
3561A	Dynamic Signal Analyzer	No longer supported	35670A
3561AR	Remarketed Dynamic Signal Analyzer	No longer supported	35670A
3562A	Dynamic Signal Analyzer	No longer supported	35670A
3562AR	Remarketed Dynamic Signal Analyzer	No longer supported	
3562S	Dynamic Signal Analyzer System	No longer supported	35670A
3563A	Control Systems Analyzer	No longer supported	35670A
3563AR	Rmkt Control Systems Analyzer	No longer supported	
3567AR	PC Spectrum/Network Analyzer	Currently supported	
3569U	3569A Option Upgrades	Currently supported	no replacement
3570A	NETWORK ANALYZER	No longer supported	
3571A	SPECTRUM ANALYZE	No longer supported	3585A
3575A	Gain/Phase Meter	No longer supported	
3577A	Network Analyzer	No longer supported	3577B
3577B	Network Analyzer 5Hz-200MHz	No longer supported	
3577BR	Remarketed Network Analyzer 5Hz-200MHz	No longer supported	
3577S	Network Analysis System Reference Model	No longer supported	3577B
3580A	Spectrum Analyzer	No longer supported	
3581A	Wave Analyzer	No longer supported	
3581C	Selective Level Meter	No longer supported	
3582A	Spectrum Analyzer	No longer supported	35660A
3582S	STRUCT ANAL SYS	No longer supported	
3585A	Spectrum Analyzer, High Perf 20Hz-40MHz	No longer supported	3585B

Product	Description	Support Status as of 1 May	Replacement Information
3585AR	Rmkt Spect. Anal. High Perf 20Hz-40MHz	No longer supported	no replacement
3585B	Spectrum Analyzer, High Perf 20Hz-40MHz	No longer supported	
3585BR	Spectrum Analyzer, High Perf 20Hz-40MHz	No longer supported	
3586A	Selective Level Meter	No longer supported	no replacement
3586B	Selective Level Meter	No longer supported	no replacement
3586C	Selective Level Meter	No longer supported	no replacement
3587B	Real Time Signal Analysis Bundle System	Currently supported	89600 or E3238S
3587S	3587S System consisting of:	Currently supported	89600 or E3238S
3588AR	Spectrum Analyzer	Currently supported	
3589AR	Rmkt Spectrum/Network Analyzer, 10Hz-150	No longer supported	
3589U	Spectrum/Network Analyzer Upgrade Kits	No longer supported	
3590A	WAVE ANALYZER	No longer supported	no replacement
3591A	WAVE ANALYZER	No longer supported	no replacement
3594A	OSCILLATOR	No longer supported	no replacement
3701A	GENERATOR	No longer supported	no replacement
3702A	DEMOD DISPLAY	No longer supported	no replacement
3702B	IF/BB RECEIVER	No longer supported	no replacement
3709A	Constellation display.	No longer supported	no replacement
3709B	Constellation Analyzer	No longer supported	no replacement
3710A	IF/BB TRANSMITTE	No longer supported	no replacement
3711A	Dual 70/140 MHz IF/BB Transmitter.	No longer supported	no replacement
3712A	Dual 70/140 MHz IF/BB Receiver.	No longer supported	no replacement
3720A	SPECTRUM DISPLAY	No longer supported	no replacement
3721A	CORRELATOR	No longer supported	no replacement
3722A	NOISE GENERATOR	No longer supported	no replacement
3724A	BASEBAND ANAL	No longer supported	no replacement
3725A	DISPLAY	No longer supported	no replacement
3726A	FILTER MAINFRAME	No longer supported	no replacement
3730A	DOWN CONVERTER	No longer supported	no replacement
3730B	Down Converter.	No longer supported	no replacement
3732A	6.420-6.920GHZ O	No longer supported	no replacement
3733A	6.870-7.270GHZ O	No longer supported	no replacement
3736A	1.7 4.2 GHZ	No longer supported	no replacement
3736B	RF MODULE	No longer supported	no replacement
3737A	3.3 6.5 GHZ	No longer supported	no replacement
3737B	RF MODULE	No longer supported	no replacement
3738A	6.3-9.06GHZ PLUG	No longer supported	no replacement
3738B	RF MODULE	No longer supported	no replacement
3739A	10.7-11.7GH PLUG	No longer supported	no replacement
3739B	RF MODULE	No longer supported	no replacement
3739BR	Remarketed RF Module	No longer supported	no replacement
3740A	I.F. SWITCH	No longer supported	no replacement
3743A	IF AMPLIFIER	No longer supported	no replacement
3744A	BASE BAND SWEEPE	No longer supported	no replacement
3745A	SEL LEVEL MEAS S	No longer supported	no replacement
3745B	SEL LEVEL MEAS S	No longer supported	no replacement
3746A	32 MHz Selective Level Measuring Set	No longer supported	no replacement
3747A	90MHZ S L M S	No longer supported	no replacement
3747B	90 MHZ SLMS	No longer supported	no replacement
3750A	COAXIAL EXPAND	No longer supported	no replacement
3754A	ACCESS SWITCH	No longer supported	no replacement
3755A	SWITCH CONTROL	No longer supported	no replacement
3756A	ACCESS SWITCH	No longer supported	no replacement
3757A	ACCESS SWITCH	No longer supported	no replacement
3760A	DATA GENERATOR	No longer supported	no replacement
3761A	ERROR DETECTOR	No longer supported	no replacement
3762A	DATA GENERATOR	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
3763A	ERROR DETECTOR	No longer supported	no replacement
3764AR	Remarketed Transmission Analyzer	No longer supported	
3770A	DIST ANALYZER	No longer supported	no replacement
3770B	TEL LIN ANALYZER	No longer supported	no replacement
3771A	DATA LINE ANALYZ	No longer supported	no replacement
3771B	DATA LINE ANALYZ	No longer supported	no replacement
3776A	PCM TERMINAL TEST SET.	No longer supported	no replacement
3776B	PCM TERMINAL TEST SET.	No longer supported	no replacement
3776BR	Remarketed PCM Terminal Test Set	No longer supported	no replacement
3777A	CHANNEL SELECTOR	No longer supported	no replacement
3779A	PRIM MUX ANAL	No longer supported	no replacement
3779B	PRIM MUX ANAL	No longer supported	no replacement
3779C	PRIMARY MULTIPLEX ANALYZER	No longer supported	no replacement
3779D	PRIMARY MULTIPLEX ANALYZER	No longer supported	no replacement
3781A	PATTERN GENERATOR	No longer supported	no replacement
3781B	PATTERN GENERATOR	No longer supported	no replacement
3782A	ERROR DETECTOR	No longer supported	no replacement
3782B	ERROR DETECTOR	No longer supported	no replacement
3783A	30CH PCM FAMED	No longer supported	no replacement
3784AR	Portable digital transmission analyzer	No longer supported	
3789AR	DS3 Transmission Test Set	No longer supported	
3790A	IF/BB TRANSMITTE	No longer supported	no replacement
3791A	BB TRANSMITTER	No longer supported	no replacement
3791B	BB transmitter plug-in for 3711A	No longer supported	no replacement
3792A	IF/BB RECEIVER	No longer supported	no replacement
3793A	PHASE DETECTOR	No longer supported	no replacement
3793B	Dif. Phase Detector plug-in for 3712A	No longer supported	no replacement
3800A	DISTANCE METER	No longer supported	no replacement
3800B	DISTANCE METER	No longer supported	no replacement
3801A	POWER UNIT	No longer supported	no replacement
3801B	POWER UNIT	No longer supported	no replacement
3805A	DISTANCE METER	No longer supported	no replacement
3808A	MEDIUM RANGE DM	No longer supported	no replacement
3810A	TOTAL STATION	No longer supported	no replacement
3810B	SURVEY TOTAL STA	No longer supported	no replacement
3820A	ELECT TOTAL STA	No longer supported	no replacement
3822A	COORD DETERM SYS	No longer supported	no replacement
3840A	DATA COL PROC SY	No longer supported	no replacement
3840B	DATA COLLECT SYS	No longer supported	no replacement
3841A	SURVEY COMP SYS	No longer supported	no replacement
3841B	SURVEY COMP SYS	No longer supported	no replacement
3842A	SURVEY COMP SYS	No longer supported	no replacement
3842B	SURV COMP SYSTEM	No longer supported	no replacement
3845A	CDS CONTROLLER	No longer supported	no replacement
3846A	INDUS POS SYSTEM	No longer supported	no replacement
3850A	INDUSTRIAL DM	No longer supported	no replacement
3851A	DATA COLLECTOR	No longer supported	no replacement
3852AR	DA&C Mainframe	No longer supported	
3852PS	MAINFRAME POWER SUPPLY MODULE	Currently supported	no replacement
3852S	DATA ACQUISITION AND CONTROL SYSTEM	Currently supported	34970A, 3499A & VXI
3853AR	Extender Chassis	No longer supported	
4022A	FREQ MULTIPLIER	No longer supported	
4050A	ANALOG COMPARATO	No longer supported	
4062A	TEST SYSTEM	No longer supported	
4140A	PA METER SOURCE	No longer supported	
4140BR	PA Meter/DCV SRC	No longer supported	
4145BR	Semiconductor parameter analyzer	No longer supported	
4191A	RF IMPEDANCE ANL	No longer supported	E4991A
4191AR	RF Impedance ANL	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
4193A	IMPEDANCE METER	No longer supported	no replacement
4193AR	Remarketed Impedance Meter	Currently supported	
4195AR	Remarketed Network/Spectrum Analyzer	No longer supported	
4204A	OSCILLATOR	No longer supported	
4260A	UNIVERSAL BRIDGE	No longer supported	4363B
4261A	LCR METER	No longer supported	4263B
4262A	DIGIT LCR METER	No longer supported	4263B
4263A	LCR Meter	No longer supported	4263B
4263AR	LCR Meter	No longer supported	
4263S	Transformer Test System	No longer supported	no replacement
4263U	Upgrade Kit for 4263A	No longer supported	no replacement
4263V	Upgrade kit for the 4263B	Currently supported	no replacement
4265A	UNIVERSAL BRIDGE	No longer supported	
4265B	UNIVERSAL BRIDGE	No longer supported	
4268U	Upgrade Kit for the 4268A	Currently supported	no replacement
4270A	CAPACITANCE BRID	No longer supported	
4271A	DIGITAL LCR METE	No longer supported	
4271B	1MHZ LCR METER	No longer supported	4279A
4272A	1MHZ PRESET C MT	No longer supported	4285A
4273A	CAPACITANCE MTR	No longer supported	4284A
4274A	LCR METER	No longer supported	4284A
4275A	LCR METER	No longer supported	4284A/85A
4276A	LCZ METER	No longer supported	4284A
4277A	LCZ METER	No longer supported	4284A
4278U	Upgrade Kit for 4278A	Currently supported	no replacement
4282A	METER	No longer supported	4284A
4284CV	Semiconductor C-V Measurement Set	No longer supported	no replacement
4284S	Scanning LCR Component Test System	No longer supported	no replacement
4284U	Upgrade Kit for the 4284A	Currently supported	no replacement
4285U	Upgrade kit for the 4285A	Currently supported	no replacement
4286U	Upgrade Kit for the 4286A	Currently supported	no replacement
4287U	Upgrade Kit for the 4287A	Currently supported	no replacement
4291A	RF Impedance/Material Analyzer	No longer supported	E4991A
4291AR	RF Impedance/Material Analyzer	No longer supported	
4291U	Upgrade Kit for the 4291A	No longer supported	no replacement
4291V	Upgrade Kit for the 4291B	Currently supported	no replacement
4294U	Upgrade Kit for the HP 4294A	Currently supported	no replacement
4304B	DC VOLT/AMMETER	No longer supported	
4328A	MILLIOHMETER	No longer supported	4338B
4329A	H.R. METER	No longer supported	4339B
4332A	LCR METER	No longer supported	4263B
4333A	DISTORTION ANALY	No longer supported	
4338A	Milliohmeter	No longer supported	4338B
4338AR	Milliohmeter	No longer supported	
4338U	Upgrade kit for the 4338A	No longer supported	no replacement
4338V	Upgrade kit for the 4338B	No longer supported	no replacement
4339A	High Resistance Meter	No longer supported	4339B
4339AR	High Resistance Meter	No longer supported	
4339U	Upgrade kit for the 4339A	No longer supported	no replacement
4339V	Upgrade kit for the 4339B	No longer supported	no replacement
4342A	Q-METER	No longer supported	4294A
4349A	4-Channel High Resistance Meter	No longer supported	4349B
4349AR	4-Channel High Resistance Meter	No longer supported	
4349U	Upgrade kit for the 4349A	No longer supported	no replacement
4349V	Upgrade kit for the 4349B	No longer supported	no replacement
4350A	CAPACITANCE METE	No longer supported	
4350B	CAPACITANCE METE	No longer supported	
4352A	VCO/PLL Signal Analyzer	No longer supported	4352B
4352AR	VCO/PLL Signal Analyzer	No longer supported	
4352U	Upgrade kit for the 4352A	No longer supported	no replacement
4352V	Upgrade Kit for the 4352B	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
4380A	8-PORT TEST SET	No longer supported	N4413/14/15/16 test sets
4380AR	8-Port Test Set	Currently supported	
4380S	RF Balanced Component/Cable Test System	No longer supported	N4441/42/43/44/46A balanced meas systems
4380U	Upgrade kit for the HP 4380A	Currently supported	no replacement
4395U	Upgrade Kit for the 4395A	Currently supported	no replacement
4396A	RF Network/Spectrum Analyzer	No longer supported	4396B
4396AR	RF Network/Spectrum Analyzer	No longer supported	
4396S	RF AGC Amplifier Test System	No longer supported	no replacement
4396U	Upgrade Kit for the 4396A	No longer supported	no replacement
4396V	Upgrade Kit for the 4396B	Currently supported	no replacement
4436A	ATTENUATOR	No longer supported	
4437A	ATTENUATOR	No longer supported	
4440B	DECADE CAPACITOR	No longer supported	no replacement
4800A	VECTOR IMPED MET	No longer supported	no replacement
4815A	VECTOR IMPED MET	No longer supported	no replacement
4925B	Bit Error Rate Test Set.	No longer supported	no replacement
4935A	Transmission Impairment Measurement Set	No longer supported	no replacement
4935S	Data Test System: 4935A, 4925B, 18134A	No longer supported	no replacement
4936A	CCITT Compatible T I M S	No longer supported	no replacement
4937A	T I M S with signaling	No longer supported	no replacement
4937S	Network Access Transmission Test Set	No longer supported	no replacement
4938A	Network Circuit Access Test Set	No longer supported	no replacement
4945A	Transmission Impairment Measuring Set	No longer supported	no replacement
4947A	TRANSMISSION IMPAIRMENT MEASURING SET	No longer supported	no replacement
4948A	In Service Transm Impairmt Measuring Set	No longer supported	no replacement
4957AR	WAN protocol analyzer, disk-based	No longer supported	
4972AR	Remarketed LAN Protocol Analyzer	No longer supported	
4985AR	LanProbe III Plus/Token Ring	No longer supported	
4985BR	Token-ring Lanprobe	Currently supported	
4986AR	LanProbe III Plus/Ethernet Monitor	No longer supported	
4986BR	Ethernet LanProbe	No longer supported	
4987AR	LanProb III Plus/Ethernet monitor-AUI	Currently supported	
5000A	LOGIC ANALYZER	No longer supported	no replacement
5001A	MPU EXERCISER	No longer supported	no replacement
5001B	MPU EXERCISER	No longer supported	no replacement
5001C	MPU Exerciser for 8085A.	No longer supported	no replacement
5001D	MPU Exerciser for Z80A.	No longer supported	no replacement
5004A	SIGNATURE ANALYZ	No longer supported	no replacement
5005A	Signature Multimeter	No longer supported	no replacement
5005AR	Signature Multimeter	No longer supported	
5005BR	Signature Multimeter with HP-IB	Currently supported	
5006AR	Signature Analyzer	No longer supported	
5010A	IC TROUBLESHOOTI	No longer supported	no replacement
5011T	Logic Kit	No longer supported	no replacement
5015T	LOGIC KIT	No longer supported	no replacement
5021A	Logic Kit	No longer supported	no replacement
5022A	Logic Kit	No longer supported	no replacement
5023A	Logic Kit	No longer supported	no replacement
5024A	Logic Kit	No longer supported	no replacement
5035A	BASIC LOGIC LAB	No longer supported	no replacement
5035T	Logic Laboratory	No longer supported	no replacement
5036A	Microprocessor Laboratory	No longer supported	no replacement
5045A	DIGITAL IC TESTR	No longer supported	no replacement
5046A	IC TEST SYSTEM	No longer supported	no replacement
5046B	IC TEST SYSTEM	No longer supported	no replacement
5046S	Digital IC Test System	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
5050B	DIGITAL RECORDER	No longer supported	no replacement
5055A	DIGITAL RECORDER	No longer supported	no replacement
5061A	FREQUENCY STANDA	No longer supported	5071A.
5061B	Cesium Beam Frequency Standard	No longer supported	5071A
5062C	CS BEAM FREQ REF	No longer supported	5071A
5065A	Rubidium Frequency Standard	No longer supported	5071A
5085A	POWER SUPPLY	No longer supported	no replacement
5089A	Standby Power Supply	product family sold	http://www.agilent.com/find/symmetricom
5089AR	Standby Power Supply	Currently supported	
5100B	FREQ SYNTHESIZER	No longer supported	no replacement
5105A	FREQ SYNTHESIZER	No longer supported	no replacement
5110B	SYNTHESIZER DRIV	No longer supported	no replacement
5150A	Thermal Printer	No longer supported	no replacement
5180A	Waveform Recorder	No longer supported	70700A
5180S	Waveform Measure	No longer supported	no replacement
5180T	Digitizing Scope	No longer supported	70700A
5180U	Digitizing Scope	No longer supported	70700A
5181A	DISPLAY/STORAGE	No longer supported	no replacement
5182A	Waveform Recorder and Generator	No longer supported	70700A
5182S	Waveform Generation	No longer supported	no replacement
5183A	Waveform Recorder	No longer supported	70700A
5183T	Digitizing Scope	No longer supported	70700A
5183U	Digitizing Scope	No longer supported	70700A
5185A	Waveform Recorder	No longer supported	no replacement
5185AR	Waveform Recorder	No longer supported	no replacement
5185T	Precision Digitizing Oscilloscope	No longer supported	no replacement
5185TR	Digitizing Oscilloscope	No longer supported	no replacement
5210A	FREQUENCY METER	No longer supported	
5216A	COUNTER	No longer supported	
5221A	COUNTER	No longer supported	
5221B	COUNTER	No longer supported	
5245L	COUNTER	No longer supported	
5245M	COUNTER	No longer supported	
5246L	COUNTER	No longer supported	
5248L	COUNTER	No longer supported	
5248M	COUNTER	No longer supported	
5252A	PRESALER PLUG I	No longer supported	
5253B	FREQUENCY CONVER	No longer supported	
5254C	FREQUENCY CONVER	No longer supported	
5255A	FREQUENCY CONVER	No longer supported	
5256A	FREQUENCY CONVER	No longer supported	
5257A	TRANS OSC PLUG I	No longer supported	
5258A	SENSITIVE PRESCA	No longer supported	
5261A	VIDEO AMPLIFIER	No longer supported	
5262A	TIME INTERVAL UN	No longer supported	
5264A	PRESET UNIT PLUG	No longer supported	
5265A	DVM PLUG IN	No longer supported	
5267A	TIME INTERVAL UN	No longer supported	
5300A	COUNTER MAINFRM	No longer supported	
5300B	COUNTER MAINFRM	No longer supported	
5301A	10 MHZ FREQ CNTR	No longer supported	
5302A	50 MHZ UNIV CNTR	No longer supported	
5303B	525 MHZ FRQ CNTR	No longer supported	
5304A	TIME INTRVL CNTR	No longer supported	
5305A	FREQUENCY COUNT	No longer supported	
5305B	1300 MHZ COUNTER	No longer supported	
5306A	DIGITAL MULTMETR	No longer supported	
5307A	HIGH RES COUNTER	No longer supported	
5308A	UNIV CNTR/TIMER	No longer supported	
5310A	BATTERY PACK	No longer supported	
5311A	D A C	No longer supported	

Product	Description	Support Status	Replacement Information
5311B	D TO A CONVERTER	No longer supported	
5312A	HP-IB OUTPUT	No longer supported	
5314AR	Universal counter	Currently supported	
5315AR	100 MHz Universal Counter	Currently supported	
5315B	Rack-Mountable 100 MHz Universal Counter	No longer supported	
5316A	HP-IB Universal Counter	No longer supported	
5321A	FREQUENCY COUNT	No longer supported	
5321B	FREQUENCY COUNT	No longer supported	
5323A	FREQ/RPM COUNTER	No longer supported	
5325B	COUNTER	No longer supported	
5326A	TIMER/COUNTER	No longer supported	
5326B	TIMER/COUNTR/DVM	No longer supported	
5326C	FREQUENCY COUNT	No longer supported	
5327A	550 MHZ TIMER	No longer supported	
5327B	550 MHZ TIMER	No longer supported	
5327C	550 MHZ COUNTER	No longer supported	
5328A	100 MHZ UNV CNTR	No longer supported	
5328AH99	TRI-SERVICE COUNTER	No longer supported	
5328B	100 MHz Universal Counter	No longer supported	53131A/32A
5328BR	100 MHz Universal counter	No longer supported	
5330A	PRESET COUNTER	No longer supported	
5330B	PRESET COUNTER	No longer supported	
5332B	PRESET CONTROLLE	No longer supported	
5334A	100 MHz Universal Counter	No longer supported	53131A/32A
5334AR	100MHz Universal Counter	No longer supported	no replacement
5334BR	100 MHz Universal Counter	No longer supported	
5334R	Beacon Radio Set	No longer supported	H06-5334A
5335AR	200MHz Universal Counter	Currently supported	
5340A	Microwave Frequency Counter	No longer supported	53150A
5340AR	Remarketed Microwave Frequency Counter	No longer supported	no replacement
5341A	FREQUENCY COUNT	No longer supported	
5342A	Microwave Frequency Counter	No longer supported	53150A
5342AR	Microwave Frequency Counter	No longer supported	5350B
5342M	Microwave Frequency Counter	No longer supported	
5343A	Microwave Frequency Counter	No longer supported	53151A
5343AR	Microwave Frequency Counter	No longer supported	5351B
5344A	NOT FOR SALE PRODUCT	No longer supported	no replacement
5344S	Microwave Source Synchronizer System	No longer supported	no replacement
5345AR	500 MHz Universal Counter	Currently supported	
5345M	MATE Pulse Microwave Counter	No longer supported	
5348AR	26.5 GHz Counter/Power Meter	Currently supported	
5350A	20 GHz Microwave Frequency Counter	No longer supported	
5350BR	CW microwave frequency counter	Currently supported	
5351A	26.5 GHZ MICROWAVE FREQUENCY COUNTER	No longer supported	
5352A	Microwave Frequency Counter	No longer supported	
5353A	CHANNEL C	No longer supported	
5354A	FREQ CONVERTER	No longer supported	no replacement
5355A	Auto Frequency Converter	No longer supported	no replacement
5355AR	Auto frequency converter	Currently supported	
5356A	18 GHz Frequency Converter	No longer supported	53131A
5356AR	18 GHz Frequency converter	No longer supported	
5356B	26.5 GHz Frequency Converter	No longer supported	53131A
5356BR	26.5 GHz Frequency Converter	No longer supported	
5356C	Frequency Converter Head	No longer supported	no replacement
5356CR	Frequency converter head	Currently supported	
5356D	36-110 GHz Harmonic Mixer Driver	No longer supported	no replacement
5356DR	36-110 GHz Harmonic Mixer Driver	No longer supported	no replacement
5358A	MEASURE STORAGE	No longer supported	

Product	Description	Support Status	Replacement Information
5359AR	Time Synthesizer	Currently supported	
5360A	COMPUTING COUNT	No longer supported	
5361A	20 GHz Pulse/CW Microwave Counter	No longer supported	5361b
5363A	TIME INT PROBES	No longer supported	no replacement
5363B	Time Interval Probes	No longer supported	no replacement
5364A	MICROWAVE MIXER/DETECTOR	Currently supported	no replacement
5364AR	Microwave Mixer/Detector	Currently supported	
5370A	UNIVERSAL CNTR	No longer supported	
5371AR	Rmkt Frequency & Time Interval Analyzer	No longer supported	
5372AR	Rmkt Frequency & Time Interval Analyzer	No longer supported	
5373AR	Modulation domain pulse analyzer	No longer supported	
5375A	KEYBOARD	No longer supported	
5376A	SYSTEMS PROGRAMM	No longer supported	
5379A	TIME INTERVAL PL	No longer supported	
5381A	80 MHZ FREQ CNTR	No longer supported	
5382A	225 MHz Frequency Counter	No longer supported	
5383A	520 MHz Frequency Counter	No longer supported	
5385AR	1000 MHz Frequency Counter	Currently supported	
5386AR	Frequency counter	Currently supported	
5390A	FREQ STAB ANALY	No longer supported	no replacement
5391A	F&T DATA ACQ SYS	No longer supported	no replacement
5401B	MULTICHAN ANALYZ	No longer supported	no replacement
5402A	MCA/BASIC SYSTEM	No longer supported	no replacement
5406B	NUCLEAR ANALYZER	No longer supported	no replacement
5420A	SIGNAL ANALYZER	No longer supported	
5420B	SIGNAL ANALYZER	No longer supported	
5423A	STR DYN ANALYZER	No longer supported	35670A
5425A	VIBRATION CONTRO	No longer supported	no replacement
5427A	VIBRATION CONTROL SYSTEM	No longer supported	no replacement
5451A	FOURIER ANALYZER	No longer supported	no replacement
5451B	FOURIER ANALYZER	No longer supported	no replacement
5451C	FOURIER ANALYZER	No longer supported	no replacement
5453A	ANALYZER	No longer supported	no replacement
5468A	TRANSPONDER	No longer supported	no replacement
5470B	FOURIER PROCESSO	No longer supported	no replacement
5471A	FFT ARITH	No longer supported	no replacement
5480B	SIGNAL ANALYZER	No longer supported	no replacement
5480S	SIGNAL ANALYZER	No longer supported	no replacement
5481A	SIGNAL ANALYZER	No longer supported	no replacement
5485A	DUAL CHANNEL PLU	No longer supported	no replacement
5486B	PROCESS CONTROL	No longer supported	no replacement
5487A	FOUR CHANNEL INP	No longer supported	no replacement
5488A	AVERAGE CORRELAT	No longer supported	no replacement
5489A	LOW PASS FILTER	No longer supported	no replacement
5500C	LASER HEAD	No longer supported	5517A
5501A	Laser Head	No longer supported	5517B
5505A	LASER DISPLAY	No longer supported	Electronics
5507A	Laser Position Transducer Electronics	No longer supported	5507B
5507BR	Laser Position Transducer Electronics	Currently supported	
5510A	Auto Compensator	No longer supported	no replacement
5517BR	Laser Head for PC,VME,5501A and 5527A	Currently supported	
5526A	LASER MEAS SYSTM	No longer supported	5529B
5527A	Laser Position Transducer	No longer supported	5527B
5529VR	Dynamic Calibrator	No longer supported	
5554A	PREAMPLIFIER	No longer supported	no replacement
5580B	NIM POWER SUPPLY	No longer supported	no replacement
5582A	LINEAR AMPLIFIER	No longer supported	no replacement
5583A	ANALYZER	No longer supported	no replacement
5586A	SPECTR STABILIZE	No longer supported	no replacement
5590A	SCALER TIMER	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
5851A	RG-213 Antenna Cable (N toTNC)	product family sold	http://www.agilent.com/find/symmetricom
6002A	DC POWER SUPPLY	No longer supported	664XA
6010AR	DC Power Supply,0-200Vdc,0-17Amps	Currently supported	
6011AR	DC power supply,0-20Vdc,0-120Amps	Currently supported	
6012A	DC POWER SUPPLY	No longer supported	6012B
6012BR	DC power supply, 0-60Vdc, 0-50Amps	Currently supported	
6015AR	DC Power Supply, 0-500Vdc, 0-5 Amps	Currently supported	
6023AR	DC power supply, 0-20Vdc, 0-30A	Currently supported	
6024A	DC power supply, 0-60 Vdc, 0-10 amps	No longer supported	6028A
6024AR	DC power supply, 0-60 Vdc, 0-10 amps	No longer supported	
6030AR	DC system power supply, 0-200Vdc, 0-17A	Currently supported	
6031AR	DC System Power Supply, 0-20 Vdc,0-120A	Currently supported	
6033AR	DC system power supply, 0-20Vdc,0-30amps	Currently supported	
6034A	DC POWER SUPPLY	No longer supported	
6034L	DC POWER SUPPLY	No longer supported	
6034LR	Remarketed DC Power Supply	No longer supported	no replacement
6038AR	Rmkt Support Purpose Only Not For Sale	Currently supported	
6038L	SYSTEM POWER SUPPLY	No longer supported	6038A
6038LR	Remarketed System Power Supply	No longer supported	
6051AR	600 Watt Load Mainframe.	Currently supported	
6060A	Order 6060B	No longer supported	6060B
6063A	Order 6063B	No longer supported	
6063BR	250W single load (0-10A, 3-240V)	Currently supported	
6101A	DC POWER SUPPLY	No longer supported	6111A
6102A	DC POWER SUPPLY	No longer supported	6112A
6104A	DC POWER SUPPLY	No longer supported	6114A
6105A	DC POWER SUPPLY	No longer supported	6115A
6106A	DC POWER SUPPLY	No longer supported	6116A
6110A	DC POWER SUPPLY	No longer supported	
6111A	DC POWER SUPPLY	No longer supported	
6112A	DC POWER SUPPLY	No longer supported	
6113A	DC POWER SUPPLY	No longer supported	
6114AR	Precision DC Power Supply, Dual Range	Currently supported	
6115AR	DC Power Supply	Currently supported	
6116A	DC POWER SUPPLY	No longer supported	
6128C	VOLTAGE SOURCE	No longer supported	
6129B	VOLTAGE SOURCE	No longer supported	
6129C	DIGITAL VOLTAGE SOURCE	No longer supported	no replacement
6130B	VOLTAGE SOURCE	No longer supported	
6130C	DIGITAL VOLTAGE SOURCE	No longer supported	no replacement
6131B	D16. VOLT. SOURC	No longer supported	
6131C	VOLTAGE SOURCE	No longer supported	no replacement
6140A	DIGITAL CURRENT SOURCE	No longer supported	no replacement
6145A	CURRENT SOURCE	No longer supported	
6177B	POWER SUPPLY	No longer supported	
6181B	POWER SUPPLY	No longer supported	
6181CR	DC Power Supply	Currently supported	
6186B	POWER SUPPLY	No longer supported	
6186CR	Power Supply	Currently supported	
6200B	DC POWER SUPPLY	No longer supported	
6201B	DC POWER SUPPLY	No longer supported	
6202B	DC POWER SUPPLY	No longer supported	
6203B	DC POWER SUPPLY	No longer supported	
6204B	DC POWER SUPPLY	No longer supported	
6205B	DC POWER SUPPLY	No longer supported	
6205CR	DC Power Supply	Currently supported	
6206B	DC POWER SUPPLY	No longer supported	6294A
6207B	DC POWER SUPPLY	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
6209BR	DC Power Supply	Currently supported	
6211A	DC POWER SUPPLY	No longer supported	
6212A	DC POWER SUPPLY	No longer supported	
6212B	DC POWER SUPPLY	No longer supported	6212C
6212C	DC POWER SUPPLY	No longer supported	E3612A
6213A	DC POWER SUPPLY	No longer supported	
6214A	DC POWER SUPPLY	No longer supported	
6214B	DC POWER SUPPLY	No longer supported	6214C
6214C	DC POWER SUPPLY	No longer supported	E3610A
6215A	DC POWER SUPPLY	No longer supported	
6216A	DC POWER SUPPLY	No longer supported	
6216B	DC POWER SUPPLY	No longer supported	6216C
6216C	DC POWER SUPPLY	No longer supported	E3611A
6217A	DC POWER SUPPLY	No longer supported	
6218A	DC POWER SUPPLY	No longer supported	
6218B	DC POWER SUPPLY	No longer supported	6218C
6218C	DC POWER SUPPLY	No longer supported	E3612A
6220B	DC POWER SUPPLY	No longer supported	
6224B	DC POWER SUPPLY	No longer supported	
6226B	DC POWER SUPPLY	No longer supported	
6227BR	DC Power Supply	Currently supported	
6228BR	DC Power Supply	Currently supported	
6234A	DC POWER SUPPLY	No longer supported	E3620A
6235A	DC POWER SUPPLY	No longer supported	E3630A
6235AR	DC Power Supply	No longer supported	
6236A	DC POWER SUPPLY	No longer supported	
6236B	DC POWER SUPPLY	No longer supported	E3630A
6237A	DC POWER SUPPLY	No longer supported	
6237B	DC POWER SUPPLY	No longer supported	
6253AR	DC Power Supply	Currently supported	
6255AR	DC power supply	Currently supported	
6256B	DC POWER SUPPLY	No longer supported	
6259B	DC POWER SUPPLY	No longer supported	6260B
6260BR	DC Power Supply	Currently supported	
6261B	DC POWER SUPPLY	No longer supported	6269B
6263B	DC POWER SUPPLY	No longer supported	6542A
6264B	DC POWER SUPPLY	No longer supported	
6265B	DC POWER SUPPLY	No longer supported	
6266B	DC POWER SUPPLY	No longer supported	6543A
6267B	DC POWER SUPPLY	No longer supported	6553A
6267BR	DC Power Supply	No longer supported	
6268BR	DC Power Supply	Currently supported	
6271B	DC POWER SUPPLY	No longer supported	
6281A	DC POWER SUPPLY	No longer supported	E3614A
6281AR	DC Power Supply	No longer supported	E3614A
6284A	DC POWER SUPPLY	No longer supported	E3615A
6284AR	DC Power Supply	No longer supported	
6285A	DC POWER SUPPLY	No longer supported	6286A
6289A	DC POWER SUPPLY	No longer supported	E3616A
6289AR	DC Power Supply	No longer supported	
6290A	DC POWER SUPPLY	No longer supported	6291A
6291AR	DC Power Supply	Currently supported	
6294A	DC POWER SUPPLY	No longer supported	E3617A
6296AR	DC Power Supply	Currently supported	
6299A	DC POWER SUPPLY	No longer supported	
6384A	DC POWER SUPPLY	No longer supported	
6427B	DC POWER SUPPLY	No longer supported	
6428B	DC POWER SUPPLY	No longer supported	
6433B	DC POWER SUPPLY	No longer supported	
6434B	DC POWER SUPPLY	No longer supported	6012B
6438B	DC POWER SUPPLY	No longer supported	

Product	Description	Support Status	Replacement Information
6439B	DC POWER SUPPLY	No longer supported	
6443B	DC POWER SUPPLY	No longer supported	no replacement
6448B	DC POWER SUPPLY	No longer supported	6015A
6453A	DC POWER SUPPLY	No longer supported	2 of 6572A
6456B	DC POWER SUPPLY	No longer supported	2 of 6572A
6459A	DC POWER SUPPLY	No longer supported	2 of 6573A
6464C	DC POWER SUPPLY	No longer supported	2 of 6681A
6466C	DC POWER SUPPLY	No longer supported	2 of 6681A
6469C	DC POWER SUPPLY	No longer supported	2 of 6683A
6472C	DC POWER SUPPLY	No longer supported	
6475C	DC POWER SUPPLY	No longer supported	no replacement
6477C	DC POWER SUPPLY	No longer supported	no replacement
6479C	DC POWER SUPPLY	No longer supported	no replacement
6483C	DC POWER SUPPLY	No longer supported	no replacement
6515A	DC POWER SUPPLY	No longer supported	no replacement
6516A	DC POWER SUPPLY	No longer supported	no replacement
6521A	DC POWER SUPPLY	No longer supported	no replacement
6522A	DC POWER SUPPLY	No longer supported	
6525A	DC POWER SUPPLY	No longer supported	no replacement
6541AR	DC Power Supply	Currently supported	
6542AR	DC Power Supply	Currently supported	
6543AR	DC Power Supply	Currently supported	
6544AR	DC Power Supply	Currently supported	
6545AR	DC Power Supply	Currently supported	
6551AR	DC Power Supply	Currently supported	
6554AR	DC Power supply	Currently supported	
6555AR	DC Power Supply	Currently supported	
6571AR	DC Non-System Power Supply 0-8V,0-220A	Currently supported	
6573AR	DC Non-System Power Supply 0-35V,0-60A	Currently supported	
6574AR	DC non-system power supply	Currently supported	
6612B	GPIB DC Power Supply, 20Vdc, 2A	No longer supported	6612C
6612BR	HP-IB DC Power Supply, 20Vdc, 2A	Currently supported	
6612CR	GPIB DC Power Supply, 20Vdc, 2A	Currently supported	
6621AR	Dual-out HP-IB DC Power Supply, 0-7 Vdc	Currently supported	
6622AR	Dual out HP-IB DC power supply 0-20 Vdc	Currently supported	
6625AR	Precision dual-out HP-IB dc power supply	Currently supported	
6627AR	Quad-out HP-IB dc power supply, 0-20Vdc	Currently supported	
6628AR	DC Power Supply	Currently supported	
6632A	GPIB dc power supply, 0-20 Vdc, 0-5 A	No longer supported	6632B
6632AR	HP-IB DC power supply, 0-20 Vdc, 0-5 A	Currently supported	
6633A	GPIB dc power supply, 0-50 Vdc, 0-2 A	No longer supported	6633B
6633AR	HP-IB DC Power Supply, 0-50 Vdc, 0-2A	Currently supported	
6633BR	HP-IB dc power supply, 50Vdc, 2A	Currently supported	
6634A	GPIB dc power supply, 0-100 Vdc, 0-1 A	No longer supported	6634B
6634BR	HP-IB dc power supply, 100Vdc, 1A	Currently supported	
6641AR	DC Power Supply	Currently supported	
6643AR	HP-IB DC power supply,35V,6A,200W	Currently supported	
6644AR	HP-IB dc power supply, 60V, 3.5A, 200W	Currently supported	
6645AR	DC Power Supply	Currently supported	
6651AR	DC Power supply	Currently supported	
6673AR	DC System Power Supply 0-35V,0-60A	Currently supported	
6674AR	DC System Power Supply 0-60V, 0-35A	Currently supported	
6680AR	DC Power Supply	Currently supported	
6681AR	DC system power supply 8V, 580A	Currently supported	
6682AR	DC Power Supply	Currently supported	
6684AR	DC Power Supply	Currently supported	

Product	Description	Support Status	Replacement Information
6811A	AC power source/analyzer 375 VA	No longer supported	
6811AR	AC power source/analyze 375VA	Currently supported	
6812A	AC power source/analyzer 750 VA	No longer supported	
6813A	AC power source/analyzer 1750 VA	No longer supported	
6814A	AC Power Source/Analyzer	No longer supported	6814B.
6814AR	AC Power source/analyzer	No longer supported	6814B
6814BR	AC Power Source/Analyzer 3000VA	Currently supported	
6823A	POWER SUPPLY/AMP	No longer supported	6825A
6824A	P/S AMPLIFIER	No longer supported	
6826AR	P/S Amplifier	Currently supported	
6827AR	P/S Amplifier	Currently supported	
6830A	SUPPLY/AMPLIFIER	No longer supported	
6831A	SUPPLY/AMPLIFIER	No longer supported	
6832A	SUPPLY/AMPLIFIER	No longer supported	
6834A	AC power source/analyzer 4500 VA	No longer supported	6834B.
6841A	750 VA Harmonic/Flicker Test System	No longer supported	
6841AR	750 VA Harmonic/Flicker Test System	Currently supported	
6842A	1750 VA Harmonic/Flicker Test System	No longer supported	
6842AR	1750 VA Harmonic/Flicker Test System	Currently supported	
6901A	64 FET CHAN SYST	No longer supported	no replacement
6901S	MES&ANALYSIS SYS	No longer supported	no replacement
6920B	METER CALIBRATOR	No longer supported	no replacement
6933B	CONVERTER	No longer supported	
6940A	MULTIPROGRAMMER	No longer supported	
6940B	MULTIPROGRAMMER	No longer supported	no replacement
6941A	EXTENDER	No longer supported	
6941B	MULTI-EXTENDER	No longer supported	no replacement
6942A	MULTIPROGRAMMER	No longer supported	no replacement
6942AR	Multiprogrammer	Currently supported	
6942S	CAT SYSTEM	No longer supported	no replacement
6943A	MULTI-EXTENDER	No longer supported	no replacement
6944A	MULTIPROGRAMMER	No longer supported	no replacement
6944S	6944 SYSTEM	No longer supported	no replacement
6947A	RASTER DISPLAY	No longer supported	
6954A	MULTIPROGRAMMER	No longer supported	no replacement
7090A	6-pen Measurment Plotting System.	No longer supported	no replacement
8002A	PULSE GENERATOR	No longer supported	81101A
8003A	PULSE GENERATOR	No longer supported	81101A
8004A	PULSE GENERATOR	No longer supported	81110A
8005A	PULSE GENERATOR	No longer supported	81101A
8005B	20 MHZ, DUAL-OUTPUT PULSE GENERATOR	No longer supported	81104A
8006A	WORD GENERATOR	No longer supported	8175A
8007B	PULSE GENERATOR	No longer supported	81110A
8008A	PULSE GENERATOR	No longer supported	81110A
8010A	PULSE GENERATOR	No longer supported	81104A
8011A	20MHz PULSE GENERATOR	No longer supported	81101A
8012A	PULSE GENERATOR	No longer supported	81101A
8012B	50 MHZ PULSE GENERATOR	No longer supported	81101A
8013A	PULSE GENERATOR	No longer supported	81101A
8013B	50 MHZ DUAL-OUTPUT PULSE GENERATOR	No longer supported	81104A
8015A	50 MHZ DUAL-OUTPUT PULSE GENERATOR	No longer supported	81104A
8016A	50 MBIT/S DATA GENERATOR, 8 CH X 32 BIT	No longer supported	no replacement
8018A	50 MBIT/S DATA GENERATOR, 2 CH X 1 KBIT	No longer supported	81104A
8057A	NOISE GENERATOR	No longer supported	no replacement
8080A	MAINFRAME FOR 8080 SERIES MODULES	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
8081A	300 MHZ RATE GENERATOR FOR 8080A	No longer supported	8130A
8082A	250MHz DUAL-OUTPUT PULSE GENERATOR	No longer supported	8130A
8083A	300 MHZ OUTPUT AMPLIFIER FOR 8080A	No longer supported	8131A
8084A	300 MBIT/S DATA MODULE FOR 8080A	No longer supported	no replacement
8091A	1 GHZ RATE GENERATOR FOR 8080A	No longer supported	no replacement
8092A	1 GHZ DELAY MODULE FOR 8080A	No longer supported	no replacement
8093A	1 GHZ OUTPUT AMPLIFIER FOR 8080A	No longer supported	no replacement
8100A	TAPE PUNCH	No longer supported	No replacement
8111A	20 MHZ PULSE/FUNCTION GENERATOR	No longer supported	33120A
8112AR	50 MHz Pulse Generator	No longer supported	
8115A	50MHz DUAL CHANNEL PULSE GENERATOR	No longer supported	8110A
8116A	50 MHZ PULSE/FUNCTION GENERATOR	No longer supported	33250A
8116AR	50 MHz Pulse/Function Generator	No longer supported	
8118A	100Mbit/s PULSE PATTERN GENERATOR	No longer supported	8110A
8130AR	300MHz Pulse Generator	No longer supported	
8131AR	500MHz Pulse Generator	No longer supported	
8140A	OPTICAL LOSS TEST SET, MAINFRAME	No longer supported	no replacement
8140CC	CARRYING CASE	No longer supported	no replacement
8145A	OTDR MAINFRAME	No longer supported	no replacement
8145AR	Remarketed CTDR Mainframe	No longer supported	no replacement
8146A	OPT. TIME DOMAIN REFLECTOMETER MAINFRAME	No longer supported	no replacement
8147A	refer to E4310A OTDR	Currently supported	no replacement
8150A	OPTICAL SIGNAL SOURCE 850 NM	No longer supported	no replacement
8151A	OPT POWER METER	No longer supported	no replacement
8152A	OPTICAL AVERAGE POWER METER	No longer supported	8163B and modules
8153A	LIGHTWAVE MULTIMETER MAINFRAME	Currently supported	8163B
8154B	LED SOURCE	No longer supported	no replacement
8155A	LASER SOURCE	No longer supported	8163B and modules
8157A	OPTICAL ATTENUATOR	No longer supported	81570A
8158B	OPTICAL ATTENUATOR	No longer supported	81570A (for SM fibers only)
8159A	OPTICAL SWITCH	No longer supported	no replacement
8160A	50MHz PULSE GENERATOR	No longer supported	8110A
8160AR	50MHz pulse generator	No longer supported	
8161A	100MHz PULSE GENERATOR	No longer supported	8110A
8161AR	100MHz Pulse Generator	No longer supported	
8165A	50 MHZ PULSE/FUNCTION GENERATOR	No longer supported	no replacement
8165AR	50MHz Pulse/Function Generator	No longer supported	
8167A	TUNABLE LASER SOURCE	No longer supported	81600B #132
8167B	Tunable Laser Source 1310nm	Currently supported	81600B #132
8168A	TUNABLE LASER SOURCE	No longer supported	81980A/81989A
8168B	Tunable Laser Source 1550nm, -4dBm	No longer supported	81980A/81989A
8168C	Tunable Laser Source 1550nm, +2.5dBm	No longer supported	81980A/81989A
8168D	Tunable Laser Source 1550nm, -4dBm	Currently supported	81980A/81989A
8168E	Tunable Laser Source 1550nm, +0dBm	Currently supported	81980A/81989A
8168F	Tunable Laser Source 1550nm, +7Bm	Currently supported	81980A/81989A
8170A	2 MBIT/S DATA GEN, 8 CHANNELS X 4 KBIT	No longer supported	8175A
8175A	DATA/WAVEFORM GENERATOR,50MBIT/S, 24/2CH	No longer supported	

Product	Description	Support Status	Replacement Information
8175AR	Data/waveform generator,50MBIT/s,24/2ch	No longer supported	
8241AR	250kHz-20 GHz Microwave Signal Generator	No longer supported	
8327A	TEST SET SELECTOR	No longer supported	
8328A	Transmission line test system. 20 GHz.	No longer supported	
8328S	Transmission line test system	No longer supported	
8340A	10 MHz 26.5 GHz Synthesized Sweeper	No longer supported	http://www.agilent.com/find/psg
8340B	Synthesized sweeper, 10 MHz to 26.5 GHz	Currently supported	http://www.agilent.com/find/psg
8341A	10 MHz 20 GHz Synthesized Sweeper	No longer supported	8341B
8341B	10 MHz 20 GHz Synthesized Sweeper	No longer supported	http://www.agilent.com/find/psg
8341BR	Rmkt synthesized sweeper, 0.01-20 GHz	Currently supported	
8346A	mm-wave amplifier, 26.5 to 40 GHz	No longer supported	
8349A	MICROWAVE AMPLIF	No longer supported	8349B
8350A	SWEEP OSCILLATOR	No longer supported	
8350BR	Remarketed sweep oscillator mainframe	No longer supported	
8403A	Modulator	No longer supported	no replacement
8404A	AMPLIFIER	No longer supported	no replacement
8405A	Vector voltmeter	No longer supported	
8406A	COMB GENERATOR	No longer supported	no replacement
8407A	NETWORK ANALYZER	No longer supported	E8362B
8408A	NETWORK ANAL SYS	No longer supported	E8362B
8408B	Network Analyzer Subsystem	No longer supported	E8362B
8408S	Automatic Network Analyzer	No longer supported	E8362B
8409A	NETWORK ANAL SYS	No longer supported	E8362B
8409B	NETWORK ANAL SYS	No longer supported	E8362B
8409C	NETWORK ANAL SYS	No longer supported	E8362B
8409S	AUTO NETWORK ANA	No longer supported	E8362B
8410A	NETWORK ANALYZER	No longer supported	E8362B
8410B	NETWORK ANALYZER	No longer supported	E8362B
8410C	Network Analyzer	No longer supported	E8362B
8410S	Network Analyzer	No longer supported	E8362B
8411A	Frequency Converter	No longer supported	
8412A	PHASE-MAG DISPLA	No longer supported	
8412B	Phase-Magnitude Display	No longer supported	
8413A	INDICATOR	No longer supported	
8414A	POLOR DISPLAY	No longer supported	
8414B	Polar Display	No longer supported	
8418A	POWER SUPPLY	No longer supported	
8418B	Auxiliary Display Holder	No longer supported	
8430A	BANDPASS FILTER	No longer supported	no replacement
8431A	BANDPASS FILTER	No longer supported	no replacement
8432A	BANDPASS FILTER	No longer supported	no replacement
8433A	BANDPASS FILTER	No longer supported	no replacement
8434A	BANDPASS FILTER	No longer supported	no replacement
8435A	BANDPASS FILTER	No longer supported	no replacement
8436A	BANDPASS FILTER	No longer supported	no replacement
8439A	NOTCH FILTER	No longer supported	
8441A	PRESELECTOR	No longer supported	
8442A	CRYSTAL FILTER	No longer supported	
8443A	TRACK GEN/COUNTR	No longer supported	
8443B	TRACKING GEN	No longer supported	
8444A	Tracking generator for 8554B, 8555A,	No longer supported	no replacement
8444AR	Tracking generator for 8554B,8555A,	No longer supported	
8445B	AUTO PRESELECTOR	No longer supported	no replacement
8447B	AMPLIFIER	No longer supported	
8447C	AMPLIFIER	No longer supported	
8447E	0.1-1300 MHz power amplifier; 115/230 V	No longer supported	no replacement
8447FR	Preamp obsolete: Opt. H64 avail. for EM	No longer supported	
8449A	Preamplifer. REFURBISHED	No longer supported	8449B

Product	Description	Support Status as of 1 May	Replacement Information
8470A	Coaxial Crystal Detector	No longer supported	8470B
8471A	RF Point-Contact Detector	No longer supported	no replacement
8472A	Point Contact Crystal Detector	No longer supported	8472B
8473DR	Coax detector	Currently supported	
8474D	Detector, Coaxial, .01 to 40 Ghz	No longer supported	no replacement
8481AR	Power sensor, 10 MHz to 18 GHz	Currently supported	
8481BR	High-power thermocouple power sensor	Currently supported	
8481DR	Diode power sensor, 10 MHz-18 GHz	Currently supported	
8481HR	3-Watt Power Sensor, 10 MHz 18 GHz	Currently supported	
8482AR	Power Sensor, 100 kHz to 4.2 GHz	Currently supported	
8482HR	3-W Power Sensor, 100 KHz to 4.2 GHz	Currently supported	
8483AR	75-ohm power sensor,100kHz to 2 GHz	Currently supported	
8484A	Power Sensor	Currently supported	8481D
8484AR	Power sensor	Currently supported	
8485AR	Power sensor, 50 MHz to 26.5 GHz	Currently supported	
8491AR	Coaxial attenuator, dc-12.4 GHz, Type N	Currently supported	
8491BR	Coaxial attenuator, DC 18 GHz, Type N	Currently supported	
8493AR	Coaxial attenuator, DC to 12.4 GHz, SMA	Currently supported	
8493CR	Coaxial fixed attenuator, DC to 26.5 GHz	Currently supported	
8494BR	0-11 dB Manual Step Attenuator -0-18GHz	Currently supported	
8494GR	0-11dB programmable step atten., DC-4GHz	Currently supported	
8495BR	0-70 dB Manual Step Attenuator, 0-18 GHz	Currently supported	
8495KR	Programmable step attenuator DC-26.5GHz	Currently supported	
8498AR	Coaxial fixed attenuator, 30 dB	Currently supported	
8501A	Storage Normalizer	No longer supported	
8502A	TRANS/REF TEST S	No longer supported	
8502B	TRANS/REF TEST S	No longer supported	
8503A	S-PARM TEST SET	No longer supported	
8503B	S-PARM TEST SET	No longer supported	
8504A	Lightwave precision reflectometer	No longer supported	no replacement
8504AR	Lightwave precision reflectometer	No longer supported	
8504B-001	Fiber Optic Ref. Cable Kit for 8504B	No longer supported	no replacement
8505A	NETWORK ANALYZER	No longer supported	E8362B
8505AR	Remarketed Network Analyzer	No longer supported	no replacement
8507A	AUTO NETWORK ANA	No longer supported	E8362B
8507B	AUTO NETWORK ANA	No longer supported	E8362B
8507C	AUTO NETWORK ANA	No longer supported	E8362B
8507D	NETWORK ANALYZER SUBSYSTEM	No longer supported	E8362B
8507S	AUTO NETWORK ANA	No longer supported	E8362B
8509A	Lightwave Polarization Analyzer	No longer supported	no replacement
8509B-K66	Upgrade kit	No longer supported	no replacement
8509B-K97	Programmable polarizer	No longer supported	no replacement
8509B-K99	Programmable polarizer	No longer supported	no replacement
8509C-018	LW Polarization Analyzer Controller	No longer supported	no replacement
8509C-019	LW Polarization Analyzer Upgrade 8509B	No longer supported	no replacement
8509C-020	LW Polarization Analyzer Upgrade 8509B	No longer supported	no replacement
8510A	Network Analyzer	No longer supported	E8362B
8510B	Vector Network Analyzer	No longer supported	E8362B
8510BR	Remarketed vector network analyzer	No longer supported	E8362B
8510S	System reference for 8510 systems	No longer supported	E8362B
8510T	Network Analyzer System	No longer supported	E8362B
8511AR	Remarketed Frequency Converter	No longer supported	no replacement
8512A	Reflection/transmission test set	No longer supported	E8362B
8513A	Reflection transmission test set	No longer supported	E8362B
8514A	S-parameter test set	No longer supported	E8362B
8516A	S-Parameter Test Set	No longer supported	E8363B
8517A	S-Parameter Test Set	Currently supported	E8362B

Product	Description	Support Status	Replacement Information
8517AR	S-Parameter Test Set	Currently supported	
8530S	System reference for 8530 systems	No longer supported	E8362B
8551B	SPECTRUM ANALYZER	No longer supported	
8552A	IF SECTION	No longer supported	8552B
8552B	IF SECTION	No longer supported	
8553B	110MHZ RF SECT.	No longer supported	
8553B/E03	SPECT ANALYZER	No longer supported	
8553B/E30	SPECT ANALYZER	No longer supported	
8554B	1250MHZ RF SECT	No longer supported	8590A
8554B/E29	SPECT ANALYZER	No longer supported	
8554B/E30	SPECT ANALYZER	No longer supported	
8554L	SPECTRUM ANALY R	No longer supported	
8555A	18GHZ MW SECTION	No longer supported	8562A
8555A/E29	SPECT ANALYZER	No longer supported	
8555A/E30	SPECT ANALYZER	No longer supported	
8555A/E31	SPECT ANALYZER	No longer supported	
8555A/E32	SPECT ANALYZER	No longer supported	
8556A	300KHZ LF SECT.	No longer supported	3585A
8556A/E29	SPECT ANALYZER	No longer supported	
8557A	350MHZ SPEC AN	No longer supported	
8558B	1500MHZ SPEC AN	No longer supported	8590A
8559A	21 GHZ SPEC AN	No longer supported	8592A
8559A/E30	SPECT ANALYZER	No longer supported	
8559A/E31	SPECT ANALYZER	No longer supported	
8559A/E32	SPECT ANALYZER	No longer supported	
8559A/E33	SPECTRUM ANALYZR	No longer supported	
8559A/E34	SPECTRUM ANALYZR	No longer supported	
8559A/E35	SPECT ANALYZER	No longer supported	
8559A/E36	SPECT ANALYZER	No longer supported	
8560A	RF Spectrum Analyzer	No longer supported	8560E
8560EL	RF Spectrum analyzer, 30 Hz to 2.9 GHz	Currently supported	
8561A	6.5 GHz RF Spectrum Analyzer	No longer supported	8561B.
8561B	RF Spectrum Analyzer	No longer supported	8561E
8562A	9 kHz 22 GHz spectrum analyzer	No longer supported	8563A
8562AR	Rmkt 9 kHz 22 GHz spectrum analyzer	No longer supported	
8562B	9kHz 22GHz SPECTRUM ANALYZER.	No longer supported	8563E
8562EL	RF Spectrum analyzer, 30 Hz to 13.2 GHz	Currently supported	
8563A	9 kHz 26.5 GHz spectrum analyzer	No longer supported	8563EC
8565A	22 GHZ SPEC AN	No longer supported	8569A
8566AB	85660A to 85660B retrofit kit	No longer supported	85660-60392.
8566S	AUTO RF SA	No longer supported	
8567S	AUTOMATIC SPECTRUM ANALYZER	No longer supported	
8568A	SPECTRUM ANALYZR	No longer supported	
8568AB	Kit to retrofit 85680A into an 85680B	No longer supported	no replacement
8568S	AUTO RF SA	No longer supported	
8569A	22GHZ SPEC AN	No longer supported	
8569B	MICROWAVE SA	No longer supported	
8570A	SPECTRUM ANALYZER	No longer supported	
8572A	Microwave EMI receiver with 85650A	No longer supported	
8572S	Custom EMI receiver system	Currently supported	no replacement
8573A	SPECTRUM ANALYZER/CISPR EMI RECEIVER	No longer supported	8573B
8573B	EMI receiver w/ 8567A spec. analyzer	No longer supported	8546A or 8542E
8574A	CISPR SA/EMI RECEIVER	No longer supported	8574B
8574B	EMI receiver w/ 8568B spec. analyzer	No longer supported	no replacement
8581A	AUTO SPEC ANALYZ	No longer supported	
8581B	AUTO RF SPEC ANL	No longer supported	8568S
8582A	AUTO SPEC ANL	No longer supported	
8582B	AUTO SPEC ANL	No longer supported	8566S
8587S	SIGNAL MONITORING SYSTEM	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
8590A	10 KHZ 1.5 GHZ SPECTRUM ANALYZER	No longer supported	8590B
8590B	9kHz-1.8GHz Spectrum Analyzer	No longer supported	8590D
8590BR	Rmkt 9 kHz-1.8 GHz spectrum analyzer	No longer supported	
8590D	9kHz-1.8GHz RF Spectrum Analyzer	No longer supported	"L"version
8591A	9kHz-1.8GHz RF Spectrum Analyzer	No longer supported	8591E
8592A	50kHz 22GHz Portable Spectrum Analyzer	No longer supported	8592B
8592B	9kHz-22GHz MW Spectrum Analyzer	No longer supported	8592D
8592D	9kHz-22GHz MW Spectrum Analyzer	No longer supported	"L"version
8593A	9kHz-22GHz MW Spectrum Analyzer.	No longer supported	8593E
8594A	9 kHz-2.9 GHz RF SPECTRUM ANALYZER	No longer supported	8594E
8595A	9 kHz-6.5 GHz RF SPECTRUM ANALYZER	No longer supported	8595E
8600A	DIGITAL MARKER	No longer supported	no replacement
8601A	GENERATOR/SWEEPE	No longer supported	no replacement
8605A	SWEEP OSCILLATOR	No longer supported	
8614A	Signal Generator	No longer supported	http://www.agilent.com/find/esg
8614B	SIGNAL SOURCE	No longer supported	http://www.agilent.com/find/signal_sources
8616A	Signal Generator	No longer supported	http://www.agilent.com/find/esg
8616B	SIGNAL SOURCE	No longer supported	http://www.agilent.com/find/signal_sources
8620A	SWEEP OSCILLATOR	No longer supported	
8620B	SWEEP OSCILLATOR	No longer supported	
8620C	Sweeper Mainframe	No longer supported	
8621A	RF DRAWER	No longer supported	
8621B	RF DRAWER	No longer supported	
8625A	300 kHz 3 GHz Synthesized RF Sweeper	No longer supported	http://www.agilent.com/find/psg
8640A	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
8640B	Signal generator, -0.5 to 512 MHz	No longer supported	http://www.agilent.com/find/psg
8640M	RUGGED SIG GEN	No longer supported	
8642M	Synthesized signal generator, up to 2GHz	No longer supported	http://www.agilent.com/find/esg
8642MR	Synthesized signal generator, up to 2GHz	No longer supported	
8644A	Synthesized Signal Generator 0.25-1030 M	No longer supported	http://www.agilent.com/find/esg
8654A	Signal Generator : -10 to 520 MHz	No longer supported	http://www.agilent.com/find/signal_sources
8654B	Signal Generator : 10 to 520 MHz	No longer supported	http://www.agilent.com/find/signal_sources
8655A	SYNCH COUNTER	No longer supported	no replacement
8656A	SIGNAL GENERATOR	No longer supported	http://www.agilent.com/find/signal_sources
8656AR	Signal generator	No longer supported	
8657DR	Pi/4 DQPSK signal generator	No longer supported	
8657JR	Pi/4 DQPSK signal generator for PH-Phone	No longer supported	
8660A	Synth. Signal Generator; thumbwheel ver.	No longer supported	http://www.agilent.com/find/signal_sources
8660B	SYNTH SIG GEN MF	No longer supported	http://www.agilent.com/find/signal_sources
8660C	Synthesized Signal Generator	No longer supported	http://www.agilent.com/find/signal_sources
8660D	Synthesized Signal Generator Mainframe	No longer supported	http://www.agilent.com/find/esg
8660DR	Remarketed Synthesized Signal Generator	No longer supported	no replacement
8671A	Microwave Synthesizer Generator	No longer supported	http://www.agilent.com/find/psg
8671B	Synthesized CW Generator	Currently supported	http://www.agilent.com/find/psg
8671BR	Synthesized CW generator	Currently supported	
8672A	Synthesized Signal Generator	Currently supported	http://www.agilent.com/find/psg
8672AR	Synthesized Signal Generator	Currently supported	
8672S	Synthesized Signal Generator	No longer supported	http://www.agilent.com/find/psg
8673A	SYNTH SIG GEN	No longer supported	http://www.agilent.com/find/psg
8673B	Signal Generator	Currently supported	http://www.agilent.com/find/psg
8673BR	Signal Generator	Currently supported	
8673C	Signal Generator	Currently supported	http://www.agilent.com/find/psg
8673CR	Signal Generator	Currently supported	
8673D	Signal Generator	Currently supported	http://www.agilent.com/find/psg
8673DR	Remarketed synthesized signal generator	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
8673E	Synthesized Signal Generator	Currently supported	http://www.agilent.com/find/psg
8673G	Synthesized CW Generator	Currently supported	http://www.agilent.com/find/psg
8673GR	Synthesized CW Generator	Currently supported	
8673H	SYNTHESIZED SIGNAL GENERATOR	Currently supported	http://www.agilent.com/find/psg
8674C	Switch, Coaxial, Signal Reversal, 5 Port	No longer supported	8764C
8683A	Signal Generator	No longer supported	http://www.agilent.com/find/psg
8683B	Signal Generator	No longer supported	http://www.agilent.com/find/psg
8683D	Signal Generator	No longer supported	http://www.agilent.com/find/psg
8684A	Signal Generator	No longer supported	http://www.agilent.com/find/psg
8684B	Signal Generator	No longer supported	http://www.agilent.com/find/psg
8684D	Microwave Signal Generator	No longer supported	http://www.agilent.com/find/psg
8690A	SWEEP OSCILLATOR	No longer supported	
8690B	SWEEP OSCILLATOR	No longer supported	
8691A	RF UNIT	No longer supported	
8691B	RF UNIT	No longer supported	
8692A	RF UNIT	No longer supported	
8692B	RF UNIT	No longer supported	
8693A	RF UNIT	No longer supported	
8693B	RF UNIT	No longer supported	
8694A	RF UNIT	No longer supported	
8694B	RF UNIT	No longer supported	
8695A	RF UNIT	No longer supported	
8695B	RF UNIT	No longer supported	
8696A	RF UNIT	No longer supported	
8697A	RF UNIT	No longer supported	
8698B	RF UNIT	No longer supported	
8699B	RF UNIT	No longer supported	
8700A	R F DRAWER	No longer supported	
8701A	SEQUENTIAL SWEEP	No longer supported	
8702A	Lightwave Component Analyzer	No longer supported	
8702B	Lightwave component analyzer	No longer supported	8702D
8703A-K05	Kit replaces 1300nm laser w/1550nm laser	No longer supported	
8703A-K10	Kit adds Option 100 to customer unit	No longer supported	
8703A-K15	Kit to install transmitter for 1550nm	No longer supported	
8705A	SIGNAL MULTIPLEX	No longer supported	8620C FAMILY
8706A	CONTROL UNIT	No longer supported	8620C FAMILY
8707A	RF UNIT HOLDER	No longer supported	8620C FAMILY
8708A	SYNCHRONIZER	No longer supported	no replacement
8709B	SYNCHRONIZER	No longer supported	
8711BR	Refurbished RF Scalar Network Analyzer	Currently supported	
8712BR	RF Vector Network Analyzer, 1.3 GHz	No longer supported	
8712EU	Upgrade kits for the 8712ET and 8712ES.	No longer supported	E5061A
8713BR	RF Scalar Network Analyzer, 3 GHz	No longer supported	
8714BR	RF Vector Network Analyzer, 3 GHz	No longer supported	
8714EU	Upgrade kits for the 8714ET and 8714ES.	No longer supported	E5061A
8717B	Transistor bias supply	No longer supported	
8719A	Network Analyzer, 130 MHz to 13.5 GHz	No longer supported	8719E
8719AR	Remarketed Network Analyzer 130MHz-13.5G	No longer supported	
8719CR	Rmkt Network analyzer, 50MHz to 13.5GHz	No longer supported	
8719DX	Network analyzer, 50 MHz to 13.5 GHz	No longer supported	8719ES
8720A	Microwave Network Analyzer, 130 20 GHz	No longer supported	8720ES
8720AR	Remarketed Microwave Network Analyzer	No longer supported	8720BR
8720B	Network Analyzer, 130 MHz to 20 GHz	No longer supported	8720ES
8720BR	Remarketed Network Analyzer, 130 MHz	No longer supported	
8720CR	Rmkt network analyzer, 50 MHz to 20 GHz	No longer supported	
8720DX	Network analyzer, 50 MHz to 20 GHz	No longer supported	8720ES
8721AR	Directional bridge for 8407A	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
8722A	Network Analyzer, 50 MHz to 40 GHz	No longer supported	8722ES
8722AR	Remarketed Network Analyzer 50 MHz-40GHz	No longer supported	8722C.
8722CR	Remarketed Network Analyzer, 50MHz-40GHz	No longer supported	
8722DX	Network analyzer, 50 MHz to 40 GHz	No longer supported	8722ES
8728B	NETWORK COMPARAT	No longer supported	E8362B
8730AR	Tuner analyzer	Currently supported	
8731A	PIN MODULATOR	No longer supported	no replacement
8731B	Pin Modulator	No longer supported	no replacement
8732A	PIN MODULATOR	No longer supported	no replacement
8732B	Pin Modulator	No longer supported	no replacement
8733A	PIN MODULATOR	No longer supported	no replacement
8733B	Pin Modulator	No longer supported	no replacement
8734A	PIN MODULATOR	No longer supported	no replacement
8734B	Pin Modulator	No longer supported	no replacement
8735A	PIN MODULATOR	No longer supported	no replacement
8735B	Pin Modulator	No longer supported	no replacement
8740A	TRANS TEST UNIT	No longer supported	8743A
8741A	REFL TEST UNIT	No longer supported	8745A
8742A	REFL TEST UNIT	No longer supported	8745A
8743A	TEST UNIT	No longer supported	
8743B	Reflection/transmission test set	No longer supported	
8745A	S-parameter test set	No longer supported	
8746B	S-parameter test set	No longer supported	
8748A	S-parameter test set	No longer supported	
8750A	Storage normalizer	No longer supported	
8751U	Upgrade kit for the 8751A	Currently supported	no replacement
8752A	RF network analyzer, 300 kHz to 1.3 GHz	No longer supported	E5061A
8752AR	Remarketed RF network analyzer	No longer supported	
8752B	75-ohm RF network analyzer	No longer supported	E5061A
8752BR	Remarketed 75-OHM RF Network Analyzer	No longer supported	8752C/075
8753A	Network Analyzer	No longer supported	8753ES
8753B	Network Analyzer	No longer supported	8753ES
8753CR	Remarketed network analyzer, 300kHz-3GHz	No longer supported	
8753MX	Mixer measurement system for 8753C	No longer supported	8753ES
8753S	Systems reference	No longer supported	8753ES
8754A	Network analyzer	No longer supported	E5061A
8755A	SWEPT AMPL ANALY	No longer supported	
8755B	SWEPT AMPL ANALY	No longer supported	8755C
8755C	SCALAR ANALYZER	No longer supported	8757D
8755L	FREQ RESP TEST S	No longer supported	8755S
8755M	FREQ RESP TEST S	No longer supported	8755S
8755P	AUTO SCALAR SYS	No longer supported	8757D
8755S	SCALAR NETWORK ANALYZER SYSTEM	No longer supported	8757D
8756A	Scalar analyzer	No longer supported	8757D
8756S	Scalar network analyzer	No longer supported	8757D
8757A	Network analyzer	No longer supported	8757D
8757C	Scalar Network Analyzer	No longer supported	8757D
8757S	Automatic scalar network analyzer system	No longer supported	8757D
8757X	Scalar Network Analyzer System	No longer supported	8757D
8757XA	20 GHz Coaxial Scalar System	No longer supported	8757D
8757XB	40 GHz Coaxial Scalar System	No longer supported	8757D
8757XL	Scalar Network Analyzer System	No longer supported	8757D
8761BR	Coaxial SPDT switch, DC-18 GHz, 24-30V	Currently supported	

Product	Description	Support Status	Replacement Information
8762BR	Coaxial SPDT switch, DC-18 GHz; 50 ohm	Currently supported	
8770A	Arbitrary waveform synthesizer, dc-50MHz	Currently supported	http://www.agilent.com/find/psg
8770AR	Rmkted arbitrary waveform synthesizer	Currently supported	
8770S	DC-50MHz Signal Simulator System	No longer supported	http://www.agilent.com/find/psg
8780AR	Vector Signal Generator	No longer supported	
8782A	Vector Signal Generator	No longer supported	http://www.agilent.com/find/esg
8782BR	Vector Signal Generator	No longer supported	
8900B	PK PWR MTR	No longer supported	no replacement
8902AT	18 GHz Attenuator Calibration System	No longer supported	no replacement
8902MS	Measurement System	No longer supported	no replacement
8902SG	Signal Generator Test System RF	No longer supported	no replacement
8903A	AUDIO ANALYZER	No longer supported	no replacement
8903AR	Audio Analyzer	No longer supported	8903B
8905A	WAVEMETER	No longer supported	no replacement
8921D	Dual mode cell site test system	No longer supported	E7495B
8921DR	Dual mode cell site test system	No longer supported	8921A, #500
8922B	GSM BS Test Set, 10-1000 MHz	No longer supported	E7495B
8922E	GSM Mobile Station Service Test Set	No longer supported	E5515C
8922ER	GSM Mobile Station Service Test Set	No longer supported	
8922F	GSM MS Service test set	No longer supported	E5515C
8922FR	GSM MS Service test set	Currently supported	
8922G	GSM mobile station test set, stand-alone	No longer supported	E5515C
8922GR	GSM mobile staqtion test set,stand-alone	No longer supported	
8922HR	GSM MS standalone test set	Currently supported	
8922R	GSM MS Multiband Test System	Currently supported	E5515C
8922U	8922 Retrofit Kits	Currently supported	no replacement
8922X	GSM MS Multiband Test System	Currently supported	E5515C
8922Y	GSM MS Multiband Test System	Currently supported	E5515C
8923A	DECT Test Set	No longer supported	no replacement
8923AR	DECT Test Set	No longer supported	
8923U	8923 Upgrade Kits	Currently supported	no replacement
8925A	DME/ATC TEST SET	No longer supported	
8950A	TRANSCEIVER	No longer supported	no replacement
8950B	TRANSCEIVER	No longer supported	no replacement
8952A	Signal Generator Test Set	No longer supported	no replacement
8953A	Transceiver Test Set	No longer supported	E5515C
8953CT	Cellular Radio Test System	No longer supported	E5515C
8953DT	NADC NO AMER DUALMODE CELLULAR TEST SYS	No longer supported	no replacement
8953ST	Single-Sideband Radio Test System	No longer supported	no replacement
8953XT	Transceiver Test System	No longer supported	E5515C
8954A	Transceiver Test System Interface	No longer supported	no replacement
8955A	RF Test System	No longer supported	E5515C
8956A	RF Test System Interface	No longer supported	no replacement
8957S	Cellular Radio Test System	No longer supported	E5515C
8958A	Cellular Radio Interface	No longer supported	no replacement
8958AR	Cellular Radio Interface	No longer supported	
8970A	Noise Figure Meter	No longer supported	8970B
8970T	10MHz 18GHz Noise Fig. Measure. System	No longer supported	8970B
8970U	Noise Figure Measurement System	No longer supported	N8975A
8971B	Noise Figure Test Set	No longer supported	8971C
8981B	Vector Modulation Analyzer	No longer supported	no replacement
8981BR	Vector modulation analyzer	No longer supported	
9111T	GRAPHICS TABLET	No longer supported	no replacement
9231C	AUTOMATIC TESTER	No longer supported	
9423R	DTE Runtime/Analyzer for ATS 2000.	No longer supported	
9424R	DTE File Configurator for ATS 2000.	No longer supported	
9425R	DTE File Reporter for ATS 2000.	No longer supported	

Product	Description	Support Status	Replacement Information
9426R	Digital Device Subroutines for ATS 2000.	No longer supported	
9600A	BASIC CONTROL SY	No longer supported	No replacement
9600C	OBSITEM	No longer supported	No replacement
9600E	REAL TIME EXEC	No longer supported	No replacement
9601A	DATA ACQUIS CON	No longer supported	No replacement
9601B	RTB DAC SYSTEM	No longer supported	No replacement
9601C	RTB DAC SYSTEM	No longer supported	No replacement
9601E	RT DATA ACQU CON	No longer supported	No replacement
9602A	BASE SYSTEM	No longer supported	No replacement
9603A	BASE SYSTEM	No longer supported	No replacement
9604A	BASE SYSTEM	No longer supported	No replacement
9610A	MEAS AND CONTROL	No longer supported	No replacement
9610B	MEAS AND CONTROL	No longer supported	No replacement
9610C	MEAS AND CONTROL	No longer supported	No replacement
9610E	MEAS AND CONTROL	No longer supported	No replacement
9611A	BASE SYSTEM	No longer supported	No replacement
9630A	GM30 Electrical Test System Ref List	No longer supported	
9632A	General Motors 30 IP Tester Test Site 2	No longer supported	
9633A	General Motors 30 EH Tester Test Site 3	No longer supported	
9635A	General Motors CS Tester Test Site 5	No longer supported	
9637A	General Motors Operator Interface Unit	No longer supported	
9639A	General Motors PR Tester Test Site 9	No longer supported	
9651A	Digital Test Executive File Generator.	No longer supported	
9652A	Digital Test Executive File Generator.	No longer supported	
9662A	GM Low Cost Operator I/F Unit	No longer supported	
9666A	OIU	No longer supported	
9666K	Enc Kit-9666A. Not orderable.	No longer supported	
9671A	File Generator -Hits for ATS 2000.	No longer supported	
9671R	File Generator hits for ATS 2000.	No longer supported	
9672R	File Generator-TESTAID for ATS 2000.	No longer supported	
9673R	File Generator for DTE in ATS 2000	No longer supported	
9700A	DIST SYS CENTRAL	No longer supported	No replacement
9807A	Integral Personal Computer U.S.	No longer supported	no replacement
9807AB	Integral Personal Computer -Euro/English	No longer supported	no replacement
9807AD	Integral Personal Computer German	No longer supported	no replacement
9807AE	Integral Personal Computer Spanish	No longer supported	no replacement
9807AF	Integral Personal Computer French	No longer supported	no replacement
9807AJ	Integral Personal Computer Japanese	No longer supported	no replacement
9807AK	Integral Personal Computer ICON	No longer supported	no replacement
9807AN	Integral Personal Computer Norwegian	No longer supported	no replacement
9807AP	Integral Personal Computer-Swiss/German	No longer supported	no replacement
9807AQ	Integral Personal Computer-Swiss/French	No longer supported	no replacement
9807AS	Integral Personal Computer Swedish	No longer supported	no replacement
9807AU	Integral Personal Computer U.K.	No longer supported	no replacement
9807AW	Integral Personal Computer Belgium	No longer supported	no replacement
9807AX	Integral Personal Computer Finnish	No longer supported	no replacement
9807AY	Integral Personal Computer Danish	No longer supported	no replacement
9807AZ	Integral Personal Computer Italian	No longer supported	no replacement
00510B	ATTENUATOR	No longer supported	
00515A	COAX ADAPTER	No longer supported	http://http://www.agilent.com/find/tmaccessor
00600A	ACCESSORY KIT	No longer supported	no replacement
00601A	COMPONENT HOLDER	No longer supported	
10001A	10:1 VOLTAGE DIVIDER PROBE; 1.5m	No longer supported	
10001B	DIVIDER PROBE	No longer supported	
10002A	50:1 voltage divider probe; 1.5m	No longer supported	
10002B	DIVIDER PROBE	No longer supported	
10003A	10:1 voltage divider probe; 1.2m	No longer supported	
10004B	DIVIDER PROBE	No longer supported	
10004C	DIVIDER PROBE	No longer supported	
10004D	10:1 voltage divider probe; 1.1m	No longer supported	

Product	Description	Support Status	Replacement Information
10005B	DIVIDER PROBE	No longer supported	
10005D	10:1 voltage divider probe; 3.0 m	No longer supported	
10006B	DIVIDER PROBE	No longer supported	
10006C	DIVIDER PROBE	No longer supported	
10006D	10:1 voltage probe; 1.8 m	No longer supported	
10007B	1:1 VOLTAGE PROBE; 1.1m	No longer supported	
10008B	1:1 VOLTAGE PROBE; 1.8 m	No longer supported	
10010C	BNC TIP	No longer supported	
10011B	PROBE TIP TO BNC ADAPTER	No longer supported	
10012B	DIVIDER PROBE	No longer supported	
10013A	10:1 VOLTAGE DIVIDER PROBE; 1.8 m	No longer supported	
10014A	10:1 VOLTAGE DIVIDER PROBE; 1.1 m	No longer supported	
10015A	DIVIDER PROBE	No longer supported	
10016A	DIVIDER PROBE	No longer supported	no replacement
10016B	10:1 VOLTAGE DIVIDER PROBE; 1.8 m	No longer supported	
10017A	10:1 voltage divider mini-probe; 1m	No longer supported	
10018A	10:1 VOLTAGE DIVIDER MINI-PROBE; 2m	No longer supported	
10019A	BNC TO SQUARE PIN CABLE ASSEMBLY	No longer supported	
10021A	1:1 VOLTAGE MINI-PROBE; 1 m	No longer supported	
10022A	1:1 VOLTAGE MINI-PROBE; 2 m	No longer supported	
10023A	TEMPERATURE PROBE; 1m/V/C OUTPUT	No longer supported	
10026A	MINIATURE 50 OHM 1:1 VOLTAGE PROBE; 1 m	No longer supported	
10027A	MINIATURE 50 OHM 1:1 VOLTAGE PROBE; 2 m	No longer supported	
10028A	JUMPER CABLE	No longer supported	
10029A	RETROFIT KIT	No longer supported	
10030A	10:1 DIVIDER	No longer supported	
10032A	100:1 PROBE	No longer supported	
10033A	10:1 Probe	No longer supported	
10034A	GROUND LEAD KIT	No longer supported	
10035A	PROBE TIP KIT	No longer supported	
10036A	PROBE TIP KIT	No longer supported	
10036B	PROBE TIP KIT	No longer supported	
10037A	PROBE TIPS	No longer supported	
10037B	PROBE TIP KIT	No longer supported	
10040A	10:1 VOLTAGE DIVIDER MINI-PROBE; 1 m	No longer supported	
10041A	10:1 VOLTAGE DIVIDER MINI-PROBE; 2 m	No longer supported	
10042A	10:1 voltage divider mini-probe; 3 m	No longer supported	
10050A	GP-IB ADAPTER	No longer supported	
10051A	GP-IB TEST PROBE	No longer supported	
10058A	CARRY CASE/1602A	No longer supported	
10059A	GP-IB FIELD KIT	No longer supported	
10060A	APPL. PROGRAM	No longer supported	
10062A	FRONT PANEL COVER FOR 163X AND 54XX.	No longer supported	
10066A	GP-IB PROBE	No longer supported	
10069A	GP-IB FIELD KIT	No longer supported	
10079A	Oscilloscope trace recording camera	No longer supported	no replacement
10080A	10:1 VOLTAGE DIVIDER MINI-PROBE; 1 m	No longer supported	
10081A	10:1 VOLTAGE DIVIDER MINI-PROBE; 2 m	No longer supported	
10082A	10:1 VOLTAGE DIVIDER MINI-PROBE; 3 m	No longer supported	
10083A	1:1 VOLTAGE MINI-PROBE; 1 m	No longer supported	

Product	Description	Support Status	Replacement Information
10084A	1:1 VOLTAGE MINI-PROBE; 2 m	No longer supported	
10087A	HP 54710A TO HP 54720A UPGRADE SERVICE	No longer supported	
10087B	UPGRADE SERVICE FOR THE HP 54720A	No longer supported	
10087C	UPGRADE KIT	No longer supported	
10087D	UPGRADE SERVICE FOR HP 54710D	No longer supported	
10087E	UPGRADE SERVICE FOR THE 54710A	No longer supported	
10088A	50GHz UPGRADE KIT	No longer supported	
10099A	2.5GHz TRIGGER UPGRADE KIT	No longer supported	no replacement
10100B	FEEDTHROUGH TERM	No longer supported	
10101B	STORAGE COVER	No longer supported	no replacement
10105A	CART ADAPTER	No longer supported	no replacement
10106A	CAMERA ADAPTER	No longer supported	no replacement
10108A	COVER	No longer supported	no replacement
10108B	COVER	No longer supported	no replacement
10110A	ADAPTER	No longer supported	
10111A	ADAPTER; BANANA PLUG TO BNC FEMALE	No longer supported	no replacement
10113A	ADAPTER	No longer supported	no replacement
10119A	RACKMOUNT KIT	No longer supported	no replacement
10121A	CABLE ASSEMBLY	No longer supported	no replacement
10132A	CABLE ASSEMBLY	No longer supported	no replacement
10140A	VIEWING HOOD FOR 8 X 10 cm CRT'S	No longer supported	no replacement
10167A	COVER	No longer supported	no replacement
10169A	PANEL COVER	No longer supported	no replacement
10170A	COVER	No longer supported	no replacement
10172A	COVER	No longer supported	no replacement
10176A	VIEWING HOOD FOR 5-INCH RECTANGULAR CRT	No longer supported	no replacement
10181A	CONTRAST FILTER	No longer supported	no replacement
10182A	CONTRAST FILTER	No longer supported	no replacement
10183A	VIEWING HOOD	No longer supported	no replacement
10184A	BINARY TAPE	No longer supported	no replacement
10184B	BINARY TAPE	No longer supported	no replacement
10186A	SOFTCOPY GRAPHIC	No longer supported	no replacement
10190A	LIGHT SHIELD	No longer supported	no replacement
10211A	IC probe clip	No longer supported	
10214A	10 TO 1 DIVIDER	No longer supported	
10216A	PROBE ISOLATOR TIP	No longer supported	
10217A	BLOCKING CAPACIT	No longer supported	
10219A	GR ADAPTER	No longer supported	no replacement
10220A	MICRODOT ADAPTER	No longer supported	no replacement
10230A	CLOCK PROBE	No longer supported	no replacement
10230B	CLOCK PROBE	No longer supported	
10230C	CLOCK PROBE	No longer supported	
10231A	DATA PROBE	No longer supported	no replacement
10231B	DATA PROBE	No longer supported	
10231C	DATA PROBE	No longer supported	
10247A	CLOCK PROBE	No longer supported	
10248A	DATA PROBE	No longer supported	
10248B	8 BIT DATA PROBE	No longer supported	
10248C	8 BIT DATA PROBE	No longer supported	
10250A	TTL TRIGGER PROB	No longer supported	
10251A	MOS TRIGGER PROB	No longer supported	
10252A	ECL TRIGGER PROB	No longer supported	
10253A	CARD READER	No longer supported	
10254A	STP CONVERTER	No longer supported	
10257A	INTERFACE KIT	No longer supported	
10257B	FIELD KIT	No longer supported	
10258A	INTERFACE KIT	No longer supported	

Product	Description	Support Status	Replacement Information
10258B	FIELD KIT	No longer supported	
10259A	FIELD INSTALL	No longer supported	
10260A	FIELD KIT	No longer supported	
10261A	FIELD KIT	No longer supported	
10262A	FIELD KIT	No longer supported	
10263A	FIELD KIT	No longer supported	
10264A	GP INTERFACE KIT	No longer supported	
10266A	FIELD KIT	No longer supported	
10269A	PROBE INTERFACE	No longer supported	
10269B	GENERAL PURPOSE PROBE INTERFACE	No longer supported	
10269C	GENERAL PURPOSE PROBE INTERFACE	No longer supported	
10271A	STATE DATA PROBE	No longer supported	
10272A	STATE/TIMING DATA PROBE FOR 163X PRODUCT	No longer supported	
10273A	STATE DATA PROBE FOR THE 1630G	No longer supported	
10275A	PDP/11 INTERFACE FOR THE 1630/31 FAMILY	No longer supported	
10276A	LSI/11 INTERFACE FOR 1630/31 FAMILY	No longer supported	
10277A	GP PROBE INTERFA	No longer supported	
10277B	GP PROBE INTERFA	No longer supported	
10277C	GP PROBE INTERFA	No longer supported	
10277D	PROBE INTERFACE.	No longer supported	
10278A	1000 INTRFCE	No longer supported	
10279A	DG NOVA 3 ITRFAC	No longer supported	
10280A	DG M-NOVA ITRFAC	No longer supported	
10281A	GP-IB FIELD KIT	No longer supported	
10282A	FIELD KIT	No longer supported	
10283A	FIELD KIT	No longer supported	
10284A	FIELD KIT	No longer supported	
10285A	L SERIES INFC	No longer supported	
10286A	NRZI INTERFACE	No longer supported	
10287A	MIL-STD-188C	No longer supported	
10288A	FIELD KIT	No longer supported	
10289A	FIELD KIT	No longer supported	
10289B	MYLAR OVERLAY FIELD KIT FOR 1640B	No longer supported	
10290A	CODE ROM	No longer supported	
10290B	CODE ROM	No longer supported	
10291A	MENU PROM	No longer supported	
10291B	MENU PROM-1640B	No longer supported	
10292A	APPLICATION PROG	No longer supported	
10299A	RACK MOUNT KIT	No longer supported	
10300B	Z80 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10300C	Z80 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10301B	Z8001 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10301C	Z8001 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10302B	Z8002 INTERFACE MODULE	No longer supported	
10302C	Z8002 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10303B	NSC 800 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10303C	NSC800 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10304B	8085 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10304C	8085 MICROPROCESSOR INTERFACE MODULE	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
10305B	8086/8088 MICROPROCESSOR INTERFACE	No longer supported	
10305C	8086/8088 MICROPROCESSOR INTERFACE	No longer supported	
10306B	80186/88 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10306C	80186/88 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10306G	80186 PREPROCESSOR	No longer supported	
10307B	6800/6802 MICROPROCESSOR INTERFACE	No longer supported	
10307C	6800/02 MICROPROCESSOR INTERFACE	No longer supported	
10308B	6809/6809E MICROPROCESSOR INTERFACE	No longer supported	
10308C	6809/6809E MICROPROCESSOR INTERFACE	No longer supported	
10309B	68000 INTERFACE	No longer supported	
10310B	68008 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10310C	68008 MICROPROCESSOR INTERFACE	No longer supported	
10311B	68000/68010 MICROPROCESSOR INTERFACE	No longer supported	
10311C	68000/68010 MICROPROCESSOR INTERFACE	No longer supported	
10311G	68000/10 PREPROCESSOR AND SFTWARE	No longer supported	
10312B	80286 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10312C	80286 MICROPROCESSOR INTERFACE MODULE	No longer supported	
10312D	80286 INTERFACE MODULE	No longer supported	
10313G	68020 PREPROCESSOR AND SOFTWARE	No longer supported	
10314B	80386 PREPROCESSOR AND SOFTWARE	No longer supported	
10314D	PREPROCESSOR FOR INTEL 80386	No longer supported	
10316G	68030 PREPROCESSOR	No longer supported	
10317G	UNIVERSAL INTERFACE FOR MOTOROLA 68040	No longer supported	
10320A	GENERAL PURPOSE WIRE WRAP INTERFACE	No longer supported	
10320C	USER DEFINABLE INTERFACE	No longer supported	
10321A	MICROPROCESSOR INTERFACE KIT	No longer supported	
10322A	40 PIN CABLE WITH 40 PIN DIP SOCKET	No longer supported	
10323A	48 PIN CABLE WITH 48 PIN DIP SOCKET	No longer supported	
10324A	64 PIN CABLE WITH 64 PIN DIP SOCKET	No longer supported	
10325B	MCS 51 PREPROCESSOR	No longer supported	
10326A	TIME STANDARD	No longer supported	
10330A	1630A/D TO 1631A/D UPGRADE KIT	No longer supported	
10331A	1630A/D TO 1631A/D UPGRADE KIT	No longer supported	
10335G	6301/03 INTERFACE	No longer supported	
10336G	64180 DIP INTERFACE	No longer supported	
10336H	64180 PLCC INTERFACE	No longer supported	
10337B	NEC V20/30 INTERFACE	No longer supported	
10338B	NEC V40/50 INTERFACE	No longer supported	
10339G	NEC V60 INTERFACE	No longer supported	
10340A	1630A/D TO 1630G UPGRADE KIT	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
10341B	1553 INTERFACE	No longer supported	
10342B	BUS PREPROCESSOR	No longer supported	
10342C	BUS PREPROCESSOR	No longer supported	
10342G	GP-IB PREPROCESSOR AND SOFTWARE	No longer supported	
10343B	SCSI BUS INTERFACE	No longer supported	
10344A	VME BUS PREPROCESSOR A-SIZE	No longer supported	
10344B	VME BUS INTERFACE	No longer supported	
10345A	8 CHANNEL ECL DIFFERENTIAL DRIVER POD	No longer supported	
10346A	8 CHANNEL TTL TRISTARE BUFFER POD	No longer supported	
10348A	CMOS TRISTATE POD	No longer supported	
10349B	SCOPE UPGRADE KIT FOR 1650B OR 1651B	No longer supported	
10353A	POLAROID BACK	No longer supported	no replacement
10355A	BEZEL ADAPTER	No longer supported	no replacement
10356A	BEZEL ADAPTER	No longer supported	no replacement
10357A	BEZEL ADAPTER	No longer supported	no replacement
10358B	CAMERA CARRYING CASE	No longer supported	no replacement
10360A	CAMERA ADAPTER	No longer supported	no replacement
10361A	CAMERA ADAPTER	No longer supported	no replacement
10362A	CAMERA ADAPTER	No longer supported	no replacement
10363A	CAMERA ADAPTER	No longer supported	no replacement
10365A	ROLL FILM BACK	No longer supported	no replacement
10366B	CAMERA ADAPTER	No longer supported	no replacement
10369A	CAMERA ADAPTER	No longer supported	no replacement
10370A	CAMERA ADAPTER	No longer supported	no replacement
10371A	CAMERA ADAPTER	No longer supported	no replacement
10372A	CAMERA ADAPTER	No longer supported	no replacement
10373A	CAMERA ADAPTER	No longer supported	no replacement
10374A	CARRYING CASE	No longer supported	no replacement
10377A	CAMERA ADAPTER	No longer supported	no replacement
10380A	OEM HORIZONTAL FRAME FOR 1332A,1335A	No longer supported	
10381A	RACK CONVERSION	No longer supported	no replacement
10382A	BENCH CONVERSION	No longer supported	no replacement
10383A	RACK ADAPTER	No longer supported	no replacement
10384A	RACK MOUNT KIT	No longer supported	no replacement
10385A	RACK MOUNT KIT	No longer supported	no replacement
10386A	/OEM CABINET	No longer supported	no replacement
10390A	SYSTEM PERFORMANCE ANALYSIS SOFTWARE	No longer supported	
10391A	INVERSE ASSEMBLER DEVELOPMENT PACKAGE	No longer supported	
10391B	INVERSE ASSEMBLER DEVELOPMENT PACKAGE	Currently supported	
10392A	STATE TO PATTERN LINK	No longer supported	
10392B	16550 STATE TO 16520/21 PATTERN LINK	No longer supported	
10400B	EXTENDER CABLE	No longer supported	no replacement
10443A	MINIATURE 50 OHM 20:1 VOLTAGE PROBE	No longer supported	
10448A	16510A 35MHz UPGRADE	No longer supported	
10449A	1650A/1651A UPGRADE KIT	No longer supported	
10457A	75 OHM ADAPTER	No longer supported	no replacement
10458A	ADAPTER	No longer supported	no replacement
10478A	BLANK PLUG-IN	No longer supported	no replacement
10479A	TILT TRAY	No longer supported	no replacement
10479B	TILT TRAY	No longer supported	no replacement
10481A	DUMMY PLUG-IN	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
10482A	DUMMY PLUG-IN	No longer supported	no replacement
10484A	PLUG-IN EXTENDER	No longer supported	
10486A	ACCESSORY PANEL	No longer supported	no replacement
10487A	COMPUTER INTERFA	No longer supported	no replacement
10488A	DISPLAY CABLE	No longer supported	no replacement
10489A	DISPLAY CABLE	No longer supported	no replacement
10490A	ADAPTER KIT	No longer supported	
10491A	RACK ADAPTER	No longer supported	no replacement
10491B	Rack Mounting Adapter	No longer supported	no replacement
10492A	INTERCONNECT CBL	No longer supported	no replacement
10493A	3-METER CABLE	No longer supported	no replacement
10494A	FLD RETROFIT KIT	No longer supported	
10495A	FLD RETROFIT KIT	No longer supported	
10496A	GP-IB RETRO KIT	No longer supported	
10499A	RETRO-FIT KIT	No longer supported	
10507A	CABLE ASSEMBLY	No longer supported	no replacement
10508A	DECADE EXTENDER	No longer supported	no replacement
10509A	LOOP ANTENNA	No longer supported	no replacement
10516A	HIGH VOLTAGE CAB	No longer supported	no replacement
10517A	CABLE ASSEMBLY	No longer supported	no replacement
10519A	CABLE ASSEMBLY	No longer supported	no replacement
10524A	CABLE	No longer supported	no replacement
10525E	ECL Logic Probe	No longer supported	no replacement
10525H	LOGIC PROBE	No longer supported	no replacement
10525T	LOGIC PROBE	No longer supported	no replacement
10526E	LOGIC PULSER	No longer supported	no replacement
10526T	LOGIC PULSER	No longer supported	no replacement
10528A	LOGIC CLIP	No longer supported	no replacement
10531A	OUTPUT FILTER KI	No longer supported	no replacement
10533A	RECORDER INTFACE	No longer supported	no replacement
10535A	20 LAB WORKBOOK	No longer supported	no replacement
10536A	ADAPTER	No longer supported	
10541A	Reference Boards	No longer supported	no replacement
10541A-K01	LOADED REF BDS	No longer supported	no replacement
10541B	Loaded Reference Boards	No longer supported	no replacement
10542A	REMOTE INTERFACE	No longer supported	no replacement
10543A	QUARTZ OSCILLATO	No longer supported	no replacement
10543B	QUARTZ OSCILLATO	No longer supported	no replacement
10544A	OSCILLATOR	No longer supported	no replacement
10544B	OSCILLATOR	No longer supported	no replacement
10547A	SUPPORT PACKAGE	No longer supported	no replacement
10550B	REFLECTOR & MT	No longer supported	Beam Directing and Reflecting Optics
10551A	BEAM BENDER	No longer supported	Beam Directing and Reflecting Optics
10552A	RESOLUTION EXT	No longer supported	no replacement
10555A	ERROR PLOTTING	No longer supported	no replacement
10556A	RETROREFLECTOR	No longer supported	Beam Directing and Reflecting Optics
10557A	TURNING MIRROR	No longer supported	Beam Directing and Reflecting Optics
10558A	BEAM BENDER	No longer supported	Beam Directing and Reflecting Optics
10560A	METER KIT	No longer supported	Electronics
10562A	SINGLEBEAM INFR	No longer supported	Optics
10563A	Material Temperature Sensor Assembly	No longer supported	10757D
10565B	REMOTE INTERFROM	No longer supported	Optics
10567AR	Dual Beam-Splitter	No longer supported	
10569A	QUADRATURE/PULSE	No longer supported	Electronics
10574A	RACK MOUNT KIT	No longer supported	no replacement
10576A	ACCESSORY KIT	No longer supported	Calibrator Cables and Accessories
10576B	Accessory Kit	No longer supported	Calibrator Cables and Accessories
10579A	STRGHTNESS ADAPT	No longer supported	Calibrator Optics
10580A	LASER TRIPOD	No longer supported	10753B
10581A	PLANEMIRROR CONV	No longer supported	Beam Directing and Reflecting Optics
10583A	FOOTSPACING KIT	No longer supported	Calibrator Cables and Accessories

Product	Description	Support Status as of 1 May	Replacement Information
10585A	Interface Metrology Program	No longer supported	no replacement
10586A	INTERFACE CABLE	No longer supported	Calibrator Cables and Accessories
10590A	Plug-in Adapter for 5345A	No longer supported	no replacement
10593A	INTERFACE KIT	No longer supported	no replacement
10593B	INTERFACE KIT	No longer supported	no replacement
10597A	BOARD KIT	No longer supported	no replacement
10603A	EXTENDER PLUG-IN	No longer supported	no replacement
10610A	INTERFACE KIT	No longer supported	no replacement
10625A	INTERFACE KIT	No longer supported	no replacement
10630A	DELAY LINE KIT	No longer supported	no replacement
10631A	HP-IB BUS CABLE	No longer supported	no replacement
10631B	HP-IB BUS CABLE	No longer supported	no replacement
10631C	HP-IB BUS CABLE	No longer supported	no replacement
10631D	HP-IB BUS CABLE	No longer supported	no replacement
10633A	SFTWUPDATE 5451C	No longer supported	no replacement
10634A	STORAGE CASE	No longer supported	Calibrator Cables and Accessories
10635A	STORAGE CASE	No longer supported	Calibrator Cables and Accessories
10636A	DIAGNOSTIC KIT	No longer supported	no replacement
10637A	PROGRAM LIBRARY	No longer supported	no replacement
10638A	Degausser	No longer supported	no replacement
10640B	Plotter Cable	No longer supported	no replacement
10640C	PLOTTER CABLE	No longer supported	no replacement
10646A	SERVICE KIT	No longer supported	no replacement
10649A	BLANK FILLER PAN	No longer supported	no replacement
10649B	BLANK FILLER PAN	No longer supported	no replacement
10649C	BLANK FILLER PAN	No longer supported	no replacement
10651A	INTERFACE KIT	No longer supported	no replacement
10653A	RETROFIT KIT	No longer supported	no replacement
10653B	RETROFIT KIT	No longer supported	no replacement
10653C	RETROFIT KIT	No longer supported	no replacement
10656A	5035T Textbooks	No longer supported	no replacement
10657A	Wire and Component Kit	No longer supported	no replacement
10660A	POINT PLOTTING	No longer supported	no replacement
10667A	INTERFACE KIT	No longer supported	no replacement
10671A	CONVERSION KIT	No longer supported	no replacement
10672A	CONVERSION KIT	No longer supported	no replacement
10675A	POWER SUPPLY	No longer supported	no replacement
10686A	CONVERSION KIT	No longer supported	no replacement
10690A	SR STRGHTNES INF	No longer supported	10774A
10691A	LR STRGHTNES INF	No longer supported	10775A
10692A	PENTAPRISM	No longer supported	Calibrator Optics
10692B	OPTICAL SQUARE	No longer supported	10777A
10693A	VER STRNESS ADAP	No longer supported	Calibrator Optics
10697A	FIELD ADD-ON	No longer supported	no replacement
10697B	FIELD ADD-ON	No longer supported	no replacement
10697C	FIELD ADD-ON	No longer supported	no replacement
10698A	UPGRADE KIT	No longer supported	no replacement
10706AR	Plane Mirror Interferometer	No longer supported	
10706BR	High-Stability Plane Mirror	Currently supported	
10708A	POWER SUPPLY ACC	No longer supported	no replacement
10708B	POWER SUPPLY ACC	No longer supported	no replacement
10712A	INTERFACE CABLE	No longer supported	no replacement
10713A	Retroreflector	No longer supported	Beam Directing and Reflecting Optics
10714A	DISPL INTERFACE	No longer supported	no replacement
10727A	INTERFACE CABLE	No longer supported	no replacement
10729A	COMPARATOR	No longer supported	no replacement
10741A	LSR TRNS INTERFA	No longer supported	Calibrator Optics
10742A	COUNTER	No longer supported	Electronics
10744AR	Fixturing Kit	Currently supported	
10745A	GPIB Interface	No longer supported	no replacement
10747A	Calibrator Software	No longer supported	contact Agilent

Product	Description	Support Status	Replacement Information
10747C	Metrology Application Software (32bit)	No longer supported	10747B
10747E	Metrology Application Software (16bit)	No longer supported	10747D
10751AR	Air Sensor	Currently supported	
10751BR	Air Sensor	Currently supported	
10751CR	Air sensor	Currently supported	
10751DR	Air sensor	Currently supported	
10752A	MAT TEMP SENSOR	No longer supported	10757D
10752B	MAT TEMP SENSOR	No longer supported	10757E
10752C	MAT TEMP SENSOR	No longer supported	10757F
10753A	Replaced by 10753B.	No longer supported	10753B
10753BR	Tripod	Currently supported	
10754A	Dimensional Metrology Analysis Software	No longer supported	5529A
10755A	COMPENSATION INT	No longer supported	Electronics
10755B	Compensation Interface	Currently supported	no replacement
10756A	Manual Compensator	No longer supported	no replacement
10758A	Accessory Kit	No longer supported	Calibrator Cables and Accessories
10758B	Metrology Software	No longer supported	10754A
10761A	Multiplier Card	Currently supported	Electronics in http://http://www.agilent.com/fir
10763A	English/Metric Pulse Output Card	Currently supported	Electronics in http://http://www.agilent.com/fir
10764A	PULSE CONVERTER	No longer supported	Electronics
10764B	FAST PULSE CONV	No longer supported	Electronics
10768AR	Diagonal Measurement Kit	Currently supported	
10771AR	Angular Reflector	Currently supported	
10774AR	Short Range Straightness Optics	Currently supported	
10777AR	Optical square	Currently supported	
10778A	Laser Power Cable	No longer supported	no replacement
10778B	Laser Power Cable	Currently supported	no replacement
10778C	Laser Power Cable	Currently supported	no replacement
10779A	Reference Cable	No longer supported	no replacement
10779B	Reference Cable	Currently supported	no replacement
10779C	Reference Cable	Currently supported	no replacement
10780A	Receiver Accessory	No longer supported	10780C
10780B	Receiver Accessory To 5051A/5527A System	No longer supported	10780C
10781A	Pulse Converter	No longer supported	no replacement
10782A	SERVICE KIT	No longer supported	no replacement
10783A	Numeric Display	No longer supported	no replacement
10811A	OSCILLATOR	No longer supported	no replacement
10811B	OSCILLATOR	No longer supported	no replacement
10821A	5363A Probe Tips	No longer supported	no replacement
10822A	5001 CARRY POUCH	No longer supported	no replacement
10830A	CONDITIONER/MIX	No longer supported	no replacement
10831A	TONE GENERATOR	No longer supported	no replacement
10842A	Extender Kit	No longer supported	no replacement
10844A	RETROFIT KIT	No longer supported	no replacement
10844B	PROGRAMMING KIT FOR 5046S IC TESTER	No longer supported	no replacement
10844C	5045A UPGRADE TO 5046S COMPATIBILITY	No longer supported	no replacement
10845A	IC Test Program for 5045A IC Tester	No longer supported	no replacement
10846A	Coupon Book for 10845A Programs.	No longer supported	no replacement
10847A	SERVICE KIT FOR 5045A IC TESTER	No longer supported	no replacement
10851A	Rack Mount Kit	No longer supported	no replacement
10852A	Rack Mount Kit	No longer supported	no replacement
10853A	Rack Mount Kit	No longer supported	no replacement
10854A	Rack Mount Kit	No longer supported	no replacement
10855A	1.3 GHz Pre-Amplifier	No longer supported	no replacement
10855AR	1.3 GHz Pre-amplifier.	Currently supported	
10856A	Low Pass Filters	No longer supported	no replacement
10859A	CABLE	No longer supported	no replacement
10871A	Service Kit for 5180A	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
10871B	Service Kit for 5180A and 5182A	No longer supported	no replacement
10872A	Parallel Interface	No longer supported	no replacement
10873A	Rack Mount Kit	No longer supported	no replacement
10874A	Slide Mount Kit	No longer supported	no replacement
10875A	4.8 metre DMA Cable	No longer supported	no replacement
10875B	1.0 metre DMA Cable	No longer supported	no replacement
10887A	PC Calibrator Board	No longer supported	10887B
10889A	PC Servo-Axis Board	No longer supported	10889B
10896A	Laser Compensation Board for VMEbus	No longer supported	10896B
10897A	High-Resolution Laser Axis Board for VME	No longer supported	10897B
10920A	HP-IB INTERFACE	No longer supported	no replacement
10921A	CONTROL UNIT	No longer supported	no replacement
10927A	5427A ADD-ON NO.	No longer supported	no replacement
10932A	Axis Board for Field Installations	No longer supported	10932B
10936A	Servo-Axis Board	No longer supported	10889B
10941A	Prototyping Kit for Customer Circuits	Currently supported	no replacement
10946A	Auto Compensation Brd for Field Install	No longer supported	10886A
10946B	Automatic Compensation Board	No longer supported	10946C
10960A	FIELD ADD-ON	No longer supported	no replacement
10990B	SERVICE KIT	No longer supported	no replacement
11002A	TEST LEADS	No longer supported	no replacement
11003A	TEST LEADS	No longer supported	no replacement
11004A	TRANSFORMER	No longer supported	no replacement
11005A	TRANSFORMER	No longer supported	no replacement
11009A	CABLE PLUG	No longer supported	no replacement
11018A	ADAPTER	No longer supported	no replacement
11021A	DIVIDER	No longer supported	no replacement
11022A	PROBE TIP	No longer supported	
11023A	PROBE TIP	No longer supported	
11024A	PROBE TIP	No longer supported	
11025A	PROBE TIP	No longer supported	
11026A	PROBE TIP	No longer supported	
11027A	PROBE KIT	No longer supported	
11033A	SHUNT RESISTOR	No longer supported	no replacement
11036A	AC PROBE	No longer supported	no replacement
11039A	VOLTAGE DIVIDER	No longer supported	no replacement
11040A	VOLTAGE DIVIDER	No longer supported	no replacement
11041A	VOLTAGE DIVIDER	No longer supported	no replacement
11042A	PROBE	No longer supported	no replacement
11043A	PROBE	No longer supported	no replacement
11044A	DC DIVIDER	No longer supported	no replacement
11045A	DC DIVIDER	No longer supported	no replacement
11046A	CARRYING CASE	No longer supported	no replacement
11049A	CONVERTER	No longer supported	no replacement
11050A	CONVERTER	No longer supported	no replacement
11051A	THERMAL CONVERTE	No longer supported	no replacement
11056A	HANDLE KIT	No longer supported	no replacement
11057A	HANDLE KIT	No longer supported	no replacement
11061A	DIVIDER TIP	No longer supported	no replacement
11063A	TEE	No longer supported	no replacement
11064A	BASIC PROBE KIT	No longer supported	no replacement
11065A	CABLE ACCESSORY	No longer supported	no replacement
11067A	TEST LEAD KIT	No longer supported	34132B
11068A	CARRYING CASE	No longer supported	no replacement
11069A	CABLE	No longer supported	no replacement
11071A	ACCESSORY KIT	No longer supported	no replacement
11072A	PROBE TIP	No longer supported	no replacement
11073A	PROBE	No longer supported	no replacement
11074A	PROBE	No longer supported	no replacement
11075A	INSTRUMENT CASE	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
11076A	INSTRUMENT CASE	No longer supported	no replacement
11077A	OHMS CONVERTER	No longer supported	no replacement
11078A	AC CONVERTER	No longer supported	no replacement
11079A	LIMIT TEST PLUG-	No longer supported	no replacement
11080A	PRINTER OUTPUT P	No longer supported	no replacement
11085A	CABLE	No longer supported	no replacement
11096A	PROBE	No longer supported	no replacement
11096B	RF PROBE	No longer supported	no replacement
11097A	RF DETECTOR	No longer supported	no replacement
11098A	LEVELING DETECTO	No longer supported	no replacement
11099A	REMOTE CONT PLUG	No longer supported	no replacement
11112A	LIMIT SELECTOR	No longer supported	no replacement
11113A	INTERFACE KIT	No longer supported	no replacement
11114A	CONTROLLER KIT	No longer supported	no replacement
11114B	CONTROLLER KIT	No longer supported	no replacement
11114C	CONTROLLER KIT	No longer supported	no replacement
11117A	INTERFACE KIT	No longer supported	no replacement
11121A	BCD DIGITAL OUTP	No longer supported	no replacement
11122A	REMOTE CONTROL	No longer supported	no replacement
11126A	3490A IC COMPAR.	No longer supported	no replacement
11128A	3490A SERVICE TA	No longer supported	no replacement
11135A	AC POWER PACK	No longer supported	no replacement
11136A	MERCURY POWER PA	No longer supported	no replacement
11137A	BATTERY/AC POWER	No longer supported	no replacement
11138A	IMPEDANCE ADAPTE	No longer supported	no replacement
11144A	ASCII INTERFACE	No longer supported	no replacement
11145A	3042 INTERFACE K	No longer supported	no replacement
11146A	INTERFACE KIT	No longer supported	no replacement
11147A	DIGITAL OUTPUT	No longer supported	no replacement
11148A	EXTENDER CABLE	No longer supported	no replacement
11149A	REMOTE CONTROL	No longer supported	no replacement
11151A	REMOTE CONTROL	No longer supported	no replacement
11151B	ISOLATED REMOTE	No longer supported	no replacement
11152A	OHMS CONVERTER	No longer supported	no replacement
11153A	AC CONVERTER	No longer supported	no replacement
11166A	TEN CHANNEL BOAR	No longer supported	no replacement
11167A	INPUT CABLE	No longer supported	no replacement
11168A	REMOTE CONTROL	No longer supported	no replacement
11168B	REMOTE CONTROL	No longer supported	no replacement
11172A	RF INPUT CABLE	No longer supported	no replacement
11176A	3570A HP-IB KIT	No longer supported	no replacement
11177A	REFERENCE ACCSY	No longer supported	no replacement
11177B	REFERENCE ACCSY	No longer supported	no replacement
11180A	DATA STORAGE	No longer supported	no replacement
11181A	DATA STORAGE	No longer supported	no replacement
11184A	PRINTER CABLE	No longer supported	no replacement
11186A	SAMPLE AND HOLD	No longer supported	no replacement
11186B	SAMPLE AND HOLD	No longer supported	no replacement
11187A	ISOLATED OUTPUT	No longer supported	no replacement
11187C	ISOLATED OUTPUT	No longer supported	no replacement
11191A	AUTORANGE KIT	No longer supported	no replacement
11192A	BCD KIT FOR 3403	No longer supported	no replacement
11193A	BCD AUTORANGE KI	No longer supported	no replacement
11196A	MOBILE CART	No longer supported	1183A
11197A	INSTRUMENT CLAMP	No longer supported	no replacement
11235A	ADAPTOR	No longer supported	no replacement
11237A	XTAL OVEN	No longer supported	no replacement
11238A	BCD REMOTE	No longer supported	no replacement
11238B	BCD REMOTE	No longer supported	no replacement
11238C	BCD REMOTE KIT	No longer supported	no replacement
11239A	INTERFACE KIT	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
11239B	HP-IB REMOTE KIT	No longer supported	no replacement
11240A	FIELD INSTAL KIT	No longer supported	no replacement
11300A	FREQUENCY MARKER	No longer supported	no replacement
11340A	20 METRE HPIL	No longer supported	no replacement
11340B	50 METRE HPIL	No longer supported	no replacement
11340C	100 METRE HPIL	No longer supported	no replacement
11341A	CARRYING CASE	No longer supported	no replacement
11341B	CARRYING CASE	No longer supported	no replacement
11356A	BNC GROUND ISOL	No longer supported	
11401A	AUX. POWER CABLE	No longer supported	no replacement
11402C	THEODLITE MOUNTI	No longer supported	no replacement
11404A	LINE FINDER	No longer supported	no replacement
11405A	VERTICAL CIRCLE	No longer supported	no replacement
11409A	REFLECTOR ARRAY	No longer supported	no replacement
11410C	MIRROR RETRO-REF	No longer supported	no replacement
11410D	SINGLE PRISM ASS	No longer supported	no replacement
11410E	TILT SINGL PRISM	No longer supported	no replacement
11411D	TRIPLE PRISM ASS	No longer supported	no replacement
11411E	TILT TRIPL PRISM	No longer supported	no replacement
11412A	PRISM ADAPTER	No longer supported	no replacement
11412B	PRISM SWIVEL BAS	No longer supported	no replacement
11412C	PRISM ADAPTER	No longer supported	no replacement
11412E	PRISM SWIVEL BAS	No longer supported	no replacement
11415A	RANGE POLE	No longer supported	no replacement
11415B	LAYOUT RANGE POL	No longer supported	no replacement
11415C	LAYOUT RANGE POL	No longer supported	no replacement
11415D	LAYOUT RANGE POL	No longer supported	no replacement
11419A	FIELD BACKPACK	No longer supported	no replacement
11420B	POWER SUPPLY-CAS	No longer supported	no replacement
11420C	PRISM CASE	No longer supported	no replacement
11420D	CARRYING CASE	No longer supported	no replacement
11420E	TILT PRISM CASE	No longer supported	no replacement
11421A	BATTERY	No longer supported	no replacement
11422A	CHARGER	No longer supported	no replacement
11422B	CHARGER	No longer supported	no replacement
11422C	CHARGER	No longer supported	no replacement
11422D	CHARGER	No longer supported	no replacement
11423A	CHARGER	No longer supported	no replacement
11423B	DC CHARGER	No longer supported	no replacement
11424A	OPTICAL PLUMMET	No longer supported	no replacement
11425A	PRISM ADAPTER	No longer supported	no replacement
11426A	LEVELING BASE	No longer supported	no replacement
11428A	RT ANGLE EYEPC	No longer supported	no replacement
11429A	SOLAR FILTER	No longer supported	no replacement
11430A	TRIPOD KERN	No longer supported	no replacement
11430B	TRIPOD WILD	No longer supported	no replacement
11430C	TRIPOD ZEISS	No longer supported	no replacement
11430D	TRIPOD SEILER	No longer supported	no replacement
11430E	BRUNSON TRIPOD	No longer supported	no replacement
11431A	TRIBRACH WILD	No longer supported	no replacement
11431B	BALL BASE ZEIS	No longer supported	no replacement
11431C	HVY-DUTY TRIBRAC	No longer supported	no replacement
11435A	DATA COL TRI BRA	No longer supported	no replacement
11435B	INDUSTRIAL MOUNT	No longer supported	no replacement
11440A	AC CHARGER	No longer supported	no replacement
11441A	BATTERY	No longer supported	no replacement
11442A	BATTERY	No longer supported	no replacement
11445A	PWR SPLY ADAPTER	No longer supported	no replacement
11455A	5 VOLT POWER AMP	No longer supported	no replacement
11457B	DUAL RACK MOUNT	No longer supported	no replacement
11457C	CARRING CASE MOU	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
11473A	TRANSFORMER	No longer supported	no replacement
11473B	TRANSFORMER	No longer supported	no replacement
11474A	TRANSFORMER	No longer supported	no replacement
11475A	BALANCE TRANSFOR	No longer supported	no replacement
11476A	BALANCE TRANSFOR	No longer supported	no replacement
11500AR	Cable assembly, N(m) to N(m), 72 in	No longer supported	
11503A	P Band Flexible Waveguide	No longer supported	no replacement
11504A	X Band Flexible Waveguide	No longer supported	no replacement
11505A	BENCH STAND	No longer supported	no replacement
11506A	PROBE EXTENSIONS	No longer supported	no replacement
11507A	OUTPUT TERMINATI	No longer supported	no replacement
11508A	OUTPUT CABLE	No longer supported	no replacement
11511A	Coaxial Short	No longer supported	no replacement
11515A	K Band Adapter	No longer supported	no replacement
11516A	R Band Adapter	No longer supported	no replacement
11517A	WAVEGUIDE MIXER	No longer supported	
11518A	TAPER SECTION	No longer supported	
11519A	TAPER SECTION	No longer supported	
11520A	TAPER SECTION	No longer supported	
11521A	WAVEGUIDE MIXER	No longer supported	
11527A	Adapter, Thermistor Mount	No longer supported	
11528A	Adapter, Thermistor Mount	No longer supported	
11530A	BALANCED PROBE	No longer supported	no replacement
11531A	TEST UNIT	No longer supported	8620C FAMILY
11536A	50-ohm tee for the 8405A	Currently supported	no replacement
11542A	Waveguide clamp, B Band	No longer supported	no replacement
11543A	Waveguide clamp, J Band	No longer supported	no replacement
11544A	Waveguide clamp, H Band	No longer supported	no replacement
11549A	Power splitter	Currently supported	no replacement
11566A	Air Line Extension	No longer supported	no replacement
11567A	Air Line Extension	Currently supported	no replacement
11567AR	Air line extension	No longer supported	
11570AR	Accessory kit for 8405A or 8508A	No longer supported	
11571A	COMBINING CASE	No longer supported	
11574A	VERIFICATION KIT	No longer supported	
11575A	8510A Operating System Update Kit	No longer supported	E8362B
11575B	Revision 3.1 Update Kit for 8510B	No longer supported	E8362B
11575C	Revision 4.0 Upgrade Kit for 8510B	No longer supported	11575F
11575D	Revision 5.0 Upgrade Kit for 8510B	No longer supported	11575F
11575E	Revision 5.11 upgrade kit for 8510B	No longer supported	11575F
11575F	Revision 6.5 upgrade kit for 8510B	No longer supported	E8362B
11575G	Firmware upgrade kit for the 8510C	No longer supported	11575J
11575H	Rev. 6.5 upgd kit for 8510B w/ 6.3 FW	No longer supported	E8362B
11576A	10:1 divider for the 8405A	No longer supported	
11583AR	Attenuator Calibration Data	No longer supported	
11587A	ACCESSORY KIT	No longer supported	11650A
11588A	Coaxial Swivel Adapter	No longer supported	no replacement
11589A	BIASING NETWORK	No longer supported	11590B
11590A	BIASING NETWORK	No longer supported	11590B
11591A	APC-7 TOOL KIT	Currently supported	no replacement
11592A	SERVICE KIT	No longer supported	11592B
11592B	SERVICE KIT	No longer supported	
11599A	ADAPTER	No longer supported	
11600B	Transistor fixture for TO-18/TO-72	No longer supported	no replacement
11600BR	Transistor fixture for TO-18/TO-72	No longer supported	
11602B	Transistor Fixture for TO-5/TO-12	No longer supported	no replacement
11604A	Coax Extension for 8745A	No longer supported	
11605A	Flexible Arm for 8743B	No longer supported	
11606A	Rotary Air Line	No longer supported	no replacement
11607A	SMALL SIGNAL ADAPTER	No longer supported	
11608A	Transistor Fixture	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
11609A	Cable Kit for 8410S System	No longer supported	
11610B	Test Port Extension Cable	No longer supported	
11611A	APC-7 CABLE	No longer supported	
11613A	Calibrator for 8757A	No longer supported	11613B
11614A	Firmware enhancement (rev 2.0) for 8757A	No longer supported	no replacement
11635A	Bias Decoupling Network	No longer supported	no replacement
11650A	Accessory Kit for 8410S System	No longer supported	
11652A	REFLECTION-TRANS	No longer supported	no replacement
11654A	PASSIVE PROBE KI	No longer supported	
11655A	IMPEDANCE PROBE	No longer supported	
11658A	MATCHING RESISTO	No longer supported	
11660B	75 OHM SHUNT	No longer supported	
11661B	Frequency extension module	No longer supported	http://www.agilent.com/find/psg
11663A	MOD KIT	No longer supported	
11664A	10 MHz-18 GHz scalar detector, Type N	No longer supported	
11664B	26.5GHZ DETECTOR	No longer supported	11664E
11664C	Detector adapter for 8755/8756/8757s	No longer supported	no replacement
11664D	Scalar detector, 26.5-40 GHz	No longer supported	no replacement
11664E	APC-3.5 scalar detector, 10 MHz-26.5 GHz	No longer supported	
11665A	MODULATOR	No longer supported	Electronics
11665B	Modulator for scalar analyzer	Currently supported	no replacement
11666A	REFL BRIDGE	No longer supported	85020 & 21
11667AR	DC-18 GHz power splitter, Type N, 50 ohm	No longer supported	
11669A	INTERCONNECT CAB	No longer supported	
11671A	INTERFACE KIT	No longer supported	no replacement
11672A	8660 service kit	No longer supported	http://www.agilent.com/find/psg
11673A	FILTER	No longer supported	
11674A	Description Not Available (Corp)	No longer supported	
11675A	LEVELING CABLE	No longer supported	
11676A	K-BAND SWEEPER W	No longer supported	
11676B	K-BAND L O WG	No longer supported	
11677A	R-BAND SWEEPER W	No longer supported	
11677B	R-BAND L O WG	No longer supported	
11684A	6.8-GHz low pass filter	No longer supported	no replacement
11685A	9.5-GHz low pass filter	No longer supported	no replacement
11686A	13.0-GHz low pass filter	No longer supported	no replacement
11687A	50-75 Ohm Signal Generator Adapter	No longer supported	11852B
11688A	2.8-GHz low pass filter	No longer supported	no replacement
11689A	4.4-GHz low pass filter	No longer supported	no replacement
11690A	Frequency doubler	No longer supported	
11692DR	Coaxial dual directional coupler	Currently supported	
11697A	Band Pass Filter, 512-674 MHz	No longer supported	no replacement
11697B	Band Pass Filter, 674-890 MHz	No longer supported	no replacement
11697C	Band Pass Filter, 800-1100 MHz	No longer supported	no replacement
11707A	Test plug-in	No longer supported	http://www.agilent.com/find/psg
11710A	DOWN CONVERTER	No longer supported	no replacement
11711A	ADAPTER-NOISE	No longer supported	no replacement
11717A	Attenuator/Switch Rack Mount Support Kit	Currently supported	no replacement
11719A	APP PROG;AN 64-3	No longer supported	no replacement
11720A	Pulse Modulator	No longer supported	http://www.agilent.com/find/psg
11722AR	Sensor module 100 kHz to 2.6 GHz	Currently supported	
11723A	APP PROG;AN 300	No longer supported	no replacement
11723B	Transceiver test program for HP 8953A	No longer supported	no replacement
11724A	9835A SOFTWARE	No longer supported	no replacement
11725A	9845B SOFTWARE	No longer supported	11791A
11729C	Carrier noise test set, 5 MHz to 18 GHz	No longer supported	E5500 series
11729CR	Carrier noise test set, 5 MHz to 18 GHz	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
11740A	Phase Noise Measurement system	No longer supported	3048A
11740S	Microwave Phase Noise Measurement System	No longer supported	3048A
11748A	Active Probe System	No longer supported	no replacement
11748AR	Active probe system	No longer supported	
11752C	SMA Connector Gage for Pin & Dielectric	No longer supported	no replacement
11752D	Gage, APC-3.5 Connector, Male & Female	Currently supported	
11752E	Gauge, Connector, 2.4mm Kit	Currently supported	no replacement
11757A	Multipath Fading Simulator	No longer supported	11757B
11758A	Digital Radio Test	No longer supported	11758B
11758B	Digital Radio Test Set	Currently supported	no replacement
11758BR	digital Radio Test Set	Currently supported	
11758T	Digital Radio Test System	No longer supported	11758U
11758U	Digital Radio Test System	No longer supported	11758V
11758VR	Digital radio test system	Currently supported	
11759A	RF Channel Simulator (20-1550MHz)	No longer supported	http://www.agilent.com/find/esg
11759B	RF Channel Simulator (40 2000MHz)	No longer supported	http://www.agilent.com/find/esg
11760S	Power Sensor calibration System	No longer supported	no replacement
11764A	Drive Cable, 40GHz attn to 11713A	Currently supported	11764-60004.
11764B	Drive Cable, 10pin DIP to flat wire cbl	Currently supported	11764-60001.
11764C	Drive Cable, 40GHz Attn to 14pin DIP 8in	Currently supported	11764-60002.
11764D	Drive Cable, 40GHz Attn 14pin DIP 16in	Currently supported	11764-60003.
11765A	Link Group Delay Measurement System	No longer supported	no replacement
11766A	DADE Switch	Currently supported	no replacement
11767A	Tracking Generator IF Amplifier	Currently supported	no replacement
11768A	Group Delay Retrofit Kit	Currently supported	no replacement
11769A	Return Loss Bridge	Currently supported	no replacement
11775A	Waveform Generation Software.	No longer supported	11776A
11790A	Transceiver test program for HP 8953A	No longer supported	no replacement
11790B	Transceiver test program for 8953A #100	No longer supported	no replacement
11791A	Transceiver test program for HP 8955A	No longer supported	no replacement
11792AR	Sensor module 50 MHz to 26.5 GHz	Currently supported	
11793AR	Microwave converter for 8902S System	Currently supported	
11794A	Software program for the HP 8902S system	No longer supported	no replacement
11795A	Software pacs for HP 8952	No longer supported	no replacement
11797A	Software/documentation package	No longer supported	no replacement
11798A	SOFTWARE and DOCUMENTATION PAC	No longer supported	no replacement
11798R	RIGHT TO REPRODUCE SOFTWARE	No longer supported	no replacement
11799A	SIGNALLING UNIT	No longer supported	no replacement
11800A	HP 8955A calibration and service kit	No longer supported	components
11800B	Calibration Kit for 8956A Interface	No longer supported	components
11804A	Accessory kit for Cellular Test System	No longer supported	components
11804B	Accessory kit for Cellular Test system	No longer supported	components
11805A	Trans. Test Software for HP 8953/5/7A	No longer supported	no replacement
11805B	Transceiver Test Software	No longer supported	E6560A
11806A	Attenuator Software Pac for HP 8902/52S	No longer supported	no replacement
11806B	ATTENUATOR TEST SOFTWARE	No longer supported	no replacement
11807C	Radio Test Software	No longer supported	E6560A
11807F	Test Software for 8920DT with 8920B	No longer supported	no replacement
11808A	Signal Generator Performance Test S/W	No longer supported	no replacement
11809A	HP 11805B System Calibration Accessories	No longer supported	components
11809B	CALIBRATION ACCESSORY KIT FOR 8953DT SYS	No longer supported	no replacement
11812AR	8902A option 050 verification kit	Currently supported	
11816A	Option 001 Retrofit Kit for 8904A	No longer supported	no replacement
11817A	Option 002 Retfoit Kit for 8904A	No longer supported	no replacement
11818A	Option 003 Retrofit Kit for 8904A	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
11823A	Attenuator Accessory Kit	No longer supported	no replacement
11823B	Attenuator Accessory Kit	No longer supported	no replacement
11823C	SWR Accessory Kit	No longer supported	no replacement
11826A	RF phase noise accessory kit	No longer supported	
11826B	Microwave phase noise accessory kit	No longer supported	
11826C	RF & microwave phase noise accessory kit	Currently supported	
11827A	Customer Retrofit of 8904A Option 005	No longer supported	no replacement
11835AR	Data Buffer	Currently supported	
11836A	0.3 GMSK Modulation Measurement Software	No longer supported	no replacement
11836B	GSM digital cellular radio personality	No longer supported	no replacement
11837A	Customer Retrofit of 8904A Option 006	No longer supported	no replacement
11840A	Reduced RFI Kit	No longer supported	no replacement
11842A	Audio Source Retrofit Kit for 8644A	No longer supported	no replacement
11843A	Enhanced Spectral Purity Kit	No longer supported	no replacement
11844A	2 GHz Retrofit Kit	No longer supported	
11845A	Retrofit Kit to Extend 8645A to 2060 MHz	No longer supported	
11846A	Pi/4 DQPSK I/Q Generator	No longer supported	11846B
11846AR	Pi/4 DQPSK I/Q Generator	No longer supported	
11846B	PI/4 DQPSK I/Q GENERATOR	No longer supported	no replacement
11847A	Pi/4 DQPSK Modulation Meas. Software	No longer supported	no replacement
11847B	PI/4 DQPSK JDC Software	No longer supported	no replacement
11847C	PI/4 DQPSK JAPAN DIGITAL CORDLESS SW	No longer supported	no replacement
11848A	Phase noise interface for the 3048A	No longer supported	E5500 series
11848AR	Phase noise interface for 3048A	No longer supported	
11850A	Power Splitter	No longer supported	11850C
11850B	Power Splitter, 75 ohm	No longer supported	11850D
11851A	RF Cable Kit	No longer supported	11851B
11852A	Minimum Loss Pad, 50 75 ohm	No longer supported	11852B
11853AR	Type N Accessory kit, 50 OHM	Currently supported	
11855AR	Type N Accessory Kit, 75 OHM	Currently supported	
11857A	APC-7 Test Port Extension Cables	No longer supported	11857D
11857C	EXTENSION CABLES	No longer supported	
11858A	Transistor fixture adapter	No longer supported	no replacement
11859A	AMPLIFIER SWITCH	No longer supported	11859B
11859B	AMPLIFIER SWITCH	No longer supported	
11860A	GPIB UPDATE KIT	No longer supported	
11861A	GPIB UPDATE KIT	No longer supported	
11863A	8410/9825 AP PAC	No longer supported	
11863B	8409A SOFTWARE	No longer supported	
11863C	8409B SOFTWARE	No longer supported	
11863D	8409B SOFTWARE	No longer supported	
11863E	8409C SOFTWARE	No longer supported	
11863F	8409C SOFTWARE	No longer supported	
11864A	Labeling Interface Kit for 8501A	No longer supported	
11866A	APC-7 Calibration Kit	No longer supported	
11869A	Adapter for 8620 Series RF plug-ins	No longer supported	http://www.agilent.com/find/psg
11870A	2.6 GHz LPFILTER	No longer supported	
11871A	Single-mode PC Fiber Optic Cable	Currently supported	
11871B	Single-mode ST cable	Currently supported	
11871C	Biconic Fiber Cable	Currently supported	no replacement
11872A	ST Cable, 50/125 um	Currently supported	
11872B	ST Cable, 62.5/125 um	Currently supported	
11872C	ST Cable, 100/140 um	No longer supported	no replacement
11873A	8408 Accuracy Enhancement Software Pac	No longer supported	
11875A	8340A/B & 8341A/B 40-GHz upgrade kit	No longer supported	http://www.agilent.com/find/psg
11876A	8702A Upgrade	No longer supported	no replacement
11876D	Firmware upgrade kit	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
11877A	Performance test software for 8340/41	No longer supported	http://www.agilent.com/find/psg
11878AR	3.5 mm to Type N adapter kit	Currently supported	
11880A	Replacement probe to Type N male adapter	No longer supported	
11881A	Replacement 10:1 divider	No longer supported	
11882A	Upgrade kit 8753A to 8753B	No longer supported	E5062A
11886A	SMF Interconnect Cable Kit	No longer supported	
11887A	Interconnect Cable Kit, MMF	No longer supported	no replacement
11890AR	Lightwave Coupler, SMF	Currently supported	
11891A	Lightwave Coupler, MMF	Currently supported	
11891AR	Lightwave Coupler, MMF	Currently supported	
11894A	11894A Polarization Controller	No longer supported	11896A
11895A	Workspace Cabinet	No longer supported	
11896A-K81	Retrofit to install FC/APC on ports	No longer supported	
11896A-K82	Retrofit to install 1-meter pigtail	No longer supported	
11946A	Quasi-peak upgrade kit	No longer supported	
11950X	Designing for EMC on-site instructor pkg	No longer supported	no replacement
11952A	14 Inch Monitor	No longer supported	no replacement
11965A	ACTIVE MAGNETIC LOOP ANTENNA KIT	No longer supported	11966A
11965B	VDE/FCC ANTENNA KIT	No longer supported	11966A,C,D
11965C	EMI TRANSDUCER KIT	No longer supported	11967C
11965D	EMI TRANSDUCER KIT	No longer supported	11966C,D
11965M	EMI TRANSDUCER KIT	No longer supported	11966B,C,F
11965N	EMI TRANSDUCER KIT	No longer supported	11966B,C,D
11965R	CURRENT PROBE AND ACCESSORIES	No longer supported	11967A
11966GR	Conical log spiral antenna, 1-10 GHz	Currently supported	
11966HR	Dipole antenna set, 28-1000 MHz	Currently supported	
11966IR	Dbi-ridged guide horn antenna,0.2-2GHz	Currently supported	
11966JR	Dbi-ridged guide horn antenna,18-40GHz	Currently supported	
11966KR	Magnetic field pickup coil, 20 Hz-50kHz	Currently supported	
11966NR	Log periodic antenna, 200MHz to 5 GHz	Currently supported	
11967BR	Current probe for MIL-STD CE-01 measmnts	Currently supported	
11967CR	Line impedance stabilizatin network	No longer supported	
11968A	Automatic antenna mast, 1-6 m, 110/120 V	No longer supported	contact EMCO
11968CR	Non-metallic antenna tripod	Currently supported	
11968D	Automatic equipment testing turntable	No longer supported	
11968K	Antenna tripod	No longer supported	
11969A	STORAGE/TOOL KIT	No longer supported	
11970AR	26-40 GHz waveguide harmonic mixer	Currently supported	
11970KR	18-26 GHz Waveguide Harmonic Mixer	Currently supported	
11970QR	33-50 GHz waveguide harmonic mixer	Currently supported	
11970T	MIXER SET	No longer supported	
11971A	26-40 GHZ MIXER	No longer supported	
11971K	HARMONIC MIXER	No longer supported	
11971Q	HARMONIC MIXER	No longer supported	
11971T	MIXER SET	No longer supported	
11971U	HARMONIC MIXER	No longer supported	
11971V	HARMONIC MIXER	No longer supported	
11974AR	26.5-40 GHz preselected mm mixer	Currently supported	
11974QR	33-50 GHz preselected millimeter mixer	Currently supported	
11974UR	40-60 GHz preselected millimeter mixer	Currently supported	
11975AR	2-8 GHz power amplifier	Currently supported	
11982A-001	Freq. response corrections/menus-11982A	No longer supported	
11982A-K07	Additional frequency response data	No longer supported	
12500B	COMBINING CASE	No longer supported	no replacement
12502B	REAR CONNECTOR	No longer supported	no replacement
12504B	FILLER PANEL	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
12529A	TERMINAL COVER	No longer supported	no replacement
12530C	PORTABLE CASE	No longer supported	no replacement
12697B	FRONT DOOR	No longer supported	no replacement
12770A	OBSITEM	No longer supported	no replacement
12772A	OBSITEM	No longer supported	no replacement
12962A	DISC CART SUB	No longer supported	no replacement
12962B	7905A SUBSYSTEM	No longer supported	no replacement
13510A	TRANSISTOR TEST	No longer supported	no replacement
13515A	FREQUENCY DOUBLE	No longer supported	components
14513A	RACK KIT	No longer supported	no replacement
14515A	RACK KIT	No longer supported	no replacement
14521A	RACK KIT	No longer supported	
14521B	RACK KIT	No longer supported	14521C
14521C	RACK KIT	No longer supported	no replacement
14523A	RACK KIT	Currently supported	no replacement
14524B	PANEL KIT	No longer supported	
14525A	RACK KIT	Currently supported	no replacement
14531A	RACK MOUNT PANEL	No longer supported	
14531B	RACK MOUNT PANEL	No longer supported	
14532A	RACK MOUNT PANEL	No longer supported	
14532B	RACK MOUNT PANEL	No longer supported	
14532C	RACK MOUNT PANEL	No longer supported	
14533B	PROGRAMMER	No longer supported	no replacement
14534A	EXTENSION CABLE	No longer supported	no replacement
14535A	DVS INTERFACE	No longer supported	no replacement
14536A	DVS CHAINING CABLE	No longer supported	no replacement
14537A	CABLE	No longer supported	
14539A	CABLE	No longer supported	
14540A	MULTI-CABLE	No longer supported	no replacement
14541A	CHAINING CABLE	No longer supported	no replacement
14544A	DCPS/PDP-8 CABLE	No longer supported	
14545A	CASTERS	No longer supported	14545B
14545B	CASTERS	No longer supported	no replacement
14546A	MULTI/PDP-8 CABL	No longer supported	
14550A	MULTI INTERFACE	No longer supported	
14550B	INTERFACE KIT	No longer supported	no replacement
14551A	SERVICE KIT	No longer supported	no replacement
14555A	CARD CONNECTOR	No longer supported	no replacement
14556A	SOFTWARE LIBRARY	No longer supported	no replacement
14557A	PS/MULTI-CABLE	No longer supported	no replacement
14558A	TERMINAL-PANEL	No longer supported	no replacement
14560A	MULTI-CABLE	No longer supported	no replacement
14561A	MULTI-CABLE	No longer supported	no replacement
14562A	MULTI-CABLE	No longer supported	no replacement
14570A	AC POWER CONTROLLER	No longer supported	no replacement
14700A	EXTENDER KIT	No longer supported	no replacement
14701A	EXTENDER KIT	No longer supported	no replacement
14702A	CHAINING CABLE	No longer supported	no replacement
14703A	MULTI-CONNECTOR	No longer supported	no replacement
14704A	MULTI-CABLE	No longer supported	no replacement
14704B	2 METER MULTI CABLE	No longer supported	no replacement
14704C	4 METER MULTI CABLE	No longer supported	no replacement
14711A	FIELD SERV. KIT	No longer supported	no replacement
14717A	BUFFERED A/D CABLE	No longer supported	no replacement
14718A	A/D CABLE	No longer supported	no replacement
14728A	BUFFERED A/D CABLE	No longer supported	no replacement
14750A	CAT PROG PACKAGE	No longer supported	
14750R	R TO COPY 14570A	No longer supported	
14751A	CAT SOFTWARE	No longer supported	
14751R	RIGHT TO COPY	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
14752A	CAT SOFTWARE PROGRAMMING PACKAGE	No longer supported	14753A
14752R	RIGHT TO COPY	No longer supported	no replacement
14753A	CAT SOFTWARE	No longer supported	no replacement
14753R	RIGHT TO COPY	No longer supported	no replacement
14770A	6942A ASYST LIBRARY	No longer supported	no replacement
14801A	RACK SHELF	No longer supported	no replacement
14802A	TERMINAL BLOCK	No longer supported	no replacement
14852A	BIAS CABLE	Currently supported	no replacement
14855A	D/A SOFTWARE	No longer supported	no replacement
14855AA	DATA ACQUISITION SOFTWARE HP150 VERSION	No longer supported	
14856A	D/A SOFTWARE	No longer supported	no replacement
14856AA	D/A SOFTWARE	No longer supported	14856A
14857AA	HP-IB I/O LIBRARY FOR THE HP150	No longer supported	
14857BA	HP-IB I/O SOFTWARE LIBRARY	No longer supported	no replacement
14858A	ASYST SOFTWARE	No longer supported	no replacement
14865A	COPY PROTECT KEY	No longer supported	no replacement
14921A	Power Supply Calibration Software	No longer supported	
15101A	ADAPTER	No longer supported	no replacement
15163A	INTERFACE CARD	No longer supported	no replacement
15166A	DUPLEX REGISTER	No longer supported	no replacement
15171A	RISETIME CONVERT	No longer supported	no replacement
15179A	RACK ADAPTER FOR 8011A, 8012B, 8013B	No longer supported	no replacement
15263A	CARD READER	No longer supported	no replacement
15264A	SERVICE KIT	No longer supported	
15268A	ACCESORY KIT	No longer supported	no replacement
15400A	BLANK FRONT PANEL, 1/4-WIDTH, FOR 8080A	No longer supported	
15401A	BLANK FRONT PANEL, 1/8-WIDTH, FOR 8080A	No longer supported	
15402A	BNC PANEL, 1/8-WIDTH, FOR 8080A	No longer supported	
15408A	5 GRABBERS	No longer supported	no replacement
15409A	5 BNC ADAPTORS	No longer supported	no replacement
15410A	5 SMB ADAPTORS	No longer supported	no replacement
15411A	5 OPEN-END ADAPTER	No longer supported	no replacement
15415A	5 MINI PROBES	No longer supported	no replacement
15429A	SOLDER-IN RECEPTACLES FOR 8175A OUT PODS	No longer supported	no replacement
15430A	CABLE MASTER/SLAVE FOR 8175A	No longer supported	no replacement
15432A	300ps TRANSITION TIME CONVERTER	No longer supported	15432B
15433A	500ps TRANSITION TIME CONVERTER	No longer supported	15433B
15434A	1ns TRANSITION TIME CONVERTER	No longer supported	15434B
15450A	FOUR CHANNEL	No longer supported	no replacement
15451A	FOUR CHANNEL	No longer supported	no replacement
15452A	ADDRESS OUTPUT POD FOR 8170A	No longer supported	no replacement
15453A	ADDRESS INPUT POD FOR 8170A	No longer supported	no replacement
15454A	CONTROL POD FOR 8170A	No longer supported	no replacement
15455A	OUTPUT POD FOR CHANNELS D0-D7 OF 8170A	No longer supported	no replacement
15456A	OUTPUT POD FOR CHANNELS D8-D15 OF 8170A	No longer supported	no replacement
15457A	RECEPTACLE FOR 8170A PODS	No longer supported	no replacement
15458A	SNAP-ON CONNECTOR FOR 8170A PODS	No longer supported	
15459A	1.5 M EXTENDER CABLE FOR 8170A PODS	No longer supported	no replacement
15461A	ECL POD (8 CHANNELS) FOR 8175A	No longer supported	no replacement
15462A	TTL/CMOS POD (8 CHANNELS) FOR 8175A	No longer supported	

Product	Description	Support Status	Replacement Information
15463A	TRIGGER POD (8 CHANNELS) FOR 8175A	No longer supported	
15464A	TTL POD (8 CHANNELS) FOR 8175A	No longer supported	
15475A	F/O CLEANING KIT	No longer supported	no replacement
15506A	PCM FRAME GEN	No longer supported	no replacement
15509A	AMPLIFIER	Currently supported	no replacement
15509B	AMPLIFIER	No longer supported	no replacement
15516A	CONVERSION KIT	No longer supported	no replacement
15517A	CONVERSION KIT	No longer supported	no replacement
15518A	LOOP HOLDING ACCESSORY	Currently supported	no replacement
15518B	Loop holding accessory.	Currently supported	no replacement
15518C	Loop holding accessory.	No longer supported	no replacement
15520A	HYBRID	No longer supported	no replacement
15520B	I.F. HYBRID	No longer supported	no replacement
15520C	IF HYBRID	No longer supported	no replacement
15521B	Return loss standard 17dB.	No longer supported	no replacement
15522A	TERMINATION	No longer supported	no replacement
15522C	75 Ohm termination with BNC connectors.	No longer supported	no replacement
15523A	BLANK PANEL	No longer supported	no replacement
15524A	Connecting link	No longer supported	no replacement
15530A	LOW PASS FILTER	No longer supported	no replacement
15533A	PLUG-IN EXTENDER	No longer supported	no replacement
15533B	PLUG IN EXTENDER	No longer supported	no replacement
15537A	HYBRID	No longer supported	no replacement
15539A	CABLE ASSEMBLY	No longer supported	no replacement
15540A	CABLE ASSEMBLY	No longer supported	no replacement
15542A	0.3m UF Audio Cable	Currently supported	no replacement
15543A	CABLE ASSEMBLY	No longer supported	no replacement
15548A	CABLE ASSEMBLY	No longer supported	no replacement
15550A	ACCESSORY KIT	No longer supported	no replacement
15550B	MLA ACCSY KIT	No longer supported	no replacement
15550C	ACCESSORY KIT	No longer supported	no replacement
15551A	CABLE ASSEMBLY	No longer supported	no replacement
15561A	MODEM CABLE BELL	No longer supported	no replacement
15562A	MODEM CABLE BT	No longer supported	no replacement
15563A	MODEM CABLE SPA	No longer supported	no replacement
15564A	MODEM INTF CABLE	No longer supported	no replacement
15570A	AM/PM TEST NETWO	No longer supported	no replacement
15570B	AM/PM TEST NW	No longer supported	no replacement
15572A	N2 Cable.	No longer supported	no replacement
15573A	Battery Charger.	No longer supported	no replacement
15575A	EQUALISER (5 M)	No longer supported	no replacement
15575B	EQUALISER (10M)	No longer supported	no replacement
15575C	EQUALISER (15M)	No longer supported	no replacement
15575D	EQUALISER (20M)	No longer supported	no replacement
15575E	EQUALISER (25M)	No longer supported	no replacement
15575F	EQUALISER (30M)	No longer supported	no replacement
15575G	EQUALISER (35M)	No longer supported	no replacement
15575H	EQUALISER (40M)	No longer supported	no replacement
15578A	ACTIVE PROBE	No longer supported	no replacement
15580A	ACTIVE PROBE	No longer supported	no replacement
15581A	PASSIVE PROBE	No longer supported	no replacement
15581B	PASSIVE PROBE	No longer supported	no replacement
15582A	Return loss kit.	No longer supported	no replacement
15583A	RACK MOUNT KIT	No longer supported	no replacement
15584A	TRANSIT CASE	No longer supported	no replacement
15585A	DIAGNOSTIC KIT	No longer supported	no replacement
15586A	COMBINING KIT	No longer supported	no replacement
15586B	COMBINING KIT	No longer supported	no replacement
15587A	LOW NOISE AMP	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
15588A	LOW NOISE AMP	No longer supported	no replacement
15589A	INSTRUMENT CART	No longer supported	no replacement
15600A	ISOLATOR ACC	No longer supported	no replacement
15601A	ISOLATOR ACC	No longer supported	no replacement
15602A	ISOLATOR ACC	No longer supported	no replacement
15603A	ISOLATOR ACC	No longer supported	no replacement
15609A	REMOTE EXT CABLE	No longer supported	no replacement
15614A	RS-232C/V.24 Dial-up Control Cable.	No longer supported	no replacement
15631A	TMU EXTEND CARD	No longer supported	no replacement
15676A	4948A Connection Kit.	No longer supported	no replacement
15680A	RF Accessory Kit for the 71600 Series.	Currently supported	no replacement
15692A	RS449/422 Interface Cable (Male ended).	No longer supported	no replacement
15698A	V.35 Interface Cable (Male ended)	No longer supported	no replacement
15709A	High Impedance Interface	No longer supported	no replacement
15712A	Rack Mount Kit for 15901A	No longer supported	no replacement
15720A	Rack Mount Kit for 37721A.	Currently supported	no replacement
15721A	Rack Mount kit for 37704A	No longer supported	no replacement
15723A	Soft carrying case for 37704A	No longer supported	no replacement
15741A	Carrying Pouch for the 37742A	No longer supported	no replacement
15743A	Charger/Adapter for 37742A	No longer supported	no replacement
15744A	Optical Coupler	No longer supported	no replacement
15744AR	Optical Coupler	Currently supported	
15747A	Upgrade kit to OmniBER 719 (HP 37719A)	No longer supported	OmniBER OTN
15747B	Upgrade kit to OmniBER 719 (HP37719B)	No longer supported	OmniBER OTN
15747C	Upgrade kit to OmniBER 719 (HP37719C)	No longer supported	OmniBER OTN
15748A	2M Printer Cable 9 pinM 25 pinM	No longer supported	no replacement
15749A	2M Printer Cable 9 pinM to 25 pinM.	No longer supported	no replacement
15752A	25pinM to 25pinF EIA 232 cable	Currently supported	
15759A	RS-232 cable with 25-pin connectors	Currently supported	no replacement
15770A	19 Rack Mount Kit for 37717C	No longer supported	no replacement
15771A	Rackmount kit for 37714A.	No longer supported	no replacement
15772A	Hard Transit Case for 37714A/37717A	No longer supported	no replacement
15772B	Hard transit case for 37717B/C	No longer supported	no replacement
15772B	Hard transit case for 37717B/C	No longer supported	no replacement
15773A	Transit case for 37714A.	No longer supported	no replacement
15774A	Upgrade Kits for 37714A	No longer supported	no replacement
15777A	Upgrade kits for the 37717A PDH/SDH	Currently supported	no replacement
15777B	Upgrade Kits for 37717B	Currently supported	OmniBER OTN
15777C	Upgrade Kits for 37717C	Currently supported	OmniBER OTN
15777D	Upgrade kits for OmniBER 717	No longer supported	OmniBER OTN
15821AR	Multiple bridging isolator	Currently supported	
15822A	Upgrade J1420A to J1420B (10G Rx)	Currently supported	OmniBER XM
15823A	Upgrade J1422A to J1422B (10G Tx)	Currently supported	OmniBER XM
15850A	Retrofit kits for 37XXX.	Currently supported	no replacement
15901A	Datacom Module	Currently supported	no replacement
15901AR	Datacom Module	No longer supported	
15910A	Soft Carrying Case (37714A/17A/21A/24A)	No longer supported	no replacement
15911A	Transit Case for 37721A	Currently supported	no replacement
15912A	Transit Case for 37704A	No longer supported	no replacement
15948A	4948A V.33 Upgrade Accessory.	No longer supported	no replacement
15990A	Connector Access Panel for OmniBER	No longer supported	no replacement
15996A	Upgrade kit to OmniBER 718 (HP37718A)	No longer supported	OmniBER OTN
15996B	Retrofit kit for OmniBER 718 (HP37718B)	No longer supported	OmniBER OTN
15996C	Upgrade kit to OmniBER 718 (HP 37718C)	No longer supported	OmniBER OTN
16005A	PROBE	No longer supported	16005B
16008A	RESISTIVITY CELL	No longer supported	no replacement
16009A	SOCKET KIT	No longer supported	
16011A	TEST FIXTURE	No longer supported	

Product	Description	Support Status	Replacement Information
16012A	TEST FIXTURE	No longer supported	
16013A	TEST FIXTURE	No longer supported	
16014A	LOSS TEST ADAPTER	Currently supported	no replacement
16015A	TEST FIXTURE	No longer supported	
16016A	TEST FIXTURE	No longer supported	
16017A	TEST FIXTURE	No longer supported	
16018A	BLOCKING CAPACIT	No longer supported	
16019A	TEST FIXTURE	No longer supported	no replacement
16021A	CALIB.CONNECTOR	No longer supported	
16022A	TEST FIXTURE	No longer supported	no replacement
16023A	DC BIAS CONTROLL	No longer supported	no replacement
16023B	DC BIAS CONTROL	No longer supported	no replacement
16029A	TEST FIXTURE	No longer supported	
16032A	TEST LEADS	No longer supported	no replacement
16033A	TEST LEADS	No longer supported	no replacement
16034A	TEST FIXTURE	No longer supported	no replacement
16034B	TEST FIXTURE	No longer supported	16334A
16035A	TEST LEAD	No longer supported	
16036A	TEST LEAD	No longer supported	
16037A	TEST FIXTURE	No longer supported	
16038A	TEST FIXTURE	No longer supported	no replacement
16039A	TEST FIXTURE	No longer supported	no replacement
16045A	TEST LEADS	No longer supported	16048A
16047B	TEST FIXTURE	No longer supported	no replacement
16047CR	Test Fixture	No longer supported	
16048C	TEST LEADS	No longer supported	16089A/B
16061A	FIXTURE	No longer supported	no replacement
16062A	TEST LEAD	No longer supported	no replacement
16063A	TEST LEAD	No longer supported	no replacement
16064A	COMP/HAND IF KIT	No longer supported	no replacement
16074A	CALIB. R-L STD	No longer supported	42030A/40A
16085A	TERMINAL ADAPTER	No longer supported	no replacement
16086A	4194A ACCESSORIES	Currently supported	no replacement
16091A	COAXIAL FIXTURE	No longer supported	16192A
16092AR	Test Fixture	No longer supported	
16093AR	Test Fixture	No longer supported	
16096A	4192A 2-PORT FXTR	Currently supported	no replacement
16097A	4192A ACCESSORIES	No longer supported	no replacement
16097AR	4192 Accessories	Currently supported	
16099AR	Test Fixture Adapter	No longer supported	
16117A	TEST LEAD	No longer supported	no replacement
16117D	Low Noise Test Lead	No longer supported	16117E
16122A	MATING CABLE	No longer supported	
16138A	TEST CABLE	No longer supported	no replacement
16143A	MATING CABLE	No longer supported	no replacement
16190A	Performance Test Kit	Currently supported	16190B
16191AR	Side Electrode SMD Test fixture	Currently supported	
16192AR	Parallel Electrode SMD Test Fixture	Currently supported	
16193A	Small side electrode SMD test fixture	Currently supported	16197A
16194AR	High temperature component fixture	Currently supported	
16200A	External DC Bias Adapter	Currently supported	16200B
16200AR	External DC bias Adaptor	Currently supported	
16252A	TRANSFORMER	No longer supported	
16298A	HP 8751A IBASIC RETROFIT KIT	No longer supported	no replacement
16298B	8751A Retrofit Kit	Currently supported	no replacement
16298C	Retrofit Kit for 8751A	Currently supported	no replacement
16298D	8751A IBASIC Retrofit Kit	Currently supported	no replacement
16298E	8751A UPGRADE KIT	Currently supported	no replacement
16298F	8751A UPGRADE KIT	Currently supported	no replacement
16298G	8751A UPGRADE KIT	Currently supported	no replacement
16298H	8751A UPGRADE KIT	Currently supported	no replacement

Product	Description	Support Status	Replacement Information
16339AR	Component Test Fixture	Currently supported	
16341A	LOGIC TEST BOX	No longer supported	no replacement
16342A	CALIBRATION KIT	Currently supported	no replacement
16343A	LOGIC TEST BOX	Currently supported	no replacement
16345A	4193A CALIB BOX	Currently supported	no replacement
16349A	PSP FOR 4194A	No longer supported	no replacement
16361A	120 HZ-1 KHZ DUT	No longer supported	no replacement
16362A	10KHZ DUT BOX	No longer supported	no replacement
16380AR	C Standards	Currently supported	
16380B	C STANDARDS	No longer supported	16380C
16389A	TERMINAL ADAPTER	No longer supported	no replacement
16389B	TERMINAL ADAPTER	No longer supported	no replacement
16411A	HPIB KIT/4270A	No longer supported	
16412A	HPIB KIT/ 4271	No longer supported	
16413A	HPIB KIT/ 4282	No longer supported	
16414A	HP-IB KIT/ 4261	No longer supported	
16442AR	Test Fixture	Currently supported	
16451A	DIELECTRIC TESTE	No longer supported	no replacement
16451BR	Dielectric Test Fixture	Currently supported	
16452AR	Liquid Test Fixture	Currently supported	
16453AR	Dielectric Material Test Fixture	Currently supported	
16454AR	Magnetic Material Test Fixture	Currently supported	
16459A	CASE FOR 4328A	No longer supported	no replacement
16461A	CAMERA ADAPTER	No longer supported	no replacement
16462A	AUX CAPACITOR	No longer supported	no replacement
16465A	INDUCTOR	No longer supported	no replacement
16470A	INDUCTOR;SET OF	No longer supported	no replacement
16470B	INDUCTORS;STABLE	Currently supported	no replacement
16470C	INDUCTOR;SET	No longer supported	no replacement
16471A	INDUCTOR	No longer supported	no replacement
16472A	INDUCTOR	No longer supported	no replacement
16473A	INDUCTOR	Currently supported	no replacement
16474A	INDUCTOR	Currently supported	no replacement
16475A	INDUCTOR	Currently supported	no replacement
16476A	INDUCTOR	Currently supported	no replacement
16477A	INDUCTOR	Currently supported	no replacement
16478A	INDUCTOR	Currently supported	no replacement
16479A	INDUCTOR	Currently supported	no replacement
16480A	INDUCTOR	Currently supported	no replacement
16480B	INDUCTOR;STABLE	Currently supported	no replacement
16481A	INDUCTOR	Currently supported	no replacement
16482A	INDUCTOR	Currently supported	no replacement
16483A	INDUCTOR	Currently supported	no replacement
16483B	INDUCTOR;STABLE	Currently supported	no replacement
16484A	INDUCTOR	Currently supported	no replacement
16485A	INDUCTOR	Currently supported	no replacement
16486A	INDUCTOR	Currently supported	no replacement
16486B	INDUCTOR;STABLE	Currently supported	no replacement
16487A	INDUCTOR	Currently supported	no replacement
16488A	INDUCTOR	Currently supported	no replacement
16488B	INDUCTOR;STABLE	Currently supported	no replacement
16489A	INDUCTOR	No longer supported	no replacement
16490A	INDUCTOR	No longer supported	no replacement
16498A	INTERCONNECT CAB	No longer supported	
16500A	LOGIC ANALYSIS SYSTEM MAINFRAME	No longer supported	
16500AR	Rmkt Logic Analysis System Mainframe	No longer supported	16500BR
16500BR	Rmkt Logic Analysis System Mainframe	No longer supported	
16500HR	Interface Module	No longer supported	
16500LR	Ethernet,multisynch & 16501 INTFC-Module	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
16500U	16500A to 16500B Upgrade Kit	No longer supported	
16501A	Logic Analysis System Expansion Frame	Currently supported	
16503A	Application Interface Module	No longer supported	
16505AR	Prototype Analyzer	No longer supported	
16510A	80 CHANNEL 25MHz STATE/100MHz TIME CARD	No longer supported	
16510B	80 CHANNEL LOGIC ANALYZER MODULE	No longer supported	
16510BR	Rmkt 80 Channel Logic Analyzer Module	No longer supported	no replacement
16511B	160 CHANNEL LOGIC ANALYZER CONVERSION KT	No longer supported	
16515A	16 CHANNEL 1GHz TIMING MASTER CARD	No longer supported	
16515AR	Rmkt Channel 1GHz Timing Master Card	No longer supported	no replacement
16516A	16 CHANNEL 1GHz TIMING EXPANSION CARD	No longer supported	
16516AR	Rmkt 16 Channel 1GHz Timing Expansion	No longer supported	
16520A	12 CHANNEL 50 MBITS/S PATTERN GENERATOR	No longer supported	
16520AR	Rmkt 12 Chan 50Mbps/S Pattern Generator	No longer supported	
16521A	PATTERN GENERATOR EXPANSION CARD	No longer supported	
16521AR	Rmkt Pattern Generator Expansion Card	No longer supported	
16530A	DIGITIZING OSCILLOSCOPE TIMEBASE CARD	No longer supported	
16530AR	Rmkt Digitizing Oscilloscope Timebase	No longer supported	no replacement
16531A	DIGITIZING OSCILLOSCOPE ACQUISITION CARD	No longer supported	
16531AR	Rmkt Digitizing Oscilloscope Acquisition	No longer supported	no replacement
16532A	DIGITIZING OSCILLOSCOPE CARD	No longer supported	
16532AR	Remarketed Digitizing Oscilloscope Card	No longer supported	
16540A	100 MHz State Analysis Master Card	No longer supported	
16540AR	Rmkt 100 MHz State Analysis Master Card	No longer supported	no replacement
16540D	100MHZ DEEP STATE/TIMING MASTER CARD	No longer supported	
16541A	100 MHz State Analyzer Expansion Card	No longer supported	
16541AR	Rmkt 100MHz State Analyzer Expansion Crd	No longer supported	no replacement
16541D	100MHZ DEEP STATE/TIMING EXPANSION CARD	No longer supported	
16542A	1MBITS/CH,16-CH,100MHZ STATE/TIMING CARD	No longer supported	
16542AR	1 MBITS/CH,16 CH 100 Mhz state/timing	No longer supported	
16555A	68 Ch State/Timing Logic Analyzer Card	No longer supported	
16590A	CAE LINK	No longer supported	
16590B	CAE LINK	No longer supported	
16590C	CAE LINK	No longer supported	
16590D	CAE LINK	No longer supported	
16590E	CAE LINK	No longer supported	
16590F	CAE LINK	No longer supported	
16590G	CAE LINK	No longer supported	
16590H	CAE LINK	No longer supported	
16600A	204 Chnl Logic Analysis System Frame	Currently supported	
16600S	Digital Debug Systems Solution	No longer supported	
16601A	136 Chnl Logic Analysis System Frame	Currently supported	
16602A	102 Chnl Logic Analysis System	Currently supported	
16603A	68 Chnl Logic Analysis System Frame	Currently supported	
1660ASR	136-Ch Logic Analyzer W/Oscilloscope	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
16610A	Emulation Module for Consignment Only	Currently supported	
1661ASR	102-Ch. Logic Analyzer w/Oscilloscope	No longer supported	
1662ASR	68-Channel Logic Analyzer w/Oscilloscope	No longer supported	
1663ASR	34-Ch Logic Analyzer w/Oscilloscope	No longer supported	
17090A	Measurement graphics software for 7090A.	No longer supported	no replacement
17090B	Measurement graphics software for 7090A.	No longer supported	no replacement
17090C	7090 Software for Series 300 computers.	No longer supported	no replacement
18019A	CARRYING CASE	No longer supported	no replacement
18055A	Transit case for 4942A/43A/44A.	No longer supported	no replacement
18107A	External Oscillator	No longer supported	no replacement
18108A	LINE AMPLIFIER	No longer supported	no replacement
18109A	DIAGNOSTIC KIT	No longer supported	no replacement
18110A	Laboratory Probe	No longer supported	no replacement
18111A	LABORATORY PROBE	No longer supported	no replacement
18112A	LAB PROBE	No longer supported	no replacement
18115A	HEAVY DUTY PROBE	No longer supported	no replacement
18116A	HEAVY DUTY PROBE	No longer supported	no replacement
18117A	HEAVY DUTY PROBE	No longer supported	no replacement
18119A	1 IN LAB PROBE	No longer supported	no replacement
18120A	9 IN LAB PROBE	No longer supported	no replacement
18121A	19 IN LAB PROBE	No longer supported	no replacement
18122A	1 IN H.D. PROBE	No longer supported	no replacement
18123A	5 IN H.D. PROBE	No longer supported	no replacement
18124A	7 IN H.D. PROBE	No longer supported	no replacement
18125A	Calibration Module	No longer supported	no replacement
18126A	LAB PROBE	No longer supported	no replacement
18127A	LAB PROBE	No longer supported	no replacement
18128A	LAB PROBE	No longer supported	no replacement
18130A	HEAVY DUTY PROBE	No longer supported	no replacement
18131A	HEAVY DUTY PROBE	No longer supported	no replacement
18282AR	ISDN Primary Rate 1.544Mbps Interface	No longer supported	
19609A	High Density Signal Configuration Module	No longer supported	
19611A	GM30 Preconditioned Combined Board	No longer supported	
19613A	GM30 Waveform Generation Board	No longer supported	
19614A	GM 30 Waveform Analysis Board	No longer supported	
19615A	Vehicle Input/Output Interface Board	No longer supported	
19618A	GM30 Serial/Vehicle Datalink I/O Board	No longer supported	
19620A	General Motors Video Output Board	No longer supported	
19622A	Vehicle Power Supply Interface Kit	No longer supported	
19623A	GM30 High Current Switching Module Kit	No longer supported	
19624A	GM30 Low Current Switching Module Kit	No longer supported	
19625A	GM Vehicle Input/output Power Supply	No longer supported	
19630A	GM Distributed System w/Fiber Optic Brd	No longer supported	
19631A	GM30 Vehicle Input/Output Adapter	No longer supported	
19632A	NEMA Central Processing Enclosure	No longer supported	
19635A	GM30 VIO Module Enclosure	No longer supported	
19636A	Power Supply Module Enclosure	No longer supported	
19637A	Serial Data Link w/PSI Cable Kit	No longer supported	
19642A	Programmable Serial I/F Card w/firmware	No longer supported	
19643A	Program Serial I/F w/Mfg Info DB Firmware	No longer supported	
19655B	2000 SERIES M/26	No longer supported	no replacement
19657B	2000 SERIES M/21	No longer supported	no replacement
19662B	2000 SERIES M/23	No longer supported	no replacement
19668B	Low Cost Operator Interface Unit Srv Kit	No longer supported	
19670B	Central processing Unit Service Kit	No longer supported	
19699B	Vehicle Interface Unit Kit	No longer supported	
19800A	1980A/B SOFTWARE, SERIES 200, 5 1/4"	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
19800B	1980A/B SOFTWARE, SERIES 200, 3-1/2"	No longer supported	no replacement
19801A	1980A/B SOFTWARE, HP 86 & HP 87, 5-1/4"	No longer supported	no replacement
19801B	1980A/B SOFTWARE, HP 86 & HP 87, 3-1/2"	No longer supported	no replacement
19801C	1980A/B SOFTWARE	No longer supported	no replacement
19807A	SERVICE EXTENDER	No longer supported	no replacement
19810A	SEQUENCE ROM	No longer supported	19811A
19811A	PLOT/SEQ. ROM	No longer supported	no replacement
19860A	DIGITIZER	No longer supported	no replacement
24307B	DOS-III SOFTWARE	No longer supported	no replacement
24307C	DOS-III SOFTWARE	No longer supported	no replacement
24342B	(TCS) S/W	No longer supported	no replacement
24376B	IMAGE/DOS	No longer supported	no replacement
24386A	ON-TOP SOFTWARE	No longer supported	no replacement
25501A	16 CH ADC	No longer supported	no replacement
25501B	16 CHL HISPDC ADC	No longer supported	no replacement
25502A	32CH HILVL SSMUX	No longer supported	no replacement
25503A	LOWLVL SSMUX32CH	No longer supported	no replacement
25503B	32 CHL LOLVL MUX	No longer supported	no replacement
25503C	32 CHL LLMUX TRC	No longer supported	no replacement
25503D	32 CHANNEL LOW LEVEL MULTIPLEXER CARD	No longer supported	no replacement
25504A	WID RNG RELAY MUX	No longer supported	no replacement
25504B	16 CHL RELAY MUX	No longer supported	no replacement
25504C	16 CHL RELAY TRC	No longer supported	no replacement
25510A	4 CH DAC	No longer supported	no replacement
25510B	4 CHL VLTCUR DAC	No longer supported	no replacement
25510D	4 CHANNEL V OR I DAC CARD	No longer supported	no replacement
25511A	32CH DIGITAL IN	No longer supported	no replacement
25511B	32 CHL DIGITL IN	No longer supported	no replacement
25512A	COUNTER INPUT	No longer supported	no replacement
25513A	32 CH DIG OUT	No longer supported	no replacement
25514A	DIG RELAY OUT	No longer supported	no replacement
25515A	PULSE OUTPUT	No longer supported	no replacement
25515B	4 CHL PULSE OUT	No longer supported	no replacement
25516A	16IN;16OUT MULTI	No longer supported	no replacement
25516B	16 CHL MULTIFUNCT	No longer supported	no replacement
25531B	5VDC NONISO STRB	No longer supported	no replacement
25531C	12VDC NONISO STRB	No longer supported	no replacement
25531D	24VDC NONISO STRB	No longer supported	no replacement
25531E	48VDC NONISO STRB	No longer supported	no replacement
25531K	5V DC NONISO STRB	No longer supported	no replacement
25531L	12DCSKNONISO STRB	No longer supported	no replacement
25533B	5VDC ISO STROBE	No longer supported	no replacement
25533C	12VDC ISO STROBE	No longer supported	no replacement
25533D	24VDC ISO STROBE	No longer supported	no replacement
25533E	48VDC ISO-STROBE	No longer supported	no replacement
25533F	72VDC ISO STROBE	No longer supported	no replacement
25533G	120DC72ACISO STRB	No longer supported	no replacement
25533H	115VAC ISO STROB	No longer supported	no replacement
25533J	230VAC ISO STROB	No longer supported	no replacement
25535B	5VDC NON ISO SCM	No longer supported	no replacement
25535C	12VDCNONISOINSCM	No longer supported	no replacement
25535D	24VDCNONISOINSCM	No longer supported	no replacement
25535E	48VDCNONISOINSCM	No longer supported	no replacement
25535K	5VDC NONISOINSCM	No longer supported	no replacement
25535L	12VDCNONISOINSCM	No longer supported	no replacement
25536B	5 VLT ISO SOURCE	No longer supported	no replacement
25536K	5 VLT ISO SNK IN	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
25537P	5VDC ISO IN SCM	No longer supported	no replacement
25537Q	12V DC ISO INSCM	No longer supported	no replacement
25537R	24DC16VRMTSOIPUT	No longer supported	no replacement
25537S	48V DC ISO INPUT	No longer supported	no replacement
25537T	72V DC ISO INPUT	No longer supported	no replacement
25537U	120VDC/72RMS ISO	No longer supported	no replacement
25537V	115VAC ISOIN SCM	No longer supported	no replacement
25537W	230VAC ISO INSCM	No longer supported	no replacement
25539A	ARC SUPRES BLANK	No longer supported	no replacement
25539E	30VDC ARC SUPRES	No longer supported	no replacement
25539G	24VAC ARC SUPRES	No longer supported	no replacement
25539H	115VAC ARCSUPRES	No longer supported	no replacement
25539J	230VAC ARCSUPRES	No longer supported	no replacement
25540A	ANA SCM BLANK	No longer supported	no replacement
25540B	ANA SCM FILTER	No longer supported	no replacement
25540C	ANA SCM 4-20MA	No longer supported	no replacement
25540D	ANSCMFILTR4-20MA	No longer supported	no replacement
25543N	60DC/42AC ISOSCM	No longer supported	no replacement
25544A	VMOS NON ISO SCM	No longer supported	no replacement
25544B	5VPCNONISOOUTSCM	No longer supported	no replacement
25544C	12DCNONISOOUTSCM	No longer supported	no replacement
25545P	120VACISOSSRLY	No longer supported	no replacement
25546B	5 VLT NONISO OUT	No longer supported	no replacement
25550A	CABLE; DIG-TERM	No longer supported	no replacement
25550B	CABLE;DIG-UNTERM	No longer supported	no replacement
25551A	CABLS;ANALGTERM	No longer supported	no replacement
25551B	CABLS;ANALGUNTR	No longer supported	no replacement
25555A	FWA PANEL KIT	No longer supported	no replacement
25558A	STAT IND LED;RD	No longer supported	no replacement
25558B	STAT IND LED GRN	No longer supported	no replacement
25558C	STAT IND LED YLW	No longer supported	no replacement
25558D	C LOOP TERM MOD	No longer supported	no replacement
25558E	STATINDICAT NEON	No longer supported	no replacement
25572B	PWR SUPPLY PNL MT	No longer supported	no replacement
25572C	CABLS FOR 2250	No longer supported	no replacement
25575B	FWA EXPAN CABINT	No longer supported	no replacement
25575C	MCU EXPAND CAB	No longer supported	no replacement
25577B	NEMA CABINET	No longer supported	no replacement
25578A	L BACPLANE;RACK	No longer supported	no replacement
25578B	LBACKPLANE;PANEL	No longer supported	no replacement
25581A	1000 AUTO LIB	No longer supported	no replacement
25581R	RGT TO SNGL COPY	No longer supported	no replacement
25582A	9800 AUTO LIB	No longer supported	no replacement
25585A	2250 MANUAL SET	No longer supported	no replacement
25594A	TRC WITH CABLE	No longer supported	no replacement
25595A	DIAGNOSTIC SOFWR	No longer supported	no replacement
25599A	2250 SRVC CLASS	No longer supported	no replacement
27013A	Fiat System Diagnostic Computer	No longer supported	
27013B	Fiat SDC Diagnostic System	No longer supported	
27013C	Fiat SDC Test System	No longer supported	
27070B	Rover Testbook	No longer supported	
27070C	Rover TestBook 486	No longer supported	
27080B	Rover Dealer System	No longer supported	
27080C	Rover DISCUS System	No longer supported	
28601A	HP 2250 USER CRS	No longer supported	no replacement
28667A	Real-time Interface Card (RTI).	No longer supported	no replacement
28668A	Real-Time Interface Card HP9000	No longer supported	no replacement
28671A	Real-Time Interface Developer's Kit	No longer supported	no replacement
28671R	Real-Time Interface Developer's Kit	No longer supported	no replacement
28672A	8-channel Asynchronous Serial SBX Card.	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
29403B	RACK CABINET	No longer supported	no replacement
29404B	RACK CABINET	No longer supported	no replacement
29405B	RACK CABINET	No longer supported	no replacement
29406B	RACK CABINET	No longer supported	no replacement
29407B	RACK CABINET	No longer supported	no replacement
29430B	30" RACK CABINET	No longer supported	no replacement
29431B	56" RACK CABINET	No longer supported	no replacement
29431F	56"CABINET FOR A	No longer supported	no replacement
30037A	ASYNCH REPEATER	No longer supported	no replacement
32270DS	SSS GERMAN PM	No longer supported	no replacement
32312DM	COPY GER. HPGA	No longer supported	no replacement
33300A	Attenuator, 0-70 dB	No longer supported	
33300B	Attenuator, 0-70 dB	No longer supported	
33300C	Attenuator, 0-70 dB	No longer supported	
33300D	Attenuator, 0-70 dB	No longer supported	
33301A	Attenuator, 0-42 dB	No longer supported	no replacement
33301B	Attenuator, 0-42 dB	No longer supported	no replacement
33301C	Attenuator, 0-42 dB	No longer supported	no replacement
33301D	Attenuator, 0-42 dB	No longer supported	no replacement
33304A	Attenuator, 0-11 dB	No longer supported	
33304C	Attenuator, 0-11 dB	No longer supported	
33305A	Attenuator, 0-110 dB	No longer supported	
33305C	Attenuator, 0-110 dB	No longer supported	
33311A	Coaxial switch, SPDT; dc to 4 GHz, 24 V	Currently supported	8762A
33311B	Coaxial switch, SPDT; dc to 18 GHz, 24 V	Currently supported	8762B
33311C	Coaxial Switch, SPDT	No longer supported	8762C.
33312A	Switch, Coaxial; DC-4 GHz; 4-Port	No longer supported	8763A
33312B	Coaxial Switch, 4 port	Currently supported	8763B
33312C	Coaxial Switch, 4 port	No longer supported	8763C
33313A	Switch, Coaxial; DC-4 GHz; 5-Port	Currently supported	8764A
33313B	Coaxial switch, 5 port	Currently supported	8764B
33313C	Coaxial Switch, 5 port	Currently supported	8764C
33314A	Switch, coax, 4GHz, 1 Pole 2 Throw	Currently supported	8765A
33314B	Switch, Coax, 20GHz, 1 Pole 2 Throw	Currently supported	8765B
33314C	Switch, Coax, 26.5GHz, 1 Pole 2 Throw	No longer supported	8765C
33314D	Switch, Coaxial, SPDT, 40GHz	Currently supported	8765D
33320A	Manual Step Attenuator	Currently supported	8494A
33320B	Manual 1 dB OEM step attenuator	Currently supported	8494B
33320G	Programmable step attenuator, dc 4 GHz	Currently supported	8494G
33320H	Programmable step attenuator, dc-18 GHz	Currently supported	8494H
33321A	Manual Step Attenuator	No longer supported	8495A
33321B	Manual Step Attenuator	No longer supported	8495B
33321D	Manual Step Attenuator	No longer supported	8496A
33321G	Programmable Step Attenuator	Currently supported	8495G
33321H	Programmable 10 dB OEM step attenuator	Currently supported	8495H
33321K	Programmable step attenuator; dc-26.5GHz	Currently supported	8495K
33322A	Step Attenuator	No longer supported	8496A
33322B	Step Attenuator	No longer supported	8496B
33322G	Programmable Step Attenuator	Currently supported	8496G
33322H	Programmable step attenuator; 110 dB max	Currently supported	
33323K	Programmable Step Attenuator	Currently supported	8497K
33324K	Attn, Step 11dB, 26.5GHz, 1dB Steps Prog	Currently supported	84904K
33324L	Attn, Step 11dB,40GHz, 1dB Steps, Progr	Currently supported	84904L
33326K	Attn, 90dB, 26GHz.	Currently supported	84906K

Product	Description	Support Status as of 1 May	Replacement Information
33326L	Attn,Step 90dB,40GHz, 10dB Steps, Progra	Currently supported	84906L
33327K	Attn,Step 70dB,26GHz 10dB Steps. Program	Currently supported	84907K
33327L	Attn,Step 70dB,40GHz 10dB Steps. Program	Currently supported	84907L
33330E	Detector, coaxial, 2.4mm(m), .01-50 Ghz	No longer supported	8474E
33331D	Detector, coaxial, .0001 2 GHz	No longer supported	8471D
33331E	Detector, Coaxial, .0001 to 12.4 Ghz	No longer supported	8471E
33334B	Detector, Coaxial, .01 18 GHz, Input	No longer supported	8474B
33334C	Detector, Coaxial; .01 33 GHz	No longer supported	8474C
33334D	Detector, Coaxial, 2.92mm Connector	No longer supported	8474D
33334E	Detector, Coaxial; .01 50 GHz	No longer supported	8474E
33336C	Detector, Directional, 3.5mm Connectors	Currently supported	83036C
33340A	Coaxial Attenuator	No longer supported	8493A
33340B	Coaxial Attenuator	No longer supported	8493B
33340C	Coaxial Attenuator	No longer supported	8493C
33340D	Coaxial Fixed Attenuator, DC-50 GHz	No longer supported	8490D
33363K	Switch, 1P3T	No longer supported	8766K
33364K	Switch, 1P4T	No longer supported	8767K
33365K	Switch, 1P5T	No longer supported	8768K
33366K	Switch, 1P6T	No longer supported	8769K
34110A	Soft carrying case for Systems II half	No longer supported	no replacement
34111A	HI-VOLTAGE PROBE	No longer supported	34136A
34112A	TOUCH-HOLD PROBE	No longer supported	no replacement
34113A	TEST TRIG INTRFC	No longer supported	no replacement
34114A	TEST SRCE INTRFC	No longer supported	no replacement
34115A	LOGIC TEST ROM	No longer supported	no replacement
34116A	BNC TO TRIAX	No longer supported	no replacement
34117A	TRIAx TEE	No longer supported	no replacement
34501A	ARMATURE MUX/SE	No longer supported	VXI & 3499A
34501AT	Extra Terminal Block	No longer supported	no replacement
34501B	ARMATURE MUX W/ST	No longer supported	VXI & 3499A
34501BR	Armature Mux W/ST	No longer supported	
34501BT	Extra Terminal Block	No longer supported	no replacement
34501D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34501M	ARMATURE MATRIX	No longer supported	VXI & 3499A
34501MT	EXTRA TERM BLOCK	Currently supported	no replacement
34501T	TCPLE MUX-ARMATR	Currently supported	34970A, 3499A
34501TT	EXTRA TERM BLOCK	Currently supported	
34502A	REED MUX W/SE	No longer supported	VXI & 3499A
34502AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34502B	REED MUX W/ ST	No longer supported	VXI & 3499A
34502BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34502M	REED MATRIX	No longer supported	VXI & 3499A
34502T	TCPLE MUX-REED	Currently supported	no replacement
34503A	16 CHANNEL GP RELAY	No longer supported	VXI & 3499A
34503AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34503B	GP RELAY W/ST	No longer supported	VXI & 3499A
34503BR	GP Relay W/ST	No longer supported	
34503BT	EXTRA TERMINAL BLOCK	No longer supported	no replacement
34503D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34504A	COAX MUX W/CT	No longer supported	no replacement
34504AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34504B	COAX MUX W/BH	No longer supported	no replacement
34504BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34504C	COAX MUX W/NT	No longer supported	no replacement
34504D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34505A	RF MUX W/CT	No longer supported	VXI & 3499A
34505AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34505B	RF MUX W/BH	No longer supported	VXI & 3499A

Product	Description	Support Status as of 1 May	Replacement Information
34505BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34505C	RF MUX W/NT	No longer supported	VXI & 3499A
34505CR	RF Mux w/NT	No longer supported	
34505D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34506A	COAX MATRIX W/CT	No longer supported	no replacement
34506AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34506B	COAX MATRIX W/BH	No longer supported	no replacement
34506BR	Coax matrix W/BH	No longer supported	
34506BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34506C	COAX MATRIX W/NT	No longer supported	no replacement
34506CR	Coax Matrix w/NT	No longer supported	
34506D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34507A	MERCURY MUX W/SE	No longer supported	no replacement
34507AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34507B	MERCURY MUX W/ST	No longer supported	no replacement
34507BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34507M	MERCURY MATRIX	No longer supported	no replacement
34507T	TCPLE MUX-MERCURY	Currently supported	no replacement
34508A	75 OHM RF MUX	No longer supported	VXI & 3499A
34508AT	EXTRA TERM BLOCK	Currently supported	no replacement
34508B	75 OHM RF MUX	No longer supported	VXI & 3499A
34508BT	EXTRA TERM BLOCK	Currently supported	no replacement
34508C	75 OHM RF MUX	No longer supported	VXI & 3499A
34509A	32 CHANNEL RELAY DRIVER MODULE	No longer supported	VXI & 3499A
34509AT	EXTRA TERMINAL BLOCK FOR 34509A	Currently supported	no replacement
34509B	32 CHANNEL RELAY DRIVER MODULE	No longer supported	VXI & 3499A
34509BT	EXTRA TERMINAL BLOCK FOR 34509B	Currently supported	no replacement
34509C	32 CHANNEL RELAY DRIVER MODULE	No longer supported	VXI & 3499A
34509D	DIAGNOSTIC FIXTURE FOR 34509	No longer supported	no replacement
34510B	8 CHANNEL POWER ACTUATOR MODULE	No longer supported	VXI & 3499A
34510BT	EXTRA TERMINAL BLOCK FOR 34510B	Currently supported	no replacement
34510D	DIAGNOSTIC FIXTURE FOR 34510B	No longer supported	no replacement
34511B	64 CHANNEL ARMATURE RELAY MULTIPLEXER	No longer supported	VXI & 3499A
34511BR	64 Channel Armature Relay Multiplexer	No longer supported	
34511BT	EXTRA TERMINAL BLOCK FOR 34511B	No longer supported	no replacement
34511D	DIAGNOSTIC FIXTURE FOR 34511B/M	No longer supported	no replacement
34511M	64 CHANNEL MATRIX	No longer supported	VXI & 3499A
34511MR	64 Channel Matrix	No longer supported	
34511MT	EXTRA TERMINAL BLOCK FOR 34511M	Currently supported	no replacement
34512C	TRIAxIAL MATRIX MODULE	No longer supported	no replacement
34512CR	Triaxial Matrix Module	No longer supported	
34513C	GENERAL PURPOSE 50 OHM FR MODULE	No longer supported	no replacement
34513CR	General Purpose 50 Ohm Fr Module	No longer supported	
34514C	GENERAL PURPOSE 75 OHM RF MODULE	No longer supported	no replacement
34514CR	General Purpose 75 Ohm RF Module	No longer supported	
34515B	1000 VOLT 10-CHANNEL RELAY MULTIPLEXER	No longer supported	3499A
34515BR	1000 Volt 10-Channel Relay Multiplexer	No longer supported	
34515BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34515D	DIAGNOSTIC TEST FIXTURE	No longer supported	no replacement
34516D	DIAGNOSTIC TEST FIXTURE	No longer supported	no replacement
34516M	8X32 RELAY MATRIX	No longer supported	http://www.agilent.com/find/vxi
34516MR	8X32 Relay Matrix	No longer supported	
34516MT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34516N	4X64 RELAY MATRIX	No longer supported	http://www.agilent.com/find/vxi
34516NR	4x64 Relay Matrix	No longer supported	
34516NT	EXTRA TERMINAL BLOCK	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
34520A	DMM MODULE W/SE	No longer supported	http://www.agilent.com/find/vxi
34520AR	DMM Module w/SE	No longer supported	
34520AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34520B	DMM MODULE W/ST	No longer supported	http://www.agilent.com/find/vxi
34520BR	DMM Module w/ST	No longer supported	
34520BT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34520D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34521A	AC/DC SOURCE MODULE	No longer supported	no replacement
34521AR	AC/DC Source Module	No longer supported	
34521AT	EXTRA TERMINAL BLOCK FOR 34521A	Currently supported	no replacement
34521B	AC/DC SOURCE MODULE	No longer supported	no replacement
34521BR	AC/DC Source Module	No longer supported	
34521BT	EXTRA TERMINAL BLOCK FOR 34521B	No longer supported	no replacement
34521D	DIAGNOSTIC FIXTURE FOR 34521A/B	No longer supported	no replacement
34522A	DIGITAL I/O W/SE	No longer supported	VXI & 3499A
34522AT	EXTRA TERMINAL BLOCK	Currently supported	no replacement
34522B	DIGITAL I/O W/ST	No longer supported	VXI & 3499A
34522BT	EXTRA TERMINAL BLOCK	No longer supported	no replacement
34522D	DIAGNOSTIC FIXTURE	No longer supported	no replacement
34523A	BREADBOARD WITH SOLDER-EYE	No longer supported	no replacement
34523AT	EXTRA TERMINAL BLOCK	No longer supported	no replacement
34523B	BREADBOARD WITH SCREW TERMINAL	No longer supported	no replacement
34523BT	EXTRA TERMINAL BLOCK	No longer supported	no replacement
34524A	4 CHANNEL D/A CONVERTER MODULE	No longer supported	http://www.agilent.com/find/vxi
34524AR	4 Channel D/A Converter Module	No longer supported	
34524AT	EXTRA TERMINAL BLOCK FOR 34524A	Currently supported	no replacement
34524B	4 CHANNEL D/A CONVERTER MODULE	No longer supported	http://www.agilent.com/find/vxi
34524BR	4 Channel D/A converter Module	No longer supported	
34524BT	EXTRA TERMINAL BLOCK FOR 34524B	Currently supported	no replacement
34524D	DIAGNOSTIC FIXTURE FOR 34524A/B	No longer supported	no replacement
34530A	18 GHz 1X2 SWITCH	No longer supported	VXI & 3499A
34530B	26.5 GHz 1X2 SWITCH	No longer supported	VXI & 3499A
34530R	1X2 RELAY RACK MOUNT KIT	No longer supported	no replacement
34530T	TERMINAL BLOCK KIT	Currently supported	no replacement
34531A	1X6 MICROWAVE SWITCH	No longer supported	VXI & 3499A
34531AR	1x6 Microwave Switch	No longer supported	
34531B	1X6 MICROWAVE SWITCH	No longer supported	VXI & 3499A
34531BR	1X6 Microwave Switch	No longer supported	
34531R	1X6 RELAY RACK MOUNT KIT	No longer supported	no replacement
34532R	ATTENUATOR RACK MOUNT KIT	No longer supported	no replacement
34550A	CONTROL PANEL	No longer supported	no replacement
34550AR	Control Panel	No longer supported	
34551A	CONTROL PANEL RACK KIT	No longer supported	no replacement
34560A	EXPANSION MODULE	No longer supported	no replacement
34560X	EXPANSION MODULE-3235	No longer supported	no replacement
34562A	CHAINING CABLE	No longer supported	no replacement
34570A	3 METER CABLES	No longer supported	no replacement
34580A	GPIB CONTROLLER FIELD INSTALLATION KIT	No longer supported	no replacement
34581A	MATRIX CABLE KIT	No longer supported	no replacement
34582A	MATRIX CABLE KIT	No longer supported	no replacement
34585A	50 OHM terminators	No longer supported	no replacement
34586A	75 OHM TERMINATRS	No longer supported	no replacement
34587A	75 OHM COAX CABLE KIT	No longer supported	no replacement
34587B	50 OHM COAX CABLE KIT	No longer supported	no replacement
34588A	75 OHM COAX CABLE KIT	No longer supported	no replacement
34588B	50 OHM COAX CABLE KIT	No longer supported	no replacement
34589A	75 OHM COAX CABLE KIT	No longer supported	no replacement
34589B	50 OHM COAX CABLE KIT	No longer supported	no replacement
34590A	75 OHM COAX CABLE KIT	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
34590B	50 OHM COAX CABLE KIT	No longer supported	no replacement
34591A	Quick Connect Fixture	No longer supported	no replacement
34592A	Interface Connector Assembly (ICA)	No longer supported	no replacement
34593A	BNC feedthrough panel for 3235 or 34592A	No longer supported	no replacement
34593AT	Extra Terminal Block	Currently supported	no replacement
34593B	BNC FEEDTHRU PANEL	No longer supported	no replacement
34593BT	Extra Terminal Block	Currently supported	no replacement
34593C	BNC Feedthrough Panel	No longer supported	no replacement
34594A	Low Frequency Feedthrough Panel	No longer supported	no replacement
34594B	Low Frequency Feedthrough Panel	No longer supported	no replacement
34595A	CABINET (115V)	No longer supported	E3661B opt. AW3
34595B	CABINET (230V)	No longer supported	E3661B opt. AW5
34596A	CABINET (115V)	No longer supported	E3661B opt. AW3
34596B	CABINET (230V)	No longer supported	E3661B opt. AW5
34597A	SIMPLATE BOARD-TEST FIXTURE FOR 3235	No longer supported	no replacement
34701A	DC VOLTMETER	No longer supported	34401A
34702A	MULTIMETER	No longer supported	34401A
34703A	DC/DCA/ METER	No longer supported	34401A
34720A	BATTERY MODULE	No longer supported	no replacement
34721B	BCD MODULE	No longer supported	no replacement
34740A	DISPLAY	No longer supported	
34750A	DISPLAY	No longer supported	34401A
34800A	FUNCTIONAL TEST SOFTWARE	No longer supported	no replacement
34800R	FUNCTIONAL TEST SOFTWARE R-T-U	No longer supported	no replacement
34801A	FUNCTIONAL TEST SOFTWARE	No longer supported	no replacement
34801B	FUNCTIONAL TEST SOFTWARE	No longer supported	no replacement
34801R	FUNCTIONAL TEST SOFTWARE R-T-U	No longer supported	no replacement
34801T	FUNCTIONAL TEST SOFTWARE R-T-U	No longer supported	no replacement
34802A	FUNCTIONAL TEST SOFTWARE	No longer supported	no replacement
34802R	FUNCTIONAL TEST SOFTWARE R-T-U	No longer supported	no replacement
34802U	FUNCTIONAL TEST SOFTWARE UPGRADE KIT	No longer supported	no replacement
34803A	FUNCTIONAL TEST SOFTWARE	No longer supported	no replacement
34803B	FUNCTIONAL TEST SOFTWARE	No longer supported	no replacement
34803R	FUNCTIONAL TEST SOFTWARE R-T-U	No longer supported	no replacement
34803U	FUNCTIONAL TEST SOFTWARE UPGRADE KIT	No longer supported	no replacement
34804A	FUNCTIONAL TEST MANAGER 300 (REV.3.0)	No longer supported	no replacement
34804C	FUNCTIONAL TEST MANAGER PC	No longer supported	no replacement
34804D	FUNCTIONAL TEST MANAGER PC	No longer supported	no replacement
34804E	FUNCTIONAL TEST MANAGER FOR HP-UX.	No longer supported	no replacement
34804F	UPGRADES FTM/300 TO WORK ON HP-UX.	No longer supported	no replacement
34804M	FTM RIGHT-TO-USE	No longer supported	no replacement
34804Q	FTM RIGHT-TO-USE PACKAGE	No longer supported	no replacement
34804R	FTM RIGHT-TO-USE	No longer supported	no replacement
34804U	FTM UPGRADE KIT	No longer supported	no replacement
34805A	FUNCTIONAL TEST MANAGER 300 (REV.3.0)	No longer supported	no replacement
34805B	FUNCTIONAL TEST MANAGER 300 (REV.3.0)	No longer supported	no replacement
34805C	FUNCTIONAL TEST MANAGER PC	No longer supported	no replacement
34805D	FUNCTIONAL TEST MANAGER PC	No longer supported	no replacement
34805M	FTM RIGHT-TO-USE	No longer supported	no replacement
34805Q	FTM RIGHT-TO-USE PACKAGE	No longer supported	no replacement
34805R	FTM RIGHT-TO-USE	No longer supported	no replacement
34805U	FTM UPGRADE KIT	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
34806A	FTM/300. Media is 3.5 inch disk.	No longer supported	no replacement
34806B	FTM/300. Media is 5.25 inch disk.	No longer supported	no replacement
34806C	FTM/PC. Media is 3.5 inch disk.	No longer supported	no replacement
34806D	FTM/PC. Media is 5.25 inch disk.	No longer supported	no replacement
34806E	FTM for HP-UX. Media is 1/4 inch tape.	No longer supported	no replacement
34806G	HP FTM LTU	No longer supported	no replacement
34806M	FTM Right-to-Use License.	No longer supported	no replacement
34806Q	Five FTM Right-to-Use Licenses.	No longer supported	no replacement
34806T	FTM/300 Upgrade. Media is 3.5 inch disk.	No longer supported	no replacement
34806U	FTM/300 Upgrade. Media is 5.25 in. disk.	No longer supported	no replacement
34806X	FTM Upgrade HP-UX. Media is 1/4 in. tape	No longer supported	no replacement
34806Y	FTM/PC Upgrade. Media is 3.5 inch disk.	No longer supported	no replacement
34806Z	FTM/PC Upgrade. Media is 5.25 inch disk.	No longer supported	no replacement
34810A	HP BenchLink Scope software	No longer supported	intuilink (free software)
34810U	HP BenchLink Scope 1.5 Upgrade	No longer supported	intuilink (free software)
34908AR	40-channel Single-Ended Multiplexer	No longer supported	
34970AR	Data Acquisition/Switch Unit	No longer supported	
35210A	4 Meter HP/HP Extension Cable	No longer supported	no replacement
35210B	10 Meter HP/HP Extension Cable	No longer supported	no replacement
35211A	2 Meter Bruel-and-Kjaer to Adapter	Currently supported	no replacement
35212A	2 Meter ACO Pacific to HP Adapter Cable	No longer supported	no replacement
35224B	7-pin Microphone Preamplifier	No longer supported	no replacement
35230A	Sound Intensity Probe w/out microphones	No longer supported	no replacement
35233A	Pistonphone Calibrator	No longer supported	no replacement
35234A	Calibrator Kit	No longer supported	no replacement
35235A	Barometer	No longer supported	no replacement
35236A	Cavity Calibrator	No longer supported	no replacement
35237A	Matched Pair 1/2 Inch Microphones	No longer supported	no replacement
35237B	Matched Pair 1/4 Inch Microphones	No longer supported	no replacement
35239A	B&K Type 3545A Probe Adapter Kit	No longer supported	no replacement
35602A	AMPLIFIER	No longer supported	no replacement
35605A	720 mm System Rack for 35650A mainframes	No longer supported	no replacement
35606A	1600 mm System Rack for 35650A mainframe	No longer supported	E3661B
35607A	DAC Shutdown Panel	Currently supported	no replacement
35615D	DESIGN SOFTWARE PACKAGE	No longer supported	no replacement
35615E	SOLIDS	No longer supported	no replacement
35615F	NUMERICAL CONTROL	No longer supported	no replacement
35615G	OPTIMOLD PACKAGE	No longer supported	no replacement
35615H	MOLDBASE ONLY	No longer supported	no replacement
35615J	SIMUFLOW ONLY	No longer supported	no replacement
35615K	SIMUCOOL ONLY	No longer supported	no replacement
35615M	FLAT PATTERN	No longer supported	no replacement
35615N	IGES	No longer supported	no replacement
35615P	FINITE ELEMENT MODELING	No longer supported	no replacement
35615R	AGILE COMPILER	No longer supported	no replacement
35615S	HP/GRAFTEK MECHANICAL ENGR DESIGN SYSTEM	No longer supported	no replacement
35615T	SYMBOLS	No longer supported	no replacement
35615U	SURFACE SHADING	No longer supported	no replacement
35617D	DESIGN SOFTWARE PACKAGE	No longer supported	no replacement
35617E	SOLIDS	No longer supported	no replacement
35617F	NUMERICAL CONTROL	No longer supported	no replacement
35617G	OPTIMOLD	No longer supported	no replacement
35617H	MOLDBASE ONLY	No longer supported	no replacement
35617J	SIMUFLOW ONLY	No longer supported	no replacement
35617K	SIMUCOOL ONLY	No longer supported	no replacement
35617M	FLAT PATTERN	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
35617N	IGES	No longer supported	no replacement
35617P	FINITE ELEMENT MODELING	No longer supported	no replacement
35617R	AGILE COMPILER	No longer supported	no replacement
35617S	MECHANICAL ENGINEERING DESIGN SYSTEM	No longer supported	no replacement
35617T	SYMBOLS	No longer supported	no replacement
35617U	SURFACE SHADING	No longer supported	no replacement
35617V	2-AXIS LATHE	No longer supported	no replacement
35620A	STRUCT ANAL SWE	No longer supported	no replacement
35621A	MODAL ANAL SWE	No longer supported	no replacement
35622A	MODAL EXTENSION	No longer supported	no replacement
35630A	HP VISTA Software	No longer supported	35630B
35630B	HP VISTA Measurement Software	No longer supported	no replacement
35630BR	HP VISTA Right to Copy	No longer supported	no replacement
35630R	HP Vista Right To Copy	No longer supported	35630BR
35631A	HP SINE Software	No longer supported	35631B
35631B	HP SINE Swept Sine Measurement Software	No longer supported	35670A
35631BR	HP SINE Right To Copy	No longer supported	no replacement
35631R	HP-Sine Right To Copy	No longer supported	35631BR
35632A	HP Modal Data Manager Software	No longer supported	no replacement
35632B	HP Modal Data Manager	No longer supported	35670A
35632BR	HP MDM Right to Copy	No longer supported	no replacement
35632R	HP Modal Data Manager Right To Copy	No longer supported	no replacement
35633A	HP 3565S Software Bundle	No longer supported	no replacement
35633B	HP 3565S Software Bundle	No longer supported	no replacement
35633BR	HP 3565S Software Bundle Right to Copy	No longer supported	no replacement
35633R	HP 3565S Software Bundle Right To Copy	No longer supported	no replacement
35634A	PC Measurement Software for 3566A/67A	Currently supported	35670A
35635T	E1485 SW Programming Tools and Training	No longer supported	no replacement
35636A	Order Tracking Software for 3566A/67A	Currently supported	35670A
35637A	Swept-sine Software for 3566A/67A	Currently supported	35670A
35638A	Real-Time Octave Software for 3566/67A	Currently supported	35670A
35639A	MS-Windows-based Measurement Data Viewer	No longer supported	free on PLAR FTP site
35640S	16-Channel Hardware Bundle	Currently supported	4-4channel 35670As
35641S	40-Channel MIMO Hardware Bundle	Currently supported	multiple 35670As
35645S	8-Channel Vib. Control Hardware Bundle	No longer supported	no replacement
35646S	8-Channel Vib. Control Hardware Bundle	No longer supported	2-4 channel 35670As
35647S	4-Channel Vib. Control Hardware Bundle	No longer supported	1-4 channel 35670A
35651A	Signal Processing/HP-IB Module	No longer supported	35670A
35651B	Signal Processing Module	No longer supported	no replacement
35651U	35651B Signal Processing Module	product family sold	http://www.agilent.com/find/vxitechnologies
35653A	Source/Calibration Module	product family sold	http://www.agilent.com/find/vxitechnologies
35654A	Advanced Signal Processing Module	product family sold	http://www.agilent.com/find/vxitechnologies
35654U	Advanced Signal Processor Module	product family sold	http://www.agilent.com/find/vxitechnologies
35655BR	4-Channel Input Module	Currently supported	
35656A	Programmable DAC Module	No longer supported	no replacement
35657A	Parallel Interface Module	No longer supported	no replacement
35658AR	Tachometer/Trigger Module	Currently supported	
35659AR	SCSI Interface Module	Currently supported	
35659U	SCSI Interface Module Disk Upgrade	Currently supported	no replacement
35660A	2-Channel Dynamic Signal Analyzer	No longer supported	35670A
35665AR	Rmkt Dual Channel Dynamic Signal Analyzr	No longer supported	
35665S	35665S System consisting of:	No longer supported	no replacement
35665U	HP 35665A Dyn. Sig. AnlZR. Opt.Upgr.Kits	No longer supported	35670A
35670S	35670S System consisting of:	No longer supported	no replacement
35675A	Accuracy Enhancement Software	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
35676A	Reflection/Transmission Test Kit	No longer supported	
35676B	REFLECTION/TRANSMISSION TEST KIT	No longer supported	
35677A	SParameter Test Set	No longer supported	
35677AR	S-Parameter Test Set	No longer supported	
35677B	SParameter Test Set	No longer supported	
35677BR	S-Parameter Test Set	No longer supported	
35678A	Type-N Calibration Kit	No longer supported	
35678B	Type-N Calibration Kit	No longer supported	
35679A	Type-N Cable Set	No longer supported	
35679B	Type-N Cable Set	No longer supported	
35680A	HP Instrument BASIC Language	No longer supported	no replacement
35680R	Right-To-Copy HP 35680A Instrument BASIC	No longer supported	no replacement
35681A	Analysis Pack for the HP 35680A	No longer supported	no replacement
35681R	Right to Copy HP 35681A Analysis Pack	No longer supported	no replacement
35687A	3587S Signal Analyzer Operating Software	No longer supported	89600 or E3238S
35687B	3587 Realtime Signal Analysis Sys. SW	Currently supported	89600 or E3238S
35687U	Upgrade kits for 35687B Software	Currently supported	no replacement
35688B	E3238S Signals Development Sys Software	Currently supported	35688D
35688U	Upgrade kits for 35688B Software	Currently supported	35688CU
35689A	50 Ohm S-Parameter Test Set for HP 3589A	No longer supported	
35689AR	50 Ohm S-Parameter Test Set for 3589A	Currently supported	
35689B	75 Ohm S-Parameter Test Set for HP 3589A	No longer supported	
37080A	System software.	No longer supported	no replacement
37080B	SYSTEM SOFTWARE FOR 3708S SYSTEM.	No longer supported	no replacement
37080C	3708S SYSTEM SOFTWARE	No longer supported	no replacement
37080R	RIGHT TO REPRODUCE 37080 SOFTWARE	No longer supported	no replacement
37203AR	HP-IB Extender	No longer supported	no replacement
37204AR	high speed multi-point HP-IB extender	No longer supported	
37204BR	HP-IB extender for HP 256x & 268x.	No longer supported	
37210T	4800 BPS MODEM	No longer supported	no replacement
37212A	1200 BAUD MODEM	No longer supported	no replacement
37215A	MODEM INTFE CARD	No longer supported	no replacement
37216A	I.F. CARD	No longer supported	no replacement
37220T	9600 BPS MODEM	No longer supported	no replacement
37222A	INTEGRAL MODEM	No longer supported	no replacement
37230A	SHORT HAUL MODEM	No longer supported	no replacement
37264A	BAND DEF FILTER	No longer supported	no replacement
37265A	BAND STOP FILTER	No longer supported	no replacement
37266A	BAND PASS FILTER	No longer supported	no replacement
37267A	ADAPTER CASE	No longer supported	no replacement
37268A	DUMMY PLUG IN	No longer supported	no replacement
37269A	INPUT MODULE	No longer supported	no replacement
37280A	Instrument Link Unit	No longer supported	no replacement
37281A	AC Mainframe	No longer supported	no replacement
37282A	DC Mainframe	No longer supported	no replacement
37283A	DPM Processor Card	No longer supported	no replacement
37285A	2Mb/s Line Monitor Card	No longer supported	no replacement
37286A	8Mb/s Line Monitor Card	No longer supported	no replacement
37287A	34Mb/s Line Monitor Card	No longer supported	no replacement
37288A	140Mb/s Line Monitor Card	No longer supported	no replacement
37289A	Customer premises housing for D.P.M.	No longer supported	no replacement
37301A	EXT LO PLUG-IN	No longer supported	no replacement
37461A	DISPLAY	No longer supported	no replacement
37480A	OpenView Data Line Monitor.	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
37701BR	T1/datacom tester-not for sale in EEC	No longer supported	
37702AR	Ditital data tester-not for sale in EEC	No longer supported	
37704AR	SONET 622MB/s tester-not for sale in EEC	No longer supported	
37714A	PDH/SDH/ATM test set (mainframe only)	No longer supported	OmniBER OTN
37714AR	PDH/SDH/ATM test set (mainframe only)	No longer supported	
37714C	PDH/SDH/ATM Test SEt (Colour)	No longer supported	OmniBER OTN
37716A	Tx/Rx PDH BER Test Set	No longer supported	OmniBER OTN
37717A	PDH/SDH/ATM&Jitter Test SetMframe only	No longer supported	OmniBER OTN
37717AR	PDH/SDH/ATM&Jitter Test Set-Mframe Only	No longer supported	
37717B	Communications Performance Analyzer	No longer supported	OmniBER OTN
37717BR	Communications Performance Analyzer	No longer supported	
37717CR	Communications Performance analyzer	Currently supported	
37721AR	Digital transmission analyzer, rugged	Currently supported	
37722AR	Telecom analyzer	No longer supported	
37724AR	Synchronous digital hierarchy test set	No longer supported	
37741AR	T1 Handheld Test Set	No longer supported	
37742AR	2 Mb/s (E1) handheld BER test set	No longer supported	
37771AR	STS Mux & Elect. I/F plug in module	No longer supported	
37772AR	52/155MB/s Optical Module with Adaptor	No longer supported	
37776AR	622 MB/s Optical Module with Adapter	No longer supported	
37778A	SDH (STM-1/16) test set (mainframe only)	No longer supported	OmniBER OTN
37900DR	Signaling Test Set	No longer supported	
37910AR	Slave Signaling Card	Currently supported	
37911A	2.048 Mbit/s Interface Card	No longer supported	no replacement
37912A	1.544 Mbit/s (DS-1) Interface Card.	No longer supported	no replacement
37914A	DS-0, V.35 Interface Card.	No longer supported	no replacement
37915AR	2.048 MB/s signaling interface card	Currently supported	
37916AR	1.544 MB/S signaling interface card	Currently supported	
37918AR	V35/DSO/DSO-A Signaling Interface Card	Currently supported	
37923A	Monitor only software.	No longer supported	no replacement
37924A	Monitor & emulate software.	No longer supported	no replacement
37925A	Signaling Variants Software for 37900B/C	No longer supported	no replacement
38001A	HPIB DM INTERFAC	No longer supported	no replacement
38002A	3851A INTERFACE	No longer supported	no replacement
38003A	INTERFACE/CHARG	No longer supported	no replacement
38004A	PWR-I/O MODULE	No longer supported	no replacement
38020A	CDS SOFTWARE	No longer supported	no replacement
38041A	PLOTTER PAC	No longer supported	no replacement
38042A	SURVEYING VOL A	No longer supported	no replacement
38042AE	VOL A EXCHANGE	No longer supported	no replacement
38042AR	W/38042A;B;ORC	No longer supported	no replacement
38042B	SURVEYING VOL B	No longer supported	no replacement
38042C	SURVEYING VOL C	No longer supported	no replacement
38042CE	VOL C EXCHANGE	No longer supported	no replacement
38042CP	VOL C PERIPH ADD	No longer supported	no replacement
38042CR	VOL C REPEAT SYS	No longer supported	no replacement
38042CU	38042 UPDATE	No longer supported	no replacement
38042E	DATA COLL VOL E	No longer supported	no replacement
38042EE	VOL E EXCHANGE	No longer supported	no replacement
38042EU	38042 UPDATE	No longer supported	no replacement
38042F	PLOTTER PAC	No longer supported	no replacement
38042FE	VOL F EXCHANGE	No longer supported	no replacement
38042FR	VOL F REPEAT SYS	No longer supported	no replacement
38042FU	38042 UPDATE	No longer supported	no replacement
38042G	PIPE NET VOL G	No longer supported	no replacement
38042GE	VOL G EXCHANGE	No longer supported	no replacement
38042H	EARTHWORK PAC	No longer supported	no replacement
38042HE	EARTHWORK EXCH	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
38042HR	EARTHWORK REPEAT	No longer supported	no replacement
38045A	3845A SURV VOL1	No longer supported	no replacement
38050A	SYSTEM SOFTWARE	No longer supported	no replacement
4062UXR	Semiconductor Process Control System	No longer supported	
41424AR	V Source/V Monitor Unit	No longer supported	
41425AR	Analog feedback unit	No longer supported	
41801A	PROBE POWER DIVIDER	Currently supported	no replacement
41900AR	PI-Network Test Fixture	Currently supported	
41900U	Upgrade Kit for the 41900A	Currently supported	no replacement
41901AR	SMD PI-Network Test Fixture	Currently supported	
41902A	Economy PI-network test fixture	No longer supported	41900A or 41901A
41902AR	Economy PI-network test fixture	No longer supported	
41902U	Upgrade kit for the HP 41902A	No longer supported	no replacement
41941A	IMP PROBE KIT	Currently supported	no replacement
41941AR	IMP Probe Kit	Currently supported	
41941B	IMP PROBE KIT	Currently supported	no replacement
41941BR	Imp Probe Kit	Currently supported	
41951A	IMPEDANCE TEST KIT	Currently supported	no replacement
41951AR	Impedance Test Kit	Currently supported	
41952A	TRANSMISSION/REFLECTION TEST SET	Currently supported	no replacement
41952AR	Transmission/Reflection Test Set	Currently supported	
41952B	TRANSMISSION/REFLECTION TEST SET	Currently supported	no replacement
41952BR	Transmission/Reflection Test Set	Currently supported	
42031A	1m ohm Standard Resistor	Currently supported	no replacement
42032A	10m ohm Standard Resistor	Currently supported	no replacement
42033A	100m ohm Standard Resistor	Currently supported	no replacement
42034A	1 ohm Standard Resistor	Currently supported	no replacement
42035A	10 ohm Standard Resistor	Currently supported	no replacement
42036A	100 ohm Standard Resistor	Currently supported	no replacement
42037A	1k ohm Standard Resistor	Currently supported	no replacement
42038A	10k ohm Standard Resistor	Currently supported	no replacement
42039A	100k ohm Standard Resistor	Currently supported	no replacement
42040A	Four-Terminal Pair Resistor Set	Currently supported	no replacement
42050A	Adjustment Tool	Currently supported	no replacement
42100A	FOUR-TERMINAL PAIR RESISTOR SET	Currently supported	no replacement
42842AR	Bias Current Test Fixture	Currently supported	
42842BR	Bias Current Test Fixture	Currently supported	
42842CR	Bias Current Test Fixture	Currently supported	
42851A	PRECISION Q ADAPTER	Currently supported	no replacement
44401A	LOW THERMAL MUX	No longer supported	no replacement
44402A	ACTUATOR ASSY	No longer supported	no replacement
44403A	9 CH THERM ASSY	No longer supported	no replacement
44404A	20 CH THERM ASSY	No longer supported	no replacement
44405A	19 CH THERM ASSY	No longer supported	no replacement
44413A	HIGH SPEED CNTR	No longer supported	no replacement
44414A	Four thermistor pack	No longer supported	34308A (10 kohm)
44416A	3467A/REAR FEET	No longer supported	no replacement
44420A	5 1/2 DIGIT DVM	No longer supported	34970A
44420AR	5 1/2 Digit DVM	No longer supported	
44421A	RELAY MULTPLXR	No longer supported	34970A
44421AR	Relay Multiplexer	No longer supported	
44422A	Software Compensation.	No longer supported	34970A
44422AR	Software compensation	No longer supported	
44422B	B-Type Hardware Compensation	No longer supported	34970A
44422E	E-Type Hardware Compensation	No longer supported	34970A
44422J	J-Type Hardware Compensation	No longer supported	34970A
44422K	K-Type Hardware Compensation	No longer supported	34970A
44422R	R-Type Hardware Compensation.	No longer supported	34970A
44422S	S-Type Hardware Compensation	No longer supported	34970A

Product	Description	Support Status as of 1 May	Replacement Information
44422T	T-Type Hardware Compensation	No longer supported	34970A
44423A	20 CHNL FET MUX	No longer supported	http://www.agilent.com/find/vxi
44423AR	20 Chnl FET Mux	No longer supported	
44425A	ISO DIG INPUT	No longer supported	no replacement
44425AR	ISO Digital Input	No longer supported	
44426A	100KHZ COUNTER	No longer supported	no replacement
44426AR	100 KHz Counter	No longer supported	
44427A	120 OHM STR/BRDG	No longer supported	no replacement
44427AR	120 OHM STR/BRDG	No longer supported	
44427B	350 OHM STR/BRDG	No longer supported	no replacement
44427BR	350 Ohm STR/BRDG	No longer supported	
44428A	ACTUATOR/DIG OUT	No longer supported	no replacement
44428AR	Actuator/Dig Out	No longer supported	
44429A	DUAL VOLTAGE DAC	No longer supported	no replacement
44429AR	Dual Voltage DAC	No longer supported	
44430A	DUAL CURRENT D/A	No longer supported	no replacement
44430AR	Dual Current D/A	No longer supported	
44431A	HI VLT ACTUATOR	No longer supported	34970A
44431AR	HI VLT Actuator	No longer supported	
44432A	BREADBOARD CARD	No longer supported	no replacement
44432AR	Breadboard card	No longer supported	
44446B	LOTUS MEASURE FOR LOTUS 1-2-3.	No longer supported	no replacement
44447B	LOTUS MEASURE FOR LOTUS SYMPHONY	No longer supported	no replacement
44451A	DA&C SOFTWARE	No longer supported	no replacement
44451B	DA&C SOFTWARE	No longer supported	no replacement
44453A	3054S SYSTEM DOC	No longer supported	no replacement
44454A	3054C SOFTWARE	No longer supported	no replacement
44456A	SYSTEM SOFTWARE	No longer supported	no replacement
44456B	SYSTEM SOFTWARE	No longer supported	no replacement
44456R	LICENSE TO REPRODUCE SYSTEM SOFTWARE	No longer supported	no replacement
44457A	DA&C SOFTWARE	No longer supported	no replacement
44457B	DA&C SOFTWARE	No longer supported	no replacement
44458A	DACQ/300 DATA ACQUISITION MANAGER	No longer supported	no replacement
44458B	DACQ/300 DATA ACQUISITION MANAGER	No longer supported	no replacement
44458R	DACQ/300 RIGHT TO REPRODUCE	No longer supported	no replacement
44458U	DACQ/300 Software Upgrade	No longer supported	no replacement
44458V	DACQ/300 UPGRADE KIT	No longer supported	no replacement
44459A	DACQ/PC DATA ACQUISITION MANAGER/PC	No longer supported	no replacement
44459B	DACQ/PC DATA ACQUISITION MANAGER/PC	No longer supported	no replacement
44459R	DACQ/PC RIGHT TO REPRODUCE	No longer supported	no replacement
44459U	DACQ/PC Software Upgrade	No longer supported	no replacement
44460A	DACQ/UX Data Acquisition Mgr. Software	No longer supported	no replacement
44460R	Right To Copy License for DACQ/UX S/W	No longer supported	no replacement
44460U	DACQ/UX Software Upgrade	No longer supported	no replacement
44461A	GPIB INSTAL KIT	No longer supported	no replacement
44462A	8 CHANNEL RELAY	No longer supported	34970A
44463A	ANALOG CONNECTOR	No longer supported	no replacement
44464A	BREADBOARD ASSY.	No longer supported	no replacement
44465A	DIGITAL I/O ASSY	No longer supported	no replacement
44466A	DIGITAL CONNECTR	No longer supported	no replacement
44468A	DATA ACQ. PAC	No longer supported	no replacement
44469A	ATTENUATOR SETS	No longer supported	no replacement
44470AR	10 Channel MUX	No longer supported	
44471AR	10 Channel GP Relay	No longer supported	
44472AR	VHF module	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
44473AR	Matrix module	No longer supported	
44474AR	Digital I/O	No longer supported	
44476AR	Microwave switch module for 3488A	No longer supported	
44476BR	Microwave Switch module for 3488A	No longer supported	
44477AR	Form-C Relay Module Mfrd in China	No longer supported	
44478AR	1.3GHz, 50ohm Mux for 3488A	No longer supported	
44478BR	1.3 GHz 75 Ohm Multiplexer	No longer supported	
44488A	3488A Upgrade Kit See part 03488-66541	Currently supported	no replacement
44490A	Rack slide kit for cabinets 30" deep	No longer supported	no replacement
44491A	Armature relay multiplexer assembly	No longer supported	3499A, 34970A/34901A
44491AR	Armature relay multiplexer assembly	No longer supported	
44492A	Reed relay multiplexer assembly	No longer supported	3499A, 34970A/34902A
44492AR	Reed relay multiplexer assembly	No longer supported	
44493A	Screw terminal connector for HP 44491A	No longer supported	no replacement
44494A	Screw terminal connector for HP 44492A	No longer supported	no replacement
44495A	Wiring Panel	No longer supported	no replacement
44496A	8.875" System Drawer	No longer supported	no replacement
44497A	High voltage attenuator assembly	No longer supported	no replacement
44498A	18 IN SYS DRAWER	No longer supported	no replacement
44499A	3054 INTGTN KIT	No longer supported	no replacement
44638A	Manufacturing advisory services	No longer supported	
44701AR	5 1/2 digit integrating voltmeter	No longer supported	
44701E	5 1/2-Digit Voltmeter	No longer supported	34970A, 3499A
44702A	High Speed Voltmeter	No longer supported	44704A
44702B	13 BIT HIGH-SPEED VOLTMETER 64K BUFFER	No longer supported	44704A.
44703A	MAINFRAME MEMORY CARD 256K BYTE	No longer supported	44703B
44703B	Mainframe Extended Memory Card 1MByte	Currently supported	no replacement
44703C	HSVM Extended Memory Card 56K Readings	Currently supported	no replacement
44704AR	16-Bit High Speed Voltmeter	No longer supported	
44705AR	20 Channel Relay Multiplexer	No longer supported	
44705FT	Terminal block for HP44705F	Currently supported	no replacement
44705HR	20-Channel High voltage Relay MUX	No longer supported	
44705HT	TERMINAL BLOCK	Currently supported	no replacement
44706AR	60-Ch Single-Ended Relay Multiplexer	No longer supported	
44706AT	TERMINAL BLOCK	Currently supported	no replacement
44708AR	20-Ch Relay Mux w/TC Compensation	No longer supported	
44708FR	20-Channel Solid State Mux with T/C comp	Currently supported	
44708FT	Terminal block for HP44708F	Currently supported	no replacement
44708HT	TERMINAL BLOCK	Currently supported	no replacement
44709AT	TERMINAL BLOCK	Currently supported	no replacement
44710A	20 CHANNEL FETMUX WITH T/C COMPENSATION	Currently supported	no replacement
44710AT	TERMINAL BLOCK	Currently supported	no replacement
44711A	24-channel high-speed fet mux	Currently supported	no replacement
44711AR	24-Channel High Speed FET MUX	Currently supported	
44711AT	TERMINAL BLOCK	Currently supported	no replacement
44711B	24-Channel High Speed FET MUX	Currently supported	no replacement
44711BT	Module 24-Ch Mux Term	Currently supported	no replacement
44712A	48-channel high speed fet mux	Currently supported	no replacement
44712AT	TERMINAL BLOCK	Currently supported	no replacement
44713A	24 CHANNEL HIGH SPEED FET MUX	Currently supported	no replacement
44713AR	24 Channel High Speed Fet Mux	Currently supported	
44713AT	TERMINAL BLOCK	Currently supported	no replacement
44713B	24-Channel High Speed FET MUX/TC	Currently supported	no replacement
44713BT	Module 24-Ch Mux/TC Term	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
44714A	3852A STEPPER MOTOR CONTROLLER MODULE	Currently supported	no replacement
44714AT	TERMINAL BLOCK	Currently supported	no replacement
44715AR	5 Channel counter Totalizer	Currently supported	
44717A	120 OHM STATIC STRAIN GAGE RELAY MUX	Currently supported	no replacement
44717AT	120 OHM STATIC STRAIN TERMINAL MODULE	Currently supported	no replacement
44718A	350 OHM STATIC STRAIN GAGE RELAY MUX	Currently supported	no replacement
44718AR	350 Ohm Static Strain Gage Relay Mux	No longer supported	
44718AT	350 OHM STATIC STRAIN TERMINAL MODULE	Currently supported	no replacement
44719A	120 OHM STATIC STRAIN GAGE FET MUX	Currently supported	no replacement
44719AT	120 OHM STATIC STRAIN TERMINAL MODULE	Currently supported	no replacement
44720A	350 OHM STATIC STRAIN GAGE FET MUX	Currently supported	no replacement
44720AR	350 OHM static strain gauge fet mux	Currently supported	
44720AT	350 OHM STATIC STRAIN TERMINAL MODULE	Currently supported	no replacement
44721AT	TERMINAL BLOCK	Currently supported	no replacement
44722A	8 CHANNEL AC DIGITAL INPUT	Currently supported	no replacement
44722AT	TERMINAL BLOCK	Currently supported	no replacement
44723AR	3852A Hi Speed Digital Sense/Control	Currently supported	
44723AT	TERMINAL BLOCK	Currently supported	no replacement
44724AT	TERMINAL BLOCK	Currently supported	no replacement
44725AR	16-Channel General Purpose Switch	Currently supported	
44726A	2 CHL ARBITRARY WAVEFORM DAC	Currently supported	no replacement
44727AR	4-Channel Voltage DAC	Currently supported	
44727B	4 CHANNEL CURRENT DAC	Currently supported	no replacement
44727BT	TERMINAL BLOCK	Currently supported	no replacement
44727C	2 CHANNEL VOLTS 2 CHANNEL CURRENT DAC	Currently supported	no replacement
44727CR	2 Channel volts 2 Channel current DAC	No longer supported	
44727CT	TERMINAL BLOCK	Currently supported	no replacement
44728AR	8 Channel Relay Actuator	Currently supported	
44728AT	TERMINAL BLOCK	Currently supported	no replacement
44729A	8 CHANNEL POWER CONTROLLER	Currently supported	no replacement
44729AT	TERMINAL BLOCK	Currently supported	no replacement
44730A	TRACK/HOLD MULTIPLEXER	Currently supported	no replacement
44730AT	TERMINAL MODULE	Currently supported	no replacement
44732A	120 OHM DYNAMIC STRAIN	Currently supported	no replacement
44732AR	120 Ohm Dynamic Strain	Currently supported	
44732AT	TERMINAL MODULE	Currently supported	no replacement
44733A	350 OHM DYNAMIC STRAIN	Currently supported	no replacement
44733AT	TERMINAL MODULE	Currently supported	no replacement
44736A	BREADBOARD	Currently supported	no replacement
44736AT	TERMINAL BLOCK	Currently supported	no replacement
44740A	30 INCH RACK INST INSTALLED	No longer supported	E3660A#AW3
44740B	30 INCH RACK INSTRUMENT INSTALLED	No longer supported	E3660A#AW5
44741A	56 INCH RACK INSTRUMENT INSTALLED	No longer supported	E3661B Opt. AW3
44741B	56 INCH RACK INST INSTALLED FOR 220 VAC	No longer supported	E3661B Opt. AW5
44742A	NEMA CABINET FOR THE HP3852A.	No longer supported	no replacement
44743A	PLUG-IN ACCESSORY SERVICE MODULE	No longer supported	no replacement
44743B	POWER SUPPLY SERVICE MODULE	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
44743F	3852A SERVICE KIT	Currently supported	no replacement
44744A	2 Metre GPIO Cable	Currently supported	no replacement
44744B	4 Metre GPIO Cable	Currently supported	no replacement
44745A	4 Metre GPIO Cable	Currently supported	no replacement
44746A	4 Metre Control Cable	Currently supported	no replacement
44746B	8 Metre Control Cable	Currently supported	no replacement
44746C	28 Metre Control Cable	Currently supported	no replacement
44747A	4 Metre Analog Signal Cable	Currently supported	no replacement
44747B	8 Metre Analog Signal Cable	Currently supported	no replacement
44747C	28 Metre Analog Signal Cable	Currently supported	no replacement
44788A	HP-IB CONTROLLER	Currently supported	no replacement
44788AR	HP-IB Controller	Currently supported	
44790A	Binary Mode Software For 3852A.	Currently supported	no replacement
44790R	Right to copy license for Binary Mode	Currently supported	no replacement
45220A	PAY/250 SOFTWARE	No longer supported	no replacement
45502A	MICROPLAN/80	No longer supported	no replacement
45503A	MICROPLAN CONSOL	No longer supported	no replacement
45531DA	VISICALC/125 GER	No longer supported	no replacement
45532DA	GRAPHICS/125 GER	No longer supported	no replacement
45534DA	LINK/125 GER	No longer supported	no replacement
45560DA	GERMAN WORDSTAR	No longer supported	no replacement
45560SA	WORDSTAR/125 SWE	No longer supported	no replacement
45584A	WORDSTAR-SER 80	No longer supported	no replacement
45584X	WS DEMO SER 80	No longer supported	no replacement
45587A	MAILMERGE-SER 80	No longer supported	no replacement
45587X	MAILMERGE DEMO	No longer supported	no replacement
45588A	SPELLSTAR-SER 80	No longer supported	no replacement
45588X	SPELLSTAR DEMO	No longer supported	no replacement
45861A	GPIB CONTROLLER	No longer supported	
45862A	PCIB CONTROLLER	No longer supported	
46103Y	Base GSM Gate System	No longer supported	
46103Z	Base CDMA Gate System	No longer supported	
46111BA	Single DCT-3 F/UI Digital Test System	No longer supported	46111CA
46112BA	Double DCT-3 F/UI Digital Test System	No longer supported	
46120A	Global Rack (Core) Test System	No longer supported	
46180A	Passive Component bldg block-CD S/WARE	No longer supported	
46190A	CONTROLLER TO CONTROLLER COMMUNICATIONS	No longer supported	
46190R	CONTROLLER TO CONTROLLER COMMUNICAT. PAC	No longer supported	NEW PROD
48074A	COMMUNICATION HANDLER SOFTWARE	No longer supported	no replacement
51083A	Bottom Box for 5183	No longer supported	
51089A	Top Box	No longer supported	no replacement
51800A	Waveform Measurement Library	No longer supported	no replacement
51810A	Video Measurement System	No longer supported	no replacement
51810R	Video Measurement Set	No longer supported	no replacement
51810S	Video Measurement System	No longer supported	no replacement
51820A	Waveform Generation Software	No longer supported	no replacement
52101A	HPIB INTERFACE	No longer supported	no replacement
52102A	RS232S INTERFACE	No longer supported	no replacement
52103A	16 BIT INTERFACE	No longer supported	no replacement
52104A	HPIB INTERFACE	No longer supported	
52105A	RS232C INTERFACE	No longer supported	no replacement
52106A	16 BIT BINARY	No longer supported	no replacement
52113A	INTEGRAL/60	No longer supported	no replacement
52121A	INTERCONNECT CBL	No longer supported	no replacement
52122A	INTERCONNECT CABLE	No longer supported	no replacement
52124A	10-METER CABLE	No longer supported	no replacement
52125A	ONE-METER CABLE	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
52126A	MULTIBUS INTRFCE	No longer supported	
53700A	Continuous Measurement Software	No longer supported	
54001A	1 GHz miniature active probe, 1.5 m	No longer supported	
54001AR	1 GHz miniature active probe, 1.5 M	No longer supported	
54002A	50 ohm BNC input for HP 54100A/D scopes	No longer supported	
54002AR	50 OHM BNC input for 54100A/D scopes	No longer supported	
54003A	1 megohm BNC input for 54100A/D scopes	No longer supported	
54006AR	6 GHz resistive divider probe kit	Currently supported	
54007AR	Accessory kit for the 54120A/54121A	Currently supported	
54008A	DELAY LINE	Currently supported	
54050A	FRONT PANEL COVER FOR 54100A/D SCOPES	No longer supported	
54051A	PROBE ADAPTER FOR THE 54001A PROBE	No longer supported	
54100A	1 GHz DIGITIZING OSCILLOSCOPE	No longer supported	
54100D	1 GHz DIGITIZING SCOPE/ENHANCED TRIGGER	No longer supported	
54110D	1 GHz DIGITIZING OSCILLOSCOPE	No longer supported	
54110DR	1 GHz Digitizing Oscilloscope	No longer supported	
54111D	1 GSa/sec Digitizing Oscilloscope	No longer supported	
54111DR	Rmkt 1GSa/Sec Digitizing Oscilloscope	No longer supported	no replacement
54112D	4 CHANNEL DEEP MEMORY DIGITIZING SCOPE	No longer supported	
54112DR	Rmkt 4 Channel Deep Mem Digitizing Scope	No longer supported	
54114A	2 GSa/s TEST SET	No longer supported	
54118A	0.5-18 GHz trigger for 54120T/21A	Currently supported	
54120A	20 GHz DIGITIZING OSCILLOSCOPE	No longer supported	
54120B	Digitizing oscilloscope mainframe	No longer supported	http://www.agilent.com/find/infiniium
54120BR	Digitizing oscilloscope mainframe	No longer supported	
54120T	20 GHz Digitizing Oscilloscope System	No longer supported	
54121A	Four channel test set for the HP 54120B	No longer supported	
54121AR	Four channel test set for the 54120B	No longer supported	
54121T	20 GHz digitizing oscilloscope system	No longer supported	
54121TR	20 GHz digitizing oscilloscope system	No longer supported	
54122A	12.4 GHz four-channel test set	No longer supported	
54122AR	12.4 GHz four-channel test set	No longer supported	
54122T	12.4 GHz digitizing oscilloscope system	No longer supported	
54122TR	12.4 GHz digitizing oscilloscope system	No longer supported	
54123A	34 GHz four channel test set	No longer supported	
54123T	34 GHz digitizing oscilloscope	No longer supported	
54123TR	34 GHz digitizing oscilloscope	No longer supported	
54124A	50 GHz four channel test set	No longer supported	
54124T	50 GHz digitizing oscilloscope	No longer supported	
54200A	200 Msa/s DIGITIZING OSCILLOSCOPE, 50MHz	No longer supported	
54200D	200 Msa/s DIGITIZING OSCILLOSCOPE,50 MHz	No longer supported	
54201A	300 MHz DIGITIZING OSCILLOSCOPE	No longer supported	
54201D	300 MHz DIGITIZING OSCILLOSCOPE	No longer supported	
54300A	1 GHz PROBE MULTIPLEXER	No longer supported	
54300AR	1 GHz probe multiplexer	No longer supported	
54501ABSK	100MHz DIGITIZING OSCILLOSCOPES	No longer supported	
54501AISK	100MHz DIGITIZING OSCILLOSCOPE	No longer supported	
54501AK	100MHZ DIGITIZING OSCILLOSCOPE	No longer supported	
54501AR	100 MHz digitizing oscilloscope	No longer supported	
54502A	400 MHZ DIGITIZING OSCILLOSCOPE	No longer supported	
54502ABSK	400MHZ DIGITIZING OSCILLOSCOPE	No longer supported	
54502AK	400MHz DIGITIZING OSCILLOSCOPE	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
54502AR	Rmkt 400 MHz Digitizing Oscilloscope	No longer supported	no replacement
54503A	500 MHz digitizing oscilloscope	No longer supported	
54503ABSK	500MHZ DIGITIZING OSCILLOSCOPE	No longer supported	
54503AK	500 MHz digitizing oscilloscope China	No longer supported	
54503AR	500 MHz digitizing oscilloscope	No longer supported	
54504A	400 MHz digitizing oscilloscope, 2 ch.	No longer supported	
54504AK	400MHz DIGITIZING OSCILLOSCOPE	No longer supported	
54504AR	400 mhZ DIGITIZING OSCILLOSCOPE, 2 CH.	No longer supported	
54505B	500 MSa/s DIGITIZING OSCILLOSCOPE	No longer supported	
54506B	500 MSa/S DIGITIZING OSCILLOSCOPE	No longer supported	
54510A	1 GSa/s Digitizing Oscilloscope	No longer supported	
54510AR	Rmkt 1 GSa/s digitizing oscilloscope	No longer supported	
54510B	1 GSA/s DIGITIZING OSCILLOSCOPE	No longer supported	
54510BR	1 GSA/s Digitizing Oscilloscope	No longer supported	
54512B	1 GSa/s DIGITIZING OSCILLOSCOPE	No longer supported	
54512BR	1 GS/s Digitizing Oscilloscope	No longer supported	
54520U	Upgrade HP 54520A to 54522A certificate	No longer supported	http://http://www.agilent.com/find/infiniium
54540CR	500 MSa/s per ch.color dig.scope, 4 ch	Currently supported	
54540U	Upgrade HP 54540A to 54542A certificate	No longer supported	http://http://www.agilent.com/find/infiniium
54550A	FFT UPGRADE KIT FOR HP 54510A	No longer supported	
54551A	Scope View PC software	No longer supported	
54600A	2 CHANNEL, 100MHz OSCILLOSCOPE	No longer supported	
54600AK	100MHz DIGITIZING OSCILLOSCOPE	No longer supported	
54600AR	2 Channel, 100MHz Oscilloscope	No longer supported	
54600BK	100 MHz digitizing scope with 2 channels	No longer supported	
54601A	4 CHANNEL, 100MHz OSCILLOSCOPE	No longer supported	
54601AK	100MHz DIGITIZING OSCILLOSCOPE	No longer supported	
54601B	4 channel, 100 MHz oscilloscope	No longer supported	
54601BK	100 MHz digitizing scope with 4 channels	No longer supported	
54601BR	4-Channel, 100 MHz Oscilloscope	No longer supported	
54602A	4 CHANNEL 150 MHz OSCILLOSCOPE	No longer supported	
54602AK	4 CHANNEL 150 MHz OSCILLOSCOPE	No longer supported	
54602AR	4 Channel 150 Mhz Oscilloscope	No longer supported	
54602BK	4 channel 150 MHz oscilloscope	No longer supported	
54610A	2 Channel, 500MHz Oscilloscope	No longer supported	
54610AK	2 Channel, 500MHz Oscilloscope	No longer supported	
54610BK	2 channel, 500 MHz portable oscilloscope	No longer supported	
54615T	Mixed Signal Test System	No longer supported	
54615TC	Mixed Signal Test System	No longer supported	54615B, 54620C or 54616TC
54616B	2 Channel 2 GSa/s 500 MHz Oscilloscope	Currently supported	
54616TC	500 MHz, Mixed Signal Test System	No longer supported	
54650AR	HP-IB I/O module for HP 54600 series	Currently supported	
54651A	RS-232 I/O module for HP 54600 Series	No longer supported	
54652A	Parallel I/O module for 54600 Series	No longer supported	54652B
54653A	ScopeLink software	No longer supported	
54657AR	HP-IB meas/storage module for HP 546xx	Currently supported	
54658A	RS-232 meas/storage module for HP 546xx	Currently supported	
54658AR	RS-232 meas/storage for 546XX	Currently supported	
54700A	BLANK PANEL FOR 54700 SERIES SCOPES	No longer supported	
54700B	Blank 1 slot filler plug-in	No longer supported	
54702A	REV 3.00 OP SYS FOR 547XX OSCILLOSCOPES	No longer supported	
54710A	REAL-TIME MODULAR OSCILLOSCOPE MAINFRAME	No longer supported	
54710D	4 GSa/s deep memory modular oscilloscope	No longer supported	
54711A	Attenuator plug-in for HP 54720D	No longer supported	54845A

Product	Description	Support Status	Replacement Information
		as of 1 May	
54711AR	Attenuator plug-in for 54720D	Currently supported	
54712A	1.1 GHz amplifier plug-in for 54720D	No longer supported	54845A
54713A	AMPLIFIER PLUG-IN	No longer supported	
54713B	500 MHz amplifier plug-in for 54720D	No longer supported	54845A
54713BR	500 MHz amplifier plug-in for 54720D	Currently supported	
54714A	2 ch amplifier plug-in for HP 54720D	No longer supported	54845A
54714AR	2 ch amplifier plug-in for 54720D	Currently supported	
54715A	1 ch differential plug-in for HP 54720D	No longer supported	54845A
54715S	HP 54715A plug-in and 1141A probe	No longer supported	54845A
54715SR	54715A plug-in and 1141A probe	No longer supported	
54717A	Calibration plug-in for HP 54720D	No longer supported	54845A
54717AR	Calibration plug-in for 54720D	Currently supported	
54718A	TRIGGER PLUG-IN	No longer supported	
54720A	REAL-TIME MODULAR OSCILLOSCOPE MAINFRAME	No longer supported	
54720AR	Rmkt real-time modular oscilloscope	No longer supported	
54720DR	Deep Memory Modular Oscilloscope	Currently supported	
54721A	1.1 GHz Amplifier Plug-in for HP 54720D	No longer supported	54845A
54722A	8 GSa/s Plug-in for HP 54720D	No longer supported	54845A
54722AR	8 GSa/s plug-in for 54720A or 54720D	Currently supported	
54751A	2 channel, 20 GHz vertical plug-in	Currently supported	86112A
54752A	2 channel, 50 GHz plug-in for 54750A	Currently supported	83484A
54752B	1 channel, 50 GHz vert module for 54750A	Currently supported	no replacement
54752BR	1 channel, 50GHz vert module for 54750A	Currently supported	
54755A	TDR software for the 83480A	Currently supported	no replacement
54771A	Bit Error Analyzer Software Package	No longer supported	54845A
54772A	Test Manager Software Package	No longer supported	54845A
54774A	Time-interval measurement software	No longer supported	
54825N	Infiniium Oscilloscope 2 GSa/s, 4 ch	Currently supported	
55000A	Logic Troubleshooting Software	No longer supported	no replacement
55005A	LOGIC TRBLSH SYS	No longer supported	no replacement
55005S	Logic Troubleshooting System	No longer supported	no replacement
55286A	DIM METR ANA SYS	No longer supported	Calibration Systems
55286S	Dimensional Metrology Analysis System	No longer supported	no replacement
55288A	DIM METR ANA SYS	No longer supported	Calibration Systems
55288S	Dimensional Metrology Analysis System	No longer supported	10754A
55292AL	Calibrator Usb Expansion Module	No longer supported	55292A
55300A	GPS Telecom Primary Reference Source	product family sold	http://www.agilent.com/find/symmetricom
55300AR	GPS Telecom Primary Reference Source	Currently supported	
55310A	GPS NEBS/EIA Rack Mount Shelf	product family sold	http://www.agilent.com/find/symmetricom
55320A	GPS ETSI Rack Mount Shelf	product family sold	http://www.agilent.com/find/symmetricom
55322A	GPS ETSI Rack Mount Shelf D Sub Connec	product family sold	http://www.agilent.com/find/symmetricom
55401A	2048 Mbps Master Rack	No longer supported	55401B
55401B	Master Subrack 9 Input References	product family sold	http://www.agilent.com/find/symmetricom
55401C	SSU Master Subrack	product family sold	http://www.agilent.com/find/symmetricom
55401D	SSU Master Subrack	product family sold	http://www.agilent.com/find/symmetricom
55402B	Expansion Subrack	product family sold	http://www.agilent.com/find/symmetricom
55402C	SSU Expansion Subrack	product family sold	http://www.agilent.com/find/symmetricom
55402CS	SSU Expansion Subrack Bundle	product family sold	http://www.agilent.com/find/symmetricom
55402D	SSU Expansion Subrack	product family sold	http://www.agilent.com/find/symmetricom
55402DS	SSU Expansion Subrack Bundle	product family sold	http://www.agilent.com/find/symmetricom
55409A	Mini-SSU Subrack	product family sold	http://www.agilent.com/find/symmetricom
55411A	Stratum 2 ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55411B	Stratum 2 ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55412A	Transit Node ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55412B	Transit Node ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55413A	Local Node ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55413B	Local Node ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55414A	Enhanced Stratum 2 ITH Card.	product family sold	http://www.agilent.com/find/symmetricom

Product	Description	Support Status	Replacement Information
55414B	Enhanced Stratum 2 ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55415B	Enhanced Transit Node ITH Card.	product family sold	http://www.agilent.com/find/symmetricom
55419A	Expansion Synchronization Card	product family sold	http://www.agilent.com/find/symmetricom
55421A	Clk Dist Output Card-2048kbps-16 outputs	product family sold	http://www.agilent.com/find/symmetricom
55422A	Clk Dist Output Card-2048 kHz-16 outputs	product family sold	http://www.agilent.com/find/symmetricom
55423A	Composite Clock Output Card 64/8 kbps	product family sold	http://www.agilent.com/find/symmetricom
55424A	SSU Expansion Subrack Cable Kit	product family sold	http://www.agilent.com/find/symmetricom
55425A	SSU Expansion Subrack Comm Return Cable	product family sold	http://www.agilent.com/find/symmetricom
55426A	SSU Subrack Adapter.	product family sold	http://www.agilent.com/find/symmetricom
55429B	Mini-SSU Local Node ITH Card	product family sold	http://www.agilent.com/find/symmetricom
55431A	Alarm Interface Card (AIC)	product family sold	http://www.agilent.com/find/symmetricom
55441A	Information Management Card. (IMC)	product family sold	http://www.agilent.com/find/symmetricom
55442A	Network IMC Card (NIMC)	product family sold	http://www.agilent.com/find/symmetricom
55443A	Expansion Communications Card	product family sold	http://www.agilent.com/find/symmetricom
55450A	Local Craft Terminal	product family sold	http://www.agilent.com/find/symmetricom
55450AM	Remote Management Software	product family sold	http://www.agilent.com/find/symmetricom
55451CA	HP OSMF-NT 3.xx Media	product family sold	http://www.agilent.com/find/symmetricom
55452AA	OSMF For HP-UX 1.xx Media	product family sold	http://www.agilent.com/find/symmetricom
55452BA	OSMF For HP-UX Media	product family sold	http://www.agilent.com/find/symmetricom
55452BB	OSMF For HP-UX Media, Resiliency Add-On.	product family sold	http://www.agilent.com/find/symmetricom
55452CA	HP OSMF-UX 3.xx Media	product family sold	http://www.agilent.com/find/symmetricom
55452CB	HP OSMF-UX 3.xx Resiliency Media.	product family sold	http://www.agilent.com/find/symmetricom
55453AA	OSMF 1.xx License To Use Per SSU	product family sold	http://www.agilent.com/find/symmetricom
55453BA	OSMF 2.xx License to use per SSU.	product family sold	http://www.agilent.com/find/symmetricom
55453BB	OSMF License To Use, Resiliency Add-on	product family sold	http://www.agilent.com/find/symmetricom
55453CA	HP OSMF-UX 3.xx License To Use Per SSU.	product family sold	http://www.agilent.com/find/symmetricom
55453CB	HP OSMF-UX 3.xx Resiliency LTU per WS.	product family sold	http://www.agilent.com/find/symmetricom
55454AA	OSMF For HP-UX 1.xx Manuals	product family sold	http://www.agilent.com/find/symmetricom
55454BA	OSMF For HP-UX 2.xx Manuals	product family sold	http://www.agilent.com/find/symmetricom
55454BB	OSMF Manuals, Resiliency Add-On.	product family sold	http://www.agilent.com/find/symmetricom
55454CA	HP OSMF-UX 3.xx Manuals.	product family sold	http://www.agilent.com/find/symmetricom
55454CB	HP OSMF-UX 3.xx Resiliency Manuals.	product family sold	http://www.agilent.com/find/symmetricom
55455BA	HP OSMF-UX 2.xx License To Use Per GPS	product family sold	http://www.agilent.com/find/symmetricom
55455CA	HP OSMF-UX 3.xx License To Use Per GPS.	product family sold	http://www.agilent.com/find/symmetricom
55457CA	HP OSMF-NT Standard 3.xx LTU Per SSU.	product family sold	http://www.agilent.com/find/symmetricom
55458CA	HP OSMF-NT 3.xx License To Use Per GPS.	product family sold	http://www.agilent.com/find/symmetricom
55459CA	HP OSMF-NT 3.xx Manuals.	product family sold	http://www.agilent.com/find/symmetricom
55460A	Sync Audit Service	product family sold	http://www.agilent.com/find/symmetricom
55471A	Traffic Re-Synchronization Card	product family sold	http://www.agilent.com/find/symmetricom
55481A	2048 kbps Clock Distribution Output Card	product family sold	http://www.agilent.com/find/symmetricom
55481B	2048 Kbps Prog Clock Dist Output Card.	product family sold	http://www.agilent.com/find/symmetricom
55482A	2048 KHz Clock Distribution Output Card	product family sold	http://www.agilent.com/find/symmetricom
55482AR	2048 KHz clock Distribution Output Card	Currently supported	
55483AR	64/8 KHz Composite Clk Dist Output Card	Currently supported	
55484A	Prog 1,5,10 MHz Clock Dist Output Card	product family sold	http://www.agilent.com/find/symmetricom
55485A	1.544 Mbhs Clock Dist Card, 8 outputs	product family sold	http://www.agilent.com/find/symmetricom
55485B	1.544 Mbps Clock Dist Card, 16 outputs	product family sold	http://www.agilent.com/find/symmetricom
55488A	2048KHz/Kbps Combination Output Card	product family sold	http://www.agilent.com/find/symmetricom
55497A	Mini-SSU Output Connect Module	product family sold	http://www.agilent.com/find/symmetricom

Product	Description	Support Status	Replacement Information
55498A	Mini-SSU In/Out Connect Module	product family sold	http://www.agilent.com/find/symmetricom
58502A	Broadband Distribution Amplifier	product family sold	http://www.agilent.com/find/symmetricom
58503A	GPS Time and Frequency Receiver	product family sold	http://www.agilent.com/find/symmetricom
58503A	GPS Time and Frequency Receiver	product family sold	http://www.agilent.com/find/symmetricom
58503AR	GPS Time and Frequency Receiver	Currently supported	
58503B	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
58504A	Antenna Assembly	product family sold	http://www.agilent.com/find/symmetricom
58505A	Lightning Arrester	product family sold	http://www.agilent.com/find/symmetricom
58505B	GPS Lightning Arrester	product family sold	http://www.agilent.com/find/symmetricom
58506A	Antenna Cable Assembly (50ft/15m)	product family sold	http://www.agilent.com/find/symmetricom
58507A	Antenna Cable Assembly (100ft/30m)	product family sold	http://www.agilent.com/find/symmetricom
58508A	Antenna Cable Assembly (175 ft/53m)	product family sold	http://www.agilent.com/find/symmetricom
58509A	GPS Antenna Line Amplifier	product family sold	http://www.agilent.com/find/symmetricom
58509F	GPS Line Amplifier w/L1 Bandpass Filter	product family sold	http://www.agilent.com/find/symmetricom
58510A	GPS Antenna ENV CVR/GND PL	product family sold	http://www.agilent.com/find/symmetricom
58511A	Antenna Cable Assembly (200ft/61m)	product family sold	http://www.agilent.com/find/symmetricom
58512A	GPS 1:2 Distribution Amplifier/Splitter	product family sold	http://www.agilent.com/find/symmetricom
58513A	GPS Antenna Assembly w/Cover	product family sold	http://www.agilent.com/find/symmetricom
58514A	GPS L1 Bandpass Filter	product family sold	http://www.agilent.com/find/symmetricom
58515A	GPS 1:2 Distribution Amplifier/Splitter	product family sold	http://www.agilent.com/find/symmetricom
58516A	GPS 1:4 Distribution Amplifier/Splitter	product family sold	http://www.agilent.com/find/symmetricom
58517A	GPS 1:8 Distribution Amplifier/Splitter	product family sold	http://www.agilent.com/find/symmetricom
58518A	RG-213 Antenna Cable (N to TNC)	product family sold	http://www.agilent.com/find/symmetricom
58518AA	RG-213 Antenna Cable (N to TNC) Kit	product family sold	http://www.agilent.com/find/symmetricom
58519A	RG-213 Interconnect cable (N to N)	product family sold	http://www.agilent.com/find/symmetricom
58519AA	RG-213 Interconnect Cable (N to N) Kit	product family sold	http://www.agilent.com/find/symmetricom
58520A	LMR 400 Antenna Cable (N to TNC)	product family sold	http://www.agilent.com/find/symmetricom
58520AA	LMR 400 Antenna cable (N to TNC) Kit	product family sold	http://www.agilent.com/find/symmetricom
58521A	LMR 400 Interconnect Cable (N to N)	product family sold	http://www.agilent.com/find/symmetricom
58521AA	LMR 400 Interconnect Cable (N to N) Kit	product family sold	http://www.agilent.com/find/symmetricom
58522A	Twisted Pairs Interconnect Cable	product family sold	http://www.agilent.com/find/symmetricom
58529A	GPS Line Amplifier w/L1 Bandpass Filter	product family sold	http://www.agilent.com/find/symmetricom
58530A	GPS L1 Bandpass Filter	product family sold	http://www.agilent.com/find/symmetricom
58531A	GPS Timing Rcvr Analysis/Cntrl Software	product family sold	http://www.agilent.com/find/symmetricom
58532A	GPS L1 Reference Antenna	product family sold	http://www.agilent.com/find/symmetricom
58533A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
58534A	GPS Timing Antenna	product family sold	http://www.agilent.com/find/symmetricom
58534AA	GPS Timing Antenna Evaluation Kit	product family sold	http://www.agilent.com/find/symmetricom
58535A	GPS L1 1:2 Distribution Amp/Splitter	product family sold	http://www.agilent.com/find/symmetricom
58536A	GPS L1 1:4 Distribution Amp/Splitter	product family sold	http://www.agilent.com/find/symmetricom
58538A	Lightning Arrestor	product family sold	http://www.agilent.com/find/symmetricom
58539A	GPS L1 Lightning Arrestor	product family sold	http://www.agilent.com/find/symmetricom
58540A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
59004A	INTERFACE KIT	No longer supported	no replacement
59005A	BCD INTERFACE KI	No longer supported	no replacement
59006A	SCANNER OPTION K	No longer supported	no replacement
59301A	ASCII to Parallel Converter	No longer supported	no replacement
59303A	D to A Converter	No longer supported	no replacement
59304A	NUMERIC DISPLAY	No longer supported	no replacement
59306AR	Relay Actuator	Currently supported	
59307AR	VHF Switch	Currently supported	
59308A	TIMING GENERATOR	No longer supported	no replacement
59309A	Digital Clock	No longer supported	no replacement
59310A	I/O CARD	No longer supported	no replacement
59313A	A to D Converter	No longer supported	no replacement
59400A	HP-IB/RS232 TT	No longer supported	no replacement
59401A	BUS SYS ANALYZER	No longer supported	no replacement
59403A	HPIB/CCI	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
59405A	HP-IB INTERFACE	No longer supported	no replacement
59500A	GPIB KIT	No longer supported	no replacement
59501A	GPIB D/A PRGRMR	No longer supported	
59501B	D/A CONVERTER	No longer supported	
59501BR	D/A Converter	No longer supported	
59510AR	Relay Device	Currently supported	
59511AR	Relay Device	Currently supported	
59551A	GPS Measurements Synchronization Module	product family sold	http://www.agilent.com/find/symmetricom
59551AR	GPS Measurements Synchronization Module	Currently supported	
59552A	Fiber Optic Distribution Amplifier	product family sold	http://www.agilent.com/find/symmetricom
59553A	Fiber Optic Receiver	product family sold	http://www.agilent.com/find/symmetricom
59993A	Special	No longer supported	no replacement
59994A	Special	product family sold	http://www.agilent.com/find/symmetricom
60063B	DC POWER SUPPLY	No longer supported	
60065A	DC POWER SUPPLY	No longer supported	
60066A	DC POWER SUPPLY	No longer supported	
60122B	DC POWER SUPPLY	No longer supported	
60123B	DC POWER SUPPLY	No longer supported	
60125B	DC POWER SUPPLY	No longer supported	
60126B	DC POWER SUPPLY	No longer supported	
60153D	DC POWER SUPPLY	No longer supported	
60155C	DC POWER SUPPLY	No longer supported	
60242A	NOT FOR SALE PRODUCT.	No longer supported	
60242B	DC POWER SUPPLY	No longer supported	
60243B	DC POWER SUPPLY	No longer supported	
60244B	DC POWER SUPPLY	No longer supported	
60245B	DC POWER SUPPLY	No longer supported	
60246B	DC POWER SUPPLY	No longer supported	
60501A	150W LOAD MODULE	No longer supported	
60501BR	150-Watt Load Module	Currently supported	
60502A	300W LOAD MODULE	No longer supported	60502B
60503A	250W LOAD MODULE	No longer supported	60503B
60504A	600W LOAD MODULE	No longer supported	60504B
60507BR	500 Watt load module	Currently supported	
61001A	PCI POWER UNIT	No longer supported	no replacement
61005C	DC-DC CONVERTER	No longer supported	
61005E	DC-DC CONVERTER	No longer supported	no replacement
61010A	PCI DIGITAL I/O	No longer supported	no replacement
61010AA	PC DIGITAL I/O	No longer supported	
61011A	PCI RELAY MUX	No longer supported	no replacement
61011AA	PC RELAY MUX	No longer supported	
61012A	PCI DUAL V/DAC	No longer supported	no replacement
61012AA	PC DUAL VOLT DAC	No longer supported	
61013A	PCI MULTI METER	No longer supported	no replacement
61013AA	PC 4 1/2 DIGITAL MULTIMETER	No longer supported	
61014A	PCI FUNCTION GEN	No longer supported	no replacement
61014AA	PC FUNCTION GENERATOR	No longer supported	
61015A	PCI UNIV COUNTER	No longer supported	no replacement
61015AA	PC UNIVERSAL COUNTER	No longer supported	
61016A	PCI 50 MHZ SCOPE	No longer supported	no replacement
61016AA	PC DIGITIZING 50MHZ OSCILLOSCOPE	No longer supported	
61017A	PCI ACTUATOR	No longer supported	no replacement
61017AA	PC RELAY ACTUATOR	No longer supported	
61018A	PCI BREADBOARD	No longer supported	no replacement
61018AA	PC BREADBOARD	No longer supported	
61019A	PCI POWER SUPPLY	No longer supported	no replacement
61019AA	20 VOLT PC POWER SUPPLY	No longer supported	
61020A	PCI VHF MUX	No longer supported	no replacement
61025A	PCI POWER SUPPLY	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
61025AA	50 VOLT PC POWER SUPPLY	No longer supported	
61060A	PC INTERFACE	No longer supported	
61060AA	PC INSTRUMENT INTERFACE FOR THE HP150	No longer supported	
61060AD	PCI INTERFACE	No longer supported	no replacement
61061A	PCI INTERFACE	No longer supported	61061C
61061AA	PC INSTRUMENTS INTERFACE FOR THE IBM	No longer supported	
61061BA	PC INTERFACE	No longer supported	
61061C	PCI INTERFACE	No longer supported	no replacement
61062AA	GPIB INTERFACE & SOFTWARE I/O LIBRARY	No longer supported	
61062BA	GPIB I/F & I/O SOFTWARE	No longer supported	
61080AA	DATA LOGGING PACKAGE-HP150	No longer supported	
61081AA	DATA LOGGING PACKAGE-IBM	No longer supported	
61082AA	ELECTRONIC BENCH PACKAGE-HP150	No longer supported	
61083AA	ELECTRONIC BENCH PACKAGE-IBM PC VERSION	No longer supported	
61084AA	D. LOG SYSTEM	No longer supported	
61086AA	D. LOG PKG HP150	No longer supported	
61086BA	D LOG PKG-HP150	No longer supported	
61087AA	D. LOG PKG IBM	No longer supported	
61087BA	D LOG PKG-VECTRA	No longer supported	no replacement
61088AA	BENCH PKG HP150	No longer supported	
61088BA	BENCH PKG-HP150	No longer supported	no replacement
61089AA	BENCH PKG IBM	No longer supported	
61089BA	BENCH PKG-VECTRA	No longer supported	no replacement
61315D	DC-DC CONVERTER	No longer supported	
61315E	DC-DC CONVERTER	No longer supported	no replacement
62003A	DC POWER SUPPLY	No longer supported	
62003C	DC POWER SUPPLY	No longer supported	
62003E	DC POWER SUPPLY	No longer supported	
62003G	DC POWER SUPPLY	No longer supported	
62004A	DC POWER SUPPLY	No longer supported	
62004C	DC POWER SUPPLY	No longer supported	
62004E	DC POWER SUPPLY	No longer supported	
62004G	DC POWER SUPPLY	No longer supported	
62005A	DC POWER SUPPLY	No longer supported	no replacement
62005C	DC POWER SUPPLY	No longer supported	
62005E	DC POWER SUPPLY	No longer supported	no replacement
62005G	DC POWER SUPPLY	No longer supported	no replacement
62006A	DC POWER SUPPLY	No longer supported	
62006C	DC POWER SUPPLY	No longer supported	
62006E	DC POWER SUPPLY	No longer supported	
62006G	DC POWER SUPPLY	No longer supported	
62010A	DC POWER SUPPLY	No longer supported	
62010C	DC POWER SUPPLY	No longer supported	
62010E	DC POWER SUPPLY	No longer supported	
62010G	DC POWER SUPPLY	No longer supported	
62012A	DC POWER SUPPLY	No longer supported	no replacement
62012C	DC POWER SUPPLY	No longer supported	
62012E	DC POWER SUPPLY	No longer supported	no replacement
62012G	DC POWER SUPPLY	No longer supported	no replacement
62015A	DC POWER SUPPLY	No longer supported	no replacement
62015C	DC POWER SUPPLY	No longer supported	
62015E	DC POWER SUPPLY	No longer supported	no replacement
62015G	DC POWER SUPPLY	No longer supported	no replacement
62018A	DC POWER SUPPLY	No longer supported	no replacement
62018C	DC POWER SUPPLY	No longer supported	
62018E	DC POWER SUPPLY	No longer supported	no replacement
62018G	DC POWER SUPPLY	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
62024A	DC POWER SUPPLY	No longer supported	no replacement
62024C	DC POWER SUPPLY	No longer supported	
62024E	DC POWER SUPPLY	No longer supported	no replacement
62024G	DC POWER SUPPLY	No longer supported	no replacement
62028A	DC POWER SUPPLY	No longer supported	no replacement
62028C	DC POWER SUPPLY	No longer supported	
62028E	DC POWER SUPPLY	No longer supported	no replacement
62028G	DC POWER SUPPLY	No longer supported	no replacement
62048A	DC POWER SUPPLY	No longer supported	no replacement
62048C	DC POWER SUPPLY	No longer supported	
62048E	DC POWER SUPPLY	No longer supported	no replacement
62048G	DC POWER SUPPLY	No longer supported	no replacement
62212A	DC POWER SUPPLY	No longer supported	no replacement
62212E	DC POWER SUPPLY	No longer supported	no replacement
62212G	DC POWER SUPPLY	No longer supported	no replacement
62215A	DC POWER SUPPLY	No longer supported	no replacement
62215E	DC POWER SUPPLY	No longer supported	no replacement
62215G	DC POWER SUPPLY	No longer supported	no replacement
62312D	DC POWER SUPPLY	No longer supported	
62410A	RACK MOUNTING TRAY	No longer supported	no replacement
62411A	RACK TRAY FRONT PANEL	No longer supported	no replacement
62412A	TRAY REAR PANEL	No longer supported	
62413A	COOLING UNIT	No longer supported	no replacement
62414A	RACK TRAY SLIDES	No longer supported	no replacement
62415A	RACK TRAY AC INPUT PANEL	No longer supported	no replacement
62416A	RACK COOL. TRAY	No longer supported	
62570A	DC POWER SUPPLY	No longer supported	
62604J	DC POWER SUPPLY	No longer supported	
62605J	DC POWER SUPPLY	No longer supported	
62605L	DC POWER SUPPLY	No longer supported	
62605M	DC POWER SUPPLY	No longer supported	
62606J	DC POWER SUPPLY	No longer supported	
62610J	DC POWER SUPPLY	No longer supported	
62612J	DC POWER SUPPLY	No longer supported	
62615D	550 WATT DUAL	No longer supported	
62615J	DC POWER SUPPLY	No longer supported	
62615M	DC POWER SUPPLY	No longer supported	
62618J	DC POWER SUPPLY	No longer supported	
62624J	DC POWER SUPPLY	No longer supported	
62628J	DC POWER SUPPLY	No longer supported	
63005C	DC POWER SUPPLY	No longer supported	
63005E	DC POWER SUPPLY	No longer supported	
63312D	BASIC POWER SUPPLY	No longer supported	
63312F	MODULAR SUPPLY	No longer supported	no replacement
63315D	DC POWER SUPPLY	No longer supported	
63315E	MODULAR DC POWER SUPPLY	No longer supported	
63330F	MODULAR DC POWER SUPPLY	No longer supported	
63331F	MODULAR DC POWER SUPPLY	No longer supported	
63340F	MODULAR SUPPLY	No longer supported	no replacement
63341F	MODULAR DC POWER SUPPLY	No longer supported	
63350F	MODULAR DC POWER SUPPLY	No longer supported	
64000S	Obsolete	No longer supported	
64001S	64000 PERIPHERAL	No longer supported	
64005S	CONFIGURABLE SYS	No longer supported	
64010S	64700 Series 8-Bit System	No longer supported	
64011S	16-bit 64700 Series System	No longer supported	
64012S	32-Bit 64700 Series System	No longer supported	
64013S	8-Bit 64700 Series System	No longer supported	
64014S	16-Bit 64700 Series System	No longer supported	
64015S	64700 Series System	No longer supported	
64016S	8-Bit 64700 Series System	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
64017S	Embedded Debug Systems Solution	No longer supported	
64020A	64020 Conversion Kit	No longer supported	
64021A	64021 Conversion Kit	No longer supported	no replacement
64022A	64120A External IMB Cable	No longer supported	
64023A	4 Meter CMB Cable	No longer supported	
64030A	Development Station Cart	No longer supported	no replacement
64032A	16K Memory Expansion Module	No longer supported	no replacement
64034A	Accessories Pouch For The 64110A	No longer supported	no replacement
64035A	Accessories Pouch	No longer supported	no replacement
64037A	PC High Speed RS-422 Interface	No longer supported	no replacement
64037AX	Host Interface One-Time-Update	No longer supported	
64039A	RS422 Board for 9801	No longer supported	
64039AX	One-Time Update	No longer supported	
64050A	Graphics Board For 64000 Subsystems	No longer supported	
64070A	64000 VAX High Speed Interface	No longer supported	
64100A	Logic Development Station	No longer supported	
64100AF	Operating Software On 5 1/4 Inch Floppy	No longer supported	
64100AR	Right to make 1 copy 64100A/AF software	No longer supported	
64100AT	OPER SW ON TAPE	No longer supported	64100AF
64100AX	One-Time-Update to current 64100A/AF SW	No longer supported	
64100B	64100A Station Bundle	No longer supported	
64100RA	Remarketed Logic Development Station	No longer supported	no replacement
64100UF	64100UF SW SUBSC	No longer supported	
64100UT	64100UT SW SUBSC	No longer supported	
64110A	Transportable Logic Development System	No longer supported	
64120A	64120A Instrumentation Cardcage	No longer supported	
64120RA	Instrumentation Card Cage	No longer supported	no replacement
64121A	64000-UX Microprocessor Dev. Environ.	No longer supported	
64130S	64000-UX Microprocessor Dev. Env.	No longer supported	64131S
64131S	64000-UX Microprocessor Dev. Env.	No longer supported	
64132S	64000-UX MDE with 370MH workstation	No longer supported	
64133S	64000-UX MDE	No longer supported	
64133SB	64000-UX Microprocessor Dev. Env.	No longer supported	
64134B	64000 Microprocessor Development Env.	No longer supported	
64134S	64000-UX Microprocessor Dev. Env.	No longer supported	
64135S	64000-PC Development Environment	No longer supported	
64142A	Japan Emulator/Analyzer 48 channel	No longer supported	
64142B	Japan Emulator/Analyzer 128KB 48 channel	No longer supported	
64142C	Japan Emulator/Analyzer 80ch/1K Depth	No longer supported	
64143A	Japan Emulator/Analyzer with 80 channel	No longer supported	
64143B	Japan Emulator/Analyzer 128KB 64 channel	No longer supported	
64143C	Japan Emulator/Analyzer 80ch/8K Depth	No longer supported	
64145A	MELPS 7700 Series Emulator/Analyzer	No longer supported	
64145AL	MELPS 7700 Emulator/Analyzer + Ext. Anlz	No longer supported	
64145AX	One-Time-Update	No longer supported	
64145B	7700 Series Emulator/Analyzer 512KB	No longer supported	
64145BL	7700 Emulator/Analyzer/512KB + Ext. Anlz	No longer supported	
64145C	7700 Emulator/Analyzer without pod	No longer supported	
64145CL	7700 Emul/Anlz without pod + Ext. Anlz.	No longer supported	
64145D	7700 Emulator/Analyzer 512KB without pod	No longer supported	
64145DL	7700 Emul/Anlz 512KB without pod + Anlz.	No longer supported	
64145F	7700 Emulation Board with no memory	No longer supported	
64145S	7700 Hosted User Interface	No longer supported	

Product	Description	Support Status	Replacement Information
64146A	M7700 emulation board with no memory	No longer supported	
64146B	M7700 emul. board with no emul. memory	No longer supported	
64146S	M7700 PC Interface Software	No longer supported	
64147AR	MELPS7750/51 Emul.board with no memory	Currently supported	
64147SY	MELPS 7750/7751 Series Emulation System	No longer supported	
64150A	EMULATION MEMORY	No longer supported	
64151A	Memory Control	No longer supported	
64151S	EMUL MEM 32K	No longer supported	64152S
64152A	32 K STATIC RAM	No longer supported	64151A
64152B	32KB EMUL MEM	No longer supported	64155A
64152S	32K Byte Emulation Memory Subsystem	No longer supported	
64153A	16K STATIC RAM	No longer supported	
64153B	16KB EMUL MEM	No longer supported	
64154A	8K STATIC RAM	No longer supported	
64154B	8KB EMUL MEM	No longer supported	
64155A	Wide Address Memory Controller	No longer supported	
64155B	Emulation Memory Control with 128k bytes	No longer supported	
64155S	EMUL MEM 32K	No longer supported	
64156S	32K Byte Emulation Memory Subsystem	No longer supported	
64161A	128K Emulation RAM	No longer supported	
64161RA	128 kbyte Emulation Ram board.	No longer supported	
64162A	64K EMUL RAM	No longer supported	
64163A	32K Byte Emulation Memory Board	No longer supported	
64165S	16500B Software Analyzer Bundle	No longer supported	
64166S	1661C Software Analyzer Bundle	No longer supported	
64167S	Pentium Software Probe Bundle	No longer supported	
64168S	1671A Software Analyzer Bundle	No longer supported	
64169S	1670A Software Analyzer Bundle	No longer supported	
64170A	68000/68302 Emulation Memory Control Bd.	No longer supported	
64170AR	68000/68302 Emulation Memory Control Bd.	No longer supported	
64171A	256K Byte 35 ns SRAM Memory Module	No longer supported	
64171B	1M Byte 35 ns SRAM Memory Module	No longer supported	
64171BR	Rmkt 1Mb 35 ns SRAM Memory Module	No longer supported	
64172A	256K Byte 20ns SRAM Memory Module	No longer supported	
64172B	1M Byte 20ns SRAM Memory Module	No longer supported	
64172BR	1M Byte 20ns SRAM Memory Module	Currently supported	
64172C	64K Byte 20ns SRAM Memory Module	No longer supported	
64173A	4 Megabyte 25ns SIMM Memory Module	No longer supported	
64180AA	64180 SDIP Emulator	No longer supported	
64180AB	64180 PLCC emulator	No longer supported	
64180AX	One-Time-Update for 64180 software	No longer supported	
64191A	6805 EMUL CNTL	No longer supported	64197A
64192A	6805U/R Emulation Pod	No longer supported	no replacement
64192AX	One-Time-Update to current 64192A SW	No longer supported	
64192S	6805U/R Emulation Subsystem	No longer supported	no replacement
64192SF	6805U/R EMUL SW	No longer supported	
64192ST	6805U/R EMUL SW	No longer supported	
64192UF	6805U/R SW UPDAT	No longer supported	
64192UT	6805U/R SW UPDAT	No longer supported	
64193A	6805P Emulation Pod	No longer supported	no replacement
64193AX	One-Time-Update to current 64193A SW	No longer supported	
64193S	6805P Emulation Subsystem	No longer supported	no replacement
64194A	146805G2 Emulation Pod	No longer supported	no replacement
64194AX	One-time-Update to current 64194A SW	No longer supported	
64194S	146805G2 Emulation Subsystem	No longer supported	no replacement
64195A	146805E2 Emulation Pod	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
64195AX	One-Time-Update to current 64195A SW	No longer supported	
64195S	146805E2 Emulation Subsystem	No longer supported	no replacement
64197A	6805 Emulation Controller	No longer supported	no replacement
64200A	8080 FAMILY EMUL	No longer supported	
64201A	8080/85 Emulator Control Card	No longer supported	
64202A	8080 Emulation Pod	No longer supported	no replacement
64202AX	One-Time-Update to current 64202A SW	No longer supported	
64202S	8080 Emulation Subsystem	No longer supported	no replacement
64202SF	8080 EMUL SW	No longer supported	64203A
64202ST	8080 EMUL SW	No longer supported	64203SF
64202UF	64202UF SW SUBSC	No longer supported	
64202UT	64202UT SW SUBSC	No longer supported	
64203A	8085 Emulator Pod	No longer supported	
64203AX	One-Time-Update to current 64203A SW	No longer supported	
64203S	8085 Emulation Subsystem	No longer supported	
64203SF	8085 EMUL SW	No longer supported	
64203ST	8085 EMUL SW	No longer supported	
64203UF	64203UF SW SUBSC	No longer supported	
64203UT	64203UT SW SUBSC	No longer supported	
64205A	6301V/03R EMULATION CONTROL BOARD	No longer supported	64205B
64205B	6301/03 Emulator Control Card	No longer supported	
64206A	6301V EMULATION POD	No longer supported	
64206AX	ONE-TIME UPDATE	Currently supported	
64206S	6301V EMULATOR	No longer supported	
64207A	6301X/6303X Emulation Pod	No longer supported	
64207AX	One-Time-Update	No longer supported	
64207S	6301X/6303X Emulation Subsystem	No longer supported	
64208A	6301Y/6303Y Emulation Pod	No longer supported	
64208AX	One-Time-Update	No longer supported	
64208S	6301Y/6303Y Emulation Subsystem	No longer supported	
64209A	2A03 Emulator Pod	No longer supported	
64209AX	One-Time-Update	No longer supported	
64209S	2A03 Emulator Subsystem	No longer supported	
64210A	6800 FAMILY EMUL	No longer supported	
64211A	6800 Emulator Control	No longer supported	
64212A	6800 Emulator Pod	No longer supported	
64212AX	One-Time-Update to current 64212A SW	No longer supported	
64212S	6800 Emulation Subsystem	No longer supported	
64212SF	6800 EMUL SW	No longer supported	64212A
64212ST	6800 EMUL SW	No longer supported	64212SF
64212UF	64212UF SW SUBSC	No longer supported	
64212UT	64212UT SW SUBSC	No longer supported	
64213A	6802 Emulator Pod	No longer supported	
64213AX	One-Time-Update to current 64213A SW	No longer supported	
64213S	6802 Emulation Subsystem	No longer supported	
64213SF	6802 EMUL SW	No longer supported	64213S
64213ST	6802 EMUL SW	No longer supported	64213SF
64213UF	64213UF SW SUBSC	No longer supported	
64213UT	64213UT SW SUBSC	No longer supported	
64214A	6809 Emulator Control Card	No longer supported	
64215A	6809 Emulator Pod	No longer supported	
64215AX	One-Time-Update to current 64215A SW	No longer supported	
64215S	6809 EMU SUBSYS	Currently supported	
64215SF	6809 EMUL SW	No longer supported	
64215ST	6809 EMUL SW	No longer supported	64216SF
64215UF	64215UF SW SUBSC	No longer supported	
64215UT	64215UT SW SUBSC	No longer supported	
64216A	6809E Emulator Pod	No longer supported	
64216AX	One-Time-Update to current 64216A SW	No longer supported	
64216S	6809E Emulation Subsystem	No longer supported	

Product	Description	Support Status	Replacement Information
64216SF	6809E EMUL SW	No longer supported	
64216ST	6809E EMUL SW	No longer supported	64216SF
64216UF	6809E SW UPDATE	No longer supported	
64216UT	6809E SW UPDATE	No longer supported	
64220A	8086 FAMILY EMUL	No longer supported	
64220AX	One-Time-Update to 64220S and 64220S/001	No longer supported	
64220B	8086/8087 EMULATION POD.	No longer supported	
64220C	80C86 EMULATION POD.	No longer supported	
64220S	8086/8087 EMULATOR SUBSYSTEM.	No longer supported	
64221AX	One-Time-Update to 64221S and 64221S/001	No longer supported	
64221B	8088/8087 EMULATION POD	No longer supported	
64221C	80C88 EMULATION POD	No longer supported	
64221S	8088/8087 EMULATION SUBSYSTEM	No longer supported	
64222A	8086 Emulator Pod	No longer supported	64220B/C
64222AX	One-Time-Update to current 64222A SW	No longer supported	
64222S	8086 Emulation Subsystem	No longer supported	
64222SF	8086 EMUL SW	No longer supported	64220B
64222ST	8086 EMUL SW	No longer supported	64222SF
64222UF	64222UF SW SUBSC	No longer supported	
64222UT	64222UT SW SUBSC	No longer supported	
64223A	8018X EMUL CTL	No longer supported	64223B
64223B	GP Deque Control Board	No longer supported	
64224A	80186 Emulator Pod	No longer supported	
64224AX	One-Time-Update to current 64224A SW	No longer supported	
64224S	80186 Emulation Subsystem	No longer supported	
64225A	80188 Emulator Pod	No longer supported	
64225AX	One-Time-Update to current 64225A SW	No longer supported	
64225S	80188 Emulation Subsystem	No longer supported	
64226A	8088 Emulator Pod	No longer supported	
64226AX	One-Time-Update to current 64226A SW	No longer supported	
64226S	8088 Emulation Subsystem	No longer supported	64221S
64226SF	8088 EMUL SW	No longer supported	64223B
64226ST	8088 EMUL SW	No longer supported	64226SF
64226UF	64226UF SW SUBSC	No longer supported	
64226UT	64226UT SW SUBSC	No longer supported	
64227AX	One-Time-Update To Current 64227B SW	No longer supported	
64227B	80826 Emulation Pod	No longer supported	64228S
64227S	80286 Emulation Subsystem	No longer supported	64228S
64228S	80286 Emulation Subsystem	No longer supported	
64228SX	One-Time-Update to current 64228S SW	No longer supported	
64230A	Z8000 FAMILY EMU	No longer supported	
64232A	Z8001 Emulator Pod	No longer supported	
64232AX	One-Time-Update to current 64232A SW	No longer supported	
64232S	Z8001 Emulation Subsystem	No longer supported	
64232SF	Z8001 EMUL SW	No longer supported	64232A
64232ST	Z8001 EMUL SW	No longer supported	64232SF
64232UF	64232UF SW SUBSC	No longer supported	
64232UT	64232UT SW SUBSC	No longer supported	
64233A	Z8002 Emulator Pod	No longer supported	
64233AX	One-Time-Update to current 64233A SW	No longer supported	
64233S	Z8002 Emulation Subsystem	No longer supported	
64233SF	Z8002 EMUL SW	No longer supported	
64233ST	Z8002 EMUL SW	No longer supported	64233SF
64233UF	64233UF SW SUBSC	No longer supported	
64233UT	64233UT SW SUBSC	No longer supported	
64240A	68000 FAMILY EMU	No longer supported	
64242A	68000 Emulator Pod	No longer supported	
64242AX	One-Time-Update to current 64242A SW	No longer supported	
64242S	68000 Emulation Subsystem	No longer supported	64243AB

Product	Description	Support Status as of 1 May	Replacement Information
64242SF	68000 EMUL SW	No longer supported	64243AA
64242ST	68000 EMUL SW	No longer supported	64242SF
64242UF	64242UF SW SUBSC	No longer supported	
64242UT	64242UT SW SUBSC	No longer supported	
64243AA	68000 EMULATION SUBSYSTEM	No longer supported	
64243AB	68000 EMULATION SUBSYSTEM	No longer supported	
64243AX	One-Time-Update to 64243AA/AB software	No longer supported	
64243DL	68000 Programmatic Interface	No longer supported	no replacement
64243DM	68000 Programmatic Interface Media & Doc	No longer supported	no replacement
64243DU	68000 Programmatic Interface Multi-user	No longer supported	no replacement
64244AA	68008 EMULATION SUBSYSTEM	No longer supported	
64244AX	One-Time-Update to current 64244AA SW	No longer supported	
64245AA	68010 EMULATION SUBSYSTEM	No longer supported	
64245AB	68010 EMULATION SUBSYSTEM	No longer supported	
64245AX	One-Time-Update to 64245AA/AB software	No longer supported	
64249A	68010 Emulator Pod	No longer supported	64245AA
64249AX	One-Time-Update to current 64249A SW	No longer supported	
64249S	68010 Emulation Subsystem	No longer supported	64245AB
64250A	Z80 FAMILY EMUL	No longer supported	
64251A	Z80 Emulator Control	No longer supported	64281B
64252A	Z80 Emulator Pod	No longer supported	64253A
64252AX	One-Time-Update to current 64252A SW	No longer supported	
64252S	Z80 Emulation Subsystem	No longer supported	64253S
64252SF	Z80 EMUL SW	No longer supported	64253A
64252ST	Z80 EMUL SW	No longer supported	64253SF
64252UF	64252UF SW SUBSC	No longer supported	
64252UT	64252UT SW SUBSC	No longer supported	
64253A	Z80 Emulation Pod	No longer supported	
64253AX	One-Time-Update to current 64253A SW.	No longer supported	
64253S	Z80 Emulation Subsystem	No longer supported	
64255A	6801/03 Emulation Control Board	No longer supported	
64256A	6801/03 Emulator Pod	No longer supported	
64256AX	One-Time-Update to current 64256A SW	No longer supported	
64256S	6801/03 Emulation Subsystem	No longer supported	
64256SF	6801/03 EMUL SFT	No longer supported	64256A
64256ST	6801/03 EMUL SFT	No longer supported	64256SF
64256UF	6801/03 EMUL SHT	No longer supported	
64256UT	6801/03 EMUL SFT	No longer supported	
64260A	8048 EMUL SYSTEM	No longer supported	64262S
64261A	8048 Family Emulation Control Card	No longer supported	
64262A	8048 Emulator Pod	No longer supported	
64262AX	One-Time-Update to current 64262A SW	No longer supported	
64262S	8048 Emulation Subsystem	No longer supported	
64262SF	8048 EMUL SW	No longer supported	64262A
64262ST	8048 EMUL SW	No longer supported	64262SF
64262UF	64262UF SW SUBSC	No longer supported	
64262UT	64262UT SW SUBSC	No longer supported	
64263A	8051 Emulation Control Board	No longer supported	
64263RA	Remarketed 8051 Family Control Card.	No longer supported	
64264A	8051 Emulator Pod	No longer supported	
64264AX	One-Time-Update to current 64264A SW	No longer supported	
64264RA	Remarketed 8051 Emulator POD.	No longer supported	
64264S	8051 Emulation Subsystem	No longer supported	
64265A	68HC11A emulation subsystem	No longer supported	
64265AX	One-Time-Update to current 64265A SW	No longer supported	
64268A	48-pin DIP CPU cable for 68HC11	No longer supported	
64268B	52-pin PLCC CPU cable for 68HC11	No longer supported	no replacement
64271A	GP EMUL CONT	No longer supported	64271B

Product	Description	Support Status	Replacement Information
64271B	GP Control Card	No longer supported	
64272A	ROM Emulator Pod	No longer supported	no replacement
64272AX	One-Time-Update to current 64272A SW	No longer supported	
64272S	ROM Emulator	No longer supported	no replacement
64272SF	ROM EMUL SW	No longer supported	64272A
64272ST	ROM EMUL SW	No longer supported	64272SF
64272UF	ROM SW UPDATE	No longer supported	
64272UT	ROM SW UPDATE	No longer supported	
64274A	User Definable Emulation Control Board	No longer supported	
64274B	User Definable Emulation Pod Kit	No longer supported	
64274BX	One-Time-Update to current 64274B SW	No longer supported	
64274C	Emulation Software	No longer supported	
64274DL	MDC281 Programmatic Interface	No longer supported	
64274DM	MDC281 Programmatic Interface Media	No longer supported	
64274DU	MDC281 Programmatic Intf. Lic. Upgrade	No longer supported	
64274S	User Definable Emulator Subsystem	No longer supported	
64274SF	UDE SOFTWARE	No longer supported	
64274ST	UDE SOFTWARE	No longer supported	64274SF
64274UF	UDE SW UPDATE	No longer supported	
64274UT	UDE SW UPDATE	No longer supported	
64275A	Writable Control Store	No longer supported	no replacement
64276A	Run Control Module	No longer supported	no replacement
64276AX	One-Time-Update To Current 64276A/B/C SW	No longer supported	
64276B	Run Control Module With 32K Bytes Of WCS	No longer supported	no replacement
64276C	Run Control Module With 64K Bytes Of WCS	No longer supported	no replacement
64277A	User Definable WCS Control	No longer supported	no replacement
64277AX	One-Time-Update To Current 64277A SW	No longer supported	
64285A	TMS 32010 Emulation Pod	No longer supported	
64285AX	One-Time-Update to current 64285A SW	No longer supported	
64285S	TMS 32010 Emulation Pod	No longer supported	
64286AA	F9450 EMULATOR POD	No longer supported	64286AB
64286AB	15 MHz F9450 Emulation Pod	No longer supported	
64286AX	One-Time-Update to current 64286SA SW	No longer supported	
64286DL	F9450 Programmatic Interface	No longer supported	
64286DM	F9450 Programmatic Interface Media & Doc	No longer supported	
64286DU	F9450 Programmatic Interface Multi-user	No longer supported	
64286SA	F9450 EMULATION SUBSYSTEM	No longer supported	64286SB
64286SB	15MHz F9450 Emulation Subsystem	No longer supported	
64288A	PACE 1750A 20MHz Emulation Pod	No longer supported	
64288AX	One-Time-Update	No longer supported	
64288DL	P1750 Programmatic Interface Single-user	No longer supported	
64288DM	P1750 Programmatic Interface	No longer supported	
64288DU	P1750 Programmatic Interface	No longer supported	
64288S	PACE 1750A Emulation Subsystem	No longer supported	
64291A	NSC800 Emulation Control Board	No longer supported	no replacement
64292A	NSC800 Emulator Pod	No longer supported	no replacement
64292AX	One-Time-Update to current 64292A SW	No longer supported	
64292S	NSC800 Emulation Subsystem	No longer supported	no replacement
64294A	70116 EMULATION POD	No longer supported	
64294AX	ONE-TIME UPDATE	No longer supported	
64294S	70116 EMULATOR	No longer supported	
64295A	70108 EMULATION POD	No longer supported	
64295AX	ONE-TIME UPDATE	No longer supported	
64295S	70108 EMULATOR	No longer supported	
64296A	70216 Emulation Pod	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
64296AX	One-Time-Update to current 64296A SW	No longer supported	
64296S	70216 Emulation Subsystem	No longer supported	
64297A	70208 Emulation Pod.	No longer supported	
64297AX	One-Time-Update to current 64297A SW	No longer supported	
64297S	70208 Emulation Subsystem	No longer supported	
64300A	Logic Analyzer	No longer supported	64302A
64302A	48 Channel Internal Analysis	No longer supported	
64303A	Intermodule Bus Extender	No longer supported	
64303AX	One-Time-Update to current 64303A SW	No longer supported	
64303RA	Remarketed IMB Extender	No longer supported	
64304A	Emulation Bus Preprocessor	No longer supported	
64304AX	One-Time-Update to current 64304A SW	No longer supported	
64306A	IMB/CMB Interface Board	No longer supported	
64310A	Software Performance Analyzer	No longer supported	
64310AF	SPA SW FLOPPY	No longer supported	
64310AT	SPA SW TAPE	No longer supported	
64310AX	One-Time-Update to current 64310A SW	No longer supported	
64310RA	Remarketed Software performance analyzer	No longer supported	
64310UF	64310UF SW SUBSC	No longer supported	
64310UT	64310UT SW SUBSC	No longer supported	
64320S	25MHz State 30 Channel	No longer supported	
64321A	25MHz Control Board For Use With 64320S	No longer supported	
64321AX	One-Time-Update to current 64320S SW	No longer supported	
64322A	25MHz Data Acquisition Board For 64320S	No longer supported	
64324A	25MHz Data Probe For Use With 64320S	No longer supported	
64325A	25MHz Clock Probe For Use With 64320S	No longer supported	
64331A	High Level Software Analyzer	No longer supported	
64331AR	Right to make 1 copy of 64331A SW	No longer supported	
64331AX	One-Time-Update to current 64331A SW	No longer supported	
64331B	HIGH-LEVEL SOFTWARE ANALYZER FOR 68000	No longer supported	
64331BR	Right to make 1 copy of 64331B SW	No longer supported	
64331BX	One-Time-Update to current 64331B SW	No longer supported	
64332A	High Level Software Analyzer	No longer supported	
64332AR	Right to make 1 copy of 64332A SW	No longer supported	
64332AX	One-Time-Update to current 64332A SW	No longer supported	
64332B	HIGH-LEVEL SOFTWARE ANALYZER	No longer supported	
64332BR	Right to make 1 copy of 64332B SW	No longer supported	
64332BX	One-Time-Update to current 64332B SW	No longer supported	
64333A	Software Analyzer For 8088 Emulation Sub	No longer supported	
64333AR	Right to make 1 copy of 64333A SW	No longer supported	
64333AX	One-Time-Update to current 64333A SW	No longer supported	
64333B	HIGH-LEVEL SOFTWARE ANALYZER	No longer supported	
64333BR	Right to make 1 copy of 64333B SW	No longer supported	
64333BX	One-Time-Update to current 64333B SW	No longer supported	
64334A	Software Analyzer For 68010 Emul Subsys	No longer supported	
64334AR	Right to make 1 copy of 64334A SW	No longer supported	
64334AX	One-Time-Update to current 64334A SW	No longer supported	
64334B	HIGH-LEVEL SOFTWARE ANALYZER FOR 68010	No longer supported	
64334BR	Right to make 1 copy of 64334B SW	No longer supported	
64334BX	One-Time-Update to current 64334B SW	No longer supported	
64335A	High Level SW Analyzer For The 80186	No longer supported	
64335AR	Right to make 1 copy of 64335A SW	No longer supported	
64335AX	One-time-Update to current 64335A SW	No longer supported	

Product	Description	Support Status	Replacement Information
64336A	High Level SW Analyzer For The 80188	No longer supported	
64336AR	Right to make 1 copy of 64336A SW	No longer supported	
64336AX	One-Time-Update to current 64336A SW	No longer supported	
64337A	HIGH-LEVEL SOFTWARE ANALYZER FOR 68008	No longer supported	
64337AR	Right to make 1 copy of 64337A SW	No longer supported	
64337AX	One-Time-Update to current 64337A SW	No longer supported	
64338A	High-Level Software Analyzer For 70116	No longer supported	no replacement
64338AR	Right To Reproduce One Copy Of 64338A SW	No longer supported	no replacement
64338AX	One-Time-Update Of 64338A Software	No longer supported	
64339A	HIGH LEVLE SOFTWARE ANALYZER FOR 70108	No longer supported	no replacement
64339AR	Right To Reproduce One Copy Of 64339A SW	No longer supported	no replacement
64339AX	One-Time-Update Of 64339A Software	No longer supported	
64340A	Software Analyzer For Pascal Or C	No longer supported	
64340AX	One-Time-Update to current 64340A SW	No longer supported	
64341AA	SOFTWARE FOR 64340A	No longer supported	
64341AR	Right to make 1 copy of 64341AA SW	No longer supported	
64341AX	One-Time-Update to current 64341A SW	No longer supported	
64341BA	Software Required For 64340A	No longer supported	
64341BR	Right to make 1 copy of 64341BA SW	No longer supported	
64341BX	One-Time-Update to current 64341BA SW	No longer supported	
64341CA	SOFTWARE FOR 64340A	No longer supported	
64341CR	Right to make 1 copy of 64341CA SW	No longer supported	
64341CX	One-Time-Update to current 64341CA SW	No longer supported	
64341DA	Software Required For 64340A	No longer supported	
64341DR	Right to make 1 copy of 64341DA SW	No longer supported	
64341DX	One-Time-Update to current 64341DA SW	No longer supported	
64341EA	Software Required For 64340A	No longer supported	
64341ER	Right to make 1 copy of 64341EA SW	No longer supported	
64341EX	One-Time-Update to current 64341EA SW	No longer supported	
64341FA	Software Required For 64340A	No longer supported	
64341FR	Right to make 1 copy of 64341FA SW	No longer supported	
64341FX	One-Time-Update to current 64341FA SW	No longer supported	
64341GA	SOFTWARE REQUIRED FOR USE WITH 64340A	No longer supported	
64341GR	Right to make 1 copy of 64341GA SW	No longer supported	
64341GX	One-Time-Update to current 64341GA SW	No longer supported	
64341IA	SOFTWARE FOR 64340A	No longer supported	
64341IR	Right to make 1 copy of 64341IA SW	No longer supported	
64341IX	One-Time-Update to current 64341IA SW	No longer supported	
64342AA	Software Required For Use With 64340A	No longer supported	no replacement
64342AR	Right To Reproduce One Copy Of 64341AA	No longer supported	no replacement
64342AX	One-Time-Update Of 64342AA Software	No longer supported	
64342BA	Software Required For Use With 64340A	No longer supported	no replacement
64342BR	Right To Copy	No longer supported	no replacement
64342BX	One-Time-Update Of 64342BA Software	No longer supported	
64360L	68000 Series Debugger/Simulator License	No longer supported	
64360M	68000 Series Debugger/Simulator	No longer supported	
64360U	68000 Series Debugger/Simulator License	No longer supported	
64361L	68000 Debugger/Emulator	No longer supported	
64361M	68000 Debugger/Emulator	No longer supported	
64361U	68000 Debugger/Emulator	No longer supported	
64362L	68000/10/302 Debugger/Emulator License	No longer supported	
64362M	68000/10/302 Debugger/Emulator Media	No longer supported	
64362U	68000/10/302 Debugger/Emulator Lic. Upgd	No longer supported	

Product	Description	Support Status	Replacement Information
64363L	68020/030 Debugger/Emulator	No longer supported	
64363M	68020/030 Debugger/Emulator	No longer supported	
64363U	68020/030 Debugger/Emulator	No longer supported	
64364L	68010 Debugger/Emulator	No longer supported	
64364M	68010 Debugger/Emulator Media	No longer supported	
64364U	68010 Debugger/Emulator License Upgrade	No longer supported	
64365L	68331/332 Debugger/Emulator	No longer supported	
64365M	68331/332 Debugger/Emulator	No longer supported	
64365U	68331/332 Debugger/Emulator	No longer supported	
64367L	8086 Series Debugger/Simulator License	No longer supported	
64367M	8086 Series Debugger/Simulator Media	No longer supported	
64367U	8086 Series Debugger/Simulator License	No longer supported	
64368L	68030/40 Debugger/Simulator License	No longer supported	
64368M	68030/40 Debugger/Simulator Media	No longer supported	
64368U	68030/40 Debugger/Simulator License	No longer supported	
64371L	68040 Debugger/Emulator License	No longer supported	
64371M	68040 Debugger/Emulator Media and Doc.	No longer supported	
64371U	68040 Debugger/Emulator License Upgrade	No longer supported	
64372L	68020/030 (64748/747)Debug/Emul Lic.	No longer supported	
64372M	68020 (64748) Debugger/Emulator	No longer supported	
64372U	68020 (64748) Debugger/Emulator	No longer supported	
64375L	8086 Series Debugger/Emulator License	No longer supported	
64375M	8086 Series Debugger/Emulator Media	No longer supported	
64375U	8086 Series Debugger/Emulator Lic. Upgrd	No longer supported	
64376L	80186/88 Debugger/Emulator Single Lic.	No longer supported	
64376M	80186/88 Debugger/Emulator Media & Doc.	No longer supported	
64380L	68000 Basis Branch Analyzer Single-user	No longer supported	
64380M	Basis Branch Analyzer for 68000 Media	No longer supported	
64380U	68000 Basis Branch Analyzer Multi-user	No longer supported	
64381L	68020 BBA Single-user license	No longer supported	
64381M	68020 BBA Media and Documentation	No longer supported	
64381U	68020 BBA Multi-user license	No longer supported	
64382L	8086/186 Basis Branch Analyzer Single	No longer supported	
64382M	8086/186 Basis Branch Analyzer	No longer supported	
64382U	8086/186 Basis Branch Analyzer Multi	No longer supported	
64383L	68030 BBA Single-user license	No longer supported	
64383M	68030 BBA Media and Documentation	No longer supported	
64383U	68030 BBA Multi-user license	No longer supported	
64384L	68332 BBA Single-user license	No longer supported	
64384M	68332 BBA Media and Documentation	No longer supported	
64384U	68332 BBA Multi-user license	No longer supported	
64385L	68040 BBA Single-user license	No longer supported	
64385M	68040 BBA Media and Documentation	No longer supported	
64385U	68040 BBA Multi-user license upgrade	No longer supported	
64386L	V Series Basis Branch Anlz Single-user	No longer supported	
64386M	V Series BBA Media and Documentation	No longer supported	
64386U	V Series BBA Multi-user license	No longer supported	
64404A	Internal Analysis Board For 8/16-Bit uP	No longer supported	
64404B	Internal analysis board for 8 and 16 bit	No longer supported	
64405A	Internal Analysis Expansion Board	No longer supported	
64405B	Internal Analysis Expansion Board 32-bit	No longer supported	
64406B	Analysis Interconnect Board (3 Position)	No longer supported	
64410A	68020 Emul Pod (256K Memory)	No longer supported	64410C
64410AX	One-Time-Update to current 64410A SW	No longer supported	64410SX
64410B	68020 Emul Pod (512K Memory)	No longer supported	64410D
64410C	68020 Emulation Pod (256K Memory)	No longer supported	

Product	Description	Support Status	Replacement Information
64410D	68020 Emulation Pod (512K)	No longer supported	
64410DL	68020 Programmatic Interface	No longer supported	
64410DM	68020 Programmatic Interface Media	No longer supported	
64410DU	68020 Programmatic Interface Multi-user	No longer supported	
64410E	68020 20 > 25 MHz Upgrade	No longer supported	
64410SA	68020 Emul/Anal Sys (256K Memory)	No longer supported	64410SC
64410SB	68020 Emul/Anal System (512K Memory)	No longer supported	64410SD
64410SC	68020 Emul/Anal Sys (256K)	No longer supported	
64410SD	68020 Emul/Anal System (512K)	No longer supported	
64410SX	One-Time-Update	No longer supported	
64411A	Nondequeued Analysis Bus Generator Board	No longer supported	
64414A	68020 CPU Cable, 114-Pin PGA	No longer supported	
64416A	68020 Emulation Subsystem with 256k Mem.	No longer supported	64410A
64416B	68020 Emulation Subsystem with 512k Mem.	No longer supported	64410B
64420A	80386 Emulator	No longer supported	
64420B	80386 Emulator	No longer supported	
64420SA	80386 Emulator/Analyzer	No longer supported	
64420SB	80386 Emulator/Analyzer	No longer supported	
64420SX	One-Time-Update	No longer supported	
64430A	68030 Emulation Pod (1 Mbyte Memory)	No longer supported	
64430B	68030 Emulation Pod (2 Mbyte Memory)	No longer supported	
64430DL	68030 Programmatic Interface	No longer supported	
64430DM	68030 Programmatic Interface Media	No longer supported	
64430DU	68030 Programmatic Interface Lic Upgrade	No longer supported	
64430SA	68030 Emulation Analysis System 1 Mbyte	No longer supported	
64430SB	68030 Emulation/Analysis System 2 Mbyte	No longer supported	
64430SX	One-Time-Update	No longer supported	
64431A	68030 ABG Board with MMU Translation	No longer supported	
64433A	68030 Active Probe	No longer supported	
64440A	68020 Emulation Pod (1 Mbyte Memory)	No longer supported	
64440B	68020 Emulation Pod (2Mbyte Memory)	No longer supported	
64440DL	68020 Active Probe Programmatic Interfac	No longer supported	
64440DM	68020 Active Probe Programmatic Interfac	No longer supported	
64440DU	68020 Active Probe Programmatic Interfac	No longer supported	
64440SA	68020 Emul/Anlz System (1 Mbyte)	No longer supported	
64440SB	68020 Emul/Anlz System (2 Mbyte)	No longer supported	
64440SX	One-Time-Update	No longer supported	
64441A	68020 Active Probe	No longer supported	
64500A	ROM PROG SUBSYS	No longer supported	64500S
64500S	PROM Programming Subsystem For 2716	No longer supported	
64500SF	PROM PROG SFTWRE	No longer supported	
64500ST	PROM PROG SFTWRE	No longer supported	64500SF
64500UF	64500UF SW SUBSC	No longer supported	
64500UT	64500UT SW SUBSC	No longer supported	
64501A	PROM Programmer Control	No longer supported	
64501AX	One-Time-Update To Current 64501A SW	No longer supported	
64502A	PROM Programmer Interface For INTEL 2716	No longer supported	
64503A	PROM INTR TIS47X	No longer supported	
64504A	PROM Programmer Interface For Harris	No longer supported	no replacement
64505A	PROM Programmer Interface For Signetics	No longer supported	no replacement
64507A	PROM Interface For INTEL 2708/04	No longer supported	
64508A	PROM INTR TIS287	No longer supported	

Product	Description	Support Status	Replacement Information
64509A	PROM Interface For INTEL 2732	No longer supported	
64510A	PROM INTR 8748	No longer supported	64510B
64510B	PROM Programmer Module For INTEL 8748/49	No longer supported	
64513A	PROM Interface For INTEL 8755A	No longer supported	no replacement
64514A	PROM Interface For MOTOROLA 68764	No longer supported	no replacement
64515A	PROM INTR 2764	No longer supported	64515B
64515B	PROM INTR 2764	No longer supported	64515C
64515C	PROM Programmer INTEL 2764/27128/27256	No longer supported	
64516A	PROM Interface Module For 27512/513	No longer supported	
64517A	PROM Programmer Interface For MOTOROLA	No longer supported	64517B
64517B	PROM Programmer Module for Motorola	No longer supported	no replacement
64520A	PROM Interface For INTEL 8751A	No longer supported	
64550S	Hosted PROM Programming Subsystem	No longer supported	
64551A	PROM Module Adapter	No longer supported	
64552A	PROM Programmer Interface for 68HC11	No longer supported	
64553A	27010 PROM Prog Module	No longer supported	
64554A	27210 PROM Prog Module	No longer supported	
64600S	8 CHAN TIM ANALY	No longer supported	
64600SF	TIMING SW MINI F	No longer supported	64610S
64600ST	TIMING SW TAPE	No longer supported	64600SF
64600UF	64600UF SW SUBSC	No longer supported	
64600UT	64600UT SW SUBSC	No longer supported	
64601A	CONTROL BOARD	No longer supported	64601B.
64601AX	One-Time-Update	No longer supported	64601BX.
64601B	Control Board For 64610S	No longer supported	no replacement
64601BX	One-Time-Update to current 64610S SW	No longer supported	
64602A	Data Qcquisition Board	No longer supported	no replacement
64604A	Logic Timing Analyzer 8 Channel Probe	No longer supported	no replacement
64605A	Clock Probe For 64610S	No longer supported	no replacement
64606A	Data Delay Pod	No longer supported	no replacement
64610S	Logic Analyzer	No longer supported	no replacement
64620S	20 Channel Logic State/SW Analysis Sub	No longer supported	
64620SF	STATE SW MINI F	No longer supported	
64620ST	STATE SW ON TAPE	No longer supported	64620SF
64620UF	64620UF SW SUBSC	No longer supported	
64620UT	64620UT SW SUBSC	No longer supported	
64621A	Logic State Analyzer Control Board	No longer supported	
64621AX	One-Time-Update to 64621A software	No longer supported	
64621RA	Remarketed Logic State/SW analyzer card.	No longer supported	
64622A	40 Channel Logic State Data Acq. Card	No longer supported	
64622RA	40 Channel Acquisition card.	No longer supported	
64623A	20 Channel Logic State Data Acq. Card	No longer supported	
64623RA	Remarketed 20-Channel Data Acquisition	No longer supported	
64630S	20 Channel General Purpose Probe	No longer supported	
64635A	20 CH DATA PROBE	No longer supported	
64636A	8 CH CLOCK PROBE	No longer supported	
64650A	G.P. PREPROCESSR	No longer supported	
64650RA	Remarketed preprocessor module	No longer supported	
64651A	G.P. IFC MODULE	No longer supported	64651B
64651B	VW INTRFC MODULE	No longer supported	no replacement
64653A	8086/88 Interface Module	No longer supported	
64653AX	One-Time-Update to current 64653A SW	No longer supported	
64653SF	8086/88 PP SW MI	No longer supported	64653A
64653ST	8086/88 PP SW TP	No longer supported	64653SF
64653UF	64653UF SW SUBSC	No longer supported	
64653UT	64653UT SW SUBSC	No longer supported	
64655A	8085 Interface Module	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
64655AX	One-Time-Update to current 64655A SW	No longer supported	
64655SF	8085 P.P. SW MIN	No longer supported	64655A
64655ST	8085 P.P.SW TAPE	No longer supported	64655SF
64655UF	64655UF SW SUBSC	No longer supported	
64655UT	64655UT SW SUBSC	No longer supported	
64657A	80286 Interface Module	No longer supported	64657B
64657AX	One-Time-Update to current 64657B SW	No longer supported	
64657B	80286 Interface Module	No longer supported	
64658A	80186/80188 Interface Module	No longer supported	
64658AX	One-Time-Update to current 64658A SW	No longer supported	
64659A	80386 Interface Module	No longer supported	no replacement
64659AX	One-Time-Update to current 64659A SW	No longer supported	
64670A	68000 INTFC MOD	No longer supported	64674A
64670AU	64670AU SW SUBSC	No longer supported	64674AU
64670AW	RIGHT TO COPY	No longer supported	64674AW
64670SF	68000 PP SW FDSK	No longer supported	
64670ST	68000 PP SW TAPE	No longer supported	64670SF
64670UF	64670UF SW SUBSC	No longer supported	
64670UT	64670UT SW SUBSC	No longer supported	
64671A	6809/6809E Interface Module	No longer supported	
64671AX	One-Time-Update to current 64671A SW	No longer supported	
64672A	6800/02 INTF MOD	No longer supported	
64672AU	64672AU SW SUBSC	No longer supported	64672BU
64672AW	RIGHT TO COPY	No longer supported	64672BW
64672B	6800/02 Interface Module	No longer supported	
64672BX	One-Time-Update to current 64672B SW	No longer supported	
64673A	68008 Interface Module	No longer supported	
64673AX	One-Time-Update to current 64673A SW	No longer supported	
64674A	68000/10 Interface Module	No longer supported	
64674AX	One-Time-Update to current 64674A SW	No longer supported	
64675A	68020 Interface Module	No longer supported	
64675AX	One-Time-Update to current 64675A SW	No longer supported	
64675B	68020 Interface Module with MMU support	No longer supported	
64680A	Z8001 Interface Module	No longer supported	
64680AX	One-Time-Update to current 64680A SW	No longer supported	
64680SF	Z8001/02 SW FDSK	No longer supported	
64680ST	Z8001/02 SW TAPE	No longer supported	64680SF
64680UF	64680UF SW SUBSC	No longer supported	
64680UT	64680UT SW SUBSC	No longer supported	
64681A	Z8002 Interface Module	No longer supported	
64681AX	One-Time-Update to current 64681A SW	No longer supported	
64683A	Z80 Interface Module	No longer supported	
64683AX	One-Time-Update to current 64683A SW	No longer supported	
64683SF	Z80 PP SW FDSK	No longer supported	
64683ST	Z80 P.P. SW TAPE	No longer supported	64683SF
64683UF	64683UF SUBSC	No longer supported	
64683UT	64683UT SW SUBSC	No longer supported	
64690A	NSC800 Interface Module	No longer supported	
64690AX	One-Time-Update to current 64690A SW	No longer supported	
64695A	GPIO/RS232C/RS449 Interface Module	No longer supported	
64695AX	One-Time-Update to current 64695A SW	No longer supported	
64700A	64700 Series Cardcage	No longer supported	
64700AR	Rmkt 64700 Series Cardcage	No longer supported	no replacement
64700AX	PC Generic Emulation Firmware	No longer supported	
64700B	64700 Series CardCage	No longer supported	
64700BR	64700 Series Card Cage	Currently supported	
64700TN	64700 Course Student Kit	No longer supported	
64701A	Local Area Network Card	No longer supported	
64701AR	Rmkt Local Area Network Card	No longer supported	no replacement
64702S	Teamwork/ACCESS	No longer supported	
64702SR	Right to make 1 copy of 64702S software	No longer supported	

Product	Description	Support Status	Replacement Information
64702SX	One-Time-Update for 64702S software	No longer supported	
64703A	64CH Internal + 16CH External Analyzer	No longer supported	
64703AR	Rmkt 64 Chn Internal + 16 Chn External	No longer supported	no replacement
64704A	80 Channel Internal Analyzer	No longer supported	
64704AR	80 Channel Internal Analyzer	No longer supported	no replacement
64705A	108 Channel Emulation Bus Analyzer	No longer supported	
64706A	48 Channel Internal Analyzer	No longer supported	
64706AR	Rmkt 48 Channel Internal Analyzer	No longer supported	no replacement
64708A	Software Performance Analyzer	No longer supported	
64708AR	Rmkt Software Performance Analyzer	No longer supported	no replacement
64708SA	pSOS+ Real-Time Op.Sys./SPA Bundle	No longer supported	
64708SB	VRTX32 Real-Time Op. Sys. / SPA Bundle	No longer supported	
64708SY	SPA + 64K Deep Trace Bundle	No longer supported	
64710S	Teamwork/SA for Structured Analysis	No longer supported	
64710SR	Right To Reproduce. Must order option.	No longer supported	
64710SX	One-Time-Update. Must order option.	No longer supported	
64712S	Add Teamwork/SD to Teamwork/SA	No longer supported	
64712SR	Right To Reproduce. Must order option.	No longer supported	
64713S	SE Teamwork Consulting Kit	No longer supported	
64714S	Add Teamwork/IM	No longer supported	
64714SR	Right To Copy	No longer supported	
64715S	Real-time extensions for Teamwork/SA	No longer supported	
64715SR	Right To Reproduce. Must order option.	No longer supported	
64715SX	One-Time-Update. Must order option.	No longer supported	
64716S	Teamwork/IM	No longer supported	
64716SR	Right To Copy	No longer supported	
64716SX	One-Time-Update	No longer supported	
64717S	Add Teamwork/SA to Teamwork/SD	No longer supported	
64717SR	Right To Reproduce. Must order option.	No longer supported	
64718S	Trial Copy of Teamwork	No longer supported	
64720S	Teamwork/SD for Structured Design	No longer supported	
64720SR	Right To Reproduce. Must order option.	No longer supported	
64720SX	One-Time-Update. Must order option.	No longer supported	
64722S	Teamwork Project Environment	No longer supported	B1400A
64723S	Teamwork / ADA	No longer supported	
64723SR	Right to Copy	No longer supported	
64723SX	One-Time-Update	No longer supported	
64724S	Add TEAMWORK/Ada	No longer supported	
64724SR	Right to Copy	No longer supported	
64725A	8 bit emulation memory board 128KB	No longer supported	
64726A	16 bit emulation memory board 128KB	No longer supported	
64727A	16 bit emulation memory board 512KB	Currently supported	
64727AR	16 bit emulation memory board 512KB	Currently supported	
64728A	1 Mbyte Emulation Memory Board	No longer supported	
64729A	2M Byte Emulation Memory Board	Currently supported	
64729AR	2Mb Emulation memory board	Currently supported	
64730A	H8/570 Emulation Board with no memory	No longer supported	
64730S	H8/570 PC Interface Software	No longer supported	
64731A	V25 Emulator/Analyzer	No longer supported	
64731AL	V25 Emulator/Analyzer with ext. anal	No longer supported	
64731AX	One-Time-Update	No longer supported	
64731F	V25 emulation board with no memory	No longer supported	
64731S	V25 Hosted Interface	No longer supported	
64732A	H8/510 emulation board with no memory	No longer supported	
64732AX	One-Time-Update	No longer supported	
64732S	H8/510 Hosted User Interface	No longer supported	
64733A	H16 Emulator	No longer supported	
64733AL	H16 Emulator/Analyzer + Ext. Anal	No longer supported	
64733AX	One-Time-Update	No longer supported	
64733F	H16 emulation board with no memory	No longer supported	

Product	Description	Support Status	Replacement Information
64733S	H16 Hosted Interface	No longer supported	
64734A	H8/325 Series Emulator/Analyzer	No longer supported	
64734AL	H8/325 Emulator/Analyzer + Ext. Analysis	No longer supported	
64734F	H8/325 emulation board with no memory	No longer supported	
64734S	H8/325 Hosted User Interface	No longer supported	
64735A	647180X Emulator/Analyzer	No longer supported	
64735AL	647180X Emul/Anal with ext. anal	No longer supported	
64735AX	One-Time-Update	No longer supported	
64735F	647180X emulation board with no memory	No longer supported	
64735S	Hosted Interface SW	No longer supported	
64736A	H8/330 (HD6473308) Emulator/Analyzer	No longer supported	
64736AL	H8/330 (HD6473308) Emul. with Ext. Anlz.	No longer supported	
64736AX	One-Time-Update	No longer supported	
64736F	H8/330 emulation board with no memory	No longer supported	
64736S	H8/330 Hosted User Interface	No longer supported	
64737A	H8/532 Emulator/Analyzer	No longer supported	
64737AL	H8/532 Emulator/Analyzer + Ext. Analysis	No longer supported	
64737AX	One-Time-Update	No longer supported	
64737F	H8/532 emulation board with no memory	No longer supported	
64737S	H8/532 Hosted User Interface	No longer supported	
64738A	H8/520 Emulator/Analyzer	No longer supported	
64738AL	H8/520 Emulator/Analyzer + Ext. Analysis	No longer supported	
64738AX	One-Time-Update	No longer supported	
64738F	H8/520 emulation board with no memory	No longer supported	no replacement
64738S	H8/520 Hosted User Interface	No longer supported	no replacement
64739AX	One-Time-Update	No longer supported	
64739B	H8/536S 16MHz emul. bd. with no memory	No longer supported	
64739S	H8/536 Hosted User Interface	No longer supported	
64742A	68000 DIP Emulator/Analyzer	No longer supported	
64742AL	68000 DIP Emulator/Analyzer + Ext Anal	No longer supported	
64742AX	One-Time-Update	No longer supported	
64742B	68000 PGA Emulator/Analyzer	No longer supported	
64742BL	68000 PGA Emulator/Analyzer + Ext Anal	No longer supported	
64742C	68000 DIP 512K Emulator/Analyzer	No longer supported	
64742CL	68000 512k DIP Emul/Anal + Ext. Anal	No longer supported	
64742D	68000 PGA 512K Emulator/Analyzer	No longer supported	
64742DL	68000 512K PGA Emul/Anal + Ext. Anal	No longer supported	
64742G	68000 12MHz emulation board with 128KB	No longer supported	
64742H	68000 12MHz PGA emulation board 128KB	No longer supported	
64742J	68000 12MHz DIP emulation board 512KB	No longer supported	
64742K	68000 12MHz PGA emulation board 512KB	No longer supported	
64742S	68000 Hosted User Interface	No longer supported	
64743A	68000 16 MHz DIP Emulator/Analyzer	No longer supported	
64743AL	68000 16 MHz DIP Emulator/Analyzer +Anal	No longer supported	
64743AX	One-Time-Update	No longer supported	
64743B	68000 16 MHz PGA Emulator/Analyzer	No longer supported	
64743BL	68000 16 MHz PGA Emulator/Analyzer +Anal	No longer supported	
64743C	68000 16MHz DIP Emulator/Analyzer	No longer supported	

Product	Description	Support Status	Replacement Information
64743CL	68000 16MHz DIP Emulator/Analyzer +Anal	No longer supported	
64743D	68000 16 MHz PGA Emulator/Analyzer	No longer supported	
64743DL	68000 16 MHz PGA Emulator/Analyzer +Anal	No longer supported	
64743E	16MHz 128K Upgrade	No longer supported	
64743F	16 MHz 512K Upgrade	No longer supported	
64743G	68000 16MHz DIP emulation board 128KB	No longer supported	
64743H	68000 16 MHz PGA emulation board 128KB	No longer supported	
64743J	68000 16MHz DIP emulation board 512KB	No longer supported	
64743K	68000 16MHz PGA emulation board 512KB	No longer supported	
64743N	68000 16 MHz DIP Emulator / 0 Memory	No longer supported	
64743P	68000 16MHz Emulator Board / 0 memory	No longer supported	
64743R	68000 16MHz PLCC Emulator Board /0 mem.	No longer supported	
64743RA	68000 16MHz PLCC emulation board 512KB	No longer supported	
64743S	68000 16 MHz Hosted User Interface	No longer supported	
64744AR	68EC000/000 16MHz Emulation Probe	Currently supported	
64744B	68000 DIP Adapter	No longer supported	
64744BY	68000 DIP Emulation Subsystem	No longer supported	
64744C	68000/HC001 PGA Adapter	No longer supported	
64744CY	68000/HC001 PGA Emulation Subsystem	No longer supported	
64744D	68000/HC001 PLCC Adapter	No longer supported	
64744DY	68000/HC001 PLCC Emulation Subsystem	No longer supported	
64744E	68EC000 PLCC Adapter	No longer supported	
64744EY	68EC000 PLCC Emulation Subsystem	No longer supported	
64744S	68000/EC000 Hosted User Interface	No longer supported	
64745A	68010 DIP Emulator/Analyzer	No longer supported	
64745AL	68010 DIP Emul/Anal + Ext Ana	No longer supported	
64745AX	Host Interface One-Time-Update	No longer supported	
64745B	68010 PGA Emulator/Analyzer	No longer supported	
64745BL	68010 PGA Emul/Anal + Ext Ana	No longer supported	
64745C	68010 DIP 512K Emulaotr/Analyzer	No longer supported	
64745CL	68010 512K DIP Emul/Anal + Ext. Anal	No longer supported	
64745D	68010 PGA 512K Emulator/Analyzer	No longer supported	
64745DL	68010 PGA 512K Emul/Anal + Ext. Anal	No longer supported	
64745J	68010 12MHz DIP emulation board 512K	No longer supported	
64745K	68010 12MHz PGA emulation board 512KB	No longer supported	
64745S	68010 Hosted User Interface	No longer supported	no replacement
64746A	68302 PGA Emulator/Analyzer 128Kbyte	No longer supported	
64746AL	68302 PGA Emulator/Analyzer + Ext. Anlz.	No longer supported	
64746AX	One-Time-Update	No longer supported	
64746B	68302 PGA Emulator/Analyzer 512K	No longer supported	
64746BL	68302 PGA Emulator/Analyzer + Ext. Anlz.	No longer supported	
64746H	68302 16MHz PGA emulation board 512KB	No longer supported	
64746JR	Rmkt 68302 PGA Emulator Board w/0 Memory	No longer supported	no replacement
64746S	68302 Hosted User Interface	No longer supported	
64746SY	68302 Emulation Subsystem	No longer supported	

Product	Description	Support Status	Replacement Information
64747A	68EC030 Emulation probe with no memory	No longer supported	
64747BR	Rmkt 68030/EC030 Emulation Probe w/0 Mem	No longer supported	no replacement
64747S	68EC030 Hosted User Interface	No longer supported	
64747SY	68030/EC030 Emulation Subsystem	No longer supported	
64748A	68020 33 MHz emulation probe/no memory	No longer supported	
64748B	68020/030 Analysis Bus Generator Board	No longer supported	
64748C	Emulation Control Card	No longer supported	
64748CR	Rmkt Emulation Control Card	No longer supported	no replacement
64748D	68020 33MHz emulation probe/no memory	No longer supported	
64748DR	68020 33MHz emulation probe/no memory.	Currently supported	
64748S	68020 Hosted User Interface	No longer supported	
64748SY	68020 Emulation Subsystem	No longer supported	
64749A	68332 ACT Emulator/Analyzer	No longer supported	
64749AL	68332 ACT Emulator/Analyzer + Ext. Anlz	No longer supported	
64749AX	One-Time-Update	No longer supported	
64749B	68332 512K Emulator/Analyzer	No longer supported	
64749BL	68332 512K Emulator/Analyzer + Ext Anlz	No longer supported	
64749C	68331 512K Emulator/Analyzer	No longer supported	
64749CL	68331 512K Emulator/Analyzer + Ext Anlz	No longer supported	
64749G	68332 16MHz emulation board with no mem.	No longer supported	
64749H	68332 16MHz emulation board with 512KB	No longer supported	
64749HR	Rmkt 68332 16MHz Emulation Board w/512Kb	No longer supported	no replacement
64749J	68331 16MHz emulation board with 512KB	No longer supported	
64749S	68332 Hosted User Interface	No longer supported	
64750A	68040 emulation subsystem with 512KB	No longer supported	
64750S	68040 Hosted User Interface	No longer supported	
64751A	68340 25MHz PGA Emulation Probe	No longer supported	
64751AR	68340 25MHz PGA Emulation Probe	Currently supported	
64751S	68340 Hosted User Interface Software	No longer supported	
64751SY	68340 Emulation Subsystem	No longer supported	
64752A	V810 emul. board with no emul. memory	No longer supported	
64752AX	64752A Firmware One-Time-Update	No longer supported	
64753A	Z80 Emulator/Analyzer	No longer supported	
64753AL	Z80 Emulator/Analyzer + Ext Anal	No longer supported	64753G
64753AX	One-Time-Update	No longer supported	no replacement
64753G	Z80 10Mhz emulation board with 64KB	No longer supported	
64753S	Z80 Hosted User Interface	No longer supported	
64754A	V25+ 10MHz Emulator/Analyzer	No longer supported	
64754AL	V25+ 10MHz Emulator/Analyzer + Ext. Anlz	No longer supported	
64754AX	One-Time-Update	No longer supported	
64754B	V25+ 10MHz Emulator with 512KB memory	No longer supported	
64754BL	V25+ 10MHz Emulator with Ext. Anlz 512KB	No longer supported	
64754F	V25+ 10MHz emulation board with no mem.	No longer supported	no replacement
64754S	V25+ Hosted User Interface	No longer supported	no replacement
64755A	V35+ 10MHz Emulator/Analyzer	No longer supported	

Product	Description	Support Status	Replacement Information
64755AL	V35+ 10MHz Emulator/Analyzer + Ext. Anlz	No longer supported	
64755AX	One-Time-Update	No longer supported	
64755B	V35+ 10MHz Emulator 512KB memory	No longer supported	
64755BL	V35+ 10MHz Emulator with Ext. Anlz 512K	No longer supported	
64755F	V35+ 10MHz emulation board with no mem.	No longer supported	
64755S	V35+ Hosted User Interface	No longer supported	
64756A	V33 16 MHz Emulator 128KB	No longer supported	
64756AL	V33 16MHz Emulator with Ext. Anlz 128KB	No longer supported	
64756AX	One-Time-Update	No longer supported	
64756B	V33 16MHz Emulator 512KB	No longer supported	
64756BL	V33 Emulation + Ext. Analysis 512KB	No longer supported	
64756F	V33 16MHz emulation board with no memory	No longer supported	
64756S	V33 (uPD70136) Hosted User Interface	No longer supported	
64757A	V53 16MHz Emulator/Analyzer 128KB	No longer supported	
64757AL	V53 16MHz Emulator with Ext. Anlz 128KB	No longer supported	
64757AX	One-Time-Update	No longer supported	
64757B	V53 16MHz Emulator 512KB	No longer supported	
64757BL	V53 16MHz Emulator with Ext. Anlz 512KB	No longer supported	
64757F	V53 16MHz emulator with no memory	No longer supported	no replacement
64757G	V53A emul. board with no emul. memory	No longer supported	
64757S	V53 (uPD70236) Hosted User Interface	No longer supported	
64758A	V70 20MHz Emulator 512KB of Emul. mem.	No longer supported	
64758AX	One-Time-Update	No longer supported	
64758B	V70 20MHZ Emulator 1MB of Emulation mem.	No longer supported	
64758G	V70 20MHz emulation subsystem 512KB	No longer supported	
64758H	V70 20MHz emulation subsystem 1MB	No longer supported	
64758S	V70(uPD70632) Hosted User Interface	No longer supported	
64759A	7821x Series Emulator/Analyzer	No longer supported	
64759AL	7821x Emulator/Analyzer + Ext. Analysis	No longer supported	
64759AX	One-Time-Update	No longer supported	
64759B	7822x Series Emulator/Analyzer	No longer supported	
64759BL	7822x Emulator + External Analysis	No longer supported	
64759C	7823x Series Emulator/Analyzer	No longer supported	
64759CL	7823x Emulator/Analyzer with Ext. Anlz	No longer supported	
64759F	782XX emulation board with no probe,mem	No longer supported	
64759S	782xx Hosted User Interface	No longer supported	
64760G	80960 KA/KB/MC emulation board	No longer supported	
64760S	80960 Hosted User Interface	No longer supported	
64761A	80960SA/SB Emulation Board	No longer supported	
64761S	80960SA/SB Hosted User Interface	No longer supported	
64762A	8086/8087 Emulator/Analyzer	No longer supported	
64762AL	8086/8087 Emulator/Analyzer + Ext. Anal	No longer supported	
64762AX	One-Time-Update	No longer supported	
64762B	8086/87 512K Emulator/Analyzer	No longer supported	
64762BL	8086/87 512K Emulator/Analyzer + Ext. An	No longer supported	
64762G	8086/8087 10MHz emulation board 128KB	No longer supported	
64762H	8086/8087 10MHz emulation board 512K	No longer supported	
64762S	8086/8087 Hosted User Interface	No longer supported	
64763A	8088/8087 Emulator/Analyzer	No longer supported	

Product	Description	Support Status	Replacement Information
64763AL	8088/8087 Emulator/Analyzer + Ext. Anal.	No longer supported	
64763AX	One-Time-Update	No longer supported	
64763G	8088/8087 10MHz emulation board 128K	No longer supported	
64763S	8088/8087 Hosted User Interface	No longer supported	
64764A	80186 Emulator/Analyzer	No longer supported	
64764AL	80186 Emulator/Analyzer + Ext Anal	No longer supported	
64764AX	One-Time-Update	No longer supported	
64764C	80C186 Emulator/Analyzer	No longer supported	
64764CL	80C186 Emulator/Analyzer	No longer supported	
64764D	80C186 Emulator/Analyzer	No longer supported	
64764DL	80C186 Emulator/Analyzer	No longer supported	
64764DX	One-Time-Update	No longer supported	
64764H	80C186 12.5MHz emulation board with 128K	No longer supported	
64764J	80C186 12.5MHz emulation board with 512K	No longer supported	
64764S	80186 Hosted User Interface	No longer supported	
64764SD	80C186 Hosted Interface	No longer supported	
64765A	80188 Emulator/Analyzer	No longer supported	
64765AL	80188 Emulator/Analyzer + Ext Anal	No longer supported	
64765AX	One-Time-Update	No longer supported	
64765D	80C188 Emulator/Analyzer	No longer supported	
64765DL	80C188 Emulator/Analyzer	No longer supported	
64765DX	One-Time-Update	No longer supported	
64765J	80C188 16MHz emulation board with 512K	No longer supported	
64765S	80188 Hosted User Interface	No longer supported	
64765SD	80C188 Hosted Interface	No longer supported	
64766B	80C286 Emulator/Analyzer with 512KB	No longer supported	
64766H	80C286 20MHz emulation board with 512KB	No longer supported	
64766S	80C286 Hosted User Interface	No longer supported	
64767A	80C186/88 EA/XL emulation board	No longer supported	
64767AL	80L186/88 EA/XL 3V Low Voltage Probe	No longer supported	
64767AR	80C186/88 EA/XL Emulation Board	Currently supported	
64767AY	80C186/88EA Emulation Subsystem	No longer supported	
64767B	80186/88 EB emulation probe board	No longer supported	
64767BL	80L186/88 EB 3V Low Voltage Probe	No longer supported	
64767BR	80186/88 EB emulation probe board	Currently supported	
64767BY	80186/88EB Emulation Subsystem	No longer supported	
64767C	80186/C186/188/C188 EC emulation probe	No longer supported	
64767CL	80L186/88 EC 3V Low Voltage Probe	No longer supported	
64767CY	80C186/88EC Emulation Subsystem	No longer supported	
64767S	80186/88Ex Hosted Interface Software	No longer supported	
64768A	V55PI emulation board with no memory	No longer supported	
64768B	V55PI 16MHz Emul. board with no memory	No longer supported	
64768S	V55PI (uPD70433) Hosted User Interface	No longer supported	
64770B	TLCS9000/42 Emulation Probe no memory	Currently supported	
64771A	80C196 Emulator/Analyzer	No longer supported	
64771AL	80C196 Emulator /Analyzer + Ext. Anlz.	No longer supported	
64771AX	One-Time-Update	No longer supported	
64771G	80C196 12MHz emulation board 64KB	No longer supported	
64771S	80C196-KA Hosted User Interface	No longer supported	
64772A	NS32532 Emulator/Analyzer	No longer supported	
64772AX	One-Time-Update	No longer supported	
64772G	NSC32532/32GX32 emulation board 512KB	No longer supported	

Product	Description	Support Status	Replacement Information
64772S	NS32532 Hosted User Interface	No longer supported	
64773A	AT&T DSP32C Emulator/Analyzer	No longer supported	
64773AL	AT&T DSP32C Emulator/Analyzer	No longer supported	
64773AX	One-Time-Update	No longer supported	
64773G	AT&T DSP32C emulation board with 64KB	No longer supported	
64773S	AT&T DSP32C Hosted User Interface	No longer supported	
64774A	29000 25MHz PGA Emul/Anlz with no memory	No longer supported	
64774AX	One-Time-Update	No longer supported	
64774B	29000 512K 25MHz PGA Emulator/Analyzer	No longer supported	
64774C	29000 1Mbyte PGA Emulator/Analyzer	No longer supported	
64774G	Am29000 30MHz PGA emulation board 0K mem	No longer supported	
64774H	Am29000 30MHz PGA emulation board 512KB	No longer supported	
64774J	Am29000 30MHz PGA emulation board 1MB	No longer supported	
64774K	Am29050 30MHz Emulation Board 0K memory	No longer supported	
64774S	AM29000/29050 Hosted User Interface	No longer supported	
64774SX	29000 Hosted User Interface	No longer supported	
64774Y	512KB memory module for 64774G	No longer supported	
64774Z	2 MB memory module for 64774G	No longer supported	
64775G	HPC16003, HPC16083 emulation board 128K	No longer supported	
64775H	HPC16004, HPC16064, HPC16164 emulator	No longer supported	
64775J	HPC16400E emulation board 128K	No longer supported	
64775S	HPC Hosted User Interface	No longer supported	
64778A	NS32GX320 Emulator/Analyzer 4Mbyte mem.	No longer supported	
64778AX	One-Time-Update	No longer supported	
64778G	NSC32GX20 emulation board with 2Mbyte	No longer supported	
64778S	NS32GX320 Hosted User Interface	No longer supported	
64779A	NS32FX16 Emulator/Analyzer 2 Mbyte mem.	No longer supported	
64779AL	NS32FX16 Emulator/Analyzer + Ext. Anlz.	No longer supported	
64779AX	One-Time-Update	No longer supported	
64779B	NS32CG16 Emulator/Analyzer 2 Mbyte mem	No longer supported	
64779BL	NS32CG16 Emulator/Analyzer + Ext. Anlz.	No longer supported	
64779C	NS32CG160 Emulator/Analyzer 2 Mbyte mem	No longer supported	
64779CL	NS32CG160 Emulator/Analyzer + Ext. Anlz.	No longer supported	
64779G	NS32FX16 emulation board with 2 Mbytes	No longer supported	
64779H	NS32CG16 emulation board with 2 Mbytes	No longer supported	
64779J	NS32CG160 emulation board with 2 Mbytes	No longer supported	
64779S	NS32FX16/32CG16/32CG160 Hosted Interface	No longer supported	
64780A	68360 Emulation Probe	No longer supported	
64780AR	68360 emulation probe	Currently supported	
64780SY	68360 Emulation Subsystem	No longer supported	
64781A	Hitachi PA/10 PGA emulation board 128K	No longer supported	

Product	Description	Support Status	Replacement Information
64781B	Hitachi PA/10 PQFP emulation board 128K	No longer supported	
64781S	Hitachi PA/10 Hosted User Interface	No longer supported	
64782BR	68331 emulation probe	Currently supported	
64782BY	68331 Emulation Subsystem	No longer supported	
64782CR	68040 40MHz Emulation probe-No Memory	Currently supported	
64782CY	68332 Emulation Subsystem	No longer supported	
64782EY	68334 Emulation Subsystem	No longer supported	
64782GY	68336 Emulation Subsystem	No longer supported	
64782J	68338 Emulation Probe	No longer supported	
64782JY	68338 Emulation Subsystem	No longer supported	
64783BR	68040 40MHz emulation Probe-No memory	Currently supported	
64783S	68040 Hosted User Interface	No longer supported	
64783SYR	68040 Emulation Subsystem	No longer supported	
64783SY	68040 Emulation Subsystem	No longer supported	
64784B	Optional Low Voltage Adapter	No longer supported	no replacement
64784C	H8/3003 QFP Adapter	Currently supported	
64784D	H8/3002/4X QFP Adapter	Currently supported	
64784E	H8/300H 135pin PGA Adapter	Currently supported	
64784F	H8/3003 112pin Flexible Cable	No longer supported	
64784G	H8/3002/4X 100pin Flexible Cable	Currently supported	
64784H	H8/303x 80pin Flexible Cable	Currently supported	
64784J	H8/3001 80pin Flexible Cable.	Currently supported	
64784K	H8/3004/5 80-pin flexible cable	No longer supported	
64784S	H8/300H Hosted User Interface	Currently supported	
64784SY	H8/300H 3003 Series Emulation Subsystem	Currently supported	
64785AX	64785A One-Time Firmware Update	Currently supported	
64785B	SH7020/21/32/34 Emul. Probe w/ no memory	Currently supported	
64785BY	SH7020/21/32/34 Emul. Subsystem	No longer supported	
64785C	112 pin Flexible Cable	Currently supported	
64785D	100 pin Flexible Cable	Currently supported	
64785SY	SH7000 Emulation Subsystem	No longer supported	
64786A	TMS32020 PGA Emulator/Analyzer	No longer supported	no replacement
64786AL	TMS32020 PGA Emulator/Analyzer	No longer supported	no replacement
64786AX	One-Time-Update	No longer supported	
64786S	TMS32020 Hosted User Interface	No longer supported	
64787A	TMS320C25 PGA Emulator/Analyzer	No longer supported	
64787AL	TMS320C25 PGA Emulator/Analyzer	No longer supported	
64787AX	One-Time-Update	No longer supported	
64787G	TMS320C25 40MHz emulation board 128K	No longer supported	
64787S	TMS320C25 Hosted User Interface	No longer supported	
64788A	8051 Family DIP Emulator/Analyzer	No longer supported	
64788AL	8051 Family DIP Emul/Anal. + Ext. Anal	No longer supported	
64788AX	One-Time-Update	No longer supported	
64788B	8051 Family PLCC Emulator/Analyzer	No longer supported	
64788BL	8051 Family PLCC Emul/Anal + Ext. Anal.	No longer supported	
64788G	8051 family 16MHz DIP emulation board	No longer supported	
64788H	8051 family 16MHz PLCC emulation board	No longer supported	
64788S	8051 Family Hosted User Interface	No longer supported	
64789AR	80386DX Emulation probe with no memory	Currently supported	
64789C	80386Ex Emulator Probe	No longer supported	
64789CR	80386Ex Emulator Probe	Currently supported	
64789DY	80386DX Emulation Subsystem	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
64789EY	80386EX Emulation Subsystem	No longer supported	
64790L	Softkey Editor Single-user	No longer supported	
64790M	Softkey Editor Media & Documentation	No longer supported	
64790S	Softkey Driven Editor	No longer supported	
64790SR	Right To Reproduce. Must order option.	No longer supported	
64790SX	One-Time-Update. Must order option.	No longer supported	
64790U	Softkey Editor Multi-user	No longer supported	
64791AX	One-Time-Update	Currently supported	
64791B	V40HL 16MHz emulation board no memory	No longer supported	
64791S	V40 10MHz Hosted User Interface	No longer supported	
64792AX	One-Time-Update	Currently supported	
64792B	V50HL 16MHz emulation board no memory	No longer supported	
64792S	V50 10MHz Hosted User Interface	No longer supported	
64792SX	V50 10MHz Hosted User Interface	No longer supported	
64793A	H8/338 Series emulation board no memory	No longer supported	
64793B	H8/329 Series emulator board no memory	No longer supported	
64793S	H8/338/329 PC Interface Software	No longer supported	
64794AR	8K Emulation bus analyzer	Currently supported	
64797B	H8/3003/3048 Low Voltage Adapter.	Currently supported	
64797C	QFP 80 pin flexible cable	Currently supported	
64797S	H8/300H 3048 Hosted User Interface	Currently supported	
64797SY	H8/300H 3048 Series Emulation Subsystem	Currently supported	
64798CY	68302 Emulation Subsystem	No longer supported	
64798EY	68EN302 Emulation Subsystem	No longer supported	
64798FY	68LC302 Emulation Subsystem	No longer supported	
64800A	64000 OP SYS S/W	No longer supported	64100AF
64801L	64000-UX Operating Env. Single-user	No longer supported	
64801M	64000-UX Operating Env. Media & doc.	No longer supported	
64801S	HP 64000-UX Operating Environment SW	No longer supported	
64801SR	Right To Reproduce. Must order option.	No longer supported	
64801SX	One-Time-Update. Must order option.	No longer supported	
64801U	64000-UX Operating Env. Multi-user	No longer supported	
64802A	8080/85 TRANSLTR	No longer supported	
64802AF	8080/85 REL TRAN	No longer supported	
64802AT	8080/85 REL TRAN	No longer supported	
64802UF	64802UF SW SUBSC	No longer supported	
64802UT	64802UT SW SUBSC	No longer supported	
64808L	64000 User Interface	No longer supported	
64808M	64000 User Interface Media & Doc.	No longer supported	
64808S	64000 User Interface Software	No longer supported	
64808SR	Right To Reproduce. Must order option.	No longer supported	
64808SX	One-Time-Update. Must order option.	No longer supported	
64808U	64000 User Interface Multi-user	No longer supported	
64809A	TERM. PROM SFTWR	No longer supported	
64810A	8080/85 COMPILER	No longer supported	64810AF
64810AF	PASCAL 8080/85	No longer supported	
64810AR	Right to make 1 copy of 64810AF/A SW	No longer supported	
64810AT	PASCAL 8080/85	No longer supported	64810AF
64810AX	One-Time-Update to current 64810AF SW	No longer supported	
64810L	8080/85 LIBRARY	No longer supported	
64810UF	64810UF SW SUBSC	No longer supported	
64810UT	64810UT SN SUBSC	No longer supported	
64811A	6800 COMPILER	No longer supported	64811AF
64811AF	Pascal Compiler For 6800/02	No longer supported	
64811AR	Right to make 1 copy of 64811AF/A SW	No longer supported	
64811AT	PASCAL 6800/02	No longer supported	64811AF
64811AX	One-Time-Update to current 64811AF SW	No longer supported	

Product	Description	Support Status	Replacement Information
64811L	Pascal 6800 Language System Single-user	No longer supported	
64811M	Pascal 6800 Media and Documentation	No longer supported	
64811S	Pascal 6800 Family Language System	No longer supported	
64811SR	Right To Reproduce. Must order option.	No longer supported	
64811SX	One-Time-Update. Must order option.	No longer supported	
64811U	Pascal 6800 Language System Multi-user	No longer supported	
64811UF	64811UF SW SUBSC	No longer supported	
64811UT	64811UT SW SUBSC	No longer supported	
64812A	Z-80 COMPILER	No longer supported	64812AF
64812AF	PASCAL Z-80	No longer supported	
64812AR	Right to make 1 copy 64812AF/A software	No longer supported	
64812AT	PASCAL Z-80	No longer supported	64812AF
64812AX	One-Time-Update to current 64812AF SW	No longer supported	
64812L	Z-80 LIBRARY	No longer supported	
64812UF	64812UF SW SUBSC	No longer supported	
64812UT	64812UT SW SUBSC	No longer supported	
64813A	6809 COMPILER	No longer supported	64813AF
64813AF	Pascal Compiler For 6809 Microprocessors	No longer supported	
64813AR	Right to make 1 copy of 64813AF/A SW	No longer supported	
64813AT	PASCAL 6809	No longer supported	64813AF
64813AX	One-Time-Update to current 64813AF SW	No longer supported	
64813L	Pascal 6809 Language System Single-user	No longer supported	
64813M	Pascal 6809 media and documentation	No longer supported	
64813S	Pascal 6809 Language System	No longer supported	
64813SR	Right To Reproduce. Must order option.	No longer supported	
64813SX	One-Time-Update. Must order option.	No longer supported	
64813U	Pascal 6809 Language System Multi-user	No longer supported	
64813UF	64813UF SW SUBSC	No longer supported	
64813UT	64813UT SW SUBSC	No longer supported	
64814A	8086 COMPILER	No longer supported	64814AF
64814AF	Pascal 8086/88/186/188/286	No longer supported	
64814AR	Right to make 1 copy of 64814AF/A SW	No longer supported	
64814AT	PASCAL 8086	No longer supported	64814AF
64814AX	One-Time-Update to current 64814AF SW	No longer supported	
64814L	Pascal 8086/286 Language System	No longer supported	
64814M	Pascal 8086/80286 Language System	No longer supported	
64814S	Pascal 8086/88/186/188/286 language sys.	No longer supported	
64814SR	Right To Reproduce. Must order option.	No longer supported	
64814SX	One-Time-Update. Must order one option.	No longer supported	
64814U	Pascal 8086 Language System Multi-user	No longer supported	
64814UF	64814UF SW SUBSC	No longer supported	
64814UT	64814UT SW SUBSC	No longer supported	
64815A	68000 COMPILER	No longer supported	64815AF
64815AF	Pascal Compiler For 68000 Microprocessor	No longer supported	
64815AR	Right To Copy 64815AF/A Software	No longer supported	
64815AT	PASCAL 68000	No longer supported	64815AF
64815AX	One-Time-Update To Current 64815AF SW	No longer supported	
64815L	Pascal 68000 Language System Single-user	No longer supported	
64815M	Pascal 68000 Language System	No longer supported	
64815S	Pascal 68000/08/10 Language System	No longer supported	
64815SR	Right To Reproduce. Must order option.	No longer supported	
64815SX	One-Time-Update. Must order option.	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
64815U	Pascal 68000 Language System Multi-user	No longer supported	
64815UF	64815UF SW SUBSC	No longer supported	
64815UT	64815UT SW SUBSC	No longer supported	
64816A	Z-8000 COMPILER	No longer supported	64816AF
64816AF	Pascal Compiler For Z8001/2	No longer supported	
64816AR	Right to make 1 copy of 64816A software	No longer supported	
64816AT	PASCAL Z8001/2	No longer supported	64816AF
64816AX	One-Time-Update to current 64816AF SW	No longer supported	
64816L	Pascal Z8000 Language System Single-user	No longer supported	
64816M	Pascal Z8000 Language System Media & Doc	No longer supported	
64816S	Pascal Language System For Z8001/2	No longer supported	
64816SR	Right To Reproduce. Must order option.	No longer supported	
64816SX	One-Time-Update. Must order option.	No longer supported	
64816U	Pascal Z8000 Language System Multi-user	No longer supported	
64816UF	64816UF SW SUBSC	No longer supported	
64816UT	64816UT SW SUBSC	No longer supported	
64817A	HOST PASCAL	No longer supported	64817AF
64817AF	Pascal Compiler For 64000 Host System	No longer supported	
64817AR	Right to make 1 copy of 64817AF/A SW	No longer supported	
64817AT	HOST PASCAL	No longer supported	64817AF
64817AX	One-Time-Update to current 64817AF SW	No longer supported	
64817UF	64817UF SW SUBSC	No longer supported	
64817UT	64817UT SW SUBSC	No longer supported	
64818AF	C Compiler for 8086/88/186/188/286	No longer supported	
64818AR	Right to make 1 copy of 64818AF/A SW	No longer supported	
64818AT	C COMPLR 8086/88	No longer supported	64818AF
64818AX	One-Time-Update to current 64818AF SW	No longer supported	
64818L	C Language System 8086/80286 Single-user	No longer supported	
64818M	C Language System 86/286 Media & Documen	No longer supported	
64818S	C Compiler System 8086/88/186/188/286	No longer supported	
64818SR	Right To Reproduce. Must order option.	No longer supported	
64818SX	One-Time-Update. Must order option.	No longer supported	
64818U	C Language System 8086/80286 Multi-user	No longer supported	
64818UF	64818UF SW SUBSC	No longer supported	
64818UT	64818UT SW SUBSC	No longer supported	
64819AF	C Compiler For The 68000 Microprocessors	No longer supported	
64819AR	Right to make 1 copy of 64819AF/A SW	No longer supported	
64819AT	C COMPLR 68000	No longer supported	64819AF
64819AX	One-Time-Update to current 64819AF SW	No longer supported	
64819L	C 68000/08/10 Language System Single-use	No longer supported	
64819M	C Language System 68000/08/10 Media	No longer supported	
64819S	C Language System For 68000/08/10 Family	No longer supported	
64819SR	Right To Reproduce. Must order option.	No longer supported	
64819SX	One-Time-Update. Must order option.	No longer supported	
64819U	C Language System 68000/08/10 Multi-user	No longer supported	
64819UF	64819UF SW SUBSC	No longer supported	
64819UT	64819UT SW SUBSC	No longer supported	
64820AF	C Compiler For The Z8001/2	No longer supported	
64820AR	Right to make 1 copy of 64820AF/A SW	No longer supported	
64820AT	C COMPLR Z8001/2	No longer supported	64820AF

Product	Description	Support Status	Replacement Information
64820AX	One-Time-Update to current 64820AF SW	No longer supported	
64820L	C Language System for Z8001/2 Single-user	No longer supported	
64820M	C Language System Z8001/2 Media & Doc.	No longer supported	
64820S	C Language System For Z8001/Z8002	No longer supported	
64820SR	Right To Reproduce. Must order option.	No longer supported	
64820SX	One-Time-Update. Must order option.	No longer supported	
64820U	C Language System Z8001/Z8002 multi-user	No longer supported	
64820UF	64820UF SW SUBSC	No longer supported	
64820UT	64820UT SW SUBSC	No longer supported	
64821AF	C Compiler For 6800 Microprocessors	No longer supported	
64821AR	Right to make 1 copy of 64821AF/A SW	No longer supported	
64821AT	C COMPLR 6800	No longer supported	64821AF
64821AX	One-Time-Update to current 64821AF SW	No longer supported	
64821L	C 6800 Language System Single-user	No longer supported	
64821M	C 6800 Language System Media & Doc.	No longer supported	
64821S	C Language System For 6800 Family	No longer supported	
64821SR	Right To Reproduce. Must order option.	No longer supported	
64821SX	One-Time-Update. Must order option.	No longer supported	
64821U	C Language System 6800 Multi-user	No longer supported	
64821UF	64821UF SW SUBSC	No longer supported	
64821UT	64821UT SW SUBSC	No longer supported	
64822AF	C Compiler For The 6809 Microprocessors	No longer supported	
64822AR	Right to make 1 copy of 64822AF/A SW	No longer supported	
64822AT	C COMPLR 6809	No longer supported	64822AF
64822AX	One-Time-Update to current 64822AF SW	No longer supported	
64822L	C 6809 Language System Single-user	No longer supported	
64822M	C 6809 Language System media & doc.	No longer supported	
64822S	C Language System For 6809 Processor	No longer supported	
64822SR	Right To Reproduce. Must order option.	No longer supported	
64822SX	One-Time-Update. Must order option.	No longer supported	
64822U	C Language System 6809 Multi-user	No longer supported	
64822UF	64822UF SW SUBSC	No longer supported	
64822UT	64822UT SW SUBSC	No longer supported	
64823A	Pascal Compiler For Z80/NSC800	No longer supported	
64823AR	Right to make 1 copy of 64823A software	No longer supported	
64823AX	One-Time-Update to current 64823A SW	No longer supported	
64823L	Pascal Language System Z80/NSC800 Single	No longer supported	
64823M	Pascal Language Sys Z80/NSC800 Media &	No longer supported	
64823S	Pascal Language System For Z80/NSC800	No longer supported	
64823SR	Right To Reproduce. Must order option.	No longer supported	
64823SX	One-Time-Update. Must order option.	No longer supported	
64823U	Pascal Language System Z80/NSC800 Multi	No longer supported	
64824A	C Compiler For Z80/NSC800 Microprocessor	No longer supported	
64824AR	Right to make 1 copy of 64824A software	No longer supported	
64824AX	One-Time-Update to current 64824A SW	No longer supported	
64824L	C Z80/NSC800 Language System Single-user	No longer supported	
64824M	C Z80/NSC800 Language System Media & Doc	No longer supported	
64824S	C Language System For Z80/NSC800	No longer supported	
64824SR	Right To Reproduce. Must order option.	No longer supported	
64824SX	One-Time-Update. Must order option.	No longer supported	

Product	Description	Support Status	Replacement Information
64824U	C Z80/NSC800 Language System Multi-user	No longer supported	
64825A	Pascal Compiler For 8085 Microprocessor	No longer supported	
64825AR	Right to make 1 copy of 64824A software	No longer supported	
64825AX	One-Time-Update to current 64825A SW	No longer supported	
64825L	Pascal 8080/85 Language Sys. Single-user	No longer supported	
64825M	Pascal 8080/85 Lang. Sys Media & Doc.	No longer supported	
64825S	Pascal Language System For 8080/8085	No longer supported	
64825SR	Right To Reproduce. Must order option.	No longer supported	
64825SX	One-Time-Update. Must order option.	No longer supported	
64825U	Pascal 8080/8085 Language System Multi	No longer supported	
64826A	C Compiler For 8085 Microprocessor	No longer supported	
64826AR	Right To Reproduce. Must order option.	No longer supported	
64826AX	One-Time-Update. Must order option.	No longer supported	
64826L	C 8080/8085 Language System Single-User	No longer supported	
64826M	C 8080/85 Lang. Sys. Media & Doc.	No longer supported	
64826S	C Language System For 8080/8085	No longer supported	
64826SR	Right To Reproduce. Must order option.	No longer supported	
64826SX	One-Time-Update. Must order option.	No longer supported	
64826U	C 8080/8085 Language System Multi-User	No longer supported	
64830A	8080/85 EMUL TER	No longer supported	
64831A	6800 EMUL TER	No longer supported	
64832A	Z80 EMUL TERM	No longer supported	
64840A	ASSEMBLR 8080/85	No longer supported	64840AF
64840AF	Assembler And Linker For The 8080/8085	No longer supported	
64840AR	Right to make 1 copy of 64840AF/A SW	No longer supported	
64840AT	ASMBLR 8080/85	No longer supported	64840AF
64840AX	One-Time-Update to current 64840AF SW	No longer supported	
64840B	ASSEMBLR 8080/85	No longer supported	
64840L	Cross Assembler/Linker Single-User	No longer supported	
64840M	Cross Asm/L 8080/85 Media & Doc.	No longer supported	
64840S	Assembler/Linker System For 8080/8085	No longer supported	
64840SR	Right To Reproduce. Must order option.	No longer supported	
64840SX	One-Time-Update. Must order option.	No longer supported	
64840U	Cross Assembler/Linker 8085 Multi User	No longer supported	
64840UF	64840UF SW SUBSC	No longer supported	
64840UT	64840UT SW SUBSC	No longer supported	
64841A	ASSEMBLER 6800	No longer supported	64841AF
64841AF	Assembler/Linker For The 6800/02	No longer supported	
64841AR	Right to make 1 copy of 64810AF/A SW	No longer supported	
64841AT	ASMBLR 6800/02	No longer supported	64841AF
64841AX	One-Time-Update to current 64841AF SW	No longer supported	
64841B	ASSEMBLER 6800	No longer supported	64841AF
64841L	Cross Asm/L Lang. Sys. 6800/02 Single	No longer supported	
64841M	Cross Asm/L Lang. Sys. 6800/02 Media	No longer supported	
64841S	Assembler/Linker System For 6800 Family	No longer supported	
64841SR	Right To Reproduce. Must order option.	No longer supported	
64841SX	One-Time-Update. Must order option.	No longer supported	
64841U	Cross asm/L Lang. Sys. 6800/02 Multi	No longer supported	
64841UF	64841UF SW SUBSC	No longer supported	
64841UT	64841UT SW SUBSC	No longer supported	
64842A	ASSEMBLER Z80	No longer supported	64842AF
64842AF	Assembler/Linker For The Z80	No longer supported	
64842AR	Right to make 1 copy of 64842AF/A SW	No longer supported	
64842AT	ASMBLR Z-80	No longer supported	64842AF
64842AX	One-Time-Update to current 64842AF SW	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
64842B	ASSEMBLR Z80	No longer supported	64842AF
64842L	Cross Asm/L Lang. Sys. Z80/NSC800 Single	No longer supported	
64842M	Cross Asm/L Lang. Sys. Z80 Media & Doc.	No longer supported	
64842S	Assembler/Linker System For Z80/NSC800	No longer supported	
64842SR	Right To Reproduce. Must order option.	No longer supported	
64842SX	One-Time-Update. Must order option.	No longer supported	
64842U	Cross Asm/L Lang. Sys. Z80/NSC800 Multi	No longer supported	
64842UF	64842UF SW SUBSC	No longer supported	
64842UT	64842UT SW SUBSC	No longer supported	
64843A	6502 ASSEMBLER	No longer supported	64843AF
64843AF	Assembler/Linker For The 6502	No longer supported	
64843AR	Right to make 1 copy of 64843AF/A SW	No longer supported	
64843AT	ASMBLR 6502	No longer supported	64843AF
64843AX	One-Time-Update to current 64843AF SW	No longer supported	
64843L	Cross Asm/L Lang. Sys. for 6502 Single	No longer supported	
64843M	Cross Asm/L Lang. Sys. for 6502 Media &	No longer supported	
64843S	Assembler/Linker System For 6502 Family	No longer supported	
64843SR	Right To Reproduce. Must order option.	No longer supported	
64843SX	One-Time-Update. Must order option.	No longer supported	
64843U	Cross Asm/L Lang. Sys. for 6502 Multi	No longer supported	
64843UF	64843UF SW SUBSC	No longer supported	
64843UT	64843UT SW SUBSC	No longer supported	
64844A	6809/05 ASSMBLR	No longer supported	64844AF
64844AF	Assembler/Linker For The 6805/09	No longer supported	
64844AR	Right To Reproduce. Must order option.	No longer supported	
64844AT	ASMBLR 6805/09	No longer supported	64844AF
64844AX	One-Time-Update to current 64844AF SW	No longer supported	
64844B	6809 EMUL SW	No longer supported	64844AF
64844L	Cross Asm/L Lang. Sys. for 6805/9 Single	No longer supported	
64844M	Cross Asm/L Lang. Sys. for 6805/09 Media	No longer supported	
64844S	Assembler/Linker System For 6805/6809	No longer supported	
64844SR	Right To Reproduce. Must order option.	No longer supported	
64844SX	One-Time-Update. Must order option.	No longer supported	
64844U	Cross Asm/L Lang. Sys. for 6805/9 Multi	No longer supported	
64844UF	64844UF SW SUBSC	No longer supported	
64844UT	64844UT SW SUBSC	No longer supported	
64845A	68000 ASSEMBLER	No longer supported	64845AF
64845AF	Assembler/Linker For The 68000	No longer supported	
64845AR	Right to make 1 copy of 64845AF/A SW	No longer supported	
64845AT	ASMBLR 68000	No longer supported	64845AF
64845AX	One-Time-Update to current 64845AF SW	No longer supported	
64845B	68000 EMUL SW	No longer supported	64845AF
64845L	Cross Asm/L Lang. Sys. for 68000 Single	No longer supported	
64845M	Cross Asm/L Lang. Sys. for 68000 Media	No longer supported	
64845S	Assembler/Linker System For 68000 Family	No longer supported	
64845SR	Right To Reproduce. Must order option.	No longer supported	
64845SX	One-Time-Update. Must order option.	No longer supported	
64845U	Cross Asm/L Lang. Sys. for 68000 Multi	No longer supported	
64845UF	64845UF SW SUBSC	No longer supported	
64845UT	64845UT SW SUBSC	No longer supported	
64846A	8048 ASSEMBLER	No longer supported	64846AF
64846AF	Assembler/Linker For The 8048 Family	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
64846AR	Right to make 1 copy of 64846AF/A SW	No longer supported	
64846AT	ASMBLR 8048 FMLY	No longer supported	64846AF
64846AX	One-Time-Update to current 64846AF SW	No longer supported	
64846B	8048 EMUL SW	No longer supported	64846AF
64846L	Cross Asm/L Lang. Sys. for 8048 Single	No longer supported	
64846M	Cross Asm/L Lang. Sys. for 8048 Media	No longer supported	
64846S	Assembler/Linker System For 8048	No longer supported	
64846SR	Right To Reproduce. Must order option.	No longer supported	
64846SX	One-Time-Update. Must order option.	No longer supported	
64846U	Cross Asm/L Lang. Sys. for 8048 Multi	No longer supported	
64846UF	64846UF SW SUBSC	No longer supported	
64846UT	64846UT SW SUBSC	No longer supported	
64847A	9900 ASSEMBLER	No longer supported	64847AF
64847AF	Assembler/Linker For The 9900	No longer supported	
64847AR	Right to make 1 copy of 64847AF/A SW	No longer supported	
64847AT	ASMBLR 9900	No longer supported	64847AF
64847AX	One-Time-Update to current 64847AF SW	No longer supported	
64847L	Cross Asm/L Lang. Sys. for 99000 Single	No longer supported	
64847M	Cross Asm/L Lang. Sys. for 99000 Media	No longer supported	
64847S	Assembler/Linker System For 9900/99000	No longer supported	
64847SR	Right To Reproduce. Must order option.	No longer supported	
64847SX	One-Time-Update. Must order option.	No longer supported	
64847U	Cross Asm/L Lang Sys. for 99000 Multi	No longer supported	
64847UF	64847UF SW SUBSC	No longer supported	
64847UT	64847UT SW SUBSC	No longer supported	
64848A	1802 ASSEMBLER	No longer supported	64848AF
64848AF	Assembler/Linker For The 1802	No longer supported	
64848AR	Right to make 1 copy of 64847AF/A SW	No longer supported	
64848AT	ASMBLR 1802	No longer supported	64848AF
64848AX	One-Time-Update to current 64848AF SW	No longer supported	
64848S	1802 SOURCES	No longer supported	64848AF
64848UF	64848UF SW SUBSC	No longer supported	
64848UT	64848UT SW SUBSC	No longer supported	
64849A	F8/3870 ASSMBLR	No longer supported	64849AF
64849AF	Assembler/Linker For The F8/3870	No longer supported	
64849AR	Right to make 1 copy 64849AF/A software	No longer supported	
64849AT	ASMBLR F8/3870	No longer supported	64849AF
64849AX	One-Time-Update to current 64849AF SW	No longer supported	
64849S	F-8 SOURCES	No longer supported	64849AF
64849UF	64849UF SW SUBSC	No longer supported	
64849UT	64849UT SW SUBSC	No longer supported	
64850A	Z-8 ASSEMBLER	No longer supported	64850AF
64850AF	Assembler/Linker For The Z-8	No longer supported	
64850AR	Right to make 1 copy of 64850AF/A SW	No longer supported	
64850AT	ASMBLR Z-8	No longer supported	64850AF
64850AX	One-Time-Update to current 64850AF SW	No longer supported	
64850S	Z-8 SOURCES	No longer supported	64850AF
64850UF	64850UF SW SUBSC	No longer supported	
64850UT	64850UT SW SUBSC	No longer supported	
64851A	USER DEF. ASMLK	No longer supported	64851AF
64851AF	Assembler/Linker For User Define	No longer supported	
64851AR	Right to make 1 copy of 64851AF/A SW	No longer supported	
64851AT	ASMBLR USER DEFN	No longer supported	64851AF
64851AX	One-Time-Update to current 64851AF SW	No longer supported	
64851L	User Definable Assembly Language Single	No longer supported	
64851M	User Definable Assembler/Linker Media	No longer supported	
64851S	User Defined Assembler/Linker System	No longer supported	
64851SR	Right To Reproduce. Must order option.	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
64851SX	One-Time-Update. Must order option.	No longer supported	
64851T	64851A TRNG.CRSE	No longer supported	
64851U	User Definable Assembler/Linker Multi	No longer supported	
64851UF	64851UF SW SUBSC	No longer supported	
64851UT	64851UT SW SUBSC	No longer supported	
64852A	1000L ASSEMBLER.	No longer supported	64852AF
64852AF	Assembler/Linker For The 1000L	No longer supported	
64852AR	Right to make 1 copy of 64852AF/A SW	No longer supported	
64852AT	ASMBLR 1000L	No longer supported	64852AF
64852AX	One-Time-Update to current 64852AF SW	No longer supported	
64852S	1000L SOURCES	No longer supported	64852AF
64852UF	64852UF SW SUBSC	No longer supported	
64852UT	64852UT SW SUBSC	No longer supported	
64853A	8086 ASSEMBLER	No longer supported	64853AF
64853AF	Assembler/Linker For 8086/8088/186/188	No longer supported	
64853AR	Right to make 1 copy of 64853AF/A SW	No longer supported	
64853AT	ASMBLR 8086/186	No longer supported	64853AF
64853AX	One-Time-Update to current 64853AF SW	No longer supported	
64853B	8086/8 EMUL SW	No longer supported	64853AF
64853L	Cross Asm/L Lang. Sys. for 8086 Single	No longer supported	
64853M	Cross Asm/L Lang. Sys. for 8086 Media	No longer supported	
64853S	Assembler/Linker System For 8086/186	No longer supported	
64853SR	Right To Reproduce. Must order option.	No longer supported	
64853SX	One-Time-Update. Must order option.	No longer supported	
64853U	Cross Asm/L Lang. Sys. for 8086 Multi	No longer supported	
64853UF	64853UF SW SUBSC	No longer supported	
64853UT	64853UT SW SUBSC	No longer supported	
64854A	Z8000 ASSEMBLER	No longer supported	64854AF
64854AF	Assembler/Linker For The Z8001/02	No longer supported	
64854AR	Right to make 1 copy of 64854AF/A SW	No longer supported	
64854AT	ASMBLR Z8001/02	No longer supported	64854AX
64854AX	One-Time-Update to current 64854AF SW	No longer supported	
64854B	Z8001/2 EMUL SW	No longer supported	64854AF
64854L	Cross Asm/L Lang. Sys. for Z8000 Single	No longer supported	
64854M	Cross Asm/L Lang. Sys. for Z8000 Media	No longer supported	
64854S	Assembler/Linker System For Z8001/Z8002	No longer supported	
64854SR	Right To Reproduce. Must order option.	No longer supported	
64854SX	One-Time-Update. Must order option.	No longer supported	
64854U	Cross Asm/L Lang. Sys. for Z8000 Multi	No longer supported	
64854UF	64854UF SW SUBSC	No longer supported	
64854UT	64854UT SW SUBSC	No longer supported	
64855A	8051 ASSEMBLER	No longer supported	64855AF
64855AF	Assembler/Linker For The 8051	No longer supported	
64855AR	Right to make 1 copy of 64855AF/A SW	No longer supported	
64855AT	ASMBLR 8051	No longer supported	64855AF
64855AX	One-Time-Update to current 64855AF SW	No longer supported	
64855L	Cross Asm/L Lang. Sys. for 8051 Single	No longer supported	
64855M	Cross Asm/L Lang. Sys. for 8051 Media	No longer supported	
64855S	Assembler/Linker System For 8051	No longer supported	
64855SR	Right To Reproduce. Must order option.	No longer supported	
64855SX	One-Time-Update. Must order option.	No longer supported	
64855U	Cross Asm/L Lang. Sys. for 8051 Multi	No longer supported	
64855UF	64855UF SW SUBSC	No longer supported	
64855UT	64855UT SW SUBSC	No longer supported	
64856AF	Inverse Assembly Language Software	No longer supported	
64856AR	Right to make 1 copy of 64856AF/A SW	No longer supported	
64856AT	INV ASMB SW TAPE	No longer supported	
64856AX	One-Time-Update to current 64856AF SW	No longer supported	
64856L	User-definable Inverse Assembler Single	No longer supported	
64856M	User-definable Assembler/linker media	No longer supported	

Product	Description	Support Status	Replacement Information
64856S	User-definable Inverse Assembler System	No longer supported	
64856SR	Right to make 1 copy of 64856S software	No longer supported	
64856SX	One-Time-Update to current 64856S SW	No longer supported	
64856U	User-definable Inverse Assembler Multi	No longer supported	
64856UF	64856UF SW SUBSC	No longer supported	
64856UT	64856UT SW SUBSC	No longer supported	
64857A	Assembler/Linker For M-S-1750A	No longer supported	
64857AR	Right to make 1 copy of 64857A software	No longer supported	
64857AX	One-Time-Update to current 64857A SW	No longer supported	
64857L	Cross Asm/L Lang. Sys. Mil-Std-1750A Sin	No longer supported	
64857M	Cross Asm/L Lang. Sys. Mil-Std-1750A Med	No longer supported	
64857S	Assembler/Linker System For MS-1750A	No longer supported	
64857SR	Right To Reproduce. Must order option.	No longer supported	
64857SX	One-Time-Update. Must order option.	No longer supported	
64857U	Cross Asm/L Lang. Sys. Mil-Std-1750A Mul	No longer supported	
64858A	Assembler/Linker For TMS320	No longer supported	
64858AR	Right to make 1 copy of 64858A software	No longer supported	
64858AX	One-Time-Update to current 64858A SW	No longer supported	
64858L	Cross Asm/L Lang. Sys. for TMS320 Single	No longer supported	
64858M	Cross Asm/L Lang. Sys. for TMS320 Media	No longer supported	
64858S	Assembler/Linker System For TMS320	No longer supported	
64858SR	Right To Reproduce. Must order option.	No longer supported	
64858SX	One-Time-Update. Must order option.	No longer supported	
64858U	Cross Asm/L Lang. Sys. for TMS320 Multi	No longer supported	
64859A	80286 Assembler/Linker	No longer supported	
64859AR	Right to make 1 copy of 64859A software	No longer supported	
64859AX	One-Time-Update to current 64859A SW	No longer supported	
64859L	80286 Assembler/Linker Single-user	No longer supported	
64859M	80286 Assembler/Linker Media & Doc.	No longer supported	
64859S	80286 Assembler/Linker	No longer supported	
64859SR	Right To Reproduce. Must order option.	No longer supported	
64859SX	One-Time-Update	No longer supported	
64859U	80286 Assembler/Linker Multi-user	No longer supported	
64860A	ASSEMBLER/LINKER FOR INTEL 8096	No longer supported	
64860AR	Right to make 1 copy of 64860A software	No longer supported	
64860AX	One-Time-Update to current 64860A SW	No longer supported	
64860L	Cross Asm/L Lang. Sys. for 8096 Single	No longer supported	
64860M	Cross Asm/L Lang. Sys. for 8096 Media	No longer supported	
64860S	CROSS ASSEMBLER/LINKER FOR 8096	No longer supported	
64860SR	Right To Reproduce. Must order option.	No longer supported	
64860SX	One-Time-Update. Must order option.	No longer supported	
64860U	Cross Asm/L Lang. Sys. for 8096 Multi	No longer supported	
64861A	Micro-Assembler/Linker For Bit Slice	No longer supported	
64861AR	Right to make 1 copy of 64861A software	No longer supported	
64861AX	One-Time-Update to current 64861A SW	No longer supported	
64861L	Micro Asm/L for Bit Slice Single-user	No longer supported	
64861M	Micro Asm/L for Bit Slice Media & Doc.	No longer supported	
64861S	Microassembler Support For Bit Slice	No longer supported	
64861SR	Right To Reproduce. Must order option.	No longer supported	
64861SX	One-Time-Update. Must order option.	No longer supported	
64861U	Micro Asm/L for Bit Slice Multi-user	No longer supported	
64864A	Assembler/Linker for the 64180	No longer supported	
64864AR	Right To Reproduce 64864A software	No longer supported	
64864AX	One-Time-Update for 64864A software	No longer supported	

Product	Description	Support Status	Replacement Information
64864L	64180 Asm/L Lang. Sys. Single User	No longer supported	
64864M	64180 Cross Asm/Lnk Lang. Sys. Media	No longer supported	
64864S	64180 Assembler/Linker	No longer supported	
64864SR	Right To Reproduce.	No longer supported	
64864SX	One-Time-Update.	No longer supported	
64864U	64180 Cross Asm/Lnk Lang. Sys. Multi-use	No longer supported	
64865A	Cross Asmblr/Lkr for 68HC11 on HP 64000	No longer supported	
64865AR	Right to make 1 copy of 64865A software	No longer supported	
64865AX	One-Time-Update to current 64865A SW	No longer supported	
64865L	Cross Asm/L Lang. Sys. for 68HC11 Single	No longer supported	
64865M	Cross Asm/L Lang. Sys. for 68HC11 Media	No longer supported	
64865S	Cross Asmblr/Linker host computers	No longer supported	
64865SR	Right To Reproduce. Must order option.	No longer supported	
64865SX	One-Time-Update. Must order option.	No longer supported	
64865U	Cross Asm/L Lang. Sys. for 68HC11 Multi	No longer supported	
64866A	Assembler/Linker for the 78310	No longer supported	
64866AR	Right To Reproduce 64866A software	No longer supported	
64866AX	One-Time-Update to 64866A software	No longer supported	
64866L	78310 Cross Asm/Lnk Lang. Sys. Single	No longer supported	
64866M	78310 Asm/Lnk Language System	No longer supported	
64866S	78310 Assembler/Linker	No longer supported	
64866SR	Right To Reproduce.	No longer supported	
64866SX	One-Time-Update.	No longer supported	
64866U	78310 Cross Asm/Lnk Lang. Sys. Multi	No longer supported	
64867L	TMS32020/C25 Asm/Lnk Single-user	No longer supported	
64867M	TMS32020/C25 Asm/Lnk Media & Doc.	No longer supported	
64867U	TMS32020/C25 Asm/Lnk Multi-user	No longer supported	
64868L	H16 Assembler/Linker Lang. Sys. Single	No longer supported	
64868M	H16 Assembler/Linker Lang. Sys. Media	No longer supported	
64868U	H16 Assembler/Linker Lang. Sys. Upgrade	No longer supported	
64869L	H8/500 Series Assembler/Linker Single	No longer supported	
64869M	H8/500 Series Assembler/Linker Media	No longer supported	
64869U	H8/500 Series Asm/Lnk User Lic. Upgrade	No longer supported	
64870L	68000/10/20/302 Assembler/Linker License	No longer supported	
64870M	Cross Asm/L Lang. Sys. 68000/10/20/302	No longer supported	
64870S	68000/10/20 Assembler/Linker	No longer supported	
64870SR	Right to make 1 copy of 64870S software	No longer supported	
64870SX	One-Time-Update to current 64870S SW	No longer supported	
64870U	Cross Asm/L for Motorola 68000/10/20/302	No longer supported	
64871L	8086/186 Assembler/Linker License	No longer supported	
64871M	8086/186 Assembler/Linker Media & Doc.	No longer supported	
64871U	8086/186 Asm/Lnk License Upgrade	No longer supported	
64873L	V Series AxLS Asm/Lnk Single User Lic.	No longer supported	
64873M	V Series AxLS Asm/Lnk Media & Document.	No longer supported	
64873U	V Series AxLS Asm/Lnk Multi User Lic. Up	No longer supported	
64874L	68030/40 AxLS Assembler/Linker/Librarian	No longer supported	
64874M	68030/40 AxLS Asm/Lnk Media & Document.	No longer supported	
64874U	68040/40 AxLS Asm/Lnk Multi User Lic.	No longer supported	

Product	Description	Support Status	Replacement Information
64875L	Extended Mode Locator NEC V33/53 Single	No longer supported	
64875M	Extended Mode Locator V33/53 Media & Doc	No longer supported	
64875U	V33/53 Extended Mode Locator Lic. Upgrad	No longer supported	
64876L	H8/300 Series Assembler/Linker Single	No longer supported	
64876M	H8/300 Series Assembler/Linker Media	No longer supported	
64876U	H8/300 Series Assembler/Linker Multi-use	No longer supported	
64878L	78K/II Series Assembler/Linker Single	No longer supported	
64878M	78K/II Series Assembler/Linker Media	No longer supported	
64878U	78K/II Series Assembler/Linker Multi	No longer supported	
64879L	V70 Assembler/Linker Single User License	No longer supported	
64879M	V70 Assembler/Linker Media & Manuals	No longer supported	
64879U	V70 Assembler/Linker Multi-user license	No longer supported	
64880A	Hosted Development System: 9000/500 HPUX	No longer supported	
64880AR	Right to make 1 copy of 64880A software	No longer supported	
64880AX	One-Time-Update to current 64880A SW	No longer supported	
64880L	Hosted Development System	No longer supported	
64880M	Hosted Development Sys. Media & Doc.	No longer supported	
64880U	Hosted Development Software	No longer supported	
64881A	HOSTED DEVELOPMENT SYSTEM	No longer supported	
64881AR	RIGHT TO COPY	No longer supported	
64881AX	ONE-TIME-UPDATE	No longer supported	
64882A	Hosted Development System: VAX/VMS	No longer supported	
64882AR	Right to make 1 copy of 64882A software	No longer supported	
64882AX	One-Time-Update to current 64882A SW	No longer supported	
64882L	Hosted Development Sys. Single-user	No longer supported	
64882M	Hosted Development Sys. Media & Doc.	No longer supported	
64882U	Hosted Development Sys. Multi-user	No longer supported	
64883A	Software to connect 64000 to HP 9000/300	No longer supported	
64883AR	Right to make 1 copy of 64883A software	No longer supported	
64883AX	One-Time-Update to current 64883A SW	No longer supported	
64883L	Hosted Development Sys. Single-user	No longer supported	
64883M	Hosted Development Sys. Media & Doc.	No longer supported	
64883U	Hosted Development Sys. Multi-user	No longer supported	
64884A	RS-232 Transfer for 9000/500	No longer supported	
64884AR	Right to make 1 copy of 64884A software	No longer supported	
64884AX	One-Time-Update to current 64884A SW	No longer supported	
64884L	Hosted Development RS-232 Single-user	No longer supported	
64884M	Hosted Development RS-232 Transfer Media	No longer supported	
64884U	Hosted Development RS-232 Transfer Multi	No longer supported	
64885A	RS-232 Transfer on 9000/300	No longer supported	
64885AR	Right to make 1 copy of 64885A software	No longer supported	
64885AX	One-Time-Update to current 64885A SW	No longer supported	
64885L	Hosted Development RS-232 Transfer Singl	No longer supported	
64885M	Hosted Development RS-232 Transfer Media	No longer supported	
64885U	Hosted Development RS-232 Transfer Multi	No longer supported	
64886A	RS-232 Transfer on VAX/VMS	No longer supported	
64886AR	Right to make 1 copy of 64886A software	No longer supported	
64886AX	One-Time-Update to current 64886A SW	No longer supported	

Product	Description	Support Status	Replacement Information
64886L	Hosted Development RS-232 Transfer Singl	No longer supported	
64886M	Hosted Development RS-232 Transfer Media	No longer supported	
64886U	Hosted Development RS-232 Transfer Multi	No longer supported	
64887L	Network Transfer Utilities Single-user	No longer supported	
64887M	Network Transfer Utilities Media & Doc.	No longer supported	
64887S	Network Transfer Utilities for 64000-UX	No longer supported	
64887SR	Right To Reproduce. Must order option.	No longer supported	
64887SX	One-Time-Update. Must order option.	No longer supported	
64887U	Network Transfer Utilities Multi-user	No longer supported	
64888L	Utilities Package Single-user	No longer supported	
64888M	Utilities Package Media & Documentation	No longer supported	
64888S	HP 64000-UX Utilities Package. Need Opt.	No longer supported	
64888SR	Right to reproduce. Must order option.	No longer supported	
64888SX	One-Time-Update. Must order option.	No longer supported	
64888U	Utilities Package Multi-user	No longer supported	
64890S	PL/M Compiler For 8086	No longer supported	
64890SX	One-Time-Update For 64890S Software	No longer supported	
64891S	Assembler/Linker/Location/Library	No longer supported	
64891SX	One-Time-Update For 64891S Software	No longer supported	
64892S	Symbol Converter	No longer supported	
64892SX	One-Time-Update	No longer supported	
64893S	File Transfer Utility	No longer supported	
64893SX	One-Time-Update	No longer supported	
64900A	SUBSCRIPTION SER	No longer supported	
64901A	UPDATES 64001S	No longer supported	
64902L	68000 C Cross Compiler 68000 Single-user	No longer supported	
64902M	C Cross Compiler for 68000/08/10 Media	No longer supported	
64902S	68000/08/10 C Cross Compiler	No longer supported	
64902SR	Right To Copy	No longer supported	
64902SX	One-Time-Update 68000 C	No longer supported	
64902U	C Cross Compiler 68000/08/10 Multi-user	No longer supported	
64903L	C Cross Compiler Motorola 68020 Single	No longer supported	
64903M	C Cross Compiler Motorola 68020 Media	No longer supported	
64903S	68020 C Cross Compiler	No longer supported	
64903SR	Right To Reproduce	No longer supported	
64903SX	One-Time-Update	No longer supported	
64903U	C Cross Compiler Motorola 68020 Multi	No longer supported	
64904L	8086/186 C Compiler User License	No longer supported	
64904M	8086/186 C Compiler Media & Doc.	No longer supported	
64904U	8086/186 C Compiler License Upgrade	No longer supported	
64906L	V Series AxLS C Compiler Single User Lic	No longer supported	
64906M	V Series AxLS C Compiler Media & Doc.	No longer supported	
64906U	V Series AxLS C Comp. Multi User Lic Up	No longer supported	
64907L	68030 AxLS C Compiler Single User Licens	No longer supported	
64907M	68030 AxLS C Compiler Media and Doc.	No longer supported	
64907U	68030 AxLS C Compiler User Lic. Upgrade	No longer supported	
64908L	68332 AxLS C Compiler Single User Licens	No longer supported	
64908M	68332 AxLS C Compiler Media and Doc.	No longer supported	
64908U	68332 AxLS C Compiler User Lic. Upgrade	No longer supported	
64909L	C Cross Compiler Motorola 68040 Single	No longer supported	

Product	Description	Support Status	Replacement Information
64909M	68040 C Cross Compiler Media and doc.	No longer supported	
64909U	C Cross Compiler Motorola 68040 Upgrade	No longer supported	
64910A	SYSTEM TRAIN'G	No longer supported	
64910AF	SYSTEM TRAINING	No longer supported	
64910AT	SYSTEM TRAINING	No longer supported	
64911L	C Cross Compiler NEC V33/53 Single User	No longer supported	
64911M	NEC V33/53 C Cross Compiler Media/Manual	No longer supported	
64911U	NEC V33/53 C Compiler User Lic. Upgrade	No longer supported	
64914L	8086/80186 AxCASE SW User License	No longer supported	
64914M	8086/80186 AxCASE Media & Documentation	No longer supported	
64914U	8086/80186 AxCASE User Lic. Upgrade	No longer supported	
64915L	68000/10 AxCASE SW User License	No longer supported	
64915M	68000/10 AxCASE Media & Documentation	No longer supported	
64915U	68000/10 AxCASE User Lic. Upgrade	No longer supported	
64916L	68020 AxCASE Software User License	No longer supported	
64916M	68020 AxCASE Media and Documentation	No longer supported	
64916U	68020 AxCASE Multi-user Upgrade	No longer supported	
64917L	68030 AxCASE SW User License	No longer supported	
64917M	68030 AxCASE Media and Documentation	No longer supported	
64917U	68030 AxCASE Multi-user Upgrade	No longer supported	
64918L	68332 AxCASE SW User License	No longer supported	
64918M	68332 AxCASE Media & Documentation	No longer supported	
64918U	68332 AxCASE User Licence Upgrade	No longer supported	
64919L	68040 AxCASE Software User License	No longer supported	
64919M	68040 AxCASE Media and Documentation	No longer supported	
64919U	68040 AxCASE Multi-user upgrade	No longer supported	
64930A	PROD SUPPORT	No longer supported	NEW PRODC
64934A	Product Support Pkg. For 64000 System	No longer supported	no replacement
64934B	ST/TIMING PSP	No longer supported	no replacement
64934C	COMMON FSI	No longer supported	
64934D	MAINFRAME FSI	No longer supported	
64934E	8-BIT EMUL FSI	No longer supported	
64934F	16-BIT EMUL FSI	No longer supported	
64934G	ST/TIMING FSI	No longer supported	
64940A	TAPE CRTRIDGE DR	No longer supported	
64941A	Floppy Disc Drive And Controller	No longer supported	
64941RA	Remarketed Floppy Disc Drive	No longer supported	
64960A	2 Position Internal Analysis Bus	No longer supported	
64962A	2 Position Logic State Bus Cable	No longer supported	
64963A	2 Position 8 Channel Timing Bus Cable	No longer supported	no replacement
64964A	2 Position Intermodule Bus Cable	No longer supported	
64980A	SET OPER MANUALS	No longer supported	
64998KT	HP64000 AE SW Update Kit-Media & Manuals	No longer supported	
64998MD	HP64000 AE/SR SW Update Kit Media Only	No longer supported	
64999S	HP 64000 Support Operating System	No longer supported	
65105A	50 WATT SINGLE	No longer supported	no replacement
65112A	50 WATT SINGLE	No longer supported	no replacement
65115A	50 WATT SINGLE	No longer supported	no replacement
65312A	50 WATT TRIPLE	No longer supported	no replacement
65315A	50 WATT TRIPLE	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
65317A	50 WATT TRIPLE	No longer supported	no replacement
65512A	50 WATT 5 OUTPUT	No longer supported	no replacement
65612A	50 WATT 6 OUTPUT	No longer supported	no replacement
66001AR	MPS Keyboard	Currently supported	
66104AR	DC power module 60 V. 2.5 A, 150 W	Currently supported	
66105AR	120V DC Module	Currently supported	
66312AR	Dynamic measurement DC source,20Vdc,2A	Currently supported	
69280A	BREADBOARD CARD	No longer supported	no replacement
69321B	D/A VOLTAGE CARD	No longer supported	no replacement
69322A	D/A VOLTAGE CARD	No longer supported	no replacement
69325A	BPSA V PROG CARD	No longer supported	
69326A	BPSA C PROG CARD	No longer supported	
69327A	BPSA C PROG CARD	No longer supported	
69328A	BPSA GAIN PRO CA	No longer supported	
69330A	RELAY CARD	No longer supported	no replacement
69331A	OUTPUT CARD	No longer supported	
69331B	TTL OUTPUT CARD	No longer supported	no replacement
69332A	OUTPUT CARD	No longer supported	no replacement
69335A	STEPPER CARD	No longer supported	no replacement
69336A	HI SPEED SCANNER	No longer supported	
69336B	HI SPEED SCANNER	No longer supported	no replacement
69351A	REGULATOR CARD	No longer supported	
69351B	REGULATOR CARD	No longer supported	
69351C	REGULATOR CARD	No longer supported	no replacement
69360A	PARALLEL PLUG-IN	No longer supported	
69370A	D/A CURRENT CARD	No longer supported	no replacement
69380A	BREADBOARD CARD	No longer supported	no replacement
69421A	VOLTAGE MONITOR	No longer supported	
69422A	HIGH SPEED A/D	No longer supported	no replacement
69423A	LOW LEVEL A/D	No longer supported	no replacement
69430A	ISOLATED INPUT	No longer supported	no replacement
69431A	DIG. INPUT CARD	No longer supported	no replacement
69433A	RELAY READBACK	No longer supported	no replacement
69434A	EVENT SENSE CARD	No longer supported	no replacement
69435A	PULSE COUNTER	No longer supported	no replacement
69436A	INTERRUPT CARD	No longer supported	no replacement
69480A	BREADBOARD CARD	No longer supported	no replacement
69500A	RESISTANCE CARD	No longer supported	no replacement
69501A	RESISTANCE CARD	No longer supported	no replacement
69502A	RESISTANCE CARD	No longer supported	no replacement
69503A	RESISTANCE CARD	No longer supported	no replacement
69504A	RESISTANCE CARD	No longer supported	no replacement
69505A	RESISTANCE CARD	No longer supported	no replacement
69506A	RESISTANCE CARD	No longer supported	no replacement
69510A	RESISTANCE CARD	No longer supported	no replacement
69511A	RESISTANCE CARD	No longer supported	no replacement
69512A	RESISTANCE CARD	No longer supported	no replacement
69513A	RESISTANCE CARD	No longer supported	no replacement
69520A	PS CONTROL CARD	No longer supported	no replacement
69600A	TIMER CARD	No longer supported	
69600B	TIMER CARD	No longer supported	no replacement
69601A	FREQUENCY CARD	No longer supported	
69601B	FREQUENCY CARD	No longer supported	no replacement
69602A	TIMER/PACER CARD	No longer supported	no replacement
69700A	RESISTANCE CARD	No longer supported	no replacement
69701A	RESISTANCE CARD	No longer supported	no replacement
69702A	RESISTANCE CARD	No longer supported	no replacement
69704A	RESISTANCE CARD	No longer supported	no replacement
69705A	RESISTANCE CARD	No longer supported	no replacement
69706A	RESISTANCE CARD	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
69709A	PS CONTROL CARD	No longer supported	no replacement
69720A	VOLTAGE DAC	No longer supported	no replacement
69721A	CURRENT DAC	No longer supported	no replacement
69730A	RELAY CARD	No longer supported	no replacement
69731A	DIGITAL OUT	No longer supported	no replacement
69731B	DIGITAL CARD	No longer supported	no replacement
69734A	TIMEBASE CARD	No longer supported	no replacement
69735A	PULSE CARD	No longer supported	no replacement
69736A	TIMER CARD	No longer supported	no replacement
69750A	SCANNER CARD	No longer supported	no replacement
69751A	HI SPEED ADC	No longer supported	no replacement
69752A	64-CHAN FET SCAN	No longer supported	no replacement
69753A	TEMPERATURE SCAN	No longer supported	no replacement
69754A	RELAY CARD	No longer supported	no replacement
69755A	16-CHAN FET SCAN	No longer supported	no replacement
69759A	500 KHZ A/D	No longer supported	no replacement
69761A	INTEGRATING DMM	No longer supported	no replacement
69770A	INPUT CARD	No longer supported	no replacement
69771A	DIG INPUT CARD	No longer supported	no replacement
69771AR	Dig Input Card	Currently supported	
69774A	COUNTER CARD	No longer supported	no replacement
69775A	COUNTER CARD	No longer supported	no replacement
69776A	INTERRUPT CARD	No longer supported	no replacement
69790A	MEMORY	No longer supported	
69790B	4K MEMORY CARDS	No longer supported	no replacement
69791A	HIGH SPEED MEMORY	No longer supported	no replacement
69792A	MEMORY EXPANSION	No longer supported	no replacement
69793A	BREADBOARD CARD	No longer supported	no replacement
70100AR	Power meter module for MMS	Currently supported	
70110AR	Digital multimeter module	Currently supported	
70138A	Vector voltmeter for 70000 MMS	No longer supported	
70205AR	Graphics Display Module	Currently supported	
70206A	SYSTEM GRAPHICS DISPLAY	No longer supported	
70206AR	System graphics display	Currently supported	
70207AR	PC Display for MMS	No longer supported	70207B
70311A	3 GHz Clock Source	Currently supported	N4906A
70311AR	3 GHz Clock Source	Currently supported	
70312A	1.5 GHz Clock Source Module	No longer supported	N4906A
70320A	Synthesized signal generator module	No longer supported	http://www.agilent.com/find/psg
70322A	Synthesized signal generator module	No longer supported	http://www.agilent.com/find/psg
70330A	300MHz PULSE GENERATOR, MMS MODULE (5/8)	Currently supported	E8305A
70332A	100MHz MULTIPLE CLOCK GENERATOR, MMS	Currently supported	E8306A
70340AR	Modular signal generator, 1 to 20GHz	Currently supported	
70428AR	Microwave source module	Currently supported	
70590A	No-parts shell module for 70000 MMS	No longer supported	
70591A	1/8 MODULE PARTS KIT	No longer supported	
70592A	1/4 MODULE PARTS KIT	No longer supported	
70593A	3/8 RACK WIDE MODULE PARTS KIT	No longer supported	
70594A	4/8 Module Part Kit	No longer supported	
70595A	3 Design Guides: Electrical, EMC, Mech'l	No longer supported	no replacement
70596A	3 module communication design guides	No longer supported	no replacement
70597A	MSIB module interface software	No longer supported	no replacement
70600A	Microwave preselector module	Currently supported	71209A/P or 71210C/P
70600AR	Microwave preselector module	Currently supported	
70601A	PRESELECTOR MODULE 0-26.5 GHz	No longer supported	
70601AR	Preselector Module 0-26.5 GHz	Currently supported	
70611AR	Attenuator/switch driver;1/8 MMS module	Currently supported	
70612B	Custom MMS interface module	No longer supported	8760 series
70612Q	Custom MMS switch interface module	No longer supported	8760 series

Product	Description	Support Status as of 1 May	Replacement Information
70620A	Preamplifier Module. REFURBISHED	No longer supported	70620B
70700AR	Digitizer module for the 70000	Currently supported	
70703AR	500 MHz digitizing oscilloscope module	Currently supported	
70800E	MSIB cable, standard 30 meter long	Currently supported	no replacement
70810A	LIGHTWAVE SECTION	No longer supported	no replacement
70810A-K50	Kit to retrofit multimode input conn.	No longer supported	no replacement
70810BR	Lightwave section	Currently supported	
70820A-K06	Calibration certificate w/test data	No longer supported	
70820AR	Microwave transition analyzer module	Currently supported	
70841A	3 Gbit/s Pattern Generator Module	No longer supported	N4906A
70841B	3 Gbit/s Pattern Generator Module	Currently supported	N4906A
70842A	3 Gbit/s Error Detector Module	No longer supported	N4906A
70842B	3 Gb/s Error Detector Module	Currently supported	N4906A
70842BR	3 gb/s Error Detector Module	Currently supported	
70843A	12 Gb/s Product Identification Number	No longer supported	N4901B
70843B	12 Gb/s identification number	Currently supported	N4901B
70845A	1 Gbit/s Pattern Generator Module	No longer supported	N4906A
70846A	1 Gbit/s Error Detector Module	No longer supported	N4906A
70847B	Jitter and Eye-diagram Analyzer DLP card	No longer supported	70874B
70860A	CPU/firmware upgrade to the 70900A	Currently supported	70900A.
70862A	Firmware Upgrade Kit for 70950A/70951A	No longer supported	no replacement
70872A	VECTOR PERSONALITY	No longer supported	
70874A	Eye Diagram Personality	Currently supported	
70874B	Jitter/Eye-Diagram Analyzer Upgrade Kit	Currently supported	
70874B-K01	Kit to upgrade 70864A to 70874B	No longer supported	
70874B-K02	Jitter s/w & memory expansion for 70820A	No longer supported	
70900A	LOCAL OSCILLATOR MODULE, REFURBISHED.	No longer supported	70900B
70900AR	Local oscillator module	No longer supported	
70904AR	RF section module, 100Hz to 2.9 GHz	Currently supported	
70905AR	RF section module, 50kHz to 22GHz	Currently supported	
70905BR	RF section, 50 kHz-22 GHz, for 70600A	Currently supported	
70906A	RF SECTION	No longer supported	
70906B	RF SECTION 50 KHz TO 26.5 GHz	No longer supported	
70906BR	RF section 50 KHz to 26.5 GHz	Currently supported	
70907A	EXTERNAL MIXER INTERFACE. REFURBISHED	No longer supported	70907B
70907BR	External Mixer Interface Module	Currently supported	
70908AR	RF section, 100Hz-22 GHz, for 71210A	Currently supported	
70909AR	RF Section, 100 Hz-26.5GHz, for 71209A	Currently supported	
70910AR	Wide bandwidth RF section, 100Hz-26.5GHz	Currently supported	
70911AR	Ultra-wide bandwidth IF module	Currently supported	
70912A	10 TO 1500 MHz Downconverter Module	No longer supported	no replacement
70912B	10 to 2000 mHz Downconverter Module	No longer supported	no replacement
70912BR	10 to 2000 MHz Downconverter Module	Currently supported	
70950A	Optical Spectrum Analyzer Module	Currently supported	8614X OSA Family
70950AR	Optical Spectrum analyzer Module	No longer supported	
70950B	Optical Spectrum Analyzer Module	Currently supported	8614X OSA Family
70950BR	Optical Spectrum Analyzer Module	Currently supported	
70951A	Optical spectrum analyzer module	Currently supported	8614X OSA Family
70951AR	Optical Spectrum Analyzer Module	No longer supported	"B" Model
70951B	Optical Spectrum Analyzer Module	Currently supported	8614X OSA Family
70951B-K07	Kit to install Option C07	No longer supported	no replacement
70952B	Optical Spectrum Analyzer Module	Currently supported	8614X OSA Family
70953A	Time Domain Extinction Upgrade	Currently supported	8614X OSA Family
71000E	Wide Bandwidth Signal Analysis System	No longer supported	no replacement
71000S	Spectrum analyzer system reference	No longer supported	no replacement
71100A	RF SPECTRUM ANALYZER, REFURBISHED	No longer supported	71100C

Product	Description	Support Status	Replacement Information
71100CR	RF Spectrum Analyzer, 100Hz to 2.9GHz	Currently supported	
71100XL	SCALAR/SPECTRUM ANALYZER	No longer supported	70900B SYS
71150C	GSM test system, 100 Hz to 2.9 GHz	No longer supported	no replacement
71200A	MW SPECTRUM ANALYZER, REFURBISHED.	No longer supported	71200C
71200CR	MW spectrum analyzer, 50kHz to 22GHz	Currently supported	
71200P	MW Spectrum Analyzer, 50 KHz to 22 GHz	Currently supported	
71201A	MW SPECTRUM ANALYZER, REFURBISHED.	No longer supported	71200C-002
71201XL	SCALAR/SPECTRUM ANALYZER	No longer supported	70900B SYS
71210A	MW SPECTRUM ANALYZER, REFURBISHED.	No longer supported	71210C
71210XL	SCALAR/SPECTRUM ANALYZER	No longer supported	70900B SYS
71250C	GSM test system, 100 Hz to 22 GHz	No longer supported	no replacement
71300A	MM SPECTRUM ANALYZER	No longer supported	70900B SYS
71400A	LIGHTWAVE SIGNAL ANALYZER	No longer supported	no replacement
71400S	Lightwave System Reference	No longer supported	no replacement
71400C-910	Extra User's Manual Set	No longer supported	no replacement
71400C-915	Service Manual Set & Troubleshooting S/W	No longer supported	no replacement
71401A	LIGHTWAVE SIGNAL ANALYZER-RF	No longer supported	no replacement
71401C-910	Extra User's Manual Set	No longer supported	no replacement
71401C-915	Service Manual Set	No longer supported	no replacement
71401CR	Lightwave Signal Analyzer	Currently supported	
71450A	Optical spectrum analyzer	Currently supported	8614X OSA Family
71450AR	Optical spectrum analyzer	No longer supported	
71450B	Optical Spectrum Analyzer	Currently supported	8614X OSA Family
71451A	Optical spectrum analyzer with OT switch	Currently supported	8614X OSA Family
71451AR	Optical spectrum analyzer with OT switch	No longer supported	
71451B	Optical Spectrum Analyzer	Currently supported	8614X OSA Family
71452B	Optical Spectrum Analyzer Module	Currently supported	8614X OSA Family
71500AR	Microwave transition analyzer system	Currently supported	
71501A	Eye diagram analyzer	No longer supported	71501B and 83480A
71501B	Jitter and eye-diagram analyzer	No longer supported	71501C, Option K90
71501B	Jitter and eye-diagram analyzer	No longer supported	71501C, Option K90
71501B-K10	Jitter System Upgrade	No longer supported	
71501B-K11	Jitter System Upgrade	No longer supported	
71501B-K26	Jitter system upgrade	No longer supported	
71501C	Jitter Analysis Sys: 50 Mb/s to 10 Gb/s	Currently supported	71501D
71501C-005	Adds eye diagram analysis to 71501C	No longer supported	
71501C-0B1	Extra manual set for the 71501C	No longer supported	
71501C-0BW	Service documentation 71501C	No longer supported	
71501C-915	Service manuals for the 70820 MTA	No longer supported	
71501C-K05	Eye diagram software	No longer supported	
71501C-K21	Jitter software	No longer supported	
71501C-K88	Items to comprise 71501C, Opt. 200, 201	No longer supported	
71501C-K89	70820A memory upgrade	No longer supported	
71501C-K90	70820A memory upgrade	No longer supported	
71501C-K91	70820A memory upgrade	No longer supported	
71601A	1 Gbit/s Error Performance Analyzer	No longer supported	N4906A
71602A	1 Gbit/s Pattern Generator	No longer supported	N4906A
71603A	3 Gbit/s Error Performance Analyzer	No longer supported	N4906A
71604A	3 Gbit/s Pattern Generator	No longer supported	N4906A
71604B	3 Gb/s Pattern Generator	Currently supported	N4906A
71707AR	Microwave downconverter	Currently supported	
71910PR	Wide bandwidth surveillance receiver	Currently supported	
74791S	4-Channel 3565S	No longer supported	35670A
74792S	8-Channel 3565S	No longer supported	35670A
74793S	16-Channel 3565S	No longer supported	35670A

Product	Description	Support Status as of 1 May	Replacement Information
81000AB	ADAPTER DIAMOND/HMS-10 TO BARE FIBER	No longer supported	no replacement
81000AM	HMS-10/HMS-10 THROUGH ADAPTER	No longer supported	no replacement
81000AS	SPLITTER 850NM	No longer supported	no replacement
81000BS	SPLITTER 1300NM	No longer supported	no replacement
81000CA	CONNECTOR ADAPTER BARE FIBER 140UM	Currently supported	no replacement
81000DA	CONNECTOR ADAPTER RADIALL	Currently supported	no replacement
81000EA	Connector Adapter for EC	Currently supported	no replacement
81000JA	CONNECTOR ADAPTER SMA	Currently supported	no replacement
81000KB	Adapter to connect SC/PC to bare fiber	No longer supported	no replacement
81000LA	CONNECTOR ADAPTER FOR F+G 3702	No longer supported	no replacement
81000NA	CONNECTOR ADAPTER STRATOS 430	No longer supported	no replacement
81000SB	Adapter to connect DIN to bare fiber	No longer supported	no replacement
81000VB	ADAPTER ST TO BARE FIBER	No longer supported	no replacement
81000WA	CONNECTOR ADAPTER BICONIC	Currently supported	no replacement
81000WB	ADAPTER BICONIC TO BARE FIBER	No longer supported	no replacement
81000WI	CONNECTOR INTERFACE BICONIC	Currently supported	no replacement
81000YA	CONNECTOR ADAPTER FOR DIAMOND HFS-1	No longer supported	no replacement
81001JA	Connector Adapter MT-RJ	No longer supported	no replacement
81001PI	Connector interface E-2000 (sensor only)	No longer supported	no replacement
81003FD	Connector Adapter FP/PC/APC(8163 series), D-shape	No longer supported	81001FA
81003MD	Connector Adapter MU (8163 series), D-shape	No longer supported	81001MA
81005AA	Connector Adapter Diamond HMS-10	Currently supported	no replacement
81005AI	Connector Interface Diamond HMS-10	Currently supported	no replacement
81005BA	Connector Adapter Bare Fiber 120 145um	Currently supported	no replacement
81005FA	Connector Adapter FC/PC/SPC/APC	Currently supported	no replacement
81005FI	Connector Interface FC/PC/SPC/	Currently supported	no replacement
81005JA	Connector Adapter SMA	Currently supported	no replacement
81005SA	Connector Adapter DIN 47256/4108	Currently supported	no replacement
81005SI	Connector Interface DIN 47256	Currently supported	no replacement
81005VA	Connector Adapter ST	Currently supported	no replacement
81005VI	Connector Interface ST	Currently supported	no replacement
81005WA	Connector Adapter Biconic	Currently supported	no replacement
81005WI	Connector Interface Biconic	Currently supported	no replacement
81010BS	SPLITTER 1300NM, 1550NM	Currently supported	no replacement
81050AL	LENS 850NM	Currently supported	no replacement
81101AC	Adapter Cable HMS-10 to HMS-10. 9um	No longer supported	Diamond HMS-10 PC + HMS-10 PC SMF 9/125
81101BC	ADAPTER CABLE HMS-10 TO BAREFIBER, 9UM	Currently supported	no replacement
81101DC	ADAPTER CABLE HMS-10 TO VFO-DF(sl), 9UM	Currently supported	no replacement
81101EC	ADAPTER CABLE HMS-10 TO VFO-DF(st), 9UM	Currently supported	no replacement
81101FC	Adapter Cable HMS-10 to FC PC. 9um	No longer supported	Diamond HMS-10 PC + FC PC SMF 9/125, 2m
81101GC	HMS-10/D4	No longer supported	no replacement
81101PC	Adapter Cable HMS-10 to FC/SPC PC. 9um	No longer supported	Diamond HMS-10 PC + FC/SPC PC SMF 9/125,
81101SC	ADAPTER CABLE HMS-10 TO DIN 47256, 9UM	Currently supported	no replacement
81101VC	ADAPTER CABLE HMS-10 TO ST, 9UM	Currently supported	no replacement
81101WC	ADAPTER CABLE HMS-10 TO BICONIC, 9UM	Currently supported	no replacement
81102DC	ADAPTER CABLE HRL TO VFO-DF(sl), 9UM	Currently supported	no replacement
81113BC	Adapter Cable DIN47256/4108 to bare fiber. 9um	No longer supported	Diamond DIN47256/4108 + bare fiber SMF 9/1

Product	Description	Support Status as of 1 May	Replacement Information
81113EC	ADAPTER CABLE DIN 4108 TO RADIALL EC,9UM	Currently supported	no replacement
81113PC	Adapter Cable DIN47256/4108 to FC/SPC PC. 9um	No longer supported	Diamond DIN47256/4108 + FC/SPC PC SMF 9/
81113SC	Adapter Cable DIN47256/4108 to DIN47256/4108. 9um	No longer supported	Diamond DIN47256/4108 + DIN47256/4108 SM
81210LI	OPTICAL ISOLATOR 1310NM	No longer supported	no replacement
81220FL	ATTENUATING LENS ADAPTER	No longer supported	no replacement
81230FL	LENS ADAPTER FOR DIVERGENT BEAMS	Currently supported	no replacement
81310LI	OPTICAL ISOLATOR, 1550NM	No longer supported	no replacement
81400A	SENSOR MODULE, 400-1100NM	No longer supported	no replacement
81401A	SENSOR, 750-1700NM	No longer supported	no replacement
81411A	LED MODULE, 850NM	No longer supported	no replacement
81412A	LED MODULE, 1300NM	No longer supported	no replacement
81413A	LED MODULE, 1550NM	No longer supported	no replacement
81450A	MEMORY MODULE	No longer supported	no replacement
81460SA	8146A OTDR EMULATION SOFTWARE FOR PC	No longer supported	no replacement
81461MH	850NM MULTIMODE PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81462MH	1300NM MULTIMODE PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81462SH	1310NM SINGLEMODE PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81462SL	1310NM singlemode plug-in for 8146A OTDR	No longer supported	no replacement
81463SH	1550NM SINGLEMODE PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81464MH	0.85/1.3UM PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81465SH	1.3/1.5UM PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81465SHR	1.3/1.5UM Plug-in for 8146A OTDR	No longer supported	no replacement
81465SL	1300/1550NM SM plug-in for 8146A OTDR	No longer supported	no replacement
81467MH	1300NM 62.5um PLUG-IN FOR 8146A OTDR	No longer supported	no replacement
81500A	FO CABLE HSF1	No longer supported	no replacement
81500B	FO CABLE NEC D4	No longer supported	no replacement
81500C	FO CABLE BARE	No longer supported	no replacement
81500E	FIBER OPTIC CABLE DIAMOND HFS1/AMPH 906	No longer supported	no replacement
81500F	FIBER OPTIC CABLE DIAMOND HFS1/HFS24 SMA	No longer supported	
81500G	FO CABLE FC, NTT	No longer supported	no replacement
81500J	FIBER OPTIC CABLE DIAMOND HFS1/F+G 3702	No longer supported	no replacement
81500K	FIBER OPTIC CABLE DIAMOND HFS1/STRATOS	No longer supported	no replacement
81500N	FIBER OPTIC CABLE DIAMOND HFS1/AMP SMA	No longer supported	no replacement
81501AC	Adapter Cable HMS-10 PC to HMS-10 PC MM	No longer supported	Diamond HMS-10 PC + HMS-10 PC MMF 50/12
81501BC	ADAPTER CABLE HMS-10 TO BAREFIBER, 50UM	Currently supported	no replacement
81501FC	Adapter Cable HMS-10 PC to FC PC MMF 50	No longer supported	Diamond HMS-10 PC + FC PC MMF 50/125, 2rr
81501GC	ADAPTER CABLE FOR D4, MULTIMODE	No longer supported	no replacement
81501HC	ADAPTER CABLE FOR AMP 906, MULTIMODE	No longer supported	no replacement
81501JC	ADAPTER CABLE FOR AMP SMA, MULTIMODE	No longer supported	no replacement
81501LC	ADAPTER CABLE FOR F+G3702, MULTIMODE	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
81501NC	ADAPTER CABLE FOR STRATOS 430, MULTIMODE	No longer supported	no replacement
81501SC	ADAPTER CABLE FOR DIN 47256, MULTIMODE	No longer supported	no replacement
81501VC	ADAPTER CABLE HMS-10 TO ST, 50UM	Currently supported	no replacement
81501WC	ADAPTER CABLE FOR BICONIC, MULTIMODE	No longer supported	no replacement
81501YC	ADAPTER CABLE FOR HFS-1, MULTIMODE	No longer supported	no replacement
81510A	CONNECTOR ADAPTER DIAMOND HFS1	No longer supported	no replacement
81510B	CONNECTOR ADAPTER NEC D4	No longer supported	no replacement
81510C	ADAPTER BARE 125UM	No longer supported	no replacement
81510D	ADAPTER BARE 250UM	No longer supported	no replacement
81510E	CONNECTOR ADAPTER AMPH 906	No longer supported	no replacement
81510F	F/O CONNECTOR ADAPTER HFS-24 (SMA)	No longer supported	
81510G	CONNECTOR ADAPTER FC (NTT), NEC D3	No longer supported	no replacement
81510H	CONNECTOR ADAPTER BICONIC (WE)	No longer supported	no replacement
81510J	CONNECTOR ADAPTER F+G3702	No longer supported	no replacement
81510K	CONNECTOR ADAPTER STRATOS 430	No longer supported	no replacement
81510N	CONNECTOR ADAPTER AMP SMA	No longer supported	no replacement
81510Q	BASE PLATE FOR MOUNTING AN OPTICAL HEAD	No longer supported	no replacement
81510R	PARALLEL BEAM ADAPTER	No longer supported	no replacement
81510Z	CONNECTOR ADAPTER BLANK	No longer supported	no replacement
81511A	OPT HEAD 850NM	No longer supported	no replacement
81512A	OPTICAL HEAD 1300NM	No longer supported	no replacement
81512B	OPTICAL TEST HEAD 1300NM	No longer supported	
81519A	OPTICAL RECEIVER	No longer supported	no replacement
81520A	SI OPTICAL HEAD, 5MM DIAMETER	Currently supported	no replacement
81521B	GE OPTICAL HEAD, 5MM DIAMETER	Currently supported	81623B (must be used with 8163A/B, 8164A/
81522A	Optical Head, 1000 to 1650 nm	No longer supported	no replacement
81524A	InGaAs OPTICAL HEAD, 5MM DIAMETER	Currently supported	81624A
81525A	High power InGaAs Optical Head, 5mm	Currently supported	81625B
81530A	POWER SENSOR MODULE	Currently supported	no replacement
81531A	POWER SENSOR MODULE	Currently supported	81632B with 8163A/B, 8164A/B, 8166A/B
81532A	POWER SENSOR MODULE	Currently supported	81634A
81533A	Interface Module for 8153A/obsolete	No longer supported	81618A/81619A (goes with 8162xA/B heads)
81533B	Interface module for 8153A	Currently supported	no replacement
81534A	replaced by 81610A	Currently supported	81610A (must be used with 8163A/B, 8164A/
81536A	POWER SENSOR MODULE	Currently supported	81632A or 81635A (dual)
81541MM	LED SOURCE MODULE 850NM	No longer supported	no replacement
81541MMR	Led source module 850nm	No longer supported	
81542MM	LED SOURCE MODULE 1300NM	Currently supported	no replacement
81551MM	LASER SOURCE MODULE 850NM	Currently supported	no replacement
81552SM	LASER SOURCE MODULE 1310NM	Currently supported	81650A (must be used with 8163A/B, 8164A/
81553SM	LASER SOURCE MODULE 1550NM	Currently supported	81651A (must be used with 8163A/B, 8164A/
81554SM	LASER SOURCE MODULE 1310/1550NM	Currently supported	81654A (must be used with 8163A/B, 8164A/
81621AC	HMS-10/HMS-10	No longer supported	no replacement
81621BC	ADAPTER CABLE HMS-10/BAREFIBER, 62.5UM	Currently supported	no replacement
81621VC	HMS-10/WE ST	No longer supported	no replacement
81623A	Ge Optical Head, 5mm Diameter	Currently supported	81623B
81624A	InGaAs Optical Head, 5mm Diameter	Currently supported	81624B
81625A	High Power InGaAs Optical Head, 5mm	Currently supported	81626B
81625B	High Power InGaAs Optical Head 27dBm	Currently supported	81626B
81625C	High Power InGaAs Optical Head, 20dBm	No longer supported	81626B

Product	Description	Support Status	Replacement Information
		as of 1 May	
81632B	Power Sensor Module (single channel)	Currently supported	81636B
81633A	Optical Power Sensor Module	Currently supported	81636B
81633B	Optical Power Sensor Module	Currently supported	81636B
81634A	Optical Power sensor Module	Currently supported	81634B
81991AC	HMS-10/HMS-10	No longer supported	no replacement
81991BC	HMS-10/BAREFIBER	No longer supported	no replacement
81991HC	HMS-10/AMP	No longer supported	no replacement
81991JC	HMS-10/AMP SMA	No longer supported	no replacement
82300A	BASIC LANGUAGE PROCESSOR	No longer supported	no replacement
82300B	BASIC Language Processor	No longer supported	no replacement
82300BJ	Measurement Coprocessor, Japanese	No longer supported	no replacement
82300C	Measurement Coprocessor	No longer supported	no replacement
82300CJ	Measurement Coprocessor, Japanese	No longer supported	no replacement
82300D	Measurement Coprocessor	No longer supported	no replacement
82300U	Upgrade Kit for Measurement Coprocessor	No longer supported	no replacement
82301A	BASIC SW ONLY	No longer supported	no replacement
82301B	BASIC Software	No longer supported	no replacement
82301BJ	BASIC Lang. Proc. Software Japanese	No longer supported	no replacement
82301C	BASIC Language Processor Software	No longer supported	no replacement
82301D	Measurement Coprocessor Software	No longer supported	no replacement
82302A	BASIC for Instr. Control Self Study	No longer supported	no replacement
82303A	512Kb RAM Kit	No longer supported	no replacement
82304B	BASIC ROM	No longer supported	no replacement
82305A	RAM Expansion Board	No longer supported	no replacement
82306A	GPIO Interface	Currently supported	no replacement
82307A	GPIO Interface Cable	Currently supported	no replacement
82310A	Pascal Language Processor	No longer supported	no replacement
82312A	Meas. Coprocessor with Right to Execute	No longer supported	no replacement
82313A	Hierarchical File System	No longer supported	no replacement
82313B	Hierarchical File System	No longer supported	no replacement
82314A	PC-308M BASIC CONTROLLER	No longer supported	no replacement
82314AB	PC-308M BASIC CONTROLLER/EURO ENGLISH	No longer supported	no replacement
82314B	PC-308ML U.S.	No longer supported	no replacement
82314BB	PC-308ML Euro/English	No longer supported	no replacement
82314BC	PC-308ML SPU	No longer supported	no replacement
82314BD	PC-308ML German	No longer supported	no replacement
82314BE	PC-308ML Spanish	No longer supported	no replacement
82314BF	PC-308ML French	No longer supported	no replacement
82314BK	PC-308ML ICON	No longer supported	no replacement
82314BS	PC-308ML Swedish	No longer supported	no replacement
82314BU	PC-308ML U.K.	No longer supported	no replacement
82314BZ	PC-308ML Italian	No longer supported	no replacement
82314C	PC-308M SPU	No longer supported	no replacement
82314CB	PC-308M SPU EURO/ENGLISH	No longer supported	no replacement
82314D	PC-308ML Controller U.S.	No longer supported	no replacement
82314DB	PC-308ML Controller Euro/English	No longer supported	no replacement
82314DD	PC-308ML Controller German	No longer supported	no replacement
82314DE	PC-308ML Controller Spanish	No longer supported	no replacement
82314DF	PC-305ML Controller French	No longer supported	no replacement
82314DK	PC-308ML Controller ICON	No longer supported	no replacement
82314DS	PC-308ML Controller Swedish	No longer supported	no replacement
82314DU	PC-305ML Controller U.K.	No longer supported	no replacement
82314DX	PC-308ML Controller Finnish	No longer supported	no replacement
82314DZ	PC-308ML Controller Italian	No longer supported	no replacement
82314E	PC-308ML Controller U.S.	No longer supported	no replacement
82314EB	PC-308ML Controller Euro/English	No longer supported	no replacement
82314ED	PC-308ML Controller German	No longer supported	no replacement
82314EE	PC-308ML Controller Spanish	No longer supported	no replacement
82314EF	PC-308ML Controller French	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
82314EK	PC-308ML Controller ICON	No longer supported	no replacement
82314ES	PC-308ML Controller Swedish	No longer supported	no replacement
82314EU	PC-308ML Controller U.K.	No longer supported	no replacement
82314EX	PC-308ML Controller Finnish	No longer supported	no replacement
82314EZ	PC-308ML Controller Italian	No longer supported	no replacement
82314F	PC-308ML BASIC Controller	No longer supported	no replacement
82314FB	PC-308ML BASIC Controller Euro/English	No longer supported	no replacement
82314FD	PC-308ML BASIC Controller German	No longer supported	no replacement
82314FE	PC-308ML BASIC Controller Spanish	No longer supported	no replacement
82314FF	PC-308ML BASIC Controller French	No longer supported	no replacement
82314FK	PC-308ML BASIC Controller ICON	No longer supported	no replacement
82314FS	PC-308ML BASIC Controller Swedish	No longer supported	no replacement
82314FU	PC-308ML BASIC Controller U.K.	No longer supported	no replacement
82314FX	PC-308ML BASIC Controller Finnish	No longer supported	no replacement
82314FZ	PC-308ML BASIC Controller Italian	No longer supported	no replacement
82314G	PC-308ML Instrument Controller	No longer supported	no replacement
82314L	PC-308ML Controller SPU	No longer supported	no replacement
82314M	PC-308ML Controller SPU	No longer supported	no replacement
82315A	PC-308C BASIC CONTROLLER	No longer supported	no replacement
82315AB	PC-308C BASIC CONTROLLER EURO/ENGLISH	No longer supported	no replacement
82315B	PC-308CL U.S.	No longer supported	no replacement
82315BB	PC-308CL Euro/English	No longer supported	no replacement
82315BC	PC-308CL SPU	No longer supported	no replacement
82315BD	PC-308CL German	No longer supported	no replacement
82315BE	PC-308CL Spanish	No longer supported	no replacement
82315BF	PC-308CL French	No longer supported	no replacement
82315BK	PC-308CL ICON	No longer supported	no replacement
82315BS	PC-308CL Swedish	No longer supported	no replacement
82315BU	PC-308CL U.K.	No longer supported	no replacement
82315BZ	PC-308CL Italian	No longer supported	no replacement
82315C	PC-308C SPU	No longer supported	no replacement
82315CB	PC-308C SPU EURO/ENGLISH	No longer supported	no replacement
82315D	PC-308CL Controller U.S.	No longer supported	no replacement
82315DB	PC-308CL Controller Euro/English	No longer supported	no replacement
82315DD	PC-308CL Controller German	No longer supported	no replacement
82315DE	PC-308CL Controller Spanish	No longer supported	no replacement
82315DF	PC-308CL Controller French	No longer supported	no replacement
82315DK	PC-308CL Controller ICON	No longer supported	no replacement
82315DS	PC-308CL Controller Swedish	No longer supported	no replacement
82315DU	PC-308CL Controller U.K.	No longer supported	no replacement
82315DX	PC-308CL Controller Finnish	No longer supported	no replacement
82315DZ	PC-308CL Controller Italian	No longer supported	no replacement
82315E	PC-308CL Controller U.S.	No longer supported	no replacement
82315EB	PC-308CL Controller Euro/English	No longer supported	no replacement
82315ED	PC-308CL Controller German	No longer supported	no replacement
82315EE	PC-308CL Controller Spanish	No longer supported	no replacement
82315EF	PC-308CL Controller French	No longer supported	no replacement
82315EK	PC-308CL Controller ICON	No longer supported	no replacement
82315ES	PC-308CL Controller Swedish	No longer supported	no replacement
82315EU	PC-308CL Controller U.K.	No longer supported	no replacement
82315EX	PC-308CL Controller Finnish	No longer supported	no replacement
82315EZ	PC-308CL Controller Italian	No longer supported	no replacement
82315F	PC-308CL BASIC Controller	No longer supported	no replacement
82315FB	PC-308CL BASIC Controller Euro/English	No longer supported	no replacement
82315FD	PC-308CL BASIC Controller German	No longer supported	no replacement
82315FE	PC-308CL BASIC Controller Spanish	No longer supported	no replacement
82315FF	PC-308CL BASIC Controller French	No longer supported	no replacement
82315FK	PC-308CL BASIC Controller ICON	No longer supported	no replacement
82315FS	PC-308CL BASIC Controller Swedish	No longer supported	no replacement
82315FU	PC-308CL BASIC Controller U.K.	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
82315FX	PC-308CL BASIC Controller Finnish	No longer supported	no replacement
82315FZ	PC-308CL BASIC Controller Italian	No longer supported	no replacement
82315L	PC-318CL Controller SPU	No longer supported	no replacement
82315M	PC-308CL Controller SPU	No longer supported	no replacement
82316A	PC-305M Controller U.S.	No longer supported	no replacement
82316AB	PC-305M Controller Euro/English	No longer supported	no replacement
82316AD	PC-305M German	No longer supported	no replacement
82316AE	PC-305M Controller Spanish	No longer supported	no replacement
82316AF	PC-305M Controller French	No longer supported	no replacement
82316AK	PC-305M Controller ICON	No longer supported	no replacement
82316AS	PC-305M Controller Swedish/Finnish	No longer supported	no replacement
82316AU	PC-305M Controller U.K.	No longer supported	no replacement
82316AZ	PC-305M Controller Italian	No longer supported	no replacement
82316C	PC-305M SPU	No longer supported	no replacement
82316D	PC-305M CONTROLLER U.S.	No longer supported	no replacement
82316DB	PC-305M Controller Euro/English	No longer supported	no replacement
82316DD	PC-305M Controller German	No longer supported	no replacement
82316DE	PC-305M Controller Spanish	No longer supported	no replacement
82316DF	PC-305M Controller French	No longer supported	no replacement
82316DK	PC-305M Controller ICON	No longer supported	no replacement
82316DS	PC-305M Controller Swedish	No longer supported	no replacement
82316DU	PC-305M CONTROLLER U.K.	No longer supported	no replacement
82316DX	PC-305M Controller Finnish	No longer supported	no replacement
82316DZ	PC-305M Controller Italian	No longer supported	no replacement
82316L	PC-308M Controller SPU	No longer supported	no replacement
82317A	PC-305ML Controller U.S.	No longer supported	no replacement
82317AB	PC-305ML Controller Euro/English	No longer supported	no replacement
82317AD	PC-305ML Controller German	No longer supported	no replacement
82317AE	PC-305ML Controller Spanish	No longer supported	no replacement
82317AF	PC-305ML Controller French	No longer supported	no replacement
82317AK	PC-305ML Controller ICON	No longer supported	no replacement
82317AS	PC-305ML Controller Swedish	No longer supported	no replacement
82317AU	PC-305ML Controller U.K.	No longer supported	no replacement
82317AZ	PC-305ML Controller Italian	No longer supported	no replacement
82317C	PC-305ML SPU	No longer supported	no replacement
82317D	PC-305ML Controller U.S.	No longer supported	no replacement
82317DB	PC-305ML Controller Euro/English	No longer supported	no replacement
82317DD	PC-305ML Controller German	No longer supported	no replacement
82317DF	PC-305ML Controller French	No longer supported	no replacement
82317DK	PC-305ML Controller ICON	No longer supported	no replacement
82317DS	PC-305ML Controller Swedish	No longer supported	no replacement
82317DU	PC-305ML Controller U.K.	No longer supported	no replacement
82317DX	PC-305ML Controller Finnish	No longer supported	no replacement
82317DZ	PC-305ML Controller Italian	No longer supported	no replacement
82317E	PC-305ML Controller U.S.	No longer supported	no replacement
82317EB	PC-305ML Controller Euro/English	No longer supported	no replacement
82317ED	PC-305ML Controller German	No longer supported	no replacement
82317EE	PC-305ML Controller Spanish	No longer supported	no replacement
82317EF	PC-305ML Controller French	No longer supported	no replacement
82317EK	PC-305ML Controller ICON	No longer supported	no replacement
82317ES	PC-305ML Controller Swedish	No longer supported	no replacement
82317EU	PC-305ML Controller U.K.	No longer supported	no replacement
82317EX	PC-305ML Controller Finnish	No longer supported	no replacement
82317EZ	PC-305ML Controller Italian	No longer supported	no replacement
82317L	PC-305ML Controller SPU	No longer supported	no replacement
82317M	PC-305ML Controller SPU	No longer supported	no replacement
82318A	PC-305CL Controller U.S.	No longer supported	no replacement
82318AB	PC-305CL Controller Euro/English	No longer supported	no replacement
82318AD	PC-305CL Controller German	No longer supported	no replacement
82318AE	PC-305CL Controller Spanish	No longer supported	no replacement
82318AF	PC-305CL Controller French	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
82318AK	PC-305CL Controller ICON	No longer supported	no replacement
82318AS	PC-305CL Controller Swedish	No longer supported	no replacement
82319D	PC-308CM Controller U.s.	No longer supported	no replacement
82319DB	PC-308CM Controller Eur/Eng.	No longer supported	no replacement
82319DD	PC-308CM Controller German	No longer supported	no replacement
82319DE	PC-308CM Controller Spanish	No longer supported	no replacement
82319DF	PC-308CM Controller French	No longer supported	no replacement
82319DK	PC-308CM Controller ICON	No longer supported	no replacement
82319DS	PC-308CM Controller Swedish	No longer supported	no replacement
82319DU	S	No longer supported	no replacement
82319DX	PC-308CM Controller Finnish	No longer supported	no replacement
82319DZ	PC-308CM Controller Italian	No longer supported	no replacement
82319E	PC-308CM Controller U.S.	No longer supported	no replacement
82319EB	PC-308CM Controller Euro/English	No longer supported	no replacement
82319ED	PC-308CM Controller German	No longer supported	no replacement
82319EE	PC-308CM Controller Spanish	No longer supported	no replacement
82319EF	PC-308CM Controller French	No longer supported	no replacement
82319EK	PC-308CM Controller ICON	No longer supported	no replacement
82319ES	PC-308CM Controller Swedish	No longer supported	no replacement
82319EU	PC-308CM Controller U.K.	No longer supported	no replacement
82319EX	PC-308CM Controller Finnish	No longer supported	no replacement
82319EZ	PC-308CM Controller Italian	No longer supported	no replacement
82319F	PC-308CM BASIC Controller	No longer supported	no replacement
82319FB	PC-308CM BASIC Controller Euro/English	No longer supported	no replacement
82319FD	PC-308CM BASIC CONTROLLER GERMAN	No longer supported	no replacement
82319FE	PC-308CM BASIC Controller Spanish	No longer supported	no replacement
82319FF	PC-308CM BASIC Controller France	No longer supported	no replacement
82319FK	PC-308CM BASIC Controller ICON	No longer supported	no replacement
82319FS	PC-308CM BASIC Controller Swedish	No longer supported	no replacement
82319FU	PC-308CM BASIC Controller U.K.	No longer supported	no replacement
82319FX	PC-308CM BASIC Controller Finnish	No longer supported	no replacement
82319FZ	PC-308CM BASIC Controller Italian	No longer supported	no replacement
82319M	PC-308CM Controller SPU	No longer supported	no replacement
82321A	HP LANGUAGE PROCESSOR	No longer supported	no replacement
82321B	BASIC Language Processor Board	No longer supported	no replacement
82321C	BASIC Language Processor Board	No longer supported	no replacement
82323A	Upgrade Kit for Measurement Coprocessor	No longer supported	no replacement
82323AJ	Measurement Coprocessor Upgrade,Japanese	No longer supported	no replacement
82324A	High Performance Measurement Coprocessor	No longer supported	no replacement
82324B	High Performance Measurement Coprocessor	No longer supported	no replacement
82324BR	High Performance Measurement Coprocessor	No longer supported	
82332E	PC-312CL BASIC Controller	No longer supported	no replacement
82332EB	PC-312CL Controller Euro/English	No longer supported	no replacement
82332ED	PC-312CL Controller German	No longer supported	no replacement
82332EE	PC-312CL Controller Spanish	No longer supported	no replacement
82332EF	PC-312CL Controller French	No longer supported	no replacement
82332EK	PC-312CL Controller ICON	No longer supported	no replacement
82332ES	PC-312CL Controller Swedish	No longer supported	no replacement
82332EU	PC-312CL Controller U.K.	No longer supported	no replacement
82332EX	PC-312CL Controller Finnish	No longer supported	no replacement
82332EZ	PC-312CL Controller Italian	No longer supported	no replacement
82332M	PC-312CL Controller SPU	No longer supported	no replacement
82333D	PC-312CM Controller U.S.	No longer supported	no replacement
82333DB	PC-312CM Controller Euro/English	No longer supported	no replacement
82333DD	PC-312CM Controller German	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
82333DE	PC-312CM Controller Spanish	No longer supported	no replacement
82333DF	PC-312CM Controller French	No longer supported	no replacement
82333DK	PC-312CM Controller ICON	No longer supported	no replacement
82333DS	PC-312CM Controller Swedish	No longer supported	no replacement
82333DU	PC-312CM Controller U.K.	No longer supported	no replacement
82333DX	PC-312CM Controller Finnish	No longer supported	no replacement
82333DZ	PC-312CM Controller Italian	No longer supported	no replacement
82333E	PC-312CM BASIC Controller	No longer supported	no replacement
82333EB	PC-312CM Controller Euro/English	No longer supported	no replacement
82333ED	PC-312CM Controller German	No longer supported	no replacement
82333EE	PC-312CM Controller Spanish	No longer supported	no replacement
82333EF	PC-312CM Controller French	No longer supported	no replacement
82333EK	PC-312CM Controller ICON/English	No longer supported	no replacement
82333ES	PC-312CM Controller Swedish	No longer supported	no replacement
82333EU	PC-312CM Controller U.K.	No longer supported	no replacement
82333EX	PC-312CM Controller Finnish	No longer supported	no replacement
82333EZ	PC-312CM Controller Italian	No longer supported	no replacement
82333F	PC-313CM Controller	No longer supported	no replacement
82333G	PC-313CM Controller	No longer supported	D1867A/B/C
82333M	PC-312CM Controller SPU	No longer supported	no replacement
82334E	PC-315CN BASIC Controller	No longer supported	no replacement
82334EB	PC-315 Controller EURO/English	No longer supported	no replacement
82334ED	PC-315CN Controller German	No longer supported	no replacement
82334EE	PC-315CN Controller Spanish	No longer supported	no replacement
82334EF	PC-315CN Controller French	No longer supported	no replacement
82334EK	PC-315CN Controller ICON	No longer supported	no replacement
82334ES	PC-315CN Controller Swedish	No longer supported	no replacement
82334EU	PC-315CN Controller U.K.	No longer supported	no replacement
82334EX	PC-315CN Controller Finnish	No longer supported	no replacement
82334EZ	PC-315CN Controller Italian	No longer supported	no replacement
82334M	PC-315CN Controller SPU	No longer supported	no replacement
82335A	GPIB Interface and Command Library	No longer supported	82341C
82335BR	HP-IB Interface for MS Windows and DOS	Currently supported	
82335U	GPIB for Windows and DOS software only	Currently supported	E2094M
82337A	Measurement Coprocessor (For OEM only)	No longer supported	no replacement
82341A	Hi-Performance GPIB Card for Inst. Cntl.	No longer supported	82341C
82342A	Upgrade 82341A to I/O Lib. for Win. NT	No longer supported	E2094M
82342B	Upgrade to SICL for Windows NT	No longer supported	E2094M
82344E	PC Win95/NT Automation Kit for Volume	No longer supported	
82344F	PC Win95/NT Automation Kit for Volume	Currently supported	
82345A	Automation kit for PCs with HP VEE	No longer supported	82345B
82345D	PC Windows 95/NT Automation Kit	No longer supported	http://www.agilent.com/find/vee
82345E	HP VEE 4.0 for Win95/NT	No longer supported	
82346C	HP BASIC Automation Kit EISA GPIB	Currently supported	
82347A	PC Automation Kit with MS Visual C++	No longer supported	
82356C	HP BASIC Automation Kit PCI GPIB	Currently supported	
82800A	VISICALC PLUS	No longer supported	no replacement
82800F	VISICALC FRE	No longer supported	no replacement
82800G	VISICALC GER	No longer supported	no replacement
82801A	GRAPHICS PAC	No longer supported	no replacement
82802A	BASIC TRAIN PAC	No longer supported	no replacement
82803A	FINANCE PAC	No longer supported	no replacement
82803F	FINANCE PAC FRE	No longer supported	no replacement
82803G	FINANCE PAC GER	No longer supported	no replacement
82804A	STATISTIC PAC	No longer supported	no replacement
82804E	STAT PAC SPANISH	No longer supported	no replacement
82804F	STAT PAC FRE	No longer supported	no replacement
82804G	STAT PAC GER	No longer supported	no replacement
82805A	BASIC STAT & DM	No longer supported	no replacement
82806A	REGRESSION ANALY	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
82807A	STAT BUNDLED PAC	No longer supported	no replacement
82808A	LINEAR PROG PAC	No longer supported	no replacement
82809A	WAVEFORM ANALYS	No longer supported	no replacement
82810A	CIRCUIT ANAL PAC	No longer supported	no replacement
82811A	MATH PAC	No longer supported	no replacement
82811E	MATH PAC SPANISH	No longer supported	no replacement
82811F	MATH PAC FRENCH	No longer supported	no replacement
82811G	MATH PAC GERMAN	No longer supported	no replacement
82812A	EE BUNDLED PAC	No longer supported	no replacement
82813A	SURVEYING PAC	No longer supported	no replacement
82814A	PORTFOLIO MGMT	No longer supported	no replacement
82815J	Datacomm Software	No longer supported	no replacement
82816A	TEXT EDITING PAC	No longer supported	no replacement
82817A	IMPAC	No longer supported	no replacement
82818A	GAMES	No longer supported	no replacement
82819A	GAMES II	No longer supported	no replacement
82820A	STANDARD PAC	No longer supported	no replacement
82820E	STAN PAC SPANISH	No longer supported	no replacement
82820F	STANDARD PAC FRE	No longer supported	no replacement
82820G	STAN PAC GERMAN	No longer supported	no replacement
82820P	STANDARD PAC POR	No longer supported	no replacement
82820T	STANDARD PAC ITL	No longer supported	no replacement
82821A	Data Communications Software	No longer supported	no replacement
82823A	WORD 80	No longer supported	no replacement
82823F	WORD 80 FRENCH	No longer supported	no replacement
82823G	WORD 80 GERMAN	No longer supported	no replacement
82823T	WORD 80 ITALIAN	No longer supported	no replacement
82824A	FILE 80	No longer supported	no replacement
82824F	FILE 80 FRENCH	No longer supported	no replacement
82824G	FILE 80 GERMAN	No longer supported	no replacement
82824T	FILE 80 ITALIAN	No longer supported	no replacement
82830A	VISICALC PLUS	No longer supported	no replacement
82830F	VISICALC FRENCH	No longer supported	no replacement
82830G	VISICALC GERMAN	No longer supported	no replacement
82831A	GRAPHICS PAC	No longer supported	no replacement
82831G	GRAPHICS PAC GER	No longer supported	no replacement
82832A	BASIC TRAIN PAC	No longer supported	no replacement
82833A	FINANCE PAC	No longer supported	no replacement
82834A	STAT PAC	No longer supported	no replacement
82835A	BASIC STAT & DM	No longer supported	no replacement
82836A	REGRESSION ANAL	No longer supported	no replacement
82837A	ST/AN BNDLD PAC	No longer supported	no replacement
82838A	LINEAR PROG PAC	No longer supported	no replacement
82839A	WAVEFORM ANALYS	No longer supported	no replacement
82840A	CIRCUIT ANAL PAC	No longer supported	no replacement
82841A	MATH PAC	No longer supported	no replacement
82842A	EE BUNDLED PAC	No longer supported	no replacement
82843A	SURVEYING PAC	No longer supported	no replacement
82844A	PORTFOLIO MGMT	No longer supported	no replacement
82846A	PER PROD PAC	No longer supported	no replacement
82847A	BUS. PROD. PAC	No longer supported	no replacement
82848A	CP/M S/W ONLY	No longer supported	no replacement
82849A	TERM/80 S/W	No longer supported	no replacement
82850A	PROF COMM PAC	No longer supported	no replacement
82851A	PROF COMM PAC	No longer supported	no replacement
82852A	Lattice C Compiler	No longer supported	no replacement
82853A	Lattice Development Tools	No longer supported	no replacement
82855A	MULTIPLAN	No longer supported	no replacement
82856J	HP-UX Tools	No longer supported	no replacement
82857J	HP-UX Compiler	No longer supported	no replacement
82858J	HP-UX Fortran	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
82859J	HP-UX Pascal	No longer supported	no replacement
82860J	HP-UX Technical BASIC	No longer supported	no replacement
82865J	Integral PC Programming Documentation	No longer supported	no replacement
82900A	82900A CP/M SYST	No longer supported	no replacement
82903A	Plug-in Memory for HP-85	No longer supported	no replacement
82904A	I/O Bus Expander U.S.	No longer supported	no replacement
82904AB	I/O Bus Expander Euro	No longer supported	no replacement
82904AK	I/O Bus Expander ICON	No longer supported	no replacement
82904AQ	I/O Bus Expander Swiss	No longer supported	no replacement
82904AU	I/O Bus Expander U.K.	No longer supported	no replacement
82904AY	I/O Bus Expander Danish	No longer supported	no replacement
82908A	64KB MEMORY MODULE	No longer supported	no replacement
82909A	128Kb Memory Module	No longer supported	no replacement
82912A	VIDEO MONITOR 9"	No longer supported	no replacement
82913A	12" Video Monitor	No longer supported	no replacement
82915A	300/1200 BPS Modem	No longer supported	no replacement
82916A	1Mb Memory Module	No longer supported	no replacement
82916B	1Mb Ram Carrier	No longer supported	no replacement
82919A	Serial Interface Card	No longer supported	no replacement
82919AD	Serial Interface Card German	No longer supported	no replacement
82919AF	Serial Interface Card French	No longer supported	no replacement
82919AJ	Serial Interface Card Japanese	No longer supported	no replacement
82919AZ	Serial Interface Card Italian	No longer supported	no replacement
82920A	Current Loop Interface	No longer supported	no replacement
82922A	BCD Interface	No longer supported	no replacement
82923A	GPIO Interface	No longer supported	no replacement
82924A	HP-IL Interface Card	No longer supported	no replacement
82925A	256K Memory Module	No longer supported	no replacement
82927A	512K Memory Module	No longer supported	no replacement
82927B	512K RAM Carrier	No longer supported	no replacement
82928A	SER80 SYS MONITR	No longer supported	no replacement
82929A	Series 80 ROM Drawer	No longer supported	no replacement
82936A	SER80 ROM DRAWER	No longer supported	no replacement
82937A	Series 80 GPIB Interface	No longer supported	no replacement
82938A	HPIL INTERFACE	No longer supported	no replacement
82939A	Series 80 Serial Interface	No longer supported	no replacement
82940A	Series 80 GPIO Interface	No longer supported	no replacement
82941A	Series 80 BCD Interface	No longer supported	no replacement
82943A	SER80 DEALER KIT	No longer supported	no replacement
82949A	SER80 PRNTR INTF	No longer supported	no replacement
82950A	SERIES 80 MODEM	No longer supported	no replacement
82959A	GRAPHICS DISPLAY	No longer supported	no replacement
82960A	GRAPHICS CONTRLR	No longer supported	no replacement
82960T	PROF REF MANUAL	No longer supported	no replacement
82962E	VECTRA CAD/CAE SPL	No longer supported	no replacement
82962M	VECTRA INST. CTRL SPU	No longer supported	no replacement
82964E	ENTRY CAD/CAE SY	No longer supported	no replacement
82964EB	CAD/CAE SYSTEM	No longer supported	no replacement
82964ED	CAD/CAE SYSTEM	No longer supported	no replacement
82964EF	CAD/CAE SYSTEM	No longer supported	no replacement
82964EU	CAD/CAE SYSTEM	No longer supported	no replacement
82964EZ	CAD/CAE SYSTEM	No longer supported	no replacement
82964M	ADV/CAD/CAE SYS	No longer supported	no replacement
82965A	High Speed Coprocessor Module	No longer supported	no replacement
82966A	DATALINK INTERF.	No longer supported	no replacement
82967A	SPEECH MODULE	No longer supported	no replacement
82968A	EPROM/ROM Board	No longer supported	no replacement
82969J	Device I/O Library	No longer supported	no replacement
82970A	EPROM/ROM Software Tools	No longer supported	no replacement
82971A	EPROM/ROM Module	No longer supported	no replacement
82972A	85A Upgrade Kit	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
82974A	Serial Modem Cable	No longer supported	no replacement
82974B	Serial Instrument Cable	No longer supported	no replacement
82974C	Serial Print Cable	No longer supported	no replacement
82974D	Serial Print Cable	No longer supported	no replacement
82975A	Current Loop Interface	No longer supported	no replacement
82976A	GPIO/BCD Interface	No longer supported	no replacement
82977A	GPIO Cable	No longer supported	no replacement
82977B	GPIO Cable	No longer supported	no replacement
82978J	HP-UX Programming Techniques	No longer supported	no replacement
82987A	Software Engineering ROM	No longer supported	no replacement
82988J	TECH BASIC UPGRD	No longer supported	no replacement
82989J	HP-UX Technical BASIC	No longer supported	no replacement
82990A	GPIO Interface Card & Command Library	No longer supported	82341C
82990E	GPIO Command Library	No longer supported	no replacement
82991A	System V Upgrade	No longer supported	no replacement
82991AD	SYSTEM V UPGRADE	No longer supported	no replacement
82991AF	SYSTEM V UPGRADE	No longer supported	no replacement
82991AJ	SYSTEM V UPGRADE	No longer supported	no replacement
82991AZ	SYSTEM V UPGRADE	No longer supported	no replacement
82995A	Operating System ROM Accessory	No longer supported	no replacement
82998A	GPIO Interface Card	No longer supported	no replacement
83006AR	Amplifier,0.01-26.5GHz,18 dB gain	Currently supported	
83022A	RF Accessory Kit	No longer supported	no replacement
83023A	Accessory Kit, Type N for 70820A	No longer supported	no replacement
83024A	Accessory Kit, 3.5mm for 70820A	No longer supported	no replacement
83025A	Accessory Kit 2.4mm for 70820	No longer supported	no replacement
83040B	Microcircuit Pkg. Starter Kit 0.635mm	No longer supported	no replacement
83040C	Starter Kit for 0.254mm Substrate	No longer supported	no replacement
83041B	Microcircuit Pkg. End Block 0.635	No longer supported	no replacement
83041C	Microcircuit Pkg. End Block 0.254	No longer supported	no replacement
83042B	Microcircuit Pkg. Dual End Block 0.635	No longer supported	no replacement
83042C	Microcircuit Pkg. Dual End Block 0.254	No longer supported	no replacement
83043B	Center Block 0.635in	No longer supported	no replacement
83043C	Center Block, 0.254in	No longer supported	no replacement
83044X	Microcircuit Pkg Cover Set	No longer supported	no replacement
83045B	Thru Line, 0.635in	No longer supported	no replacement
83045C	Thru Line Phantom Mainframe	No longer supported	no replacement
83046B	Microcircuit Pkg Launch Ckts 0.635	No longer supported	no replacement
83046C	Microcircuit Pkg Launch Ckts 0.254	No longer supported	no replacement
83047X	Microcircuit Pkg Clamp Kit	No longer supported	no replacement
83048A	Calibration Accessories Phantom Mainfram	No longer supported	no replacement
83200A	Service Kit	No longer supported	no replacement
83201AR	Dual-Mode Cellular Adapter	Currently supported	
83201BR	TDMA Cellular Adaptor	Currently supported	
83203A	CDMA Cellular Adapter	No longer supported	no replacement
83203AR	CDMA Cellular Adapter	No longer supported	
83203B	CDMA Cellular Adapter	No longer supported	no replacement
83206ART	Retrofit Kit for 83206A	No longer supported	no replacement
83210A	Service Kit for GSM Test Set	No longer supported	no replacement
83211A	DSP CONTROLLER FOR 8953DT NADC TEST SYS	No longer supported	no replacement
83211AR	DSP Controller for 8953DT NADC Test Sys	No longer supported	
83212A	GSM/DCS-1800 Mobile Station Test SW	No longer supported	E5515C
83215AR	RF Interface	Currently supported	
83216A	8920DT System Calibration Kit	Currently supported	no replacement
83219A	Test Format Upgrade	Currently supported	no replacement
83236U	Upgrade Kit for the 83236A	Currently supported	no replacement
83236V	Upgrade Kit for the 83236B	No longer supported	no replacement
83400A	Lightwave Source	No longer supported	83402A

Product	Description	Support Status	Replacement Information
83400B	83400B LW Source, 1300 nm, 3 GHz	No longer supported	83402B
83401A	Lightwave Source	No longer supported	no replacement
83402A	Lightwave Source, 1300 nm, 6 GHz	No longer supported	83402C
83402AR	Lightwave source, 1300 nm, 6 GHz	Currently supported	
83402B	83402B LW Source, 1300 nm, 6 GHz	No longer supported	83402C
83402BR	83402B LW Source, 1300nm,6GHz	Currently supported	
83403A	Lightwave Source, 1550 nm, 3 GHz	No longer supported	83403C
83403AR	Lightwave Source, 1550nm, 3GHz	No longer supported	
83403B	83403B LW Source, 1550 nm, 3 GHz	No longer supported	83403C
83403BR	83403B LW Source, 1550nm, 3GHz	No longer supported	
83404A	83404A LW Source, 840 nm, 3GHz	No longer supported	83404B
83404B	83404B LW Source, 850 nm, 3 GHz	No longer supported	no replacement
83410A	Lightwave Receiver 300 kHz to 3 GHz	No longer supported	
83410B	Lightwave Receiver, 1300 & 1550 nm, 3GHz	No longer supported	
83411A	Lightwave Receiver, 1300 & 1550 nm, 6GHz	No longer supported	
83411B	83411B LW Rcvr, 1300 & 1550 nm, 6 GHz	No longer supported	
83411C-K10	Additional calibration by NIST	No longer supported	
83412A	83412A LW Receiver, 840 nm, 3 GHz	No longer supported	
83412BR	83412B LW receiver,850 nm, 3 GHz	Currently supported	
83420A	Lightwave test set	No longer supported	
83420A-K10	83420A lightwave test set retrofit	No longer supported	
83420AR	Lightwave test set	Currently supported	
83421A	Lightwave Source	No longer supported	no replacement
83421AR	Lightwave Source	No longer supported	
83422A	Lightwave Modulator	No longer supported	no replacement
83422AR	Lightwave Modulator	No longer supported	
83423A	Lightwave Receiver	No longer supported	no replacement
83423AR	Lightwave Receiver.	No longer supported	
83424A	Lightwave CW Source, 1550 nm	No longer supported	no replacement
83424AR	Lightwave CW Source, 1550nm	Currently supported	
83425A	Lightwave CW source, 1300 nm	No longer supported	no replacement
83425AR	Lightwave CW source, 1300 nm.	Currently supported	
83437A-K02	Retrofit to add a 1200nm & 1300nm EELED	No longer supported	no replacement
83437A-K03	Retrofit to add an Option 003	No longer supported	no replacement
83437A-K06	Retrofit to add a 1650nm EELED	No longer supported	no replacement
83437A-K16	Retrofit to replace the 1200nm EELED	No longer supported	no replacement
83437A-K23	Retrofit to add a 1200nm & 1310nm EELEDs	No longer supported	no replacement
83437A-K24	Retrofit to add a 1200nm & 1430nm EELEDs	No longer supported	no replacement
83437A-K34	Retrofit to add a 1310nm & 1430nm EELEDs	No longer supported	no replacement
83437A-K43	Retrofit to add a 1430nm	No longer supported	no replacement
83437A-K46	Retrofit to add a 1310/1430/1650nm EELED	No longer supported	no replacement
83437A-K87	Passive 2-port calibrator unit	No longer supported	no replacement
83438A-K09	Retrofits a standard 83438A	No longer supported	no replacement
83440B-K20	Retrofit detector with amplitude	No longer supported	
83440DR	34 GHz Optical-to-Electrical Converter.	Currently supported	
83440D-K20	Kit to provide amplitude and phase data	No longer supported	
83441A	Lightwave receiver	No longer supported	no replacement
83441B	Lightwave receiver	No longer supported	no replacement
83442A	Lightwave receiver	No longer supported	no replacement
83446B	Lightwave clock/data receiver 622 Mb/s	Currently supported	83493A (not 83483A)
83447A	Lightwave trigger receiver	Currently supported	83493A
83447AR	Lightwave trigger receiver	No longer supported	
83450A	ST Coupling	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
83464A	WDM & passive component test systems	Currently supported	no replacement
83465A	EDFA test systems	Currently supported	no replacement
83467A	Lightwave system base model: CD test	No longer supported	no replacement
83467B	LW system base model: comm test	Currently supported	no replacement
83467C	LW system base model: WL test	Currently supported	no replacement
83469A	Lighwave Demo Kit	No longer supported	no replacement
83470A	High speed optical parametric test sys.	No longer supported	
83470A-K71	10 Gb/s reference transmitter	No longer supported	
83475A	Lightwave Communications Analyzer	No longer supported	83475B and options
83475A-K01	Retrofits a 83475A #201 to a 83475B #201	No longer supported	
83475A-K06	Calibration certificate with test data	No longer supported	
83475AR	Lighwave Communications analyzer	No longer supported	
83475B	Lightwave communications analyzer	No longer supported	
83475B-K01	Kit to install calibrated filter	No longer supported	
83475B-K02	Kit to install calibrated filter	No longer supported	
83480A-K16	1X16 RF switch multiplexer	No longer supported	
83480A-K17	1X16 RAMBUS DUT fixture	No longer supported	
83480A-K98	Kit includes one transit case	No longer supported	
83480A-K99	Kit includes one transit case	No longer supported	
83480K	Communication Test Enhancement for 54750	No longer supported	
83481A	Dual rate optical/electrical plug-in	Currently supported	86103A
83482A	30 GHz optical/40 GHz electrical plug-in	Currently supported	86109A
83482AR	30GHz optical/ 40GHz electrical plug-in	Currently supported	
83483A	2 Channel Elec. Module, 12.4/20 GHz BW	Currently supported	86112A
83484A-K35	Retrofit kit of (2) 11901B adapters	No longer supported	
83484AA	DUAL CHANNEL 50GHZ PLUG-IN FOR 83480A	No longer supported	no replacement
83484B	83484B VERTICAL MODULE	Currently supported	no replacement
83484BA	83484BA VERTICAL MODULE	No longer supported	no replacement
83485A	Optical/Electrical Module 20 GHz BW	Currently supported	86105A
83485A-K24	Retrofit to install OC-24 receiver	No longer supported	
83485A-K28	Kit to install two internal filters	No longer supported	
83485A-K29	Retrofit to install & replace filter	No longer supported	
83485A-K30	Retrofit to install an OC-3 filter	No longer supported	
83485A-K32	Kit to install two internal filters	No longer supported	
83485A-K48	Retrofit to install an OC-48 filter	No longer supported	
83485A-K91	Retrofit kit to install an OC-192 filter	No longer supported	
83485A-K92	Kit to install 2 filters into a 83485A	No longer supported	
83485A-K94	Provides two reference receivers	No longer supported	
83485B	30 GHz optical/40 GHz electrical plug-in	Currently supported	86106B
83486A	Dual rate optical/electrical plug-in	Currently supported	86103A
83486A-K12	Retrofit to add the 622 Mb/s OC-12	No longer supported	
83486A-K21	Retrofit FC & double FC into std. 83486A	No longer supported	
83486A-K41	Retrofit OC-1 & OC-48 into std. 83486A	No longer supported	
83486A-K44	Retrofit Gigabit ethernet and OC-48	No longer supported	
83486A-K48	Retrofit OC-48, OC-12 & OC-3 into 83486A	No longer supported	
83486A-K58	Retrofit for 4th and 5th order filter	No longer supported	
83487A	Dual rate optical/electrical plug-in	Currently supported	86101A
83487A-K12	Retrofit OC-12 & gigabit channel	No longer supported	
83487A-K15	Retrofit to install a 1.5 Ghz filter	No longer supported	
83487A-K21	Retrofit FC & double FC into std. 83487A	No longer supported	
83487A-K22	Retrofit gigabit ethernet & double FC	No longer supported	
83487A-K48	Retrofit OC-48,OC-12 & OC-3 into 83487a	No longer supported	
83487A-K49	Retrofit OC-48, GB Ethernet & FC 1063	No longer supported	
83522A	RF plug-in for 8350A/B, 0.01-2.4 GHz	No longer supported	http://www.agilent.com/find/psg
83522AR	RF Plug-in for 8350A/B, 0.01-2.4 GHz	No longer supported	
83525A	RF plug-in for 8350A/B, 0.01-8.4 GHz	No longer supported	http://www.agilent.com/find/psg

Product	Description	Support Status	Replacement Information
83525AR	Remarketed RF Plug-in, 0.01 8.4GHz	No longer supported	
83525B	RF plug-in, 0.01-8.4 GHz, low harmonics	No longer supported	http://www.agilent.com/find/psg
83525BR	RF plug-in,0.01-8.4 GHz low harmonics	No longer supported	
83540A	RF plug-in for 8350A/B, 2.0-8.4 GHz	No longer supported	http://www.agilent.com/find/psg
83540AR	RF plug-in for 8350A/B, 2.0-8.4 GHz	No longer supported	
83540B	RF plug-in, 2.0-8.4 GHz, low harmonics	No longer supported	http://www.agilent.com/find/psg
83540BR	RF Plug-in, 2.0-8.4 GHz, low harmonics	No longer supported	83525B
83545A	RF plug-in for 8350A/B, 5.9-12.4 GHz	No longer supported	http://www.agilent.com/find/psg
83545AR	RF plug-in for 8350A/B, 5.9-12.4 GHz	No longer supported	
83550A	RF plug-in, 8.0-20.0 GHz, for 8350B	No longer supported	http://www.agilent.com/find/psg
83550AR	RF plug-in, 8.0-20.0 GHz for 8350B	No longer supported	
83555AR	mm-wave source module, 33.0 to 50. GHz	Currently supported	
83570A	RF plug-in for 8350A/B, 18.0-26.5 GHz	No longer supported	http://www.agilent.com/find/psg
83570AR	RF plug-in for 8350A/B, 18.0-26.5 GHz	No longer supported	
83572A	RF Plug-In, 26.5 40.0 GHz	No longer supported	
83572AR	RF Plug-IN, 26.5 40.0GHz	No longer supported	
83572B	RF Plug-In, 26.5 40.0 GHz, High Power	No longer supported	
83572C	RF plug-in for 8350A/B, 26.5-40.0 GHz	No longer supported	http://www.agilent.com/find/psg
83572CR	Remarketed RF Plug-In, 26.5 40.0 GHz	No longer supported	no replacement
83590AR	Remarketed RF Plug-In, 2.0 2.0 GHz	No longer supported	no replacement
83592AR	Remarketed RF Plug-In, 0.01 2.0 GHz	No longer supported	
83592BR	Rmkt RF plug-in, 0.01-20.0 GHz, +13 dBm	No longer supported	
83592CR	Rmkt RF plug-in, 0.01-20GHz, low harmncs	No longer supported	no replacement
83595AR	Remarketed RF Plug-In, 0.01 26.5 GHz	No longer supported	no replacement
83595CR	RF plug-in, 0-01 to 26.5 GHz, +13 dBm	No longer supported	
83596A	RF Plug-In 2.4 to 40 GHz for 8350A/B	No longer supported	http://www.agilent.com/find/psg
83597A	RF Plug-In 0.01 to 40 GHz for 8350A/B	No longer supported	http://www.agilent.com/find/psg
83597BR	RF plugin, 0.01-40GHz, for 8350B	No longer supported	
83599AR	RF plug-in, 0.01-50 GHz,for 8350B	No longer supported	
83622AR	Synthesized sweeper, 2 to 20 GHz	Currently supported	
83622BR	Synthesized sweeper, 2 to 20 GHz	Currently supported	
83624AR	2-20 GHz synthesized sweeper, high power	Currently supported	83624B
83624BR	2-20 GHz synthesized sweeper, high power	Currently supported	
83630AR	Synthesized sweeper, 10 MHz to 26.5 GHz	Currently supported	83630B
83631AR	Synthesized sweeper,45Mhz to 26.5GHz	Currently supported	
83642A	2 40 GHz Synthesized Sweeper	No longer supported	http://www.agilent.com/find/psg
83642AR	2-40 GHz Synthesized Sweeper	No longer supported	
83650AR	Synthesized sweeper, 10 MHz to 50 GHz	Currently supported	
83651AR	Synthesized sweeper, 45MHz to 50GHz	Currently supported	
83711A	Synthesized CW generator, 1 to 20 GHz	No longer supported	http://www.agilent.com/find/psg
83711AR	Synthesized CW generator, 1 to 20 GHz.	No longer supported	
83711U	Factory upgrade 83711A to 83711B	No longer supported	http://www.agilent.com/find/psg
83712A	Synthesized CW generator, 0.01 to 20 GHz	No longer supported	http://www.agilent.com/find/psg
83712U	Factory upgrade 83712A to 83712B	No longer supported	http://www.agilent.com/find/psg
83731A	Synthesized signal generator, 1-20 GHz	No longer supported	http://www.agilent.com/find/psg
83731AR	Synthesized signal generator, 1-20 GHz	No longer supported	
83731U	Factory upgrade 83731A to 83731B	No longer supported	http://www.agilent.com/find/psg
83732A	Synthesized signal generator, 0.01-20GHz	No longer supported	http://www.agilent.com/find/psg
83732AR	Synthesized signal generator,0.01-20GHz	No longer supported	
83732U	Factory upgrade 83732A to 83732B	No longer supported	http://www.agilent.com/find/psg
83810A	LOW COST LIGHTWAVE SIGNAL ANALYZER.	No longer supported	no replacement
83810B	Portable Lightwave Signal Analyzer	No longer supported	no replacement
84100A	EMC DESIGN SUPPORT SYSTEM	No longer supported	84100B

Product	Description	Support Status as of 1 May	Replacement Information
84100B	EMC Design Development System	No longer supported	84100EM
84110A	EMC PRE-PRODUCTION EVALUATION SYSTEM	No longer supported	84110B
84110B	EMC Pre-production evaluation system	No longer supported	
84110EM	EMC Pre-production eval. sys 9kHz-1.8GHz	Currently supported	84115EM
84110S	Customized EMC pre-production eval. sys.	Currently supported	no replacement
84120A	Pre-compliance EMI measurement system	No longer supported	8546A or 8542E
84125AR	Microwave EMI test system.	Currently supported	
84125BR	Microwave EMI test system	Currently supported	
84125CR	Microwave EMI test system.	Currently supported	
84125S	Custom EMI microwave system	Currently supported	no replacement
84130A	Commercial compliance EMI system	No longer supported	8546A or 8542E
84130S	Custom configured EMI measurement system	Currently supported	no replacement
84300S	Custom EM susceptibility system	No longer supported	no replacement
84801A	FIBER OPTIC SENS	No longer supported	no replacement
84811AR	Peak power sensor, 100 MHz to 18 GHz	No longer supported	
84812AR	Peak power sensor, 500 MHz to 18 GHz	Currently supported	
85010A	MEAS. PROGRAM	No longer supported	
85010B	EXTRA MANUAL	No longer supported	
85011A	Accuracy enhancement software for 8507S	No longer supported	
85012A	Time domain upgrade kit for the 8510A	No longer supported	E8362B
85012B	Time domain upgrade kit for the 8510B	No longer supported	E8362B
85013A	Basic Measurements Pac	No longer supported	
85014A	Active Device Measurements Pac	No longer supported	85014B
85015A	SYSTEM SOFTWARE	No longer supported	85015B
85015B	8756/8757 System Software	No longer supported	85016B
85016A	Transmission Line Test Software	No longer supported	85016B
85016B	Transmission line test software	No longer supported	
85019A	Time domain upgrade kit for 8753A	No longer supported	E5062A
85020A	RF directional bridge, 50 ohm, Type N	No longer supported	
85020B	RF directional bridge, 75 ohm, Type N	No longer supported	
85021A	MICROWAVE BRIDGE	No longer supported	
85021B	MICROWAVE BRIDGE	No longer supported	
85021C	MICROWAVE BRIDGE	No longer supported	
85023A	Verification kit, 50-ohm APC-7 connector	No longer supported	no replacement
85023B	Verification kit, 50-ohm APC-3.5 connect	No longer supported	no replacement
85023C	Verification kit, 50-ohm Type N connect	No longer supported	no replacement
85023D	Verification kit, 75-ohm Type N connect	No longer supported	no replacement
85023F	Verification kit, 50-ohm 2.4mm connector	No longer supported	no replacement
85024AR	High-frequency probe, 300 kHz to 3 GHz	Currently supported	
85025AR	Coaxial detector; AC/DC 10 MHz-18GHz	Currently supported	
85025BR	Coaxial detector; AC/DC, 10 MHz-26.5 GHz	Currently supported	
85025CR	Detection adapter	Currently supported	
85025ER	Better return-loss 0.01-26.5GHz detector	Currently supported	
85027CR	0.01-18 GHz directional bridge, Type N	Currently supported	
85027ER	0.01-26.5GHz directional bridge, 3.5 (m)	Currently supported	
85029A	7mm Verification Kit	No longer supported	
85030A	AIM-30 SOFTWARE	No longer supported	
85030B	8507B/9825A Applications Pack	No longer supported	
85030C	APPLICATIONS PAC	No longer supported	
85031A	APC-7 CAL/VER KI	No longer supported	
85031BR	7 MM Calibration Kit for the 8753	Currently supported	
85032A	TYPE-N CAL KIT	No longer supported	
85032BR	Remarketed 50 ohm Type-N Calibration Kit	Currently supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
85033A	SMA Calibration kit, 50 ohm	No longer supported	no replacement
85033B	APC-3.5 CAL KIT	No longer supported	85033D.
85033C	3.5mm calibration kit for 8752A, 8753	No longer supported	85033D
85034A	GR-900 CAL KIT	No longer supported	
85035A	CALIBRATION KIT	No longer supported	
85036A	TYPE N CAL KIT	No longer supported	
85040B	Test set	No longer supported	
85041A	Transistor test fixture kit	Currently supported	no replacement
85043A	System rack kit	No longer supported	
85043B	System Rack Cabinet for 8753A/B/C	No longer supported	
85044AR	50-ohm ransmission/reflection test set	No longer supported	
85044BR	75-ohm transmission/reflectin test set	No longer supported	
85050A	7MM calibration kit	No longer supported	
85051A	7MM verification kit	No longer supported	
85052A	3.5 calibration kit	No longer supported	
85052BR	Remarketed 3.5 mm calibration kit	No longer supported	
85052CR	3.5 mm precision calibration kit	Currently supported	
85052DR	Remarketed 3.5mm economy calibration kit	No longer supported	no replacement
85052E	3.5mm Economy Calibration Kit	No longer supported	
85053A	3.5 MM verification kit	No longer supported	
85053BR	3.5 mm verification kit	Currently supported	
85054A	Type N calibration kit	No longer supported	85054B.
85054BR	Type N calibration kit	Currently supported	
85057A	2.4 mm Verification Kit	No longer supported	
85062AR	Electronic calibration module, 3.5 mm	Currently supported	
85070A	Dielectric Probe Kit	No longer supported	85070B
85071A	Material Measurement Software	No longer supported	85071E
85075A	Extra Dielectric Probe	No longer supported	85075B
85075B	Extra high-temperature dielectric probe	No longer supported	8710-2036
85078A	85070/85071 A-to-B upgrade kits	No longer supported	
85079A	Material measurements update kit	No longer supported	85071E
85079B	Software update for 85070B/85071B	No longer supported	
85081A	High Impedance Input Module	No longer supported	
85081BR	High-impedance probe input module	Currently supported	
85082AR	50-ohm input module(Type N inputs)	Currently supported	
85089A	Grounding clip for high impedance probes	No longer supported	no replacement
85096A	RF ECal module,75ohm N,m-f,0.03 to 3 GHz	Currently supported	85096B
85098A	RF ECal module,7-16,m-f, 0.03 to 7.5 GHz	Currently supported	85098B
85099A	RF ECal module,type-F,m-f, 0.03 to 3 GHz	Currently supported	85099B
85100A	LO/IF interface kit	No longer supported	85105A
85100V	V-Band Millimeter-Wave Source Module	No longer supported	
85100W	W-Band Millimeter-Wave Source Module	No longer supported	
85103A	Performance upgd for 8510A w/ install	No longer supported	E8362B
85103B	Performance Upgrade Package	No longer supported	E8362B
85103C	Performance upgrade for 8510A to C	Currently supported	E8362B
85103D	Performance upgrade package (8510B to C)	Currently supported	E8362B
85105AR	Millimeter-wave controller.	Currently supported	
85106A	MM-Wave Network Analyzer Subsystem	No longer supported	E8361A
85106B	Millimeter-Wave Network Analyzer Subsys.	No longer supported	E8361A
85107A	Network Analyzer System	No longer supported	E8363B
85109A	60 GHz Network Analyzer System	No longer supported	E8361A
85109B	62.5GHz on-wafer vector network	No longer supported	E8361A
85109BR	62.5GHz on-wafer vector network	No longer supported	
85109CR	75GHz on-wafer vector analyzer system	No longer supported	
8510SXR	Network analyzer system, racked.	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
85111A	Pulsed-RF upgrade	No longer supported	E8362B
85127Q	RF/microwave measurement system	No longer supported	85127A,B,C
85129A	Millimeter-Wave Measurement Software	No longer supported	no replacement
85130A	Adapter Set	No longer supported	
85130BR	Special 3.5 mm to 7 mm adapter set	Currently supported	
85130GR	Special 2.4 MM to 2.4 MM adapter set	Currently supported	
85131A	Return cable	No longer supported	
85131B	return cable set	No longer supported	
85131FR	3.5 to 3.5 mm flex test port cable set	Currently supported	
85132A	Return cable	No longer supported	
85132B	Return cable set	No longer supported	
85132FR	7 to 3.5mm flexible test port cable set	Currently supported	
85142A	SMT Passive Library Bundle	Currently supported	
85142AN	SMT Passive Library Bundle NLS	Currently supported	
85142AS	Support SMT Passive Library Bundle	Currently supported	
85142NS	Support SMT Passive Library Bundle NLS	Currently supported	
85143A	Momentum Drawing Environment	No longer supported	
85143AN	Momentum Drawing Environment NLS	No longer supported	
85144A	Upgrade to MAG	Currently supported	
85144AN	Upgrade to MAG NLS	Currently supported	
85145A	Momentum Transition Package	Currently supported	
85146A	Momentum Visualization Software	Currently supported	
85146AN	Momentum Visualization Software NLS	Currently supported	
85147A	HEMT Library	No longer supported	85259A
85147AN	HEMT Library NLS	No longer supported	85259AN
85147AS	Support HEMT Library	No longer supported	85259AS
85147NS	Support HEMT Library NetLS	No longer supported	85259NS
85148A	Circuit Envelope Simulator	Currently supported	
85148AN	Circuit Envelope Simulator NLS	Currently supported	
85149A	High Yield Software Package	Currently supported	
85149AN	High Yield Software Package NLS	Currently supported	
85150A	Microwave Design System Software	No longer supported	
85150AR	Microwave Design Sys right-to-reproduce	No longer supported	
85150B	Microwave Design System	Currently supported	
85150BD	Microwave Design Sys Family Documentatn	Currently supported	
85150BR	HP 85150BR Right-to-Reproduce MDS	No longer supported	
85150BU	8515X/8517X Documentation Update	No longer supported	
85150E	MDS plus HP 9000 model 345C+ computer	No longer supported	
85150I	MDS Internal User Suite	Currently supported	
85150IS	Support for MDS Internal User Suite	Currently supported	
85150M	MDS Family Media	Currently supported	
85150MU	85150B Media Updates	No longer supported	
85150R	Return to Current Version of MDS	Currently supported	
85150S	Sys Reference for Microwave Design Sys.	Currently supported	
85150T	MDS plus HP 9000 model 375CH computer	No longer supported	
85150U	Agilent University Donation (MDS)	Currently supported	
85150UN	Agilent University Donation MDS, NLS	Currently supported	
85150UT	MDS University Support NLS	No longer supported	
85150X	Configured Computer for MDS/RFDS	No longer supported	no replacement
85151A	Linear Simulator	Currently supported	
85151AR	MLS right to reproduce	No longer supported	
85151N	Linear Simulator NLS	Currently supported	
85152A	Microwave Artwork Generator	Currently supported	
85152AR	MAG right-to-reproduce	No longer supported	
85152N	Microwave Artwork Generator NLS	Currently supported	
85153A	GDSII Streamfile Translator	Currently supported	
85153AN	GDSII Streamfile Translator (NLS)	Currently supported	
85153AR	GDSII Strm File Transltr Rght-to-Repro	No longer supported	

Product	Description	Support Status	Replacement Information
85153B	Gerber Translator	Currently supported	
85153BN	Gerber Translator (NLS)	Currently supported	
85153C	HP 85153C EEsof Netlist Translator	No longer supported	
85153CN	EEsof Netlist Translator NLS	No longer supported	
85153CS	85153C Software Support	No longer supported	
85153CT	85153CN Software Support	No longer supported	
85153D	IGES Translator	Currently supported	
85153DN	IGES Translator (NLS)	Currently supported	
85153E	SPICE Netlist Translator	Currently supported	
85153EN	SPICE Netlist Translator (NLS)	Currently supported	
85154A	Transient Simulator(Impulse)	Currently supported	
85154AN	Transient Simulator (Impulse) NLS	Currently supported	
85155A	Microwave Nonlinear Simulator	Currently supported	
85155AR	HP 85155AR R-R Microwave Nonlin.Sim	No longer supported	
85155N	Microwave Nonlinear Simulator NLS	Currently supported	
85156A	Simulator Interface	No longer supported	85256A
85156AS	Support Simulator Interface	No longer supported	85256AS
85156N	Simulator Interface NLS	No longer supported	85257AN
85156NS	Support Simulator Interface NLS	No longer supported	85257NS
85157A	High Frequency Design Capture System	No longer supported	85257A
85157AS	Support Hi-Freq DCS	No longer supported	85257AS
85157N	High Frequency Design Capture System NLS	No longer supported	85257AN
85157NS	Support Hi-Freq DCS NLS	No longer supported	85257NS
85158A	Momentum Simulation Engine	Currently supported	
85158AN	Momentum Simulation Engine NLS	Currently supported	
85159A	Parameter Extraction Service	Currently supported	
85160A	Measurement automation S/W for 8743	No longer supported	
85161A	Measurement Automation Software	No longer supported	
85162A	Measurement automation S/W for 8720	No longer supported	
85164A	Design Rule Checker	Currently supported	
85164AN	Design Rule Checker NLS	Currently supported	
85164AS	Support Design Rule Checker	Currently supported	
85164NS	NetLS Support Design Rule Checker	Currently supported	
85165A	85165A Resonator Measurement Software	No longer supported	no replacement
85166A	Computer Platform Change	Currently supported	
85167A	MDS IFF Schematic Translator	Currently supported	
85167AN	MDS IFF Schematic Translator NLS	Currently supported	
85168A	Mentor Integration Link	No longer supported	85187A
85168AN	Mentor Integration Link NLS	No longer supported	85187AN
85168AS	Support Mentor Graphics Integration	No longer supported	85187AS
85168NS	Support Mentor Graphics Integration	No longer supported	85187NS
85169A	Passive SMT Library	Currently supported	
85169AN	Passive SMT Library NLS	Currently supported	
85169NS	Upgrades and support for 85169AN	Currently supported	
85170A	System Model Library	Currently supported	
85170N	System Model Library NLS	Currently supported	
85171A	Nonlinear Chip FET Library	No longer supported	85259A
85171AS	Support Nonlinear Chip FET Library	No longer supported	85259AS
85171N	Nonlinear Chip FET Library NLS	No longer supported	85259AN
85171NS	Support Nonlinear Chip FET Library NLS	No longer supported	85259NS
85172A	Triquint Foundry Library	Currently supported	
85172N	Triquent Foundry Library NLS	Currently supported	
85173A	RF Packaged BJT Library	No longer supported	85258A
85173AN	RF Packaged BJT Library NLS	No longer supported	85258AN
85173AS	Support RF Packaged BJT Library	No longer supported	85258AS
85173NS	Support RF Packaged BJT Library NLS	No longer supported	85258NS
85174A	RF Passive SMT Library	Currently supported	
85174AN	RF Passive Library NLS	Currently supported	
85174AS	Support RF SMT Passive Library	Currently supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
85174NS	Support RF SMT Passive Library NLS	Currently supported	
85175A	RF SMT Murata Capacitor Library	Currently supported	
85175AN	RF SMT Murata Capacitor Library NLS	Currently supported	
85175AS	Support Murata SMT Capacitor Library	Currently supported	
85175NS	Support Murata SMT Capacitor Library NLS	Currently supported	
85176A	Analog Active Device Library	Currently supported	
85176AN	Analog Active Device Library NLS	Currently supported	
85176AS	Support Analog Active Device	Currently supported	
85176NS	Support Analog Active Device Library NLS	Currently supported	
85177A	Philips GaAs Foundry Library	Currently supported	
85177AN	Philips GaAs Foundry Library NLS	Currently supported	
85178A	Nonlinear Chip BJT Library	No longer supported	85259A
85178AN	Nonlinear Chip BJT Library NLS	No longer supported	85259AN
85178AS	Support Nonlinear Chip BJT Library	No longer supported	85259AS
85178NS	Support Nonlinear Chip BJT Library NLS	No longer supported	85259NS
85179A	Packaged FET Library	No longer supported	85258A
85179AN	Packaged FET Library NLS	No longer supported	85258AN
85179AS	Support Packaged FET Library	No longer supported	85258AS
85179NS	Support Packaged FET Library NLS	No longer supported	85258NS
85180A	High Frequency Structure Simulator	No longer supported	
85180AD	HFSS Family Documentation	Currently supported	
85180AN	High Freq. Structure Simulator NLS	No longer supported	
85180AS	Support High Freq Structure Simulator	No longer supported	
85180AU	85180A Documentation Update	No longer supported	
85180I	HFSS Internal User Suite	No longer supported	
85180IS	Support for HFSS Internal User Suite	No longer supported	
85180M	HFSS Family Media	No longer supported	
85180MU	85180A Media Updates	No longer supported	
85180NS	Support HFSS NLS	No longer supported	
85180R	Return to Current Version HFSS	Currently supported	
85180S	System Reference for HFSS	Currently supported	
85180U	Agilent University Donation (EM)	No longer supported	
85180UN	Agilent University Donation (EM) NLS	No longer supported	
85180US	HFSS University Support	No longer supported	
85180UT	HFSS University Donation Support NLS	No longer supported	
85180X	Configured Computer for HFSS	Currently supported	
85181A	HFSS Simulator Interface	No longer supported	
85182A	HFSS User Interface	No longer supported	
85182AN	HFSS User Interface NLS	No longer supported	
85182AS	Support HFSS User Interface	No longer supported	
85182NS	Support HFSS User Interface NLS	No longer supported	
85183A	HFSS EM Engine	No longer supported	
85183AN	HFSS EM Engine NLS	No longer supported	
85183AS	Support HFSS EM Engine	No longer supported	
85183NS	Support HFSS EM Engine NLS	No longer supported	
85184A	Planar Electromagnetic Simulator	Currently supported	
85184AD	Momentum Documentation	Currently supported	
85184AN	Planar Electromagnetic Simulator NLS	Currently supported	
85184M	Media for Momentum Standalone	No longer supported	85150M
85185A	HP HFSS 5.0 Competitive Trade-Up	No longer supported	
85185AN	HP HFSS 5.0 Competitive Trade-Up NLS	No longer supported	
85186A	HFSS/IC-CAP Platform Transfer	Currently supported	
85187A	MDS/Mentor IFF Schematic Translator	Currently supported	
85187AN	MDS/Mentor IFF Schematic Translator NLS	Currently supported	
85188A	MDS/Mentor IFF Layout Translator	Currently supported	
85188AN	MDS/Mentor IFF Layout Translator NLS	Currently supported	
85189A	Structure Modeling Service	No longer supported	
85190UT	Support HF IC-CAP University NLS	No longer supported	
85190X	System Computer Hardware	Currently supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
85192B	EEFET3 FET Model	Currently supported	
85192BN	EEFET3 FET Model NLS	Currently supported	
85192BS	Support EEFET3 FET Model	Currently supported	
85192BT	Support EEFET3 FET Model	Currently supported	
85192C	EEHEMT1 HEMT Model	Currently supported	85192B
85192CN	EEHEMT1 HEMT Model	Currently supported	85192BN
85192CS	Support EEHEMT1 HEMT Model	Currently supported	85192BS
85192CT	Support EEHEMT1 HEMT Model	Currently supported	85192BT
85192Z	IC-CAP FETs/HEMTs Model Package	Currently supported	
85192ZN	IC-CAP FETs/HEMTs Model Package NLS	Currently supported	
85193B	EEBJT2 BJT Model	Currently supported	
85193BN	EEBJT2 BJT Model NLS	Currently supported	
85193BS	Support EEBJT2 BJT Model	Currently supported	
85193BT	Support EEBJT2 BJT Model NLS	Currently supported	
85193Z	IC-CAP BJT Model Package	Currently supported	
85193ZN	IC-CAP BJT Model Package NLS	Currently supported	
85194A	High Frequency MOS Level3 Model	Currently supported	
85194AN	High Frequency MOS Level3 Model NLS	Currently supported	
85194C	EEMOS1 MOS Model	Currently supported	
85194CN	EEFMOS1 MOS Model NLS	Currently supported	
85194D	UCB BSIM 1,2 Model Extraction Module	Currently supported	Replaced by BSIM3/4 Model
85194DN	UCB BSIM 1,2 Model Ext. Module (NetLS)	Currently supported	Replaced by BSIM3/4 Model
85194F	a-Si TFT Model Extraction Module	Currently supported	
85194FN	a-Si TFT Model Ext. Module (NetLS)	Currently supported	
85194FS	Software Support (Phone and LTU Updates)	Currently supported	
85194FT	Software Support (Phone and LTU Updates)	Currently supported	
85194G	UCB p-Si TFT Model Extraction Module	Currently supported	
85194GN	UCB p-Si TFT Model Ext. Module (NetLS)	Currently supported	
85194GS	Software Support (Phone and LTU Updates)	Currently supported	
85194GT	Software Support (Phone and LTU Updates)	Currently supported	
85194Z	IC-CAP MOS Model Package	Currently supported	
85194ZN	IC-CAP MOS Model Package NLS	Currently supported	
85200A	Microwave Design System Suite (MDS)	Currently supported	
85200AN	Microwave Design System Suite (MDS) NLS	Currently supported	
85200S	Personal Microwave Workstation	No longer supported	
85201A	RF Design System Suite (RFDS)	Currently supported	
85201AN	RF Design System Suite (RFDS) NLS	Currently supported	
85201S	Personal Microwave Workstation	No longer supported	
85202A	RFIC Simulation Suite (MDS)	Currently supported	
85202AN	RFIC Simulation Suite (MDS) NLS	Currently supported	
85222A	RFIC Simulation Suite Pro (MDS)	Currently supported	
85222AN	RFIC Simulation Suite Pro (MDS) NLS	Currently supported	
85240A	Picosecond Interconnect Modeling Suite	Currently supported	
85240AD	Picosecond Interconnect Documentation	Currently supported	
85240AN	Picosecond Interconn Modeling Suite NLS	Currently supported	
85240AS	Support Picosecond Interconn Suite	Currently supported	
85240NS	Support Picosecond Interconn Suite NLS	Currently supported	
85241A	MDS SPICE Model Generator Node-locked	Currently supported	
85241AN	MDS SPICE Model Generator NLS Version	Currently supported	
85241AS	Support, MDS SPICE Model Gen. Node-lock	Currently supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
85241NS	Support, MDS SPICE Model Generator NLS	Currently supported	
85242A	Multilayer Interconnect Model Library	Currently supported	
85242AN	Multilayer Interconn Model Library NLS	Currently supported	
85242AS	Support Multilayer Interconn Library	Currently supported	
85242NS	Support Multilayer Interconn Library NLS	Currently supported	
85243A	I/O Buffer Model Library	Currently supported	
85243AN	I/O Buffer Model Library NLS	Currently supported	
85243AS	Support I/O Buffer Model Library	Currently supported	
85243NS	Support I/O Buffer Model Library NLS	Currently supported	
85244A	Multipin Connector/Cable Library	No longer supported	
85244AN	Multipinn Connector/Cable Library NLS	No longer supported	
85244AS	Support Multipin Connector/Cable Library	No longer supported	
85244NS	Support Multipin Connector/Cable Lib.NLS	No longer supported	
85250A	HP RF Design System	No longer supported	
85250AD	RF Design System Documentation	No longer supported	85150BD
85251A	RF Linear Simulator	No longer supported	85151A
85251AN	RF Linear Simulator NLS	No longer supported	85151AN
85251AS	Support RF Linear Simulator	No longer supported	85151AS
85251NS	Support RF Linear Simulator NLS	No longer supported	85151NS
85253A	MDS IFF Layout Translator	Currently supported	
85253AN	MDS IFF Layout Translator NLS	Currently supported	
85253AS	Support MDS IFF Layout Translator	Currently supported	
85253NS	Support MDS IFF Layout Translator NLS	Currently supported	
85254A	RF Transient Simulator(HP Impulse)	No longer supported	85154A
85254AN	RF Transient Simulator(HP Impulse) NLS	No longer supported	85154AN
85254AS	Support RF Impulse Simulator	No longer supported	85154AS
85254NS	Support RF Impulse Simulator NLS	No longer supported	85154NS
85255A	RF Nonlinear Simulator	No longer supported	85155A
85255AN	RF Nonlinear Simulator NLS	No longer supported	85155AN
85255AS	Support RF Nonlinear Simulator	No longer supported	85155AS
85255NS	Support RF Nonlinear Simulator NLS	No longer supported	85155NS
85256A	Data Display	Currently supported	
85256AN	Data Display NLS	Currently supported	
85257A	HF Design Capture System	Currently supported	
85257AN	HF Design Capture System NLS	Currently supported	
85258A	RF Transistor Library	Currently supported	
85258AN	RF Transistor Library NLS	Currently supported	
85258AS	Support RF Transistor Library	Currently supported	
85258NS	Support RF Transistor Library NLS	Currently supported	
85259A	Microwave Transistor Library	Currently supported	
85259AN	Microwave Transistor Library NLS	Currently supported	
85259AS	Support Microwave Transistor Library	Currently supported	
85259NS	Support Microwave Transistor Library NLS	Currently supported	
85260A	Diode Library	Currently supported	
85260AN	Diode Library NLS	Currently supported	
85260AS	Support Diode Library	Currently supported	
85260NS	Support Diode Library NLS	Currently supported	
85290A	Active Physical Device Suite	Currently supported	
85290AN	Active Physical Device Suite NLS	Currently supported	
85290AS	Support APDS Suite	Currently supported	
85290AT	Support APDS Suite NLS	No longer supported	85290NS
85290M	APDS Family Media	No longer supported	85150M
85290NS	Support APDS Suite NLS	Currently supported	
85291A	Leeds Physical Model (LPM)	Currently supported	
85291AN	Leeds Physical Model (LPM) NLS	Currently supported	
85291AS	Support Leeds Physical Model	Currently supported	
85291AT	Support Leeds Physical Model NLS	No longer supported	85291NS
85291B	APDS User Interface (UI)	No longer supported	
85291BN	APDS User Interface NLS	Currently supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
85291BS	Support APDS User Interface	Currently supported	
85291BT	Support APDS User Interface NLS	Currently supported	
85291NS	Support Leeds Physical Model NLS	Currently supported	
85297A	HFDS Test Product.	No longer supported	no replacement
85298A	HFDS Test Product	No longer supported	no replacement
85301A	Antenna measurement system	Currently supported	E8362B
85320AR	Test mixer module	Currently supported	
85330AR	Multiple channel controller	Currently supported	
85331AR	SP2T absorptive PIN switch,0.045-40 GHz	Currently supported	
85332AR	SP4T absorptive PIN switch,0.045-40 GHz	Currently supported	
85360A	Antenna measurement software	No longer supported	85360A K10 (Dom) 85360A K
85361A	Antenna Measurement Software	No longer supported	
85370AR	Antenna position encoder	Currently supported	
85380A	Weatherproof enclosure	No longer supported	no replacement
85381A	Flexible microwave cable,0.5MHz to 18GHz	Currently supported	
85381B	Flexible Microwave Cable	No longer supported	
85381C	Flexible microwave cable,DC to 26.5 GHz	Currently supported	
85381D	Flexible microwave cable, DC to 50 GHz	Currently supported	
85382A	Utility cable, dc to 100 MHz	Currently supported	
85395A	Upgrade 8510A to 8530A w/ Option 011	No longer supported	E8362B
85395B	Upgrade 8510B to 8530A w/ Option 011	Currently supported	E8362B
85396A	Add 8510C firmware to 8530A	Currently supported	E8362B
85420E	RF filter section, 9 kHz to 2.9 GHz	Currently supported	no replacement
85420ER	RF filter section, 9kHz to 2.9 GHz	Currently supported	
85422ER	Receiver RF section, 9kHz to 2.9 GHz	Currently supported	
85426A	BIAS TEE	No longer supported	
85428B	MINIMUM LOSS PAD	No longer supported	
85460A	RF filter section, 9 kHz to 6.5 GHz	Currently supported	no replacement
85460AR	RF filter section,9kHz to 6.5GHz.	Currently supported	
85462AR	Receiver RF section,9kHz to 6.5GHz.	Currently supported	
85629A	TEST & ADJUSTMENT MODULE	No longer supported	85629B
85630AR	Rmkt 50-ohm scalar trans/reflection test	No longer supported	no replacement
85644A	300 kHz to 6.5 GHz tracking source	No longer supported	
85645A	300 kHz to 26.5 GHz tracking source	No longer supported	
85645AR	300 kHz to 26.5 GHz tracking source	No longer supported	
85650A	Quasi peak adapter	No longer supported	no replacement
85660A	RF Section	No longer supported	
85660B	RF SECTION	No longer supported	
85662A	DISPLAY SECTION	No longer supported	
85662AR	Rmkt spectrum analyzer display section	No longer supported	
85670A	8567A spectrum analyzer RF section	No longer supported	no replacement
85680A	RF SECTION	No longer supported	
85680B	RF SECTION	No longer supported	
85685AR	Remarketed RF preselector	No longer supported	
85711A	CATV measurement personality (USA)	No longer supported	85721A CATV meas personal
85711B	U.S. CATV measurement personality	No longer supported	85721A CATV meas personal
85712A	EMC Measurements Personality.	No longer supported	85712B
85712B	EMC MEASUREMENT PERSONALITY	No longer supported	85712D
85712BC	Upgrade 85712B EMC DLP to 85712C	No longer supported	
85712C	EMC AUTO-MEASUREMENT PERSONALITY.	No longer supported	85712D
85712CD	Upgrade existing 85712C to the 85712D	No longer supported	
85715A	GSM Personality for 8591A/93A/94A/95A	No longer supported	85715B
85716A	CATV system monitoring personality	No longer supported	85721A CATV meas personal
85717AU	CT2-CAI test personality upgrade kit	No longer supported	
85718A	NADC-TDMA measurement personality	No longer supported	
85718BU	NADC-TDMA test personality upgrade kit	No longer supported	
85719AR	Noise figure measurement personality	Currently supported	

Product	Description	Support Status	Replacement Information
85720A	JDC-TDMA measurement personality	No longer supported	
85720B	PDC measurement personality	No longer supported	85720C
85720BC	PDC test prsnalty upgrade kit: A-B to C	No longer supported	
85722A	DCS1800 Personality for 8590A/E	No longer supported	85722B
85725A	CDMA measurement personality	No longer supported	B version
85725AB	CDMA test personality upgrade kit:A to B	No longer supported	85725CU
85725B	CDMA test personality for 8590 E-Series	No longer supported	85725C
85725CU	CDMA test personality upgrade kit:B to C	No longer supported	
85726A	PHS measurement personality	No longer supported	85726B
85726AB	PHS test personality upgrade kit: A to B	No longer supported	
85727AU	GSM Multi-band upgrade from single band	No longer supported	
85860A	SOFTWARE PAC	No longer supported	85862A,3A
85860B	SOFTWARE PAC	No longer supported	85862A,3A
85861A	SOFTWARE PAC	No longer supported	85862A, 3A
85861B	SOFTWARE PAC	No longer supported	85862A, 3A
85862A	HPL software PAC	No longer supported	85863B
85863A	SOFTWARE LIBRARY	No longer supported	85863B
85863B	Software library for 8566B,68B,67A	No longer supported	
85864A	EMI SOFTWARE	No longer supported	
85864B	EMI SOFTWARE	No longer supported	
85864C	EMI MEASUREMENT SOFTWARE	No longer supported	85869A
85865A	SOFTWARE	No longer supported	
85865B	SIGNAL MONITORING SOFTWARE	No longer supported	
85867A	EMI receiver downloadable programs	No longer supported	no replacement
85870A	OPEN-SITE EMI MEASUREMENT SOFTWARE	No longer supported	85879A
85874A	COMBINED EMI SOFTWARE	No longer supported	85874B
85874B	EMI measurement software pack	No longer supported	no replacement
85879A	Radiated emissions measurement software	No longer supported	85876A
85900A	System rack for EMI measurement solution	No longer supported	
85901AR	Portable AC power source	Currently supported	
85902AR	Burst carrier trigger accessory	Currently supported	
85916A	PC interface & report generator software	No longer supported	85921A FCC rpt generator
85942A	Video Signal Monitor	No longer supported	no replacement
85950AR	CaLan 1776 integrated sweep receiver	Currently supported	
85951AR	CaLan 1777 sweep transmitter	Currently supported	
86037A	Chromatic dispersion test system	Currently supported	no replacement
86037B	Chromatic Dispersion Test System	Currently supported	no replacement
86037B-K39	Upgrade kit to an 86037A	No longer supported	no replacement
86037C-K10	Adds spare 83427A test set w/86037B	No longer supported	no replacement
86060A	Lightwave Switch, 1 x 4	No longer supported	no replacement
86060AR	Lightwave switch, 1 x 4	No longer supported	
86060B	Compact lightwave switch	No longer supported	no replacement
86061A	Lightwave Switch, 1x8	No longer supported	no replacement
86061AR	Lightwave switch,1x8	No longer supported	
86062A	Lightwave Switch, 1x25	No longer supported	no replacement
86062B	Full size lightwave switch	No longer supported	no replacement
86063A	Lightwave Switch, 1x50	No longer supported	no replacement
86064A	Lightwave Switch, 1x100	No longer supported	no replacement
86100A	Infinium DCA Oscilloscope Mainframe	Currently supported	
86100A-K10	Retrofit to improve Jitter to 1.0 ps	No longer supported	
86101A-K21	Retrofit FC & double FC into an 86101A	No longer supported	
86101A-K44	Retrofit Gigabit Ethernet and OC-48	No longer supported	
86105A-K02	Kit to install filters into std. 86105A	No longer supported	
86106A	10 Gb/s optic & 40 GHz elec plug-in	Currently supported	86106B
86120A	Multi-wavelength meter 700 nm to 1650 nm	No longer supported	86120B
86120AR	Multi-wavelength meter 700nm to 1650nm	No longer supported	
86120B-K01	Retrofit to provide wide line width opt.	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
86120B-K10	Retrofit to increase input sensitivity	No longer supported	no replacement
86120B-UK5	Carrying case	No longer supported	86120B, Option UK5
86120B-UK7	Hard carrying case	No longer supported	86120B, Option UK7
86125A	86125A thickness gauge	Currently supported	no replacement
86142A	Optical Spectrum Analyzer-benchtop unit	Currently supported	86142B OSA
86143A	Optical Spectrum Analyzer-portable unit	Currently supported	86143B OSA
86143B-040	Soft carrying case	No longer supported	86143B option 040
86145B-040	Replacement Lid for Portable OSA	No longer supported	86145B option 040
86145A	Optical Spectrum Analyzer-portable unit	Currently supported	86145B OSA
86200A	10 MHz to 1.3 GHz 50-ohm RF detector	No longer supported	86200B
86201A	10 MHz to 1.3 GHz 75-ohm RF detector	No longer supported	86201B
86210A	RF PLUG-IN (8620)	No longer supported	
86212A	50-ohm TNC accessory kit	No longer supported	no replacement
86214A	Spare parts kit, 50 ohm 8711A	Currently supported	E5061A
86214B	Spare parts kit, 75 ohm 8711A	Currently supported	E5061A
86215A	Spare parts kit, 50 ohm 8711/12B	Currently supported	E5061A
86215B	Spare parts kit, 75 ohm 8711/12B	Currently supported	E5061A
86215C	Spare parts kit, 50 ohm 8711/12C	Currently supported	E5061A
86215D	Spare parts kit, 75 ohm 8711/12C	Currently supported	E5061A
86216A	Spare parts kit, 50 ohm 8713/14B	Currently supported	E5061A
86216B	Spare parts kit, 75 ohm 8713/14B	Currently supported	E5061A
86216C	Spare parts kit, 50 ohm 8713/14C	Currently supported	E5061A
86216D	Spare parts kit, 75 ohm 8713/14C	Currently supported	E5061A
86217A	50 ohm type N cable, male-male	No longer supported	
86217B	50 ohm type N cable, male-female	Currently supported	
86218A	75 ohm type N cable, male-male	Currently supported	
86218B	75 ohm type N cable, male-female	Currently supported	
86220A	RF PLUG-IN	No longer supported	no replacement
86222A	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86222B	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86223A	Add step attenuator	No longer supported	no replacement
86224A	Add Instrument BASIC	No longer supported	no replacement
86224B	Adds IBASIC programming to 871xB	Currently supported	
86226A	Adds latest rev. firmware to 8711A	Currently supported	E5061A
86226B	Adds latest rev. firmware to 871xB	Currently supported	E5061A
86226T	Retrofits latest FW revision to 8730A	Currently supported	
86228A	Fault location, Structural Return loss	No longer supported	86228B
86228B	Fault location, Structural Return Loss	Currently supported	E5061A
86230A	RF PLUG-IN	No longer supported	
86230B	RF PLUG-IN	No longer supported	86235A
86235A	R-F plug-in	No longer supported	http://www.agilent.com/find/psg
86240A	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86240B	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86240C	Upconverter plug-in	No longer supported	http://www.agilent.com/find/psg
86241A	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86242A	RF PLUG-IN	No longer supported	
86242C	RF PLUG-IN	No longer supported	
86242D	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86245A	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86250A	RF PLUG-IN	No longer supported	
86250B	RF PLUG-IN	No longer supported	
86250C	RF PLUG-IN	No longer supported	
86250D	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86251A	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86260A	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86260B	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86260C	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86290A	RF PLUG-IN	No longer supported	86290B
86290B	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86290C	RF plug-in	No longer supported	http://www.agilent.com/find/psg
86320A	RF MODULE	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
86320B	RF MODULE	No longer supported	
86330A	RF MODULE	No longer supported	
86330C	RF MOD; 1.8-4.2	No longer supported	
86331A	RF MODULE	No longer supported	
86331B	RF MODULE	No longer supported	
86331C	RF MOD; 1.7-4.3	No longer supported	
86334A	MODULATION SECTI	No longer supported	no replacement
86341B	RF MODULE	No longer supported	
86341C	RF MOD; 3.2-6.5	No longer supported	
86342A	RF MODULE	No longer supported	
86342C	RF MOD; 5.9-9.0	No longer supported	
86349A	System design service	No longer supported	86020A
86350A	RF MODULE	No longer supported	
86350C	RF MOD; 8.0-12.4	No longer supported	
86351A	RF MODULE	No longer supported	
86352A	RF MODULE	No longer supported	
86370A	Mixer measurement software for 8753MX	No longer supported	
86380A	Time domain upgrade kit	No longer supported	no replacement
86381A	1-Hz source resolution upgrade kit	No longer supported	no replacement
86382A	20-GHz performance upgrade for 8719A	No longer supported	N5230A
86382B	20-GHz performance upgrade for 8719C	No longer supported	N5230A
86383A	8757E to 8757D upgrade kit	No longer supported	no replacement
86383B	8757C to 8757D upgrade kit	No longer supported	8757D
86384A	Solid-state switch upgrade for 8719C	No longer supported	N5230A
86384B	Solid-state switch upgrade for 8720C	No longer supported	N5230A
86384C	Solid state switch retrofit for 8722C	No longer supported	N5230A
86386A	CPU performance upgrade for 8719A	No longer supported	N5230A
86386B	CPU performance upgrade for 8720B	No longer supported	N5230A
86387A	Mixer measurement upgrade for 8753B	No longer supported	8753ES
86388A	Revision 3.0 firmware update for 8753B	No longer supported	E5062A
86601A	RF section .01 to 110 MHz for 8660A/C	No longer supported	http://www.agilent.com/find/esg
86602A	RF PLUG-IN SECTI	No longer supported	no replacement
86602B	RF plug-in; 1 to 1300 MHz for 8660A/C	No longer supported	http://www.agilent.com/find/esg
86603A	RF plug-in; 1 to 2600 MHz	No longer supported	http://www.agilent.com/find/esg
86607A	8660 field upgrade kit.	No longer supported	http://www.agilent.com/find/esg
86631B	Aux. section for ext. pulse modulation	No longer supported	http://www.agilent.com/find/esg
86632A	MODULATION SECTI	No longer supported	no replacement
86632B	AM/FM modulation section for 8660A/C	No longer supported	http://www.agilent.com/find/esg
86633A	AM/FM MOD SECTIO	No longer supported	no replacement
86633B	AM/FM modulation section for 8660A/C	No longer supported	http://www.agilent.com/find/esg
86634A	Phase modulation section	No longer supported	http://www.agilent.com/find/esg
86635A	FM-PM modulation section for 8660A/C	No longer supported	http://www.agilent.com/find/esg
86720A	Frequency Extension Unit	No longer supported	http://www.agilent.com/find/psg
87030AR	Tuner test set	Currently supported	
8719DXR	Network analyzer, 50 MHz to 13.5 GHz	Currently supported	
8722DXR	Network analyzer, 50MHz to 40GHz	No longer supported	
87300BR	Coupler, Coaxial, 1-20 GHz	Currently supported	
87300CR	Coupler, Coaxial 1-26.5 GHz	Currently supported	
87300DR	Coupler, coaxial, 6 to 26.5 GHz.	Currently supported	
87301BR	Coupler,directional, 10 to 46 GHz	Currently supported	
87301CR	Coupler, directional, 10 to 50 GHz	Currently supported	
87301DR	Coupler, Coaxial, 1-40 GHz	Currently supported	
87301ER	Directional Coupler, 2-50 GHz	Currently supported	
87302CR	Power divider, 5-26.5 GHz	Currently supported	
87310BR	Coupler, Coaxial, 1-18 GHz	Currently supported	
87406BR	Switch,matrix,coax,dc-20 GHz,terminated	Currently supported	
87415AR	2-8 GHz Remote System Amplifier	Currently supported	
87421AR	Rmkt. Power Supply, +/-12V DC; 25 W Max	Currently supported	
87441J	Fibre channel 133 Mb low pass filter	Currently supported	
87441K	Fibre channel 266 Mb low pass filter	Currently supported	

Product	Description	Support Status	Replacement Information
87441L	Fibre channel 531 Mb low pass filter	Currently supported	
87490A	SDH Eye Diagram Mask Software	No longer supported	83480 Family
87510A	Gain-Phase Analyzer	No longer supported	E5100A
87510U	Upgrade Kit for 87510A	No longer supported	no replacement
87511U	Upgrade kit for 87511A/B	No longer supported	no replacement
87600A	High frequency integration services	No longer supported	
87600Q	High frequency integration services	No longer supported	
8920ART	Retrofit Kits for 8920A	No longer supported	no replacement
8920DRT	Retrofit Kits for 8920D	Currently supported	no replacement
8920DTS	Subscriber Unit Production Test System	Currently supported	no replacement
8924CRT	Retrofit Kits for 8924C	No longer supported	no replacement
8924ERT	Retrofit Kits for 8924E	No longer supported	E5515C
89400A	Dummy Support Number. Non-orderable.	No longer supported	
89430A	Convert HP 89410A into HP 89440A	No longer supported	89431A
89440A	1.8 GHz Vector Signal Analyzer	No longer supported	89441A
89440U	HP 89440A Vect. Sig.Anlzn. Opt.Ugr.Kits	No longer supported	
89605A	RF Input Module	Currently supported	
89606A	Baseband Input Module	Currently supported	
91002A	IDVM SUBSYSTEM	No longer supported	No replacement
91077A	DVM/CNTR/TIMR/SW	No longer supported	no replacement
91118A	12 CHAN ICI/CP	No longer supported	No replacement
91119A	12 CHAN ICI/IP	No longer supported	No replacement
91120A	12 CHAN ISO TTL	No longer supported	No replacement
91121A	12 CHAN EVENT SE	No longer supported	No replacement
91122A	12 CHAN EVENT SE	No longer supported	No replacement
91123A	12 CH RELAY OUT	No longer supported	No replacement
91124A	12 CH RELAY OUT	No longer supported	No replacement
91125A	12 CH TTL OUTPUT	No longer supported	No replacement
91126A	D/A CUR CONV	No longer supported	No replacement
91127A	D/A VOLTAGE CONV	No longer supported	No replacement
91200A	VIDEO DISPLAY	No longer supported	No replacement
91214A	REMOTE ACCESS	No longer supported	No replacement
91421B	General Purpose Connector Block	Currently supported	no replacement
91423A	Coaxial Connector Block	Currently supported	no replacement
91426A	Power Connector Block	Currently supported	no replacement
91430A	Coax Terminal Cable Kit (ICA)	Currently supported	no replacement
91431A	Power Terminal Cable Kit (ICA)	Currently supported	no replacement
91432A	Coax Contact (ITA)	Currently supported	no replacement
91433A	Coax Contact (ICA)	Currently supported	no replacement
91434A	Coax/BNC (ICA), 25 cm (10") long	Currently supported	no replacement
91435A	Coax/BNC (ICA), 76 cm (30") long	Currently supported	no replacement
91436A	Coax/SMB (ICA), 25 cm (10") long	Currently supported	no replacement
91437A	Coax/SMB (ICA), 76 cm (30") long	Currently supported	no replacement
91438A	Coax Crimp Tool Kit	Currently supported	no replacement
91439A	Terminal Extraction Tool Kit	Currently supported	no replacement
91451A	General Purpose Connector Block (ITA)	Currently supported	no replacement
91453A	Coaxial Connector Block (ITA)	Currently supported	no replacement
91455A	Blank Connector Block	Currently supported	no replacement
91456A	Power Connector Block (ITA)	Currently supported	no replacement
91460A	Coax Terminal Cable Kit (ITA)	Currently supported	no replacement
91461A	Power Terminal Cable Kit (ITA)	Currently supported	no replacement
91462A	Power Contact (ITA)	Currently supported	no replacement
91463A	Power Contact (ICA)	Currently supported	no replacement
91474A	D20 ICA Connector Block Support	Currently supported	no replacement
91475A	Signal Connector Block (ICA) 150 pin	Currently supported	no replacement
91476A	Signal Connector Block (ITA) 150 pin	Currently supported	no replacement
91477A	Signal/Power Connector Block (ICA)	Currently supported	no replacement
91478A	Signal/Power Connector Block (ITA)	Currently supported	no replacement
91480A	2 Position Housing for Receptacle	Currently supported	no replacement
91481A	3 Position Housing for Receptacle	Currently supported	no replacement
91482A	8 Position Housing for Receptacle	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
91483A	16 Position Housing for Receptacle	Currently supported	no replacement
91484A	96 Position Housing for Receptacle	Currently supported	no replacement
91485A	96 Position Strain Release and Cable	Currently supported	no replacement
91486A	2 meter (72") Cable with Snap-in Contact	Currently supported	no replacement
91487A	Snap-In Contact (100 each)	Currently supported	no replacement
91488A	Crimp Tool Kit, General Purpose	Currently supported	no replacement
91494A	Signal Contacts (ICA) for HP 91475A	Currently supported	no replacement
91495A	Signal Contacts (ITA) for HP 91476A	Currently supported	no replacement
91496A	Power Contacts (ICA) for HP 91477A	Currently supported	no replacement
91497A	Power Contacts (ITA) for HP 91478A	Currently supported	no replacement
91498A	Signal and Power Pin Extraction Tool Kit	Currently supported	no replacement
91499A	Signal Contact Crimp Tool Kit	Currently supported	no replacement
91701A	DISTRIBUTED SYSK	No longer supported	No replacement
91701B	DIST SYS KIT	No longer supported	No replacement
91870A	SERVICE KIT	No longer supported	no replacement
91871A	SERVICE KIT	No longer supported	no replacement
91901A	EXTRA SET MNLS	No longer supported	no replacement
92220R	GP-IB right angle cable, 0.2 meter	No longer supported	no replacement
92427A	ATS/1000 (RTE-IVB)	No longer supported	
92572R	Right-to-Copy HP Real-Time Database	No longer supported	
92576R	HP Interactive Visual Interface	No longer supported	
92580R	HP Device Interface System.	No longer supported	
92801A	(RTE-C) LISTINGS	No longer supported	No replacement
92802A	(RTE-II) LISTING	No longer supported	No replacement
92851A	HP1000 HRDWR HIS	No longer supported	
93000A	CIM System Reference number	No longer supported	
93256A	POWER DISTRIBUTION	No longer supported	
93280A	ATS System.	No longer supported	no replacement
93285C	ASD Engr and Customization for VSS	No longer supported	
93285D	ASD Engineering Services for DVT	No longer supported	
93294ND	Laser Jet III Si with paper/toner alarm	No longer supported	no replacement
93294S	Removable Disk Drive Chassis-2 SCSI 664m	No longer supported	
93294T	Removable Disk Drive Dual Slot SCSI CHAS	No longer supported	
93294U	Removable Disk Pack 664MB SCSI	No longer supported	
93294V	Removable Disk Pack SCSI 332MB	No longer supported	
93294W	Removable Disk Drive Dual Slot HPIB Chas	No longer supported	no replacement
93294X	Removable Disk Pack HPIB 670MB HPIB	No longer supported	no replacement
93294Y	Removable Disk Pack HPIB 335MB	No longer supported	no replacement
93302L	Datakit Fiber.	No longer supported	
93573S	ATS/2000 (RTE-6)	No longer supported	no replacement
94160A	POWER SUPPLY PRO	No longer supported	no replacement
94161A	DUAL SUPPLY	No longer supported	no replacement
94162A	HI CURRENT SUPPL	No longer supported	no replacement
94171A	64 Chnl Input Card for ATS 2000 DTU	No longer supported	
94181A	HP-PB Real Time Interface card	No longer supported	
94182A	HP-PB RTI Developer's kit and manual	No longer supported	
94185A	2 channel HP-PB SBX card	No longer supported	
94401A	TECAP Software (AC Only)	No longer supported	
94410A	TECAP TRAINING MANUAL	No longer supported	
94420A	TECAP GaAs Model	No longer supported	
94421A	TECAP BSIM Model	No longer supported	
94430A	DC/CV MEASUREMENT SOFTWARE	No longer supported	
94430R	License To Reproduce 94430A	No longer supported	
94431A	Device Modeling and Analysis Software	No longer supported	
94431R	License To Reproduce 94431A	No longer supported	
94432A	AC Measurement Drivers	No longer supported	
94432R	License To Reproduce 94432A	No longer supported	
94445A	TECAP Software	No longer supported	

Product	Description	Support Status	Replacement Information
94450A	Curtice GaAs Model / Extraction Routines	No longer supported	
94450R	License To Reproduce 94450A	No longer supported	
94451A	BSIM Model and Extraction Routines	No longer supported	
94451R	License To Reproduce 94451A	No longer supported	
94452R	License To Reproduce 94452A	No longer supported	
94453A	UCB Bipolar Model/Extraction Routines	No longer supported	
94453R	License To Reproduce 94453A	No longer supported	
94454A	UCB/Raytheon GaAs Model/Extraction SW	No longer supported	
94454R	License To Reproduce 94454A	No longer supported	
98297A	Realtime Interface card	No longer supported	no replacement
98298A	Development Software for HP-9000 Series.	No longer supported	no replacement
98298L	RTC RTI Development Software.	No longer supported	
98353M	HP-FE Finite Element Analysis Software	No longer supported	no replacement
98355DM	RTR DESIGN VEU	No longer supported	no replacement
98355M	HP-DESIGN	No longer supported	no replacement
98356DM	GERMAN HP DESIGN LINK	No longer supported	no replacement
98356FR	HP-DESIGNLINK	No longer supported	no replacement
98356HM	DUTCH DESIGN-LNK	No longer supported	no replacement
98356M	RTR DESIGNLINK	No longer supported	no replacement
98360DM	GERMAN HP-DRAFT	No longer supported	no replacement
98360HM	DUTCH HP DRAFT	No longer supported	no replacement
98360M	EXTENDED RIGHT TO USE HP-DRAFT	No longer supported	no replacement
98360SM	SWEDISH HP-DRAFT	No longer supported	no replacement
98462A	STORAGE MODULE	No longer supported	no replacement
98464DM	RTR HP-NC	No longer supported	no replacement
98464FM	COPYRIGHT98464FA	No longer supported	no replacement
98464HM	HP-NC	No longer supported	no replacement
98464M	Right-to-Reproduce HP-NC	No longer supported	no replacement
98613B	BASIC 4.0 software.	No longer supported	no replacement
98613R	Right to reproduce BASIC.	No longer supported	no replacement
98616A	BASIC/WS 5.13 language system.	No longer supported	no replacement
98616B	BASIC/WS Media/Documentation	Currently supported	no replacement
98616BJ	BASIC/WS Media/Documentation	Currently supported	no replacement
98616D	BASIC/WS DOS File System	Currently supported	no replacement
98616K	BASIC/WS Language System Docum. Only	Currently supported	no replacement
98616KJ	BASIC/WS Language System Japan Docum.	Currently supported	no replacement
98616L	BASIC/WS L-T-U	Currently supported	no replacement
98616LJ	BASIC/WS license	Currently supported	no replacement
98616M	Right to reproduce BASIC 5.13.	No longer supported	no replacement
98616R	Right to reproduce BASIC 5.13.	No longer supported	no replacement
98616S	BASIC/WS CSUB Utilities	Currently supported	no replacement
98616SJ	BASIC/WS CSUBs	Currently supported	no replacement
98616Y	HP BASIC Y2K Revision for Workstation	Currently supported	
98618A	BASIC 5.0 compiler for S200 and S300.	No longer supported	no replacement
98618B	BASIC/WS Compiler	Currently supported	no replacement
98618BJ	BASIC/WS compiler	No longer supported	no replacement
98633A	6944A INTERFACE	No longer supported	no replacement
98642AR	4-Channel Asynch I/F	Currently supported	
98796A	Media and manuals for the 98796L.	No longer supported	no replacement
98796K	Manual kit for 98796L HP BASIC/UX.	No longer supported	no replacement
98796L	License to use HP BASIC/UX software.	No longer supported	no replacement
98869A	Media and manuals for 98869L BASIC/UX.	No longer supported	no replacement
98869L	License to use HP BASIC/UX sftwr bundle.	No longer supported	no replacement
A1303A	R/332 Controller	No longer supported	no replacement
A1305A	R/332 Controller	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
		as of 1 May	
A1307A	R/332 Controller	No longer supported	no replacement
A1308A	Series R Custom Engineering Kit	Currently supported	no replacement
A1309A	Series R Rack Mount Flange Kit	Currently supported	no replacement
A1314A	Obsolete 8/94 Order A1314B	No longer supported	A1314B
A1314AR	R362 Controller with BASIC	No longer supported	
A1314B	R/362 Integrated Controller	No longer supported	no replacement
A1314BR	R/362 Integrated Controller	No longer supported	
A1319A	Obsolete 8/94 Order A1319B	No longer supported	no replacement
A1319AR	R/382 Integrated Controller	No longer supported	
A1319B	R/382 Integrated Controller	No longer supported	no replacement
A1319BR	R/382 Integrated Controller	No longer supported	
A1324A	R/382U Integrated Controller	No longer supported	no replacement
A1324AR	R/382U Integrated Controller	No longer supported	
A1324B	R/382U Integrated Controller	No longer supported	no replacement
A1324BR	R/382U Integrated Controller	No longer supported	
A2247AR	2 Slot DIO II expander	Currently supported	
ACJ2124X	Pistonphone Calibrator	No longer supported	no replacement
ALO-60001	EISA Bus preprocessor-1650,510	No longer supported	
ALO-60002	EISA bus analysis probe	No longer supported	
ALO-60003	MicroChannel Bus preprocessor-1650,510	No longer supported	
ALO-60004	MicroChannel Bus preprocessor-1660,550	No longer supported	
ALO-60005	SBus preprocessor	No longer supported	
ALO-60006	CY7C601 SPARC preprocessor	No longer supported	
ALO-60007	MB86901 & L64801 SPARC preprocessor	No longer supported	
ALO-60009	Fujitsu MB86932/30 PQFP analysis probe	No longer supported	
ALO-60011	Fujitsu MB86933H PQFP analysis probe	No longer supported	
ALO-60013	Fujitsu MB86936/35 PQFP analysis probe	No longer supported	
ALO-60015	Motorola CF5202/03 (Coldfire) TQFP A/P	No longer supported	
ACOP-SC1XXX	Microphone/access Carry Case	No longer supported	no replacement
A1300-60020	KEYBOARD INF ASSY	No longer supported	no replacement
B1400A	HP Teamwork Project Database	No longer supported	
B1402A	Structured Analysis	No longer supported	
B1403A	HP Teamwork/ Realtime	No longer supported	
B1404A	Information Modeling	No longer supported	
B1405A	HP Teamwork Structured Design	No longer supported	
B1406A	Teamwork/Ada	No longer supported	
B1412A	Teamwork Upgrade	No longer supported	
B1416A	HP Branch Validator HP-UX C/C++ 9000/300	No longer supported	
B1417A	HP Branch Validator HP-UX C/C++ Media	No longer supported	
B1418A	LTU HP Branch Validator for AxLS C	No longer supported	
B1419A	HP Branch Validator AxLS C Media & Doc.	No longer supported	
B1420A	68000 C Cross Compiler 68000 Apollo 68K	No longer supported	
B1421A	68000/08/10 Media & Manuals for DN 68K	No longer supported	
B1422A	680XX Assembler/Linker LTU Apollo DN68K	No longer supported	
B1423A	680XX Assembler/Linker Media and Doc.	No longer supported	
B1424A	68000 Basis Branch Anlz. LTU Apollo 68K	No longer supported	
B1425A	68000 BBA Media and Documentation DN 68K	No longer supported	
B1426A	8086/80186 C Cross Compiler LTU Apollo	No longer supported	
B1427A	8086/80186 Media & Manuals for Apollo 68	No longer supported	
B1428A	8086/80186 Asm/Lnk License to Use	No longer supported	
B1429A	8086/80186 Assembler/Linker Media & Doc.	No longer supported	

Product	Description	Support Status	Replacement Information
B1432A	HP Branch Validator for HP-UX C 9000/800	No longer supported	
B1433A	HP Branch Validator HP-UX C Media & Doc.	No longer supported	
B1434A	LTU HP Branch Validator AxLS C 9000/800	No longer supported	
B1435A	HP Branch Validator HP AxLS C Media &	No longer supported	
B1442B	68340 Graphical Emulator/Analyzer Intfc.	No longer supported	
B1444A	SoftKey Editor	No longer supported	
B1445A	V Series AxLS Assembler/Linker	No longer supported	
B1446A	NEC V33/53 Extended Mode Locator	No longer supported	
B1447A	V Series AxLS C Compiler	No longer supported	
B1448A	HP NEC V33/53 C Cross Compiler	No longer supported	
B1449A	8086/186 Family Assembler/Linker	No longer supported	Third Party Vendors
B1450A	68000 Hosted User Interface Apollo DN68K	No longer supported	
B1450AX	One-Time-Update 68000 Hosted User I/F	No longer supported	
B1451A	Hosted User Interface 16MHz 68000 DN 68K	No longer supported	
B1451AX	One-Time-Update 16MHz 68000 I/F DN 68K	No longer supported	
B1452A	80186 Hosted User Interface Apollo DN68K	No longer supported	
B1452AX	One-Time-Update 80186 Hosted User I/F	No longer supported	
B1453A	80C186 Hosted User Interface Apollo 68K	No longer supported	
B1453AX	One-Time-Update 80C186 Hosted Interface	No longer supported	
B1454A	80188 Hosted User Interface Apollo DN68K	No longer supported	
B1454AX	One-Time-Update 80188 Hosted User I/F	No longer supported	
B1455A	80C188 Hosted User Interface Apoll 68K	No longer supported	
B1455AX	One-Time-Updateae 80C188 Hosted Interface	No longer supported	
B1456A	64000-UX Oper. Env. LTU DN2500/3500/4500	No longer supported	
B1457A	64000-UX Oper. System Apollo 68K Media	No longer supported	
B1458A	HP Branch Validator for AxLS C Domain	No longer supported	
B1459A	HP Branch Validator AxLS C Media & Doc.	No longer supported	
B1460A	68000/08/10/302 AxLS C Cross Compiler	No longer supported	
B1461A	68020 AxLS C Cross Compiler	No longer supported	
B1462A	68332 AxLS C Cross Compiler	No longer supported	
B1463A	68040 AxLS C Cross Compiler	No longer supported	
B1464A	68000 Series Assembler/Linker	No longer supported	
B1465A	68030/040 Assembler/Linker	No longer supported	
B1466A	68000 Series Debugger/Simulator	No longer supported	
B1466B	68000 Series Debugger/Simulator	No longer supported	Third Party Vendors
B1467A	68030/40 Series AxDB Debugger/Simulator	No longer supported	
B1467B	68030/40 Series AxDB Debugger/Simulator	No longer supported	Third Party Vendors
B1468A	68000 Hosted User Interface	No longer supported	
B1468B	68000 Graphical Emulator/Analyzer I/F	No longer supported	
B1469A	68302 Hosted User Interface	No longer supported	
B1469B	68302 Graphical Emulator/Analyzer I/F	No longer supported	
B1470A	68331/332 Hosted User Interface	No longer supported	
B1470B	68331/332 Graphical Emulator/Anlz I/F	No longer supported	
B1471A	64700-UX Operating Environment	No longer supported	
B1471B	64700-UX Operating Environment	No longer supported	
B1472A	68000/10/302 AxDB Debugger/Emulator	No longer supported	

Product	Description	Support Status	Replacement Information
B1472B	68000/10/302 AxDB Debugger/Emulator	No longer supported	Third Party Vendors
B1473A	68331/332 Debugger Emulator	No longer supported	
B1473B	68331/332/340/360 Debugger/Emulator	No longer supported	Third Party Vendors
B1474A	68040 Hosted User Interface	No longer supported	
B1474B	68040 Graphical Hosted User Interface	No longer supported	
B1475A	68020 Hosted User Interface	No longer supported	
B1475B	68020 Graphical Emulator/Analyzer I/F	No longer supported	
B1476A	68020 AxDB Debugger/Emulator	No longer supported	
B1476B	68020/030 AxDB Debugger/Emulator	No longer supported	Third Party Vendors
B1477A	68040 AxDB Debugger/Emulator	No longer supported	
B1477B	68040 AxDB Debugger/Emulator	No longer supported	Third Party Vendors
B1478A	68030 AxLS C Cross Compiler	No longer supported	
B1479A	68EC030 Hosted User Interface	No longer supported	
B1479B	68030/EC030 Graphical Emulator/Anlz I/F	No longer supported	
B1481A	68000/10/302 AxCASE Bundle	No longer supported	
B1481B	68000/10/302 AxCASE Bundle	No longer supported	
B1482A	68020 AxCASE Bundle	No longer supported	
B1482B	68020 AxCASE Bundle	No longer supported	
B1483A	68EC030 AxCASE Bundle	No longer supported	
B1483B	68030/EC030 AxCASE Bundle	No longer supported	
B1484A	68332/331 AxCASE Bundle	No longer supported	
B1484B	68332/331 AxCASE Bundle	No longer supported	
B1485A	68040 Series AxCASE Bundle	No longer supported	
B1485B	68040 AxCASE Bundle	No longer supported	
B1486A	Branch Validator for HP-UX C/C++	No longer supported	
B1486B	HP Branch Validator	No longer supported	
B1487A	SW Performance Analyzer Hosted User I/F	No longer supported	
B1488A	80960 Hosted User Interface	No longer supported	
B1488B	80960 Graphical Emulator/Analyzer Intfc.	No longer supported	
B1489B	80C186 Graphical Emulator/Analyzer Intfc	No longer supported	
B1490B	80C188 Graphical Emulator/Analyzer Intfc	No longer supported	
B1491B	80C286 Graphical Emulator/Analyzer Intfc	No longer supported	
B1492B	Hitachi PA/10 Graphical Emul/Anlz Intfc	No longer supported	
B1493A	8086/186 Family AxLS C Cross Compiler	No longer supported	Third Party Vendors
B1494A	8086/186 Family Debugger/Simulator	No longer supported	
B1494B	8086/186 Family Debugger/Simulator	No longer supported	Third Party Vendors
B1495A	8086/186 Family Debugger/Emulator	No longer supported	
B1495B	8086/186 Family Debugger/Emulator	No longer supported	Third Party Vendors
B1496B	68010 Graphical Hosted User Interface	No longer supported	
B1497B	8086/87 Graphical Emulator/Analyzer Intf	No longer supported	
B1498B	8088/87 Graphical Emulator/Analyzer Intf	No longer supported	
B1499B	8086/186 Family AxCASE Bundle	No longer supported	
B2770A	RTAP/Plus Software HP 9000 S300/400	No longer supported	no replacement
B2771A	RTAP Software HP-UX Version 7.0	No longer supported	no replacement
B2771B	RTAP/Plus Software HP9000 Series 700/800	No longer supported	no replacement
B2771BU	RTAP HP-UX Upgr.from version 7.0 to 8.2	No longer supported	no replacement
B2772A	RTAP/Plus Software HP 9000 Series 800	No longer supported	no replacement
B2773A	Knowledge Transfer (KNOT)	No longer supported	no replacement
B2774A	RTAP/Plus Software for Sun SPARCstations	No longer supported	no replacement
B2775A	RTAP/Plus Software for IBM RS/6000	No longer supported	no replacement
B2777A	RTAP/Plus software for Digital UNIX	No longer supported	no replacement
B2778A	RTAP for Windows NT	No longer supported	no replacement
B2778AU	RTAP for Windows NT Upgrade 7.X to 8.0	No longer supported	no replacement
B2779A	Visualizer	No longer supported	no replacement
B3050B	80186/88Ex Series Graphical Interface	No longer supported	
B3051B	80960 AxDB Debugger/Emulator	No longer supported	
B3052B	M37700 Graphical Hosted Uer Interface	No longer supported	
B3053B	H8/32X Graphical Hosted User Interface	No longer supported	

Product	Description	Support Status	Replacement Information
		as of 1 May	
B3054B	H8/330 Graphical Hosted User Interface	No longer supported	
B3055B	H8/510 Graphical Hosted User Interface	No longer supported	
B3056B	H8/520 Graphical Hosted User Interface	Currently supported	
B3057B	H8/532 Graphical Hosted User Interface	No longer supported	
B3058B	H8/536 Graphical Hosted User Interface	No longer supported	
B3059B	H8/570 Graphical Hosted User Interface	No longer supported	
B3060B	V25 Graphical Hosted User Interface	No longer supported	
B3061B	V25+ Graphical Hosted User Interface	No longer supported	
B3062B	V35+ Graphical Hosted User Interface	No longer supported	
B3063B	V33 Graphical Hosted User Interface	No longer supported	
B3064B	V53 Graphical Hosted User Interface	No longer supported	
B3065B	V40 Graphical Hosted User Interface	No longer supported	
B3066B	V50 Graphical Hosted User Interface	No longer supported	
B3067B	V55PI Graphical Emul/Analyzer Interface	No longer supported	
B3068B	V70 Graphical Hosted User Interface	No longer supported	
B3069B	V810 Graphical Emulator/Analyzer Intfc.	No longer supported	
B3070B	78K/II Graphical Hosted User Interface	No longer supported	
B3071B	M7700 Graphical Hosted User Interface	No longer supported	
B3072B	H8/338/329 Graphical Emulator/Analyzer	No longer supported	
B3074B	H8/300H 3003 Graphical User Interface	Currently supported	
B3075B	TLCS9000/42 Graphical Emulator/Anlz Intf	Currently supported	
B3076B	SH7000 Graphical User Interface	No longer supported	
B3077B	H8/300H 3048 Graphical User Interface	Currently supported	
B3078B	MELPS7750/51 Graphical User Interface	Currently supported	
B3080A	68K Real-Time Op Sys Meas.Tool for pSOS+	No longer supported	
B3081A	68K Real-Time Op. Sys. Meas. Tool VRTX32	No longer supported	
B3081B	68K RT Op. Sys. Meas. Tool VRTX32/sa	No longer supported	
B3082A	Custom Real-Time Op. Sys. Meas. Tool	No longer supported	
B3083A	Vendor Measurement Tool License-to-Use	No longer supported	
B3084A	68K RTOS Measurement Tool for VxWorks	No longer supported	
B3090B	68040 Graphical Emulator/Analyzer Intfc.	No longer supported	
B3091B	68360 Graphical Emulator/Analyzer Intf.	No longer supported	
B3092B	6833x Graphical Emulator/Analyzer I/F	No longer supported	
B3093B	68302 Graphical Emulator/Analyzer I/F	No longer supported	
B3095A	HP Branch Validator for HP-UX C/C++ LTU	No longer supported	
B3096A	HP Branch Validator End-User Kit 300/400	No longer supported	
B3097A	HP Branch Validator End-User Kit 700	No longer supported	
B3098A	HP Branch Validator End-User Kit 800	No longer supported	
B3099A	HP Branch Validator End-User Kit Sun	No longer supported	
B3620A	68000 Real-Time C Debugger	No longer supported	
B3621A	68302 Real-Time C Debugger	No longer supported	
B3622A	68020 Real-Time C Debugger	No longer supported	
B3623A	80186/88 EA/EB Real-Time C Debugger	No longer supported	
B3624A	68331/332 Real-Time C Debugger	No longer supported	
B3625A	68030 Real-Time C Debugger	No longer supported	
B3626A	8086/88 Real-Time C Debugger	No longer supported	
B3627A	68360 Real-Time C Debugger	No longer supported	
B3628A	68340 Real-Time C Debugger	No longer supported	
B3629A	68040 Real-Time C Debugger	No longer supported	
B3630A	M7700 Family Real-Time C Debugger	Currently supported	
B3637A	80386 Real-Time C Debugger	No longer supported	
B3637B	80386EX Real-Time C Debugger	No longer supported	
B3638A	68302 Real-Time C Debugger	No longer supported	
B3640A	68K Family AxLS C Cross Compiler	No longer supported	Third Party Vendors
B3641A	68000 Series Assembler/Linker	No longer supported	Third Party Vendors

Product	Description	Support Status as of 1 May	Replacement Information
B3642A	V20/30/40/50/33/53 C Cross Compiler	No longer supported	
B3643A	68000/302/020/332/331/340 AxCASE Bundle	No longer supported	
B3644A	68030/040 AxCASE Bundle	No longer supported	
B3725A	License Transfer for Emulator/Analyzer	No longer supported	no replacement
B3726A	License Transfer for Software Perf. Anlz	No longer supported	
B3727A	License Transfer for AxCASE SW Bundles	No longer supported	
B3728A	License Transfer for Debugger/Emulator	No longer supported	
B3729A	License Transfer for Debugger/Simulator	No longer supported	
B3730A	License Transfer for Branch Validator	No longer supported	
B3731A	License Transfer for ANSI C Compiler	No longer supported	
B3732A	License Transfer for Assembler/Linker	No longer supported	
B3733A	License Transfer for RTOS Measurement	No longer supported	
B3745A	Embedded MIPS Interface Software	No longer supported	
B3745B	Embedded MIPS Interface Software	Currently supported	
B3750A	H8/300H 3003 Netrap C debugger	Currently supported	
B3751A	H8/300H 3048 Netrap C Debugger	Currently supported	
B3752A	H8S/2000 2655 Netrap C Debugger	Currently supported	
B3753A	M16C/60 Series Netrap C Debugger	Currently supported	
B3754A	SH7032/34 Netrap C Debugger	Currently supported	
B3755A	SH7040 Netrap C Debugger	Currently supported	
B3756A	SH7050 Netrap C Debugger	Currently supported	
B3761A	CD-ROM HP Series 400/700	No longer supported	
B3762A	CD-ROM Sun/Solaris	No longer supported	
B3763A	CD-ROM PC Products	No longer supported	
B4100AA	Tsutsuji Standard Env. 1 User License	No longer supported	no replacement
B4101AA	Tsutsuji STD. ENV. 4 Multi-Users License	No longer supported	no replacement
B4102AJ	Tsutsuji Manual Set	No longer supported	no replacement
B4103AJ	Tsutsuji STD. ENV. DDS Cartridge Media	No longer supported	no replacement
B4104AA	Tsutsuji Mapper 1 User License	No longer supported	no replacement
B4105AJ	Tsutsuji Mapper DDS Cartridge Media	No longer supported	no replacement
B4110AA	Tsutsuji FUJITSU Library 1 User License	No longer supported	no replacement
B4111AJ	Tsutsuji FUJITSU Library Manual	No longer supported	no replacement
B4112AJ	Tsutsuji FUJITSU Library DDS Media	No longer supported	no replacement
B4113AA	Tsutsuji NEC Library 1 User License	No longer supported	no replacement
B4114AJ	Tsutsuji NEC Library Manual	No longer supported	no replacement
B4115AJ	Tsutsuji NEC Library DDS Media	No longer supported	no replacement
B4116AA	Tsutsuji HITACHI Library 1 User License	No longer supported	no replacement
B4117AJ	Tsutsuji HITACHI Library Manual	No longer supported	no replacement
B4118AJ	Tsutsuji HITACHI Library DDS Media	No longer supported	no replacement
B4119AA	Tsutsuji TOSHIBA Library 1 User License	No longer supported	no replacement
B4120AJ	Tsutsuji TOSHIBA Library Manual	No longer supported	no replacement
B4121AJ	Tsutsuji TOSHIBA Library DDS Media	No longer supported	no replacement
B4122AA	Tsutsuji LSI LOGIC Library 1 User Lic.	No longer supported	no replacement
B4123AJ	Tsutsuji LSI LOGIC Library Manual	No longer supported	no replacement
B4124AJ	Tsutsuji LSI LOGIC Library DDS Media	No longer supported	no replacement
B4125AA	Tsutsuji MITSUBISHI Library 1 User Lic.	No longer supported	no replacement
B4126AJ	Tsutsuji MITSUBISHI Library Manual	No longer supported	no replacement
B4127AJ	Tsutsuji MITSUBISHI Library DDS Media	No longer supported	no replacement
B4128AJ	Tsutsuji Fujitsu CG31 Cell Library	No longer supported	no replacement
B4129AJ	Tsutsuji Fujitsu CG24 Cell Library	No longer supported	no replacement
B4130AA	Tsutsuji Verilog-HDL link user license	No longer supported	no replacement
B4131AJ	Tsutsuji Verilo-HDL link manual	No longer supported	no replacement
B4132AJ	Tsutsuji Verilog-HDL link DAT media	No longer supported	no replacement
B4133AA	Tsutsuji VHDL link user license	No longer supported	no replacement
B4134AJ	Tsutsuji VHDL link manual	No longer supported	no replacement
B4135AJ	Tsutsuji VHDL link DAT media	No longer supported	no replacement
B4585A	100VG-AnyLAN Toolset	No longer supported	
B4601A	Serial Analysis Tool Set for 16505A	No longer supported	
B4620A	Software Analyzer Toolset	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
BANC-350	IRIG B Time Code Processor Card Bundle	No longer supported	no replacement
BANC-350R	IRIG B Time Code Card Right-to-Use Bndl.	No longer supported	no replacement
CEDT1002	SCSI To Parallel/Serial Converter	No longer supported	no replacement
CENC-TAC8	Eight channel tachometer module	No longer supported	no replacement
CLR-60031	PCI 64 Bit Bus Preprocessor	No longer supported	
CRL-60001	Am29000/50, PGA Preprocessor	No longer supported	
CRL-60002	Am29030, PGA Preprocessor	No longer supported	
CRL-60003	Am29200, PQFP Preprocessor	No longer supported	
CRL-60004	Am29205, PQFP Preprocessor	No longer supported	
CRL-60005	Am29240, PQFP Preprocessor	No longer supported	
CRL-60006	LR33000/50, PGA Preprocessor	No longer supported	
CRL-60007	LR33020, PGA Preprocessor	No longer supported	
CRL-60008	LR333X0, PQFP Preprocessor	No longer supported	
CRL-60009	IDT3051/52/81/82, PLCC Preprocessor	No longer supported	
CRL-60010	IDT3041, PLCC Preprocessor	No longer supported	
CRL-60011	Mot DSP 56116 inverse assembler	No longer supported	
CRL-60012	Mot DSP 56156 inverse assembler	No longer supported	
CRL-60013	Mot DSP 56166 inverse assembler	No longer supported	
CRL-60014	Mot 88100, PGA Preprocessor	No longer supported	
CRL-60015	Mot 88200, PGA Preprocessor	No longer supported	
CRL-60016	Mot 88110, PGA Preprocessor	No longer supported	
CRL-60017	PowerPC 601, CQFP Inverse Assembler	No longer supported	
CRL-60018	Intel 80960KA/KB/MC PGA analysis probe	No longer supported	
CRL-60019	Intel 80960KA/KB/MC PGA Universal Intfc.	No longer supported	
CRL-60020	Intel 80960CA PGA Universal Interface	No longer supported	
CRL-60021	Intel 80860XT PGA Universal Interface	No longer supported	
CRL-60022	ATT92010 PQFP Preprocessor	No longer supported	
CRL-60023	ATT92010 PQFP Universal Interface	No longer supported	
CRL-60024	ATT92020 PQFP Preprocessor	No longer supported	
CRL-60026	NEC Vr4200 PQFP Preprocessor	No longer supported	
CRL-60028	IEEE P1149.5 MTM Bus Analyzer	No longer supported	
CRL-60029	IBM ISA bus analysis probe	No longer supported	
CRL-60032	Inverse Assembler for TI 370C16	No longer supported	
CRL-60033	NEC Vr4300 PQFP analysis probe	No longer supported	
CRL-60034	Toshiba R3900 PQFP analysis probe	No longer supported	
CRL-60035	IDT R4600/4700 PGA analysis probe	No longer supported	
CRL-60036	IDT 4650 MQUAD analysis probe	No longer supported	
CRL-60037	IDT R36100 MQUAD analysis probe	No longer supported	
CRL-60039	IDT R4000/4400 PC PGA analysis probe	No longer supported	
CRL-60040	IDT R4600/4700 MQUAD analysis probe	No longer supported	
CRL-60041	IDT R5000 PGA analysis probe	No longer supported	
CRL-60042	TI320C32 TQFP analysis probe	No longer supported	
CRL-60043	TI320C32 PQFP analysis probe	No longer supported	
CRL-60044	TI320C20/25 PGA analysis probe	No longer supported	
CRL-60046	TI 320C31 PQFP analysis probe	No longer supported	
CRL-60048	PPI for TI 320C541/543/546 TQFP	No longer supported	
CRL-60053	PPPI/IA for Mot 68340 uP in PQFP package	No longer supported	
CRL-60055	AMD 186EM/ES TQFP analysis probe	No longer supported	
CRL-60056	AMD 188EM/ES PQFP analysis probe	No longer supported	
CRL-60057	AMD 188EM/ES TQFP analysis probe	No longer supported	
CRL-60058	AMD 29040 PGA analysis probe	No longer supported	
CRL-60059	AMD 29202 PQFP analysis probe	No longer supported	
CRL-60060	Motorola 68EN302 TQFP analysis probe	No longer supported	
CRL-60062	Motorola 56L811 TQFP analysis probe	No longer supported	
CRL-60063	Motorola 56303 TQFP analysis probe	No longer supported	
CRL-60064	DEC SA-110(StrongARM)TQFP analysis probe	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
CRL-60065	Motorola 68LC302 PGA Analysis Probe	No longer supported	
CRL-60066	Motorola 68LC302 TQFP Analysis Probe	No longer supported	
CRL-60067	NEC Vr4100 TQFP Analysis Probe	No longer supported	
CRL-60068	TI 320C80 PGA analysis probe	No longer supported	
CRL-60074	QED RM5270/71 BGA analysis probe	No longer supported	
CRL-60075	NEC Vr5464 BGA analysis probe	No longer supported	
CRL-60076	NEC Vr5432 PQFP analysis probe	No longer supported	
CRL-60077	NEC Vr4III Inverse Assembler	No longer supported	
CRL-60078	Motorola MPC801 inverse assembler	No longer supported	
CRL-60080	Motorola 56309 TQFP analysis probe	No longer supported	
CRL-60081	IDT RC64475 MQUAD analysis probe	No longer supported	
CRL-60081	IDT RC64475 MQUAD analysis probe	No longer supported	
CRL-60082	IDT RC64474 PQFP analysis probe	No longer supported	
CRL-60082	IDT RC64474 PQFP analysis probe	No longer supported	
DDCC-1553	Mil-Std-1553 VXI Card Bundle	No longer supported	no replacement
DDCC-1553R	Mil-Std-1553 VXI Card Right-to-Use Bndl.	No longer supported	no replacement
DDCC-37001	Synchro/Resolver VXI Card Bundle	No longer supported	no replacement
DDCC-37001R	Remote Management Card for NT-Server	No longer supported	no replacement
D6028-68002	Synchro/Resolver Card Right-to-Use Bndl.	No longer supported	no replacement
E1300AR	B-Size Mainframe, 9-slot	No longer supported	
E1301A	HP 75000 Series B with front panel	No longer supported	E1301B
E1301AR	75000 Series B with front panel	No longer supported	
E1303A	VME/VXI mainframe w/GPIB command module	No longer supported	no replacement
E1304A	VME/VXI mainframe w/ 486 embedded cntrl	No longer supported	E1304B
E1304B	VME/VXI mainframe w/ 486 66 MHz embedded	No longer supported	no replacement
E1305A	VME/VXI mainframe with VXLink interface	No longer supported	no replacement
E1306AR	HP-IB Command module for B-size VXI	Currently supported	
E1312AR	6 1/2 Digit DMM; High Accuracy	Currently supported	
E1313AR	32-Channel Scanning A/D converter	Currently supported	
E1313F	Field Kit to Expand E1313A to 64 Ch.	Currently supported	no replacement
E1320A	512 KByte Nonvolatile Memory	No longer supported	no replacement
E1321A	1 MByte Nonvolatile Memory	No longer supported	no replacement
E1323A	VME/VXI PREPROCESSOR	No longer supported	
E1326A	5 1/2 Digit Multimeter	No longer supported	E1326B
E1326-80002	Internal Installation Kit for E1326A	No longer supported	E1326B
E1326-80003	Internal Installation Kit for the E1326E	No longer supported	no replacement
E1326E	5 1/2-Digit Multimeter	No longer supported	E1326B
E1330A	Quad 8-Bit Digital I/O	No longer supported	E1330B
E1330BR	Quad 8-Bit digital input/output	Currently supported	
E1368AR	18 GHz Microwave Switch; (3 channels)	Currently supported	
E1383AR	VXLink Kit to Connect PC to B-size VXI	Currently supported	
E1390A	HP 75000 PC Data Acquisition System 10	No longer supported	E1390B
E1390B	HP 75000 PC Data Acquisition System 10	No longer supported	no replacement
E1390E	HP 75000 System 10 -220V Univ English	No longer supported	no replacement
E1395A	HP 75000 System 10 Software/Manuals	No longer supported	E1395B
E1395B	HP 75000 System 10 Software/Manuals	No longer supported	E1395C
E1395C	HP 75000 System 10+ Software/Manuals	No longer supported	no replacement
E1395E	System 10 Software/Manuals Int'l English	No longer supported	no replacement
E1400A	C-SIZE VXI BUS MAINFRAME	No longer supported	E1401B
E1400B	75000 Series C Mainframe	No longer supported	E1401B
E1400T	VXI Development Mainframe	No longer supported	E1401T
E1401A	C-Size VXI Hi-Power Mainframe, 13-Slot	No longer supported	E1401B
E1401TR	VXI C-size Development Mainframe	Currently supported	
E1402A	VME Module Adapter	Currently supported	no replacement
E1403A	A/B Size Active Module Carrier	Currently supported	E1403C

Product	Description	Support Status as of 1 May	Replacement Information
E1404A	C-SIZE VXI BUS SLOT 0/TRANSLATOR MODULE	No longer supported	no replacement
E1405A	Command Module	No longer supported	E1406A
E1405B	COMMAND MODULE	No longer supported	E1406A
E1405BR	Command Module	Currently supported	
E1407AR	A/B to C-size P1/P2 Active Adapter	Currently supported	
E1408A	C-SIZE CARRIER FOR A/B SIZE MODULES	No longer supported	E1407A
E1409A	C-size VXIbus chassis shield	Currently supported	no replacement
E1411A	5 1/2 Digit Multimeter	No longer supported	E1411B
E1411BR	5.5 Digit Multimeter Hi-Accuracy, C-Size	Currently supported	
E1413A	Obsolete 8/94 Order E1413B.	product family sold	http://www.agilent.com/find/vxitechnologies
E1413CR	64-channels muxed to 16-bit 100KHz A/D	Currently supported	
E1413G	E1413A upgrade kit	Currently supported	no replacement
E1414AR	Pressure Scanning A/D Converter	Currently supported	
E1414G	Flash ROM upgrade kit for E1414A	Currently supported	no replacement
E1415G	Flash Code/Driver Upgrade for E1415A	Currently supported	no replacement
E1420A	High Performance Universal Counter	product family sold	http://www.agilent.com/find/symmetricom
E1420AX	High Performance Universal Counter	product family sold	http://www.agilent.com/find/symmetricom
E1420BX	High Performance VXI Universal Counter	No longer supported	E1420B
E1421A	C-Size VXI Portable Mainframe, 6-slot	Currently supported	E1421B
E1426AA	500MHz VXI OSCILLOSCOPE	No longer supported	
E1427A	VXI digitizer with 2 GSa/s sample rate	Currently supported	no replacement
E1428AX	1 GSa/S VXI OSCILLOSCOPE	No longer supported	
E1429AR	2-Channel, 20MSa/s, 12-Bit digitizer	Currently supported	
E1429BR	20 MSa/s 12-Bit Digitizer w/ Local Bus	Currently supported	
E1430AX	10MS/s 23bit, A/D with Filter & Memory	No longer supported	E1437A
E1440AX	21MHz SYNTHESIZED FUNCTION/SWEEP GEN.	No longer supported	
E1450AR	160 MHz, 12-channel timing module	Currently supported	
E1451AR	20 MHz pattern I/O module; 32 I/O pins	Currently supported	
E1452AR	Terminating 20 MHz Pattern I/O module	Currently supported	
E1455A	Timing pod for E1450A timing module	Currently supported	no replacement
E1456A	ICA Pattern Pod for the E1451A/E1452A	Currently supported	no replacement
E1458AR	96-Channel digital I/O	Currently supported	
E1459AR	64-Channel Isolated Dig. Input/Interrupt	Currently supported	
E1460AR	64-Channel Relay Multiplexer	No longer supported	
E1463AR	32-Channel, 5 Amp, Form-C VXI Switch	Currently supported	
E1465AR	16x16 Relay Matrix Switch.	Currently supported	
E1466AR	4x64 Relay Matrix Switch	Currently supported	
E1467AR	8x32 Relay Matrix Switch	Currently supported	
E1468AR	8x8 Relay Matrix Switch	Currently supported	
E1469AR	4x16 Relay Matrix Switch	Currently supported	
E1470AR	60-Channel 50 ohm RF Multiplexer	Currently supported	
E1472AR	Six 1x4 50 Ohm RF Multiplexer	Currently supported	
E1473AR	Six 1x4 50 Ohm RF Multiplexer Expander	Currently supported	
E1474AR	Six 1x4 75 Ohm RF Multiplexer	Currently supported	
E1475AR	Six 1x4 75 ohm RF Multiplexer Expander	Currently supported	
E1476AR	64-Channel 3-wire T/C Relay Multiplexer	Currently supported	
E1481A	VXIbus Driver For Embedded Controllers	No longer supported	no replacement
E1481L	VXIbus Driver License-To-Use	No longer supported	no replacement
E1482A	VXI MXI MODULE	No longer supported	no replacement
E1482BR	VXIbus Extender (VXIbus-to-MXIbus)	Currently supported	
E1483A	VXLink Kit to Connect PC to C-size VXI	No longer supported	E8491B (firewire)
E1485AR	Digital Signal Processor Module	Currently supported	
E1485AX	Digital Signal Processing Module	No longer supported	no replacement
E1485B	Digital Signal Processor Module	No longer supported	no replacement
E1485BX	Digital Signal Processor Module	No longer supported	no replacement
E1485UX	Upgrade Kits for Dig Sig Proc Module	No longer supported	no replacement
E1488AR	2 to 16 Mbyte Instrument Memory Module	Currently supported	
E1488AU	2 Mbyte memory board for the E1488A	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E1489B	MXI interface for Series 700 + software	No longer supported	no replacement
E1489CR	MXI Interface for S/700 + softward	Currently supported	
E1489I	MXI Interface for S700	No longer supported	no replacement
E1490A	C-SIZE VXI BUS REGISTER BASED BREADBOARD	No longer supported	E1490C
E1490B	Register-based Breadboard, C-size	No longer supported	E1490C
E1491A	VXI C-size with GPIB command module	No longer supported	E1401B plus E1406A
E1491AR	VXI C-size with HP-IB command module	Currently supported	
E1492A	HP 75000 Series C Starter System	No longer supported	http://www.agilent.com/find/vxi
E1492B	HP 75000 STARTER SYSTEM	No longer supported	E1401B plus E1406A
E1493A	Model D20 digital functional test system	Currently supported	no replacement
E1493AR	Model D20 Digital functional test system	Currently supported	
E1494A	Model D20 digital test development sys	Currently supported	no replacement
E1495A	VXI BUS DEVELOPMENT SOFTWARE	No longer supported	no replacement
E1496A	75000 Model D20 Development Software	Currently supported	no replacement
E1496U	Upgrade of E1496A software	Currently supported	no replacement
E1497AR	V743/64 VXI Embedded Controller Module	Currently supported	
E1499BR	V/382 VXI Embedded Controller Module.	No longer supported	
E1514A	Isolated X1, 10 Hz Low Pass SCP	product family sold	http://www.agilent.com/find/vxitechnologies
E1515A	Isolated X1, 100 Hz Low Pass SCP	product family sold	http://www.agilent.com/find/vxitechnologies
E1516A	Isolated X64, 10 Hz Low Pass SCP	product family sold	http://www.agilent.com/find/vxitechnologies
E1517A	Isolated X64, 100 Hz Low Pass SCP	product family sold	http://www.agilent.com/find/vxitechnologies
E1520A	HD2000 development system bundle	No longer supported	no replacement
E1520B	Installation manual for HD2000 system	Currently supported	no replacement
E1521A	HD2000 run-only system bundle	No longer supported	no replacement
E1522A	HD2000 Extender System Bundle	No longer supported	no replacement
E1534A	Freq/Totalize/PWM Signal Cond. Plugon	Currently supported	no replacement
E1537A	4ch Voltage Output Signal Cond. Plugon	Currently supported	no replacement
E1550A	32-Channel Balanced Daisy Chain Switch	Currently supported	no replacement
E1550G	QTD only 32-channel daisy chain switch	Currently supported	no replacement
E1551A	STS-1/DS3 Daisy Chain Switch	Currently supported	no replacement
E1551G	STS-1/DS3 daisy chain switch	Currently supported	no replacement
E1552A	STS-1/DS3 Test Access Switch	No longer supported	no replacement
E1552AR	STS-1/DS3 Test Access Switch	No longer supported	
E1552G	QTD only STS-1/DS3 test access switch	No longer supported	no replacement
E1553A	Dual STS-1/DS3 Amplifier/LBO	No longer supported	no replacement
E1553G	Dual STS-1/DS3 Amplifier/LBO	Currently supported	no replacement
E1554A	8-Channel 75 Ohm Daisy Chain Switch	Currently supported	no replacement
E1554G	8-Channel 75 Ohm Daisy Switch	Currently supported	no replacement
E1562A	VXI Data Disk, DAT & SCSI-2 Interface	product family sold	http://www.agilent.com/find/vxitechnologies
E1562AR	VXI Data Disk,DAT & SCSI-2 Interface.	Currently supported	
E1562B	VXI, Dual Data Disk & SCSI-2 Interface	product family sold	http://www.agilent.com/find/vxitechnologies
E1562C	VXI Dual Data Disk without controller	product family sold	http://www.agilent.com/find/vxitechnologies
E1562CR	VXI Dual Data Disk without controller.	No longer supported	
E1570A	Compiled SCPI for the HP V/382	No longer supported	no replacement
E1570B	Compiled SCPI for HP V/382, LTU HP-UX 9.0	No longer supported	no replacement
E1570C	LTU C-SCPI Dev Env for HP V382 HP-UX 8.0	No longer supported	no replacement
E1570D	LTU C-SCPI Dev Env for HP V382 HP-UX 9.0	No longer supported	no replacement
E1570U	C-SCPI Upgrade to HP-UX 9.0 on V/382	No longer supported	no replacement
E1571A	Compiled SCPI for HP RADI-EPC7 (MS-DOS)	No longer supported	no replacement
E1571B	LTU C-SCPI Dev Env for RADI-EPC7 w/ DOS	No longer supported	no replacement
E1572A	LTU Compiled SCPI for MXI on the S/700	No longer supported	no replacement
E1573A	VXI drivers/development env for V743rt	No longer supported	no replacement
E1580A	Compiled SCPI for the HP V/382 (L-T-R)	No longer supported	no replacement
E1580B	Compiled SCPI for HP V382, LTR HP-UX 9.0	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E1580C	C-SCPI lic-to-run for HP V382, HP-UX 8.0	No longer supported	no replacement
E1580D	C-SCPI lic-to-run for HP V382, HP-UX 9.0	No longer supported	no replacement
E1581A	Compiled SCPI for the HP RADI-EPC7 (LTR)	No longer supported	no replacement
E1581B	C-SCPI lic-to-run for HP RADI-EPC7 w/DOS	No longer supported	no replacement
E1582A	LTR Compiled SCPI for MXI on the S/700	No longer supported	no replacement
E1583A	VXI drivers/LTU for V743rt	No longer supported	no replacement
E1590A	Portable Mechatronics Data Acq System	No longer supported	no replacement
E1591A	Mechatronics Measurement Modules	No longer supported	no replacement
E1592A	Mechatronic Vehicle Bus Monitor	No longer supported	no replacement
E1599AA	Mechatronic License, Media & Manuals	No longer supported	no replacement
E1599AD	Mechatronics German Media & Manuals	No longer supported	no replacement
E1601A	Quad OC-3c/STM-1 Multimode Port Adapter	Currently supported	
E1601A	Quad OC-3c/STM-1 Multimode Port Adapter	Currently supported	
E1603A	HP E1603A 622Mb/s ATM Analyzer	No longer supported	no replacement
E1604A	HP E1604A ATM Load Simulator	No longer supported	no replacement
E1612AR	155Mb/s Electrical Line Interface	Currently supported	
E1613AR	6.3 Mb/s J2 electrical line interface	Currently supported	
E1614AR	6.3 Mb/s J2 Optical Line Interface	Currently supported	
E1615A	2.488 Gb/s ATM Generator/Receiver	Currently supported	no replacement
E1615B	2.4Gb/s ATM/POS Generator/Receiver	No longer supported	no replacement
E1617AR	52Mb/s Optical Line Interface	Currently supported	
E1619A	25.6 Mb/s (4B/5B) Line Interface	No longer supported	E1619B.
E1619AR	25.6 Mb/s (4B/5B) line interface	No longer supported	
E1619BR	25.6Mb/s LIF for the BSTS	Currently supported	
E1620A	34 Mb/s 16-way fanout module	No longer supported	no replacement
E1623A	TS-2000 SDH & ATM functional test system	No longer supported	no replacement
E1625A	TS-2000 SONET functional test system	No longer supported	no replacement
E1629A	TS-2000 support products	No longer supported	no replacement
E1630A	SDH/SONET library of meas utilities	No longer supported	no replacement
E1631A	6 copies of SONET/SDH library meas utils	No longer supported	no replacement
E1650A	Modular SONET/SDH analyzer to 622 Mb/s	No longer supported	OmniBER OTN
E1650B	Modular SONET/SDH Analyzer to 622Mbit/s	No longer supported	OmniBER OTN
E1651A	HP75000 series 90 User Interface S/ware.	No longer supported	E1651B
E1651B	Bundled User Interface Software.	Currently supported	no replacement
E1652A	Modular Analyzer (52,155 Mb/s)	No longer supported	OmniBER OTN
E1652AR	Modular analyzer (52,155 Mb/s)	No longer supported	
E1654A	Modular SONET/SDH Analyzer	Currently supported	OmniBER OTN
E1654B	Modular SONET/SDH Analyzer	Currently supported	OmniBER OTN
E1654D	Modular SONET/SDH analyzer to 2488 Mb/s	No longer supported	OmniBER OTN
E1654DR	Modular SONET/SDH analyzer to 2488 Mb/s	No longer supported	
E1654E	Modular SONET/SDH Analyzer to 2.4Gbit/s	No longer supported	OmniBER OTN
E1654F	Modular SONET/SDH Analyzer to 2.4Gb/s	No longer supported	OmniBER OTN
E1654G	Modular SONET/SDH analyzer to 2.4Gb/s	Currently supported	OmniBER OTN
E1654GR	Modular SONET/SDH analyzer to 2.4Gb/s	Currently supported	
E1655A	75000 E1655A Series 90 ATM Analyzer	No longer supported	http://www.agilent.com/find/routertester
E1655B	HP 75000 Series 90 622 Mb/s ATM Analyzer	No longer supported	no replacement
E1658A	Automated SONET/SDH Test Suites	No longer supported	no replacement
E1659A	ATM Analyzer Software	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E1660A	DS1 32-way Fanout Module.	No longer supported	no replacement
E1660AR	DS1 32-way Fanout Module.	No longer supported	
E1660B	2 Mb/s 32-way fanout module.	No longer supported	no replacement
E1661A	Optical Interface (52/155 Mb/s)	No longer supported	OmniBER OTN
E1661AR	Optical Interface (52/155 Mb/s)	No longer supported	
E1662A	Optical Interface Module (155.622 Mb/s)	No longer supported	OmniBER OTN
E1662AR	Optical Interface Module (155.622 Mb/s)	Currently supported	
E1662B	1550nm Optical Transmitter	No longer supported	OmniBER OTN
E1662BR	1550nm Optical Transmitter	No longer supported	
E1662C	E1662A and E1662B bundle.	No longer supported	OmniBER OTN
E1663A	Electrical Interface Module	Currently supported	OmniBER OTN
E1663AR	Electrical interface module	Currently supported	
E1664A	STS-1/DS3 16-way Fanout.	No longer supported	no replacement
E1664AR	STS-1DS3 16-way Fanout.	No longer supported	
E1664B	STM-1/139Mb/s 8-way Fanout	No longer supported	no replacement
E1665A	155 Mb/s Quad O/E E/O Converter.	No longer supported	no replacement
E1665AR	155Mb/s Quad O/E E/O Converter.	No longer supported	
E1666A	EOC Access Module	Currently supported	no replacement
E1667A	SONET/SDH Jitter Analyzer (VXI module)	Currently supported	OmniBER OTN
E1667AR	SONET/SDH jitter analyzer(VXI module)	Currently supported	
E1668A	SONET/SDH Jitter Analyzer (2.4Gb/s)	Currently supported	OmniBER OTN
E1668AR	SONET/SDH Jitter Analyzer (2.4Gb/s)	Currently supported	
E1669A	SONET/SDH optical I/F module, 2.4 Gb/s	No longer supported	OmniBER OTN
E1669B	SONET/SDH 1550nm optical I/F, TX/RX	Currently supported	OmniBER OTN
E1669BR	SONET/SDH 1550nm optical I/F, TX/RX	Currently supported	
E1670A	SONET/SDH Optical Interface Module (Tx)	No longer supported	OmniBER OTN
E1670AR	SONET/SDH Optical Interface Module (Tx)	No longer supported	
E1670B	SONET/SDH 1550nm I/F module, TX	Currently supported	OmniBER OTN
E1671A	Transport Overhead Generator.	No longer supported	OmniBER OTN
E1671AR	Transport Overhead Generator	Currently supported	
E1672A	Transport Overhead Receiver	Currently supported	OmniBER OTN
E1672AR	Transport overhead Receiver	Currently supported	
E1673A	Transport Overhead Generator	No longer supported	OmniBER OTN
E1673AR	Transport Overhead Generator	No longer supported	
E1674A	Transport Overhead Receiver Module.	No longer supported	OmniBER OTN
E1674AR	Transport Overhead Receiver Module	No longer supported	
E1675A	SONET/SDH transport overhead analyzer	No longer supported	OmniBER OTN
E1675AR	SONET/SDH transport overhead analyzer	No longer supported	
E1676A	SONET/SDH Transport Overhead Analyzer	No longer supported	OmniBER OTN
E1676AR	SONET/SDH Transport Overhead Analyzer	Currently supported	
E1676B	Multi-Rate SDH/SONET Analyzer	Currently supported	OmniBER OTN
E1676BR	Multi-rate SDH/SONET analyzer	Currently supported	
E1679A	SONET/SDH Timing Reference	Currently supported	OmniBER OTN
E1679AR	SONET/SDH timing reference	Currently supported	
E1681A	Synchronous Payload Envelope Generator.	No longer supported	OmniBER OTN
E1681AR	Synchronous payload Envelope Generator.	No longer supported	
E1682A	Synchronous Payload Envelope Receiver.	No longer supported	OmniBER OTN
E1682AR	Synchronous payload Envelope Receiver.	No longer supported	
E1683A	VT/TU Generator	Currently supported	OmniBER OTN
E1683AR	VT/TU Generator	Currently supported	
E1684A	VT/TU Analyzer	Currently supported	OmniBER OTN
E1684AR	VT/TU Analyzer	Currently supported	
E1685A	STS1/DS3 Quad Transceiver.	Currently supported	OmniBER OTN
E1685AR	STS1/DS3 Quad Transceiver	Currently supported	
E1685B	STM-1/STS-3(c)/ 139Mb/s quad transceiver	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E1685BR	STM-1/STS-3(c)/139Mb/s quad transceiver	No longer supported	
E1686A	DS1/DS3 Transceiver	No longer supported	OmniBER OTN
E1686AR	DS1/DS3 Transceiver	No longer supported	
E1686B	2/8/34/139 Mb/s Transceiver	No longer supported	OmniBER OTN
E1686BR	2/8/34/139 Mbs/Transceiver	No longer supported	
E1691A	ATM Generator (155 Mb/s)	No longer supported	http://www.agilent.com/find/routertester
E1692A	ATM Receiver (155 Mb/s)	No longer supported	http://www.agilent.com/find/routertester
E1693A	ATM Generator (155/622 Mb/s)	Currently supported	http://www.agilent.com/find/routertester
E1693AR	ATM generator (155/622 Mb/s)	Currently supported	
E1694A	ATM Receiver (155/622 Mb/s)	Currently supported	http://www.agilent.com/find/routertester
E1694AR	ATM Receiver(155/622 Mb/s)	Currently supported	
E1695A	45 Mb/s DS3 Line Interface	No longer supported	no replacement
E1695AR	45 MB/s DS3 Line Interface	No longer supported	
E1696A	155 Mb/s ATM optical load generator	Currently supported	no replacement
E1696AR	155 Mb/s ATM optical load generator	Currently supported	
E1697AR	155 MB/s Optical Line Interface	Currently supported	
E1698A	100-140 Mb/s (4b/5b) optical interface	No longer supported	no replacement
E1698AR	100-140 Mb/s (4b/5b) optical interface.	Currently supported	
E1699A	LID IBT Engineering Unit	No longer supported	no replacement
E1707A	Dynamic Receiver	No longer supported	E1708A
E1710A	Angular Encoder System	Currently supported	no replacement
E1712A	Scale	Currently supported	no replacement
E1713A	Scale Servo-Axis Board	Currently supported	no replacement
E1714A	Master Arm Assembly	Currently supported	no replacement
E1721A	Non-Contact Push Pin (NCP) Sensor	No longer supported	no replacement
E1723A	DSP Servo-Axis Board	Currently supported	no replacement
E1725A	Time Interval Analyzer	No longer supported	no replacement
E1725AR	Time Interval Analyzer	No longer supported	
E1725B	Time Interval Analyzer	No longer supported	no replacement
E1742AR	Sonet/SDH Tributary Jitter Analyzer	Currently supported	
E1746A	Network Synchronization Measurement SW	Currently supported	no replacement
E1750AR	Broad Band Distribution Amplifier	Currently supported	
E1752AR	Pulse Distribution Amplifier	Currently supported	
E1799A	Custom accessory family for ESA DLP	Currently supported	no replacement
E1800A	Open Architecture Controller	No longer supported	
E1850A	E6382A Test SW for Ericsson RBS2000 BTS	No longer supported	
E1860A	E6382A Connect Kit for Ericsson RBS2000	No longer supported	
E1962A	IS-2000 Mobile Test Application	Currently supported	E1962B
E1980U	8960 Series 10 Test Application upgrades	No longer supported	
E2000A	Test Generator	No longer supported	no replacement
E2001A	INSTRUMENT DRIVERS FOR HP ITG	No longer supported	no replacement
E2011A	TestExec SL 1.5 for Win95	No longer supported	E2011 series
E2011B	TestExec SL 2.0 for Win95/WinNT	No longer supported	E2011 series
E2011C	TestExec SL 3.X for Windows NT	Currently supported	
E2011D	TestExec SL 4.X for Windows NT	Currently supported	
E2020A	Interactive Test Generator/DOS	No longer supported	no replacement
E2020B	ITG II	No longer supported	no replacement
E2020U	ITG II upgrade	No longer supported	no replacement
E2021A	TestExec SL 1.5 for HP-UX Series 700	No longer supported	E2011 series
E2040A	HP BASIC/UX Media and Documentation	No longer supported	no replacement
E2040AJ	BASIC media/docs	No longer supported	no replacement
E2040B	HP BASIC/UX 300 Media/Documentation	Currently supported	no replacement
E2040BJ	BASIC/WS Media/Documentation	Currently supported	no replacement
E2040K	HP BASIC/UX Documentation Only	Currently supported	
E2040KJ	BASIC Docs Only	No longer supported	no replacement
E2040L	BASIC/UX License-To-Use	Currently supported	no replacement
E2040LJ	BASIC License	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
E2040Y	HP BASIC for S/300 Y2K Upgrade	Currently supported	
E2040YL	HP BASIC S/300 Y2K Upgrade License	Currently supported	
E2045A	BASIC/UX S700 media and documentation	No longer supported	no replacement
E2045AJ	BASIC/UX S700 media & doc. (Japanese)	No longer supported	no replacement
E2045B	BASIC/UX 700 media and documentation	No longer supported	
E2045Y	HP BASIC Y2K Revision for HP-UX	Currently supported	
E2046AJ	BASIC/UX S700 License-to-use Japanese	No longer supported	
E2050A	LAN/GPIB Gateway	Currently supported	E5810A
E2060A	BASIC for Windows	No longer supported	no replacement
E2060Y	HP BASIC Windows Y2K Upgrade	Currently supported	
E2061A	HP BASIC for Windows CSUB Utility	Currently supported	
E2062A	HP BASIC for Windows Numeric Compiler	Currently supported	
E2063A	BASIC for Windows Revision Upgrade	No longer supported	no replacement
E2066B	HP BASIC for Windows License to Use	Currently supported	
E2066C	License to Use HP BASIC for Windows	Currently supported	
E2066D	HT BASIC License to Use for Windows	Currently supported	
E2070A	Order E2070B	No longer supported	no replacement
E2070B	GPIB interface for Series 700	No longer supported	no replacement
E2071B	High speed GPIB interface for S700	No longer supported	no replacement
E2074A	GPIO/EISA on Series 700 workstations	No longer supported	no replacement
E2074B	GPIO for S700	Currently supported	no replacement
E2080A	LIF File Utilities for the PC.	No longer supported	no replacement
E2085A	Shared Resource Manager Server Software.	No longer supported	no replacement
E2085B	Shared Resource Manager on HP-UX	No longer supported	no replacement
E2085C	Shared Resource Manager on HP-UX	No longer supported	no replacement
E2085D	SRM/UX on HP-UX 9.0	No longer supported	no replacement
E2085E	SRM/UX on HP-UX 10.0	No longer supported	no replacement
E2085Y	SRM/UX Y2K Upgrade	Currently supported	no replacement
E2090L	SICL Right-to-Execute	No longer supported	no replacement
E2091A	Std Inst. Cntrl. Lib. for S700 HP-UX 8.0	No longer supported	no replacement
E2091B	Instrument Control I/O Library for S700	No longer supported	no replacement
E2091C	Std Inst. Cntrl. Lib. for S700 HP-UX 9.0	No longer supported	no replacement
E2091D	I/O Libraries for HP-UX 9.x & 10.01	Currently supported	no replacement
E2091E	I/O Libraries for HP-UX 10.20	No longer supported	no replacement
E2092A	Std Inst. Cntrl. Library for V382 & S382	No longer supported	no replacement
E2092B	Inst. Cntrl I/O Library for S382 & V382	No longer supported	no replacement
E2092C	Std Inst Cntrl Lib V382/S382 HP-UX 9.0	No longer supported	no replacement
E2093B	Inst. Control I/O Library for MXI S700	No longer supported	no replacement
E2094A	I/O Library for 82335B in Win. 3.1 env.	No longer supported	E2094M
E2094B	Std. Inst. Control Lib. for Windows 3.1	No longer supported	E2094M
E2094C	I/O lib. for inst. control for Windows	No longer supported	E2094M
E2094D	I/O Libraries for WIN 3.1/NT/95	No longer supported	E2094M
E2094E	I/O Lib for Inst Cntl for Win 3.1/NT/95	No longer supported	E2094M
E2094F	I/O Lib for Inst Cntrl for Win95/NT	No longer supported	E2094M
E2094G	I/O Lib for Inst Cntl for Win3.1/95/NT	Currently supported	E2094M
E2094H	I/O Libraries for Win95/98/NT	Currently supported	E2094M
E2094J	I/O Libraries for Win95/98/NT/2000/Me	Currently supported	E2094M
E2095A	I/O Library for Serial Ports	No longer supported	E2094M
E2100A	VEE-Engine (300/400) L-T-U	No longer supported	
E2100B	VEE-Engine 2.0 (300/400) License-to-use	No longer supported	
E2100U	VEE-Engine 2.0 LTU (S300/400) Upgrade	No longer supported	no replacement
E2101A	VEE-Engine (700) L-T-U	No longer supported	E2101B
E2101B	VEE-Engine 2.0 license-to-use for S700	No longer supported	
E2101U	VEE-Engine 2.0 Upgrade for S700	No longer supported	no replacement
E2110A	VEE-Test (300/400 DIO) L-T-U	No longer supported	E2110B
E2110AX	VEE-Test/300 for XMO only	No longer supported	no replacement
E2110B	HP VEE 2.0.1 Series 300 License To Use	No longer supported	E2110C
E2110BX	VEE-Test 2.0/300 XMO only	No longer supported	no replacement
E2110U	VEE-Test 2.0 (S300/400) LTU Upgrade	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E2111A	VEE-Test (700 EISA) LTU	No longer supported	E2111B
E2111B	VEE-Test 2.3 S700 EISA license-to-use	No longer supported	E2111C
E2111C	HP VEE for Series 700 Rev. 3.0	No longer supported	E2111D
E2111U	S300 or S700 VEE 2.0 (EISA 700) LTU Upgd	No longer supported	no replacement
E2112B	HP VEE 2.1 for SunOS License To Use	No longer supported	
E2112C	HP VEE for Solaris Rev. 3.X.	No longer supported	
E2115A	HP VEE-Test/Run only	No longer supported	E2115B
E2115B	HP VEE-Test/RunOnly 2.3 for S300/400	No longer supported	E2115C
E2115C	HP VEE RunOnly for Series 300 Rev. 3.0	No longer supported	E2110C, Option RUN
E2115U	HP VEE-Test/RunOnly 2.0 Upgrade	No longer supported	no replacement
E2116B	HP VEE-Test/RunOnly 2.3 for S700 EISA	No longer supported	E2116C
E2116C	HP VEE RunOnly for Series 700 Rev. 3.0	No longer supported	E2111C, Option RUN
E2117A	HP VEE 3.1 Site License	No longer supported	E2117D
E2117D	HP VEE 3.2 Site License	No longer supported	http://www.agilent.com/find/vee
E2117E	HP VEE 4.0 Site License	No longer supported	
E2118A	HP VEE site license for 100 seats	No longer supported	E2117D
E2120B	HP VEE for Windows	No longer supported	E2120C
E2120D	HP VEE 3.2 for Windows 95 & Windows NT	No longer supported	http://www.agilent.com/find/vee
E2120E	HP VEE 4.0 for Win95/WinNT	No longer supported	
E2121E	HP VEE 4.0 for Win95/NT for Volume	No longer supported	
E2121F	HP VEE 5.0 for Win95/98/NT-Volume Cust	Currently supported	
E2122D	HP VEE Win 3.1 for Universities	Currently supported	
E2122E	HP VEE Win95/NT for Universities	No longer supported	H2327F #WNT.
E2125B	HP VEE for Windows RunOnly	No longer supported	E2125C
E2125C	HP VEE RunOnly for Windows Rev. 3.X.	No longer supported	E2120C, Option RUN
E2126E	PV-WAVE Visual Analysis Package	No longer supported	
E2160A	BASIC Plus License-To-Use	No longer supported	no replacement
E2160AJ	BASIC Plus L-T-U	No longer supported	no replacement
E2161A	BASIC Plus Media and Doc. for S300	No longer supported	no replacement
E2161AJ	BASIC Plus Media and Doc. (Japanese)	No longer supported	no replacement
E2162A	BASIC Plus for Measurement Copro.	No longer supported	no replacement
E2162AJ	BASIC Plus for Mea. Copro. (Japanese)	No longer supported	no replacement
E2163A	BASIC Plus Media and Doc. S700	No longer supported	no replacement
E2163AJ	BASIC Plus Media/Doc. S700 (Japanese)	No longer supported	no replacement
E2165AJ	BASIC Plus License-to-use (Japanese)	No longer supported	no replacement
E2171A	HP TS-5550LX Multi-Up Base System	No longer supported	N4042
E2171B	TS-5550 GSM 2-4 Up Cell Phone Tester	Currently supported	N4042A
E2174B	TS-5500 Action Development License & SW	Currently supported	N4041A/N4042A GS-8000
E2174C	TS-5500 Test Dev. Software and License	No longer supported	N4041A/N4042A GS-8000
E2175A	Digital Multimeter and MUX	No longer supported	N4041A/N4042A GS-8000
E2175B	Additional E1411A DVMs For TS-5550	Currently supported	N4041A/N4042A GS-8000
E2176A	Frequency Counter for TS-5500 Systems	Currently supported	N4042
E2177A	16 Ch TS-5500 Audio Test Module	No longer supported	N4042
E2177B	Audio Test Module for TS-5550/LX	Currently supported	N4042
E2179A	M-Module Carrier	Currently supported	N4041A/N4042A GS-8000
E2181A	TS-5500 Family Common Options	Currently supported	
E2182A	TS-5500 Family Support Options	Currently supported	
E2183A	Ref. Phone Design Common Options	Currently supported	
E2189B	TS-5500/LX CDMA 2-4 up Cell Phone Tester	Currently supported	N4042
E2200A	Instrument BASIC	Currently supported	no replacement
E2320A	HP LogicDart Assembled Probe w/Browser	Currently supported	no replacement
E2321A	HP LogicDart Replacement Probe	Currently supported	no replacement
E2322A	LogicDart Probe Accessory Kit	Currently supported	no replacement
E2377A	3.5 digit handheld multimeter, math func	No longer supported	no replacement
E2378A	Rugged 3.5 digit handheld multimeter	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E2400A	PREPROCESSOR FOR MOTOROLA 88200	No longer supported	
E2402A	UNIVERSAL INTERFACE FOR INTEL 80960KX	No longer supported	
E2403A	UNIVERSAL INTERFACE FOR INTEL 80486	No longer supported	
E2404A	PREPROCESSOR FOR MOTOROLA 88100	No longer supported	
E2405A	i860 UNIVERSAL INTERFACE	No longer supported	
E2406AR	Preprocessor Intfc for Motorola 68030	Currently supported	
E2407A	NEC V70 INTERFACE	No longer supported	
E2409A	PREPROCESSOR INTERFACE FOR INTEL 80286	No longer supported	
E2409B	PREPROCESSOR INTERFACE FOR INTEL 80286	No longer supported	
E2410A	UNIVERSAL INTERFACE FOR INTEL 80960CA	No longer supported	
E2411A	Preprocessor interface for Intel 80486	No longer supported	
E2411B	50 MHZ 80486 PREPROCESSOR INTERFACE	No longer supported	
E2411CR	Preprocessor interface for Intel 80486	Currently supported	
E2412AR	Preprocessor Interface for Intel 80860XP	No longer supported	
E2413A	L.A. SUPPORT FOR THE MOTOROLA 68332 EVS	No longer supported	
E2413B	PREPROCESSOR INTFC FOR MOTOROLA 68332	No longer supported	
E2414A	L.A. SUPPORT FOR THE MOTOROLA 68302 EVS	No longer supported	
E2415A	PREPROCESSOR FOR INTEL MCS-51 FAMILY	No longer supported	
E2416A	PREPROCESSOR INTFC FOR INTEL MCS-96	No longer supported	
E2417A	PREPROCESSOR FOR AM29000	No longer supported	
E2418A	Preprocessor for TMS 32020/C25	No longer supported	
E2419A	PREPROCESSOR INTFC FOR MOTOROLA 68HC16Z1	No longer supported	
E2420A	Preprocessor Interface for Motorola 6804	No longer supported	E2459A
E2423AR	SCSI 1 & 2 Preprocessor	No longer supported	
E2424A	68340 Logic Analysis Support	No longer supported	
E2425A	Preprocessor interface for Intel 80960	No longer supported	
E2426AR	Preprocessor interface for Motorola	Currently supported	
E2427AR	Logic analyzer keyboard (HIL) kit	Currently supported	
E2428A	NEC V33 INTERFACE	No longer supported	
E2429A	NEC V53 INTERFACE	No longer supported	
E2430A	MEMORY EXPANSION INTERFACE	No longer supported	
E2431A	TMS 320C30/31 PREPROCESSOR INTERFACE	No longer supported	
E2432AR	Preprocessor Interface for Intel 80960CA	Currently supported	
E2433A	TRAINING KIT FOR 16500-SERIES LOGIC ANAL	No longer supported	
E2433B	TRAINING KIT FOR 1660-SERIES LOGIC ANAL	No longer supported	
E2433C	TRAINING KIT FOR 16500B LOGIC ANAL SYS	No longer supported	aced by E2433E
E2433D	TRAINING KIT FOR 1660-SERIES LOG ANAL	No longer supported	
E2433E	Training Kit for the 16500C Log Anal	No longer supported	
E2435A	INTEL i860XR PREPROCESSOR INTERFACE	No longer supported	
E2436A	Preprocessor Interface for H8/532/4/6	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
E2443A	INTEL P5 PREPROCESSOR INTERFACE	No longer supported	
E2443BR	Intel Pentium CPU Preprocessor interface	Currently supported	
E2446L	1660/16500-SERIES COMMUNICATION PACKAGE	No longer supported	no replacement
E2449A	Inverse Assembler for Mot/IBM PowerPC601	No longer supported	
E2450A	Symbol Utility for Logic Analyzers	No longer supported	
E2452A	Preprocessor Interface for Gmicro300	No longer supported	
E2457AR	Pentium 815/100 (735/90) preprocessor	Currently supported	
E2458A	100VG-AnyLAN Module	No longer supported	
E2459AR	Preprocessor for Motorola 68040/68080	Currently supported	
E2460AA	1663A-TO-1660A UPGRADE KIT	No longer supported	
E2460AB	1662A-TO-1660A UPGRADE KIT	No longer supported	
E2460AC	1661A-TO-1660A UPGRADE KIT	No longer supported	
E2460AS	OSCILLOSCOPE UPGRADE KIT	No longer supported	
E2461AA	1663A-TO-1661A UPGRADE KIT	No longer supported	
E2461AB	1662A-TO-1661A UPGRADE KIT	No longer supported	
E2462AA	1663A-TO-1662A UPGRADE KIT	No longer supported	
E2463A	100VG-AnyLAN Development System	No longer supported	
E2464AR	80960J-series Preprocessor.	Currently supported	
E2466A	E2466A P6 PREPROCESSOR INTERFACE	No longer supported	E2466B
E2466BR	P6 Preprocessor Interface	Currently supported	
E2470A	68HC16Y1 Preprocessor	No longer supported	
E2474A	200 MHz State Analyzer	No longer supported	
E2477A	MPC821/860 Inverse Assembler	Currently supported	
E2478A	Pentium II processor probe head.	Currently supported	
E2478S	Pentium II preprocessor system.	Currently supported	
E2479A	16500A/B to 16500C Upgrade Kit	No longer supported	
E2482A	Motorola ColdFire 5202/03 Preprocessor	No longer supported	
E2485A	16 Channel Memory Expansion Interface	Currently supported	no replacement
E2487A	IA-32 preprocessor module.	No longer supported	
E2488A	16500A/B System Upgrade	No longer supported	
E2490A	Motorola MPC 505/509 Preprocessor	Currently supported	
E2491A	MPC 505 Inverse Assembler	Currently supported	
E2492A	Probe assembly for Intel Pentium II	Currently supported	
E2494A	Pentium II mobile processor	Currently supported	
E2496A	Probe	No longer supported	
E2500A	8791 Model 10 Frequency Agile Signal Sim	No longer supported	http://www.agilent.com/find/psg
E2500BR	8791 Modl 11 Freq Agile Signal Simulator	Currently supported	
E2507AR	MCSS Model 50	No longer supported	
E2534AR	Serial Digital 4:2:2 I/O card for Vidjet	No longer supported	
E2550AR	Quality Advisor QA100	Currently supported	
E2553AR	EDH Inserter EDH10	No longer supported	
E2602A	Digital signal analyzer mainframe	Currently supported	86112A
E2603A	2 channel, 20 GHz bandwidth plug-in	Currently supported	86112A
E2605A	50 GHz, 2 ch module (83484A) for 83480A	No longer supported	83484A
E2606A	50 GHz, 1 ch module (83484B) for 83480A	Currently supported	no replacement
E2630A	Bantam (m) to Bantam (m) Patch Cable	No longer supported	
E2632A	Siemens (m) to Siemens (m) Patch Cable	No longer supported	
E2648A	Cordless Keyboard and Mouse	No longer supported	
E2651A	LAN Upgrade Kit Installed by HP	No longer supported	
E2659AR	Measurement/Connectivity Kit (RS-232)	Currently supported	
E2660A	DCA Mainframe	Currently supported	E2660B
E2661A	DCA Mainframe with Trigger Option	Currently supported	E2661B
E2673A	Single-Ended TDR Module	Currently supported	
E2700A	HP Enterprise Link Software for HP-UX	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
E2700BA	Enterprise Link for HP-UX	No longer supported	no replacement
E2700BU	Elink UX Rev 1.0 to Rev 2.0 Upgrade	Currently supported	no replacement
E2702A	HP Enterprise Link for Windows NT	No longer supported	no replacement
E2702BA	Enterprise Link for Windows NT	No longer supported	no replacement
E2702BU	Elink NT Rev 1.0 to Rev 2.1 Upgrade	No longer supported	no replacement
E2705A	SCL(R) 3.8 TCL Extensions to RTAP on HP	Currently supported	
E2706A	SCL(R) 3.8 TCL Extensions to RTAP on DEC	Currently supported	
E2715AA	HP Vantera Communication Services	No longer supported	no replacement
E2715BA	HP Vantera Communications Services	No longer supported	no replacement
E2716AA	HP Vantera Comm.& Subnet Router Services	No longer supported	no replacement
E2716BA	HP Vantera Comm. and Subnet Router Svcs.	No longer supported	no replacement
E2717AA	HP Vantera Comm. & WAN Router Services	No longer supported	no replacement
E2717BA	HP Vantera Comm. and WAN Router Services	No longer supported	no replacement
E2718AA	HP Vantera Configuration & Admin Tools	No longer supported	no replacement
E2718BA	HP Vantera Configuration and Admin Tools	No longer supported	no replacement
E2720AA	Vantera Application Developer's Toolkit	No longer supported	no replacement
E2720BA	Comm. Svcs Developer's Libraries (NT)	No longer supported	no replacement
E2721AA	HP Vantera Node Application SDK	No longer supported	no replacement
E2725AA	Vantera Cummunications Software CD-ROM	No longer supported	no replacement
E2726AA	Manual Set for Vantera Comms. Services	No longer supported	no replacement
E2742A	Din Rail Mount Kit for I/O Node	No longer supported	no replacement
E2747A	Vector Waveform Generator, dc-6 MHz	Currently supported	no replacement
E2900A	E2900A DATA GENERATOR SYSTEM MAINFR.	Currently supported	
E2900AR	E2900A Data Generator System Mainfr.	No longer supported	
E2901A	E2901A DATA GENERATOR EXPANSION FRAME	Currently supported	
E2902A	E2902A 1 GHz CLOCK/STROBE MODULE	Currently supported	
E2903A	E2903A 1 GHz 4 CHANNEL DATA MODULE	Currently supported	
E2905A	1 GHz clock/strobe module 128kbit	Currently supported	
E2906A	1 GHz data module 128kbit	Currently supported	
E2910AR	PCI Bus Exerciser	Currently supported	
E2911A	5V PCI Adapter for In-system test	Currently supported	no replacement
E2911AR	5V PCI adapter for in-system test	Currently supported	
E2912A	5V Adapter for Stand-alone card test	Currently supported	no replacement
E2912AR	5V Adapter for Stand-alone card test	Currently supported	
E2913A	3.3 V PCI Adapter for In-system test	Currently supported	no replacement
E2914A	3.3 V Adapter for Stand-alone card test	Currently supported	no replacement
E2924A	PCI Host Interface Adapter	Currently supported	E2930B-400
E2925AR	32 Bit, 33MHz PCI Exerciser & Analyzer	Currently supported	
E2931A	32Bit/33MHz PCI Exer./An.Starter Bundle	Currently supported	no replacement
E2932A	32Bit/33MHz PCI Exer./An. Profess.Bundle	Currently supported	no replacement
E2936A	32/64 Bit 33MHz PCI System Debug Bundle	Currently supported	no replacement
E2937A	66 MHz PCI System Validation Package	Currently supported	E2930B-310
E2970A	PCI Analyzer Graphical User Interface	Currently supported	E2929B-100
E2970AR	PCI Analyzer Graphical User Interface	Currently supported	
E2971A	PCI Exerciser Graphical User Interface	Currently supported	E2930B-300
E2971AR	PCI Exerciser Graphical User Interface	Currently supported	
E2972A	PCI Performance Analyzer Software	Currently supported	E2929B-200

Product	Description	Support Status as of 1 May	Replacement Information
E2974A	Sub System Test Software	Currently supported	no replacement
E2975A	PCI Protocol Permutator and Randomizer	Currently supported	E2930B-320
E2979A	SW license for multiple test benches	Currently supported	no replacement
E2999A	S/W media, CD-ROM latest revision	Currently supported	no replacement
E3200A	DSP Engine for MS Windows and VXI	No longer supported	no replacement
E3201A	DSP Engine for HP-UX and VXI	No longer supported	no replacement
E3203A	HP Measurement Engine Family for HP-UX	No longer supported	no replacement
E3205A	HP Run-Only Measurement Engine for HP-UX	No longer supported	no replacement
E3211S	E3211S System Consisting of:	No longer supported	no replacement
E3212A	High Performance Data Recorder/Analyzer	No longer supported	no replacement
E3215A	Distributed Measurement System	Currently supported	no replacement
E3217A	Custom Engineering Units, PL-UG	Currently supported	no replacement
E3220A	Knowledge Transfer (KNOT), Prod Line UM	Currently supported	
E3231A	HP Vantera Discrete I/O Node	No longer supported	no replacement
E3231B	HP Vantera Discrete I/O Node	No longer supported	no replacement
E3232A	HP Vantera Analog/Discrete I/O Node	No longer supported	no replacement
E3232B	HP Vantera Analog/Discrete I/O Node	No longer supported	no replacement
E3235A	IEEE-1451.2 STIM Developer's Starter Kit	No longer supported	no replacement
E3236B	IEC Power Cord	No longer supported	no replacement
E3237A	HP Vantera Serial I/O Node	No longer supported	no replacement
E3238B	Signals Development H/W Bundle HP-UX	Currently supported	E3238S
E3238N	Signals Development H/W Bundle WinNT	Currently supported	E3238S
E3300A	IC-CAP Framework	No longer supported	85199A
E3301A	DC Measurement Drivers	No longer supported	85199D
E3302A	LCRZ Measurement Drivers	No longer supported	85199C
E3303A	AC Measurement Drivers	No longer supported	85199E
E3304A	Time Domain Measurement Drivers	No longer supported	85199F
E3305A	Analysis Module	No longer supported	85199B
E3306A	UCB MOS Model Parameter Extraction	No longer supported	85194H
E3307A	UC Berkeley BSIM 1&2 Extraction Module	No longer supported	85194D
E3308A	Bipolar Model Parameter Extraction	No longer supported	85193A
E3309A	GaAs Model Parameter Extraction	No longer supported	85192A
E3310A	Macromodel Library	No longer supported	no replacement
E3311A	HP TFT Model Parameter Ext.	No longer supported	85194F
E3312A	Poly Silicon TFT Extraction Module	No longer supported	85194G
E3313A	BSIM3 Extraction Module	No longer supported	85194E
E3320A	IC-CAP Manual Set	No longer supported	85190D
E3390S	Characterization System	No longer supported	85190S
E3400A	68020 PGA to 68EC020 PGA Adapter	No longer supported	
E3401A	68020 PGA to 68EC020 PQFP/CQFP Adapter	No longer supported	
E3403A	68020 PGA to PGA Flex Cable	No longer supported	
E3404A	68020 PGA to PQFP/CQFP Adapter	No longer supported	
E3405A	68030 PGA to PGA Flex Cable	No longer supported	
E3406A	68EC030 PGA to PQFP/CQFP Adapter	No longer supported	
E3407A	68331/332 PGA to PQFP/CQFP Adapter	No longer supported	
E3407AR	68331/332 PGA to PQFP/COFP Adapter	Currently supported	
E3408A	68302 PGA to PQFP/CQFP Adapter	No longer supported	
E3409A	68340 PGA to PQFP/CQFP Adapter	No longer supported	
E3410A	68340 PGA to PGA Flex Cable	No longer supported	
E3411A	80960SA/SB PGA to PQFP/CQFP Adapter	No longer supported	
E3412A	80186EA PGA to PQFP Adapter	No longer supported	
E3413A	80186XL PGA to PQFP Adapter	No longer supported	
E3414A	80186EB PGA to PQFP Adapter	No longer supported	
E3415A	Probe Adapter Assembly	No longer supported	

Product	Description	Support Status	Replacement Information
E3416A	Transition Board for use w/ 64782 Emul.	No longer supported	
E3417A	132 Pin QFP to PGA Adapter	Currently supported	
E3418A	68302 PGA Flex Cable	No longer supported	
E3419A	80960SA/SB PLCC Flex Cable	No longer supported	
E3420A	68000 PGA TO PGA Flex Cable	No longer supported	
E3421A	Generic 13x13 Flex Cable	No longer supported	
E3422A	68 Pin PLCC Flex Cable	No longer supported	
E3424A	100 Pin rectangular PGA to PQFP adapter	No longer supported	
E3425A	144 Pin PGA to PQFP Adapter for 68340	No longer supported	
E3426A	15x15 Flex Cable	No longer supported	
E3427A	80186XL PGA Flex Cable	No longer supported	
E3429A	68040 PGA to PGA Flex Cable	No longer supported	
E3430A	68360 PGA to PGA Flex Cable	No longer supported	
E3431A	160 Pin PQFP Adapter	No longer supported	
E3432A	80186/88EC 100 Pin Square QFP Adapter	No longer supported	
E3434A	Adapter Kit	No longer supported	
E3435A	144 pin TQFP Wedge Technology Probe Adpt	No longer supported	
E3436A	100 Pin Wedge Adapter	No longer supported	
E3437A	Adapter Kit	No longer supported	
E3438A	Probe Adapter Assembly	No longer supported	
E3439A	Transition Board used w/ 64746 & E2414B	No longer supported	
E3440A	68040 Low Voltage Adapter	No longer supported	
E3441A	144 pin TQFP Wedge to PGA flex cable	No longer supported	
E3444A	1/4 Flex Adapter	No longer supported	
E3448A	Generic Flex Adapter	No longer supported	
E3449A	GP Flex Adapter	No longer supported	
E3450A	PPC603 Processor Probe Bundle	No longer supported	
E3451A	PPC603E Distributed Emulator Bundle	No longer supported	
E3453A	DO NOT ORDER.	No longer supported	
E3470B	M16C/61 Series emul. Probe with 1Mbyte	Currently supported	
E3470BY	M16C/61 Series Emulation Subsystem	No longer supported	
E3470SY	M16C/60 Subsystem	No longer supported	
E3471B	120 pin flex cable	Currently supported	
E3471C	128 Pin flexible cable	Currently supported	
E3471D	100 Pin flexible cable	Currently supported	
E3471SY	H8S/2000 2655 Series Emul. Subsystem	No longer supported	
E3472B	112 Pin flexible cable	Currently supported	
E3472C	144 Pin flexible cable	Currently supported	
E3472D	SH7040 series Emulation Probe no memory	Currently supported	
E3472DY	SH7040 Series Emulation Subsystem	No longer supported	
E3472SY	SH7040 Series Emulation Subsystem	Currently supported	
E3473B	168 pin Flexible Cable	Currently supported	
E3473SY	SH7050 Emulation Subsystem	Currently supported	
E3477A	PPC603E Processor Probe	No longer supported	
E3480A	IBM OEM Processor Probe	No longer supported	
E3481A	IBM OEM Processor Probe with Trace	No longer supported	
E3482A	PPC603 IBM OEM Processor Probe	No longer supported	
E3483A	IBM OEM Version of PPC 403 N-Trace	No longer supported	
E3484A	IBM OEM	No longer supported	
E3486A	Motorola MPC8260 PowerQuicc II Emul. Prb	No longer supported	
E3491A	PENTIUM PROCESSOR PROBE	No longer supported	
E3491AR	Pentium Processor Probe	No longer supported	
E3492B	Embedded MIPS Processor Probe	No longer supported	
E3493B	P6 Processor Probe	Currently supported	
E3544A	2 * 4:1 Scanner Board	Currently supported	no replacement

Product	Description	Support Status	Replacement Information	
			as of 1 May	
E3611AR	DC Power Supply, 20V/1.5A and 35V/0.85A	Currently supported		
E3614AR	DC Power Supply, 60 Watt, 8V/6A	Currently supported		
E3615AR	DC Power Supply, 60W, 20V/3A	Currently supported		
E3619A	Power Supply Load Leads	Currently supported		
E3631AR	Triple Output DC Power Supply, w/HPIB/RS	Currently supported		
E3646A-AB0	Taiwan Chinese localization	No longer supported		
E3646A-ABD	Germany German localization.	No longer supported		
E3646A-ABE	Spain-Spanish localization	No longer supported		
E3646A-ABF	France-French localization	No longer supported		
E3646A-ABJ	Japan Japanese localization	No longer supported		
E3646A-ABZ	Italy-Italian localization	No longer supported		
E3647A-AB0	Taiwan Chinese localization	No longer supported		
E3647A-AB1	korean Korean localization	No longer supported		
E3647A-ABE	Spain-Spanish localization	No longer supported		
E3647A-ABF	France-French localization	No longer supported		
E3647A-ABJ	JapanJapanese localization	No longer supported		
E3647A-ABZ	Italy-Italian localization	No longer supported		
E3648A-AB1	Korean-Korean localization	No longer supported		
E3648A-AB2	Chinese-PR chinese localization	No longer supported		
E3648A-ABD	Germany-German localization	No longer supported		
E3648A-ABF	FranceFrench localization	No longer supported		
E3648A-ABJ	Japan-Japanese localization	No longer supported		
E3648A-ABO	Taiwan-Chinese localization	No longer supported		
E3648A-ABZ	Italy-Italian localization	No longer supported		
E3649A-AB0	Taiwan-Chinese localization	No longer supported		
E3649A-AB1	Korean-Korean Localization	No longer supported		
E3649A-AB2	Chinese-PR Chinese localization	No longer supported		
E3649A-ABD	Germany-German localization	No longer supported		
E3649A-ABF	France-French localization	No longer supported		
E3649A-ABJ	Japan-Japanese localization	No longer supported		
E3649A-ABZ	Italy-Italian localization	No longer supported		
E3650A	DC POWER SUPPLY TEST SYSTEM	No longer supported	E3650B.	
E3650B	DC power test system reference number	No longer supported	no replacement	
E3651B	PTS Accessories	No longer supported	no replacement	
E3660B-AW3	Rack: 1.1m w/100v/120v NA quartz NOT TO BE HOTLINED	No longer supported	E7590A opt AW3	
E3661B-AW3ND	RACK 1.6 110V PDU WODS DOOR / SIDE PANEL	NO	No longer supported	no replacement
E3661B-AW5ND	RACK 1.6 220V PDU WODS DOOR SIDE PANEL	NO	No longer supported	no replacement
E3660B-AW5	Rack 1.1m 200v/240v Int I quartz TO BE HOTLINED	NOT	No longer supported	E7590A opt AW3
E3661B-AXH	Rack 1.6m bare rack quartz TO BE HOTLINED	NOT	No longer supported	E3661B option AW1
E3661B-ND	Rack 1.6 W/Out Rear Door E Frame Without Rear Door	1.6 M	No longer supported	no replacement
E3662B-AXH	Rack 2.0m bare rack quartz TO BE HOTLINED	NOT	No longer supported	E3662B option AW1
E3662B-AW3ND	RACK 2.0 110V PDU WODS DOOR / SIDE PANEL	NO	No longer supported	no replacement
E3662B-AW3NS	RACK 2.0 110V W/O SIDE		No longer supported	no replacement
E3662B-AW5ND	RACK 2.0 220V PDU WODS DOOR / SIDE PANEL	NO	No longer supported	no replacement
E3662B-AW5NS	RACK 2.0 220V W/O SIDE		No longer supported	no replacement
E3662B-AXH3	Rack 2.0 M Bare W/110V PDU 2.0M E Bare with PDU		No longer supported	no replacement
E3662B-AXH5	Rack 2.0M Bare W/220V PDU M E Bare 220 V INT. PDU	2.0	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
E3662B-ND	Rack 2.0M W/Out Rear Door E Frame without Rear Door	2.0 M No longer supported	no replacement
E3662B-NS	RACK 2.0 W/O SIDE PANEL	No longer supported	no replacement
E3720A	VXI interface connector assembly (V/ICA)	Currently supported	no replacement
E3720AR	VXI interface connector assembly (V/ICA)	Currently supported	
E3721A	VXI interface test adapter (V/ITA)	Currently supported	no replacement
E3730A	VXI interface terminal module (V/ITM)	Currently supported	no replacement
E3790A	Fault Det start-up kit	Currently supported	
E3791A	Functl Test Fault Diag Development SW	Currently supported	
E3792A	Functl Test Fault Diag PC Run-time SW	Currently supported	
E3793A	Fault Detective UNIX Runtime SW	Currently supported	
E3856A	FTS-40 functional test system	No longer supported	no replacement
E3857A	Additional FTS-40 software license	No longer supported	no replacement
E3910CR	PT502 high speed tester base	Currently supported	
E3951A	IPATS layer 1 conformance test system	No longer supported	no replacement
E4095CR	PT500 protocol tester base	Currently supported	
E4100CR	PT540 Four Port Tester Base	Currently supported	
E4136A	DS-7850 M-module Carrier Board	No longer supported	
E4136B	DS-7850 M-module Carrier Board	Currently supported	
E4141A	HP Dynamic Emulation Sys; DesignSpan7850	Currently supported	
E4143A	DesignSpan 78XX Family ECU Test Software	No longer supported	
E4144A	DesignSpan 7850 Core System	No longer supported	
E4144B	DS-7850 Core System -220 volt	Currently supported	
E4147A	DS-7850 4-slot IP-module carrier board	Currently supported	
E4147B	DS-7850 2-slot IP-module carrier board	Currently supported	
E4147C	DS-7850 4-slot IP-module carrier board	Currently supported	
E4148A	DS7850 B-Size 4 Slot Fast Binary Ext	No longer supported	
E4148B	DS-7850 4-slot IP-module carrier	Currently supported	
E4151B	DS-7850 Accessories and cables	Currently supported	
E4151K	DS7850 DUT connector tool kit	No longer supported	
E4152B	DS7850 Cable From BNC To Mass Distr.	Currently supported	
E4152C	DS7850 Cable From E1328 To DIS Mass DIST	Currently supported	
E4152CA	DS-7850 Cable from E1328A to front panel	Currently supported	
E4152F	DS-7850 32channel ADC differential cable	Currently supported	
E4152M	DS7850 Cable From E1346 To DIS MASS Int.	Currently supported	
E4152MA	DS-7850 Cable from E1346A to front panel	Currently supported	
E4152P	DS7850 Cable From E1313 To DIS Mass Int.	Currently supported	
E4152PA	DS-7850 Cable from E1313A to front panel	Currently supported	
E4152Q	DS-7850 32channel ADC differential cable	No longer supported	
E4152S	DS7850 Cable From E1364 To DIS Mass Int.	Currently supported	
E4152SA	DS-7850 Cable from E1364A to front panel	Currently supported	
E4152TA	DS-7850 Cable from E6177A to front panel	Currently supported	
E4200A	Broadband Series Form-7 portable base	No longer supported	E4200B.
E4200AR	Broadband series Form-7 portable base	No longer supported	
E4200-92002	CARD-NAVIGATING THE BSTS	No longer supported	no replacement
E4200-92003	GUIDE-SYS INSTAL & START UP.	No longer supported	no replacement
E4203-92000	USERS GD,PROTOCOL LINE INTERFACE	No longer supported	no replacement
E4202A	2.4Gb/s ATM/POS Analyzer Bundle (1310nm)	No longer supported	

Product	Description	Support Status	Replacement Information
E4202S	2.4Gb/s ATM/POS Analyzer Bundle (1550nm)	No longer supported	
E4203A	155 Mb/s protocol line interface	No longer supported	no replacement
E4203AR	155 MB/s Protocol Line Interface	No longer supported	
E4204AR	HSSI Line interface	Currently supported	
E4205AR	155 Mb/s UTP-5 Line Interface	Currently supported	
E4206AR	T1/E1 Frame Processor	Currently supported	
E4207AR	V interface Frame Processor	Currently supported	
E4208A	VXI SCSI Disk Module	No longer supported	no replacement
E4208AR	VXI SCSI Disk Module	No longer supported	
E4208B	1 GByte SCSI Disk Drive Module	No longer supported	no replacement
E4208-92000	REF GUIDE ENGLISH	No longer supported	no replacement
E4208C	E4208C 2GB VXI SCSI Disk Drive Module	No longer supported	no replacement
E4209A	0-155 Mb/s cell protocol processor	No longer supported	E4209B
E4209AR	0-155 MB/s Cell Protocol Processor	No longer supported	
E4209-92000	REF GD, CELL PROTOCOL PROCESSOR/ENG	No longer supported	no replacement
E4210A	BSTS VXI mainframe base, 13 C-size slots	No longer supported	E4210B.
E4210AR	BSTS VXI mainframe base, 13 C-size slots	No longer supported	
E4211A	SMDS Test Software	Currently supported	
E4211-92000	USER'S GD, SMDS ENGLISH	No longer supported	no replacement
E4211-92001	PROGRAMMER'S GD SMDS ENGLISH	No longer supported	no replacement
E4212A	AAL Test Software	No longer supported	no replacement
E4212U	Upgrade from E4212A	No longer supported	no replacement
E4212-92000	USER'S GD , AAL ENGLISH	No longer supported	no replacement
E4212-92001	PROGRAMMER'S GD, AAL ENGLISH	No longer supported	no replacement
E4213A	SMDS DXI Test Software	Currently supported	
E4213AR	SMDS DXI Test Software.	Currently supported	
E4213B	SMDS DXI Test Software	Currently supported	
E4213B	SMDS DXI Test Software	Currently supported	
E4213BR	SMDS DXI Test Software.	Currently supported	
E4214A	UNI Signalling Test Software	No longer supported	E4214B.
E4214AR	UNI Signalling Test Software	Currently supported	
E4215A	B-ISDN LAN Protocols Test S.W. on CD ROM	No longer supported	E4215B.
E4217A	NNI B-ISUP Signalling Test Software	No longer supported	E4217B.
E4220A	Portable VXI 7 slot housing	No longer supported	E4220B.
E4220B	Transportable VXI 7 Slot Housing BSTS	Currently supported	
E4224A	W-CDMA Test Software	Currently supported	
E4226A	MPEG-2 Protocol Viewer Test SW on flopti	No longer supported	E4226B.
E4226B	MPEG-2 Protocol Viewer Test Software	No longer supported	
E4226B	MPEG-2 Protocol Viewer Test Software	No longer supported	
E4229A	BSTS Software and Documentation Update	No longer supported	
E4229B	HP-UX CD-ROM for E1497A V743 controller	No longer supported	
E4251AR	Measurement cardcage	Currently supported	
E4254AR	Interface processor card	Currently supported	
E4258AR	External communications card	Currently supported	
E4271AR	Bridging isolator (small siemens)	Currently supported	
E4300A	System Reference no.	No longer supported	no replacement
E4301A	Remote Fiber Testing System	No longer supported	no replacement
E4325A	Bundle for 1-channel loss, 1300NM, PC	No longer supported	no replacement
E4326A	Bundle for 1-channel loss, 1550NM, PC	No longer supported	no replacement
E4327A	Bundle for 1-channel loss, 1300NM, bare	No longer supported	no replacement
E4328A	Bundle for 1-channel loss, 1550NM, bare	No longer supported	no replacement
E4329A	Bundle for 2-channel loss, 1300NM, PC	No longer supported	no replacement
E4330A	Bundle for 2-channel loss, 1550NM, PC	No longer supported	no replacement

Product	Description	Support Status	Replacement Information as of 1 May
E4331A	Bundle for 2-channel loss, 1300NM, bare	No longer supported	no replacement
E4332A	Bundle for 2-channel loss, 1550NM, bare	No longer supported	no replacement
E4333A	Bundle for loss/return loss, 1300NM, PC	No longer supported	no replacement
E4334A	Bundle for loss/return loss, 1550NM, PC	No longer supported	no replacement
E4335A	81600 Series 100 system ref. number	No longer supported	no replacement
E4340A	81600 Series 200 EDFA Test System	No longer supported	no replacement
E4340AZ	Non-orderable.For internal purposes only	No longer supported	no replacement
E4341A	81600 Series 210 EDFA Test System	No longer supported	no replacement
E4350A	Solar Array Simulator, 450W	No longer supported	no replacement
E4372A	Charger/Discharger Card	Currently supported	
E4380A	RTAP Server for Windows NT	product family sold	http://www.agilent.com/find/verano
E4381A	RTAP PC Client Services	product family sold	http://www.agilent.com/find/verano
E4383A	RTAP Server SDK for Win NT	product family sold	http://www.agilent.com/find/verano
E4384A	RTAP for Windows NT Manual	product family sold	http://www.agilent.com/find/verano
E4385A	RTAP for Win NT SDK Manual	product family sold	http://www.agilent.com/find/verano
E4386A	RTAP PC Client Manual	product family sold	http://www.agilent.com/find/verano
E4387A	RTAP for Windows NT CD-ROM	product family sold	http://www.agilent.com/find/verano
E4388AA	RTAP/DEC Media Upgrade from 6.4 to 7.0	No longer supported	no replacement
E4388BA	RTAP/DEC 6.4 to 7.0 Right to Copy	No longer supported	no replacement
E4389AA	RTAP/UX Media Upgrade from 6.31 to 6.6	product family sold	http://www.agilent.com/find/verano
E4389BA	RTAP/UX 6.31 to 6.6 Right to Copy	product family sold	http://www.agilent.com/find/verano
E4390AA	RTAP/UX Media Upgrade from 6.31 to 6.7	product family sold	http://www.agilent.com/find/verano
E4390BA	RTAP/UX 6.31 to 6.7 Right to Copy	product family sold	http://www.agilent.com/find/verano
E4391AA	RTAP/UX Media Upgrade from 6.31 to 7.0	No longer supported	no replacement
E4391BA	RTAP/UX 6.31 to 7.0 Upgrade	No longer supported	no replacement
E4392AA	RTAP/UX Media Upgrade from 6.6 to 6.7	product family sold	http://www.agilent.com/find/verano
E4392BA	RTAP/UX 6.6 to 6.7 Right to Copy	product family sold	http://www.agilent.com/find/verano
E4393AA	RTAP/UX Media Upgrade from 6.6 to 7.0	No longer supported	no replacement
E4393BA	RTAP/UX 6.6 to 7.0 Upgrade	No longer supported	no replacement
E4394AA	RTAP/UX Media Upgrade from 6.7 to 7.0	No longer supported	no replacement
E4394BA	RTAP/UX 6.7 to 7.0 Upgrade	No longer supported	no replacement
E4395AA	RTAP/DEC Media Upgrade from 6.4 to 6.6	product family sold	http://www.agilent.com/find/verano
E4395BA	RTAP/DEC 6.4 to 6.6 Right to Copy	product family sold	http://www.agilent.com/find/verano
E4396AA	RTAP/DEC Media Upgrade from 6.4 to 6.7	product family sold	http://www.agilent.com/find/verano
E4396BA	RTAP/DEC 6.4 to 6.7 Right to Copy	product family sold	http://www.agilent.com/find/verano
E4397AA	RTAP/DEC Media Upgrade from 6.6 to 6.7	product family sold	http://www.agilent.com/find/verano
E4397BA	RTAP/DEC 6.6 to 6.7 Right to Copy	product family sold	http://www.agilent.com/find/verano
E4398AA	RTAP/DEC Media Upgrade from 6.6 to 7.0	No longer supported	no replacement
E4398BA	RTAP/DEC 6.6 to 7.0 Upgrade	No longer supported	no replacement
E4399AA	RTAP/DEC Media Upgrade from 6.7 to 7.0	No longer supported	no replacement
E4399BA	RTAP/DEC 6.7 to 7.0 Upgrade	No longer supported	no replacement
E4406V	E4406A VSA/E4431B ESG for BTS test	No longer supported	http://www.agilent.com/find/esg
E4406W	E4406A VSA/E4432B ESG for BTS test	No longer supported	http://www.agilent.com/find/esg
E4406Y	E4406A VSA/E4433B ESG for BTS test	No longer supported	http://www.agilent.com/find/esg
E4413AR	ECP-26A 50MHz to 26.5GHz CW power sensor	Currently supported	
E4430BU	Upgrade E4430A to E4430B 1.0 GHZ sig gen	Currently supported	http://www.agilent.com/find/esg
E4431BU	Upgrade E4431A to E4431B 2.0 GHZ sig gen	Currently supported	http://www.agilent.com/find/esg
E4432BU	Upgrade E4432A to E4432B 3.0 GHZ sig gen	Currently supported	http://www.agilent.com/find/esg
E4433BU	Upgrade E4433A to E4433B 4.0 GHZ sig gen	Currently supported	ESG Signal Generators
E4481A	Instrument Test Manager	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
E4487AR	CERJAC series 31XE DS3/SONET test set	Currently supported	
E4502A	Single 1x17 optical switch	Currently supported	no replacement
E4502AR	Single 1x17 optical switch	Currently supported	
E4503A	Dual 1x8 optical switch	Currently supported	no replacement
E4504A	Dual 1x4 optical switch	Currently supported	no replacement
E4504AR	Dual 1x4 optical switch	Currently supported	
E4563A	Transit case for 37778A	No longer supported	no replacement
E4571A	HS BER upgrades	Currently supported	no replacement
E4574A	Upgrades for 75000 Series 90	No longer supported	no replacement
E4583AR	OC3port handheld ATM Tester,single-mode	No longer supported	
E4584AR	OC3 port Handheld ATM tester, multi-mode	No longer supported	
E4585AR	DS1port Plus Handheld ATM Tester	No longer supported	
E4595AR	CERJAC MTS Lite SONET Maint Test Set	No longer supported	
E4600AD	Series IV Family Documentation	No longer supported	
E4600I	Series IV Internal User Suite	Currently supported	
E4600IS	Support SIV Unix Internal User Suite	Currently supported	
E4600M	Series IV Family Media	Currently supported	
E4600MN	E46xx Series IV Family Media(NLS/X-term)	No longer supported	
E4600MU	E46xx Series IV Family Media Update	No longer supported	
E4600NU	E46xx Series IV Family Media Update	No longer supported	
E4600P	Series IV PC Internal User Suite	Currently supported	
E4600PS	Support Series IV PC Internal User Suite	Currently supported	
E4600R	Return to Current Version Series IV	Currently supported	
E4600S	System Reference for Series IV Products	Currently supported	
E4600U	Agilent University Donation (Series IV)	Currently supported	
E4600UN	Agilent University Donation Ser.IV, NLS	Currently supported	
E4600X	Configured Computer for Series IVprod.	No longer supported	no replacement
E4601A	Series IV Touchstone Design Suite	Currently supported	
E4601AD	Touchstone Design Suite Documentation	No longer supported	E4600AD
E4601AN	Series IV Touchstone Design Suite NLS	Currently supported	
E4601AX	Series IV Touchstone Design Suite	No longer supported	E4601A
E4601DU	Touchstone Documentation Update	No longer supported	
E4601XS	Support Touchstone Design Suite X-Term	No longer supported	E4601AS
E4602A	Series IV Libra Design Suite	Currently supported	
E4602AD	Libra Design Suite Documentation	No longer supported	E4600AD
E4602AN	Series IV Libra Design Suite NLS	Currently supported	
E4602AX	Series IV Libra Design Suite X-Terminal	No longer supported	E4602A
E4602DU	Libra Documentation Update	No longer supported	
E4602XS	Support Libra Design Suite. X-Terminal	No longer supported	E4602AS
E4603A	Series IV J-Omega Design Suite	Currently supported	
E4603AD	J-Omega Design Suite Family Doc.	No longer supported	E4600AD
E4603AN	Series IV J-Omega Design Suite NLS	Currently supported	
E4603AX	Series IV J-Omega Design Suite. X-Term.	No longer supported	
E4603DU	J-Omega Documentation Update	No longer supported	
E4603XS	Support J-Omega Design Suite. X-Terminal	No longer supported	E4603AS
E4604A	Series IV OmniSys Design Suite	Currently supported	
E4604AD	OmniSys Product Family Documentation	No longer supported	E4600AD
E4604AN	Series IV OmniSys Design Suite NLS	Currently supported	
E4604AX	Series IV OmniSys Design Suite. X-Term	No longer supported	E4604A
E4604DU	OmniSys Documentation Update	No longer supported	
E4604S	System Ref.for OmniSys or CDS Products	Currently supported	
E4604XS	Support OmniSys Design Suite X-Terminal	No longer supported	E4604AS
E4605A	Series IV Communications Design Suite	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
E4605AD	Communications Design Suite Family Doc.	No longer supported	E4600AD
E4605AN	SIV Communications Design Suite NLS	Currently supported	
E4605AX	SIV Communications Design Suite. X-Term	No longer supported	E4605A
E4605DU	Communications documentation Update	No longer supported	
E4605XS	Supp. Communications Design Suite X-Term	No longer supported	E4605AS
E4606A	Series IV/PC Touchstone Lite	Currently supported	
E4606AD	Series IV/PC Family Documentation	Currently supported	
E4607A	RFIC Simulation Suite (Series IV)	Currently supported	
E4607AN	RFIC Simulation Suite (Series IV) NLS	Currently supported	
E4610A	SIV Linear Circuit Analysis Test Bench	Currently supported	
E4610AN	SIV Linear Circt Analysis Test Bench NLS	Currently supported	
E4610AX	SIV Linear Circt Analy Test Bench X-Term	No longer supported	E4610A
E4610XS	Supp Linear Circt Analy Test Bench Xterm	No longer supported	E4610AS
E4611A	Nonlinear Simulator	Currently supported	
E4611AN	Nonlinear Simulator NLS	Currently supported	
E4611AX	SIV Nonlinear Circ Analy Test Bench Xtrm	No longer supported	E4611A
E4611XS	Supp SIV Nonlinear Circ Analy Test Bench	No longer supported	E4611AS
E4612A	Frequency-Domain System Simulator	Currently supported	
E4612AN	Frequency-Domain System Simulator NLS	Currently supported	
E4612AX	Series IV Sys Analysis Test Bench X-term	No longer supported	E4612A
E4612XS	Support SIV Sys Analy Test Bench X-term	No longer supported	E4612AS
E4613A	SIV Transient Time Domain Test Bench	Currently supported	
E4613AN	SIV Transient Time Domain Tst Bench NLS	Currently supported	
E4613AX	SIV Transient Time Domain Tst Bench Xtrm	No longer supported	E4613A
E4613XS	Supp SIV Transient Time Doman Tst Bnch	No longer supported	E4613AS
E4614A	Series IV Convolution Test Bench	Currently supported	
E4614AN	Series IV Convolution Test Bench NLS	Currently supported	
E4614AX	Series IV Convolution Test Bench	No longer supported	E4614A
E4614XS	E4614AX Software Support	No longer supported	E4614AS
E4615A	Series IV Electromagnetic Test Bench	No longer supported	85184A
E4615AN	Series IV Electromagnetic Test Bench	No longer supported	85184AN
E4615AS	Support Electromagnetic Test Bench	Currently supported	
E4615AX	Series IV Electromagnetic Test Bench	No longer supported	85184A
E4615NS	Supp Electromagnetic Test Bench NLS	Currently supported	
E4615XS	E4615AX Software Support	No longer supported	E4615AS
E4616A	Series IV Envelope Test Bench	No longer supported	E4618A
E4616AN	Series IV Envelope Test Bench NLS	No longer supported	E4618AN
E4616AS	Support SIV Envelope Test Bench	No longer supported	E4618AS
E4616AX	Series IV Envelope Test Bench	No longer supported	E4618A
E4616NS	Support SIV Envelope Test Bench NLS	No longer supported	E4618NS
E4616XS	E4616AX Software Support	No longer supported	E4618AS
E4617A	Series IV Signal Processing Test Bench	No longer supported	E4636A
E4617AN	SIV Signal Processing Test Bench NLS	No longer supported	E4636AN
E4617AS	Support SIV Signal Processing Test Bench	No longer supported	E4636AS
E4617AX	Series IV Signal Processing Test Bench	No longer supported	E4636A
E4617NS	Supp SIV Signal Processing Tst Bench NLS	No longer supported	E4636NS
E4617XS	E4617AX Software Support	No longer supported	E4636AS

Product	Description	Support Status	Replacement Information
E4618A	Time-Domain System Simulator	Currently supported	
E4618AN	Time-Domain System Simulator NLS	Currently supported	
E4620A	Series IV Stat. Design for Circuits	No longer supported	
E4620AN	Series IV Stat. Design for Circuits	No longer supported	E4632AN
E4620AS	Support Stat. Design for Circuits	No longer supported	E4632AS
E4620AX	Series IV Stat. Design for Circuits	No longer supported	E4632A
E4620NS	Supp Statistical Design for Circuits NLS	No longer supported	E4632NS
E4620XS	E4620AX Software Support	No longer supported	E4632AS
E4621A	Series IV Statistical Design for Sys.	No longer supported	E4632A
E4621AN	SIV Statistical Design for Systems NLS	No longer supported	E4632AN
E4621AS	Support Statistical Design for Sys	No longer supported	E4632AS
E4621AX	Series IV Stat. Design for Systems	No longer supported	E4632A
E4621NS	Support Statistical Design for Sys NLS	No longer supported	E4632NS
E4621XS	E4621AX Software Support	No longer supported	E4632AS
E4622A	Series IV Statistical Design for CDS	No longer supported	E4632A
E4622AN	Series IV Statistical Design for CDS NLS	No longer supported	E3632AN
E4622AS	Support Statistical Design for CDS	No longer supported	E4632AS
E4622AX	Series IV Stat. Design for CDS	No longer supported	E4632A
E4622NS	Support Statistical Design for CDS NLS	No longer supported	E4632NS
E4622XS	E4622AX Software Support	No longer supported	E4632AS
E4623A	SIV Discrete Value Optmztn for Circts	No longer supported	
E4623AN	SIV Discrete Value Optimiztn for Circts	No longer supported	
E4623AS	Supp SIV Discrete Value Optmztn for Crct	No longer supported	
E4623AX	Series IV Discrete Value Opt. for Ckts.	No longer supported	
E4623NS	Supp SIV Discrete Value Optmztn for Crct	No longer supported	
E4623XS	E4623AX Software Support	No longer supported	
E4624A	SIV Discrete Value Optmztn for System	No longer supported	
E4624AN	SIV Discrete Value Optmztn for Sys NLS	No longer supported	
E4624AS	Supp SIV Discrete Value Optmztn for Sys	No longer supported	
E4624AX	Series IV Discrete Value Opt. for Sys.	No longer supported	
E4624NS	Supp SIV Discrete Value Optmztn for Sys	No longer supported	
E4624XS	E4624AX Software Support	No longer supported	
E4625A	SIV Discrete Value Optmztn for CDS	No longer supported	
E4625AN	SIV Discrete Value Optmztn for CDS NLS	No longer supported	
E4625AS	Supp Discrete Value Optmztn for CDS	No longer supported	
E4625AX	Series IV Discrete Value Opt. for CDS	No longer supported	
E4625NS	Supp Discrete Value Optmztn for CDS NLS	No longer supported	
E4625XS	E4625AX Software Support	No longer supported	
E4626A	Series IV Analog Systems Module	No longer supported	
E4626AN	Series IV Analog Systems Module NLS	No longer supported	
E4626AS	Support SIV Analog Systems Module	No longer supported	
E4626AX	Series IV Analog Systems Module	No longer supported	
E4626NS	Support SIV Analog Systems Module NLS	No longer supported	
E4626XS	E4626AX Software Support	No longer supported	
E4627A	Series IV Digital Systems Module	No longer supported	
E4627AN	Series IV Digital Systems Module NLS	No longer supported	
E4627AS	Support SIV Digital Systems Module	No longer supported	
E4627AX	Series IV Digital Systems Module	No longer supported	
E4627NS	Support SIV Digital Systems Module NLS	No longer supported	
E4627XS	E4627AX Software Support	No longer supported	
E4628A	SIV User Defined Models for Circuits	No longer supported	E4638A
E4628AN	SIV User Defined Models for Circuits NLS	No longer supported	E4638AN
E4628AS	Supp SIV User Defined Models for Circts	No longer supported	E4638AS
E4628AX	Series IV Usder Defined Models for Ckts.	No longer supported	E4638A
E4628NS	Supp SIV user Defined Models for Circts	No longer supported	E4638NS
E4628XS	E4628AX Software Support	No longer supported	E4638AS
E4629A	SIV User Defined Models for Systems	No longer supported	E4638A

Product	Description	Support Status as of 1 May	Replacement Information
E4629AN	SIV User Defined Models for Sys. NLS	No longer supported	E4638AN
E4629AS	Supp SIV User Defined Models for Sys	No longer supported	E4638AS
E4629AX	Series IV User Defined Models for Sys.	No longer supported	E4638A
E4629NS	Supp SIV User Defined Models for Sys NLS	No longer supported	E4638NS
E4629XS	E4629AX Software Support	No longer supported	E4638AS
E4630A	Series IV User Defined Models for CDS	No longer supported	E4638A
E4630AN	SIV User Defined Models for CDS NLS	No longer supported	E4638AN
E4630AS	Supp SIV User Defined Models for CDS	No longer supported	E4638AS
E4630AX	Series IV User Defined Models For CDS	No longer supported	E4638A
E4630NS	Supp SIV User Defined Models for CDS NLS	No longer supported	E4638NS
E4630XS	E4630AX Software Support	No longer supported	E4638AS
E4631A	Series IV E-Syn	Currently supported	
E4631AD	E-Syn Documentation	No longer supported	E4600AD
E4631AN	Series IV E-Syn NLS	Currently supported	
E4631AX	Series IV E-Syn	No longer supported	E4631A
E4631DU	E-Syn Documentation Update	No longer supported	
E4631XS	E4631AX Software Support	No longer supported	E4631AS
E4632A	Statistical Design Package	Currently supported	
E4632AN	Statistical Design Package NLS	Currently supported	
E4633A	Series IV RF Element Set	Currently supported	
E4633AN	Series IV RF Element Set NLS	Currently supported	
E4633AX	Series IV RF Element Set	No longer supported	E4633A
E4633XS	E4633AX Software Support	No longer supported	E4633AS
E4634A	Series IV Optical Element Set	Currently supported	
E4634AN	Series IV Optical Element Set NLS	Currently supported	
E4634AS	Supp Series IV Optical Element Set	Currently supported	
E4634AX	Series IV Optical Element Set	No longer supported	E4634A
E4634NS	Supp Series IV Optical Element Set NLS	Currently supported	
E4634XS	E4634AX Software Support	No longer supported	E4634AS
E4635A	Argumens CPW Library	No longer supported	
E4635AD	Argumens CPW Library Paper Documentation	No longer supported	
E4635AN	Argumens CPW Library Paper Doc. NLS	No longer supported	
E4635AS	Supp Argumens CPW Library Paper Doc.	No longer supported	
E4635AX	Argumens CPW Library. X-Terminal.	No longer supported	
E4635NS	Supp Argumens CPW Library Paper Doc NLS	No longer supported	
E4635XS	Argumens CPW Library.	No longer supported	
E4636A	Digital and Math Element Set	Currently supported	
E4636AN	Digital and Math Element Set NLS	Currently supported	
E4636AS	Support Digital & Math Element Set	Currently supported	
E4636NS	Support Digital & Math Element Set NLS	Currently supported	
E4637A	Wireless Antenna & Propagation Elements	Currently supported	
E4637AN	Wireless Antenna&Propagatn Elements NLS	Currently supported	
E4638A	Model Development Kit	Currently supported	
E4638AN	Model Development Kit NLS	Currently supported	
E4640A	Series IV Chip FET Library	No longer supported	E4649A
E4640AN	Series IV Chip FET Library NLS	No longer supported	E4649AN
E4640AS	Support Series IV Chip FET Library	No longer supported	E4649AS
E4640AX	Series IV Chip FET Library	No longer supported	E4649A
E4640NS	Support Series IV Chip FET Library NLS	No longer supported	E4649NS
E4640XS	E4640AX Software Support	No longer supported	E4649AS
E4641A	Series IV Packaged FET Library	No longer supported	E4648A
E4641AN	Series IV Packaged FET Library NLS	No longer supported	E4648AN
E4641AS	Supp Series IV Packaged FET Library	No longer supported	E4648AS
E4641AX	Series IV Packaged FET Library	No longer supported	E4648A

Product	Description	Support Status as of 1 May	Replacement Information
E4641NS	Supp Series IV Packaged FET Library NLS	No longer supported	E4648NS
E4641XS	E4641AX Software Support	No longer supported	E4648AS
E4642A	Series IV Chip BJT Library	No longer supported	E4649A
E4642AN	Support Series IV Chip BJT Library NLS	No longer supported	E4649AN
E4642AS	Support Series IV Chip BJT Library	No longer supported	E4649AS
E4642AX	Series IV Chip BJT Library	No longer supported	E4649A
E4642NS	Support Series IV Chip BJT Library NLS	No longer supported	E4649NS
E4642XS	E464sAX Softwarw Support	No longer supported	E4649AS
E4643A	Series IV Packaged BJT Library	No longer supported	E4648A
E4643AN	Series IV Packaged BJT Library NLS	No longer supported	E4648AN
E4643AS	Supp Series IV Packaged BJT Library	No longer supported	E4648AS
E4643AX	Series IV Packaged BJT Library	No longer supported	E4648A
E4643NS	Supp Series IV Packaged BJT Library NLS	No longer supported	E4648NS
E4643XS	E4643AX Software Support	No longer supported	E4648AS
E4644A	Series IV MOSFET Library	No longer supported	E4648A
E4644AN	Series IV MOSFET Library NLS	No longer supported	E4648AN
E4644AS	Support Series IV MOSFET Library	No longer supported	E4648AS
E4644AX	Series IV MOSFET Library	No longer supported	E4648A
E4644NS	Support Series IV MOSFET Library NLS	No longer supported	E4648NS
E4644XS	E4644AX Software Support	No longer supported	E4648AS
E4645A	Series IV HEMT Library	No longer supported	E4649A
E4645AN	Series IV HEMT Library NLS	No longer supported	E4649AN
E4645AS	Support Series IV HEMT Library	No longer supported	E4649AS
E4645AX	Series IV HEMT Library	No longer supported	E4649A
E4645NS	Support Series IV HEMT Library NLS	No longer supported	E4649NS
E4645XS	E4645AX Software Support	No longer supported	E4649AS
E4646A	Series IV Diode Library	Currently supported	
E4646AN	Series IV Diode Library NLS	Currently supported	
E4646AS	Support Series IV Diode Library	Currently supported	
E4646AX	Series IV Diode Library	No longer supported	E4646A
E4646NS	Support Series IV Diode Library NLS	Currently supported	
E4646XS	S464AX Software Support	No longer supported	E4646AS
E4647A	Series IV Analog Parts Library	Currently supported	
E4647AN	Series IV Analog Parts Library NLS	Currently supported	
E4647AS	Supp Series IV Analog Parts Library	Currently supported	
E4647AX	Series IV Analog Parts Library	No longer supported	E4647A
E4647NS	Supp Series IV Analog Parts Library NLS	Currently supported	
E4647XS	E4647AX Software Support	No longer supported	E4647AS
E4648A	Series IV RF ICs Library	Currently supported	
E4648AN	Series IV RF ICs Library NLS	Currently supported	
E4648AS	Support Series IV RF ICs Library	Currently supported	
E4648AX	Series IV RF ICs Library	No longer supported	E4648A
E4648NS	Support Series IV RF ICs Library NLS	Currently supported	
E4648XS	E4648AX Software Support	No longer supported	E4648AS
E4649A	Passive SMT Library	Currently supported	
E4649AN	Passive SMT Library NLS	Currently supported	
E4649AS	Support Passive SMT Library	Currently supported	
E4649AX	rmries IV Circuit Level SMT Library	No longer supported	E4649A
E4649NS	Support Passive SMT Library NLS	Currently supported	
E4649XS	E4649AX Software Support	No longer supported	E4649AS
E4650A	System Library	Currently supported	
E4650AN	System Library NLS	Currently supported	
E4650AS	Support System Library	Currently supported	
E4650AX	Series IV System Level SMT Library	No longer supported	E4650A
E4650NS	Support System Library NLS	Currently supported	
E4650XS	E4650AX Software Support	No longer supported	E4650AS
E4651A	Series IV TI Foundry	Currently supported	
E4651AN	Series IV TI Foundry NLS	Currently supported	
E4651AX	Series IV TI SMART Library	No longer supported	E4651A

Product	Description	Support Status as of 1 May	Replacement Information
E4651XS	E4651AX Software Support	No longer supported	E4651AS
E4652A	Series IV TriQuint Foundry	Currently supported	
E4652AN	Series IV TriQuint Foundry NLS	Currently supported	
E4652AX	Series IV TriQuint SMART Library	No longer supported	
E4652XS	E4652AX Software Support	No longer supported	
E4653A	Series IV Generic SMART Library	No longer supported	
E4653AN	Series IV Generic SMART Library NLS	No longer supported	
E4653AS	Supp SIV Generic SMART Library	No longer supported	
E4653AX	Series IV Generic SMART Library	No longer supported	
E4653NS	Supp SIV Generic SMART Library NLS	No longer supported	
E4653XS	E4653AX Software Support	No longer supported	
E4654A	Series IV Touchstone Library Package	No longer supported	E4648A & E4649A
E4654AN	Series IV Touchstone Library Package NLS	No longer supported	E4648AN & E4649AN
E4654AS	Supp SIV Touchstone Library Package	No longer supported	E4648AS & E4649AS
E4654AX	Series IV Touchstone Library Package	No longer supported	E4648A & E4649A
E4654NS	Supp SIV touchstone Library Package NLS	No longer supported	E4648NS & E4649NS
E4654XS	E4654AX Software Support	No longer supported	E4648AS & E4649AS
E4655A	Series IV Libra Library Package	No longer supported	E4648A + E4649A
E4655AN	Series IV Libra Library Package NLS	No longer supported	E4648AN + E4649AN
E4655AS	Supp SIV Libra Library Package	No longer supported	E4648AS & E4649AS
E4655AX	SERIES IV LIBRA LIBRARY PACKAGE	No longer supported	E4648A & E4649A
E4655NS	Supp SIV Libra Library Package NLS	No longer supported	E4648NS & E4649NS
E4655XS	E4655AX Software Support	No longer supported	E4648AS & E4649AS
E4656A	Series IV J-Omega Library Package	No longer supported	E4648A & E4649A
E4656AN	Series IV J-Omega Library Package NLS	No longer supported	E4648An & E4649AN
E4656AS	Supp SIV J-Omega Library Package	No longer supported	E4648As & E4649AS
E4656AX	Series IV J-Omega Library Package	No longer supported	E4648A & E4649A
E4656NS	Supp SIV J-Omega Library Package NLS	No longer supported	E4648NS & E4649NS
E4656XS	E4656AX Software Support	No longer supported	E4648AS & E4649AS
E4657A	Series IV Communication Library Pkg.	No longer supported	E4648A & E4649A
E4657AN	Series IV Communication Library Pkg. NLS	No longer supported	E4648AN & E4649AN
E4657AS	Supp SIV Communications Library Pkg	No longer supported	E4648AS & E4649AS
E4657AX	Series IV Communications Library Pkg.	No longer supported	E4648A & E4649A
E4657NS	Supp SIV Communications Library Pkg NLS	No longer supported	E4648NS & E4649NS
E4657XS	E4657AX Software Support	No longer supported	E4648AS & E4649AS
E4658A	RF Transistor Library	Currently supported	
E4658AN	RF Transistor Library NLS	Currently supported	
E4658AS	Support RF Transistor Library	Currently supported	
E4658NS	Support RF Transistor Library NLS	Currently supported	
E4659A	Microwave Transistor Library	Currently supported	
E4659AN	Microwave Transistor Library NLS	Currently supported	
E4659AS	Support Microwave Transistor Library	Currently supported	
E4659NS	Support Microwave Transistor Library NLS	Currently supported	
E4660A	Murata SMT Capacitor Library	Currently supported	
E4660AN	Murata SMT Capacitor Library NLS	Currently supported	
E4660AS	Support Murata SMT Cap Library	Currently supported	
E4660NS	Support Murata SMT Cap Library NLS	Currently supported	
E4665A	Series IV Momentum	Currently supported	
E4665AD	Series IV Momentum Documentation	No longer supported	E4600AD
E4665AN	Series IV Momentum NLS	Currently supported	
E4666A	Visualization for SIV Momentum	Currently supported	
E4666AN	Visualization for SIV Momentum NLS	Currently supported	
E4668A	Series IV Project Design Environment	Currently supported	
E4668AN	Series IV Project Design Environment NLS	Currently supported	
E4669A	Series IV Data Display	Currently supported	
E4669AN	Series IV Data Display NLS	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
E4670A	Series IV Project Design Environment	No longer supported	E4668A & E4669A
E4670AN	Series IV Project Design Environment NLS	No longer supported	E4668AN & E4669AN
E4670AS	Supp SIV Project Design Environment	No longer supported	E4668AS & E4669AS
E4670AX	Series IV Project Design Environment	No longer supported	E4668A & E4669A
E4670NS	Supp SIV Project Design Environment NLS	No longer supported	E4668NS & E4669NS
E4670XS	E4670AX Software Support	No longer supported	E4668AS & E4669AS
E4671A	Series IV Layout	Currently supported	
E4671AN	Series IV Layout NLS	Currently supported	
E4671AX	Series IV Layout	No longer supported	
E4671XS	E4671AX Software Support	No longer supported	
E4672A	Series IV GDS-II Stream Interface	Currently supported	
E4672AN	Series IV GDS-II Stream Interface NLS	Currently supported	
E4673A	Series IV IGES Interface	Currently supported	
E4673AN	Series IV Layout Design Opt. X-Terminal	Currently supported	
E4674A	GDS-II & IGES Package	Currently supported	
E4674AN	Series IV Layout Design Option NLS	Currently supported	
E4674AX	Series IV Layout Design Opt. X-Terminal	No longer supported	E4674A
E4674XS	Support SIV Layout Design Opt X-Terminal	No longer supported	E4674AS
E4675A	SIV MTOOLS Artwork Conversion Software	Currently supported	
E4676A	Mentor Schematic Integration Software	Currently supported	
E4676AN	Mentor Schematic Integration S/W NLS	Currently supported	
E4677A	Mentor Layout Integration Software	Currently supported	
E4677AN	Mentor Layout Integration Software NLS	Currently supported	
E4678A	Series IV IFF Schematic Translator	Currently supported	
E4678AN	Series IV IFF Schematic Translator NLS	Currently supported	
E4679A	Series IV IFF Layout Translator	Currently supported	
E4679AN	Series IV IFF Layout Translator NLS	Currently supported	
E4680A	Series IV Mentor Integration Module	No longer supported	E4676A & E4677A
E4680AN	Series IV Mentor Integration Module	No longer supported	E4676AN & E4677AN
E4680AS	Supp SIV Mentor Integration Module	No longer supported	E4676AS & E4677AS
E4680AX	Series IV Mentor Integration Module	No longer supported	E4676A & E4677A
E4680NS	Supp SIV Mentor Integration Module NLS	No longer supported	E4676NS & E4677NS
E4680XS	E4680AX Software Support	No longer supported	E4676AS & E4677AS
E4681A	Alta SPW Integration Module	Currently supported	
E4681AN	Alta SPW Integration Module NLS	Currently supported	
E4681AS	Support Alta SPW Integration Module	Currently supported	
E4681AX	Series IV Comdisco SPW Int. Module	No longer supported	E4681A
E4681NS	Support Alta SPW Integration Module NLS	Currently supported	
E4681XS	E4681AX Software Support	No longer supported	E4681AS
E4682A	SIV Cadence Dracula Integration Module	No longer supported	
E4682AN	SIV Cadence Dracula Intgratn Module NLS	No longer supported	
E4682AS	Supp SIV Cadence Dracula Integrtn Module	No longer supported	
E4682AX	Series IV Cadence Dracula Int. Module	No longer supported	
E4682NS	Supp SIV Cadence Dracula Integrtn Module	No longer supported	
E4682XS	E4682AX Software Support	No longer supported	
E4683A	Series IV Sonnet Integration Module	No longer supported	
E4683AS	Supp SIV Sonnet Integration Module	No longer supported	
E4684A	Series IV ACS MTOOLS Integration Module	No longer supported	
E4684AS	Supp SIV ACS MTOOLS Integration Module	No longer supported	
E4685A	SIV Applications Program Interface	No longer supported	
E4685AS	Supp SIV Applications Program Interface	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
E4686A	Ser IV SPICE Model Generator Node-locked	Currently supported	
E4686AN	Ser IV SPICE Model Generator NLS version	Currently supported	
E4686AS	Support, SIV SPICE Model Gen. Node-lock	Currently supported	
E4686NS	Support, SIV SPICE Model Generator. NLS	Currently supported	
E4690A	ANACAT (DOS only)	No longer supported	
E4690AS	Support ANACAT (DOS only)	Currently supported	
E4691A	Xtract Engine	No longer supported	
E4691AS	Support Xtract Engine	Currently supported	
E4692A	Xtract MESFET Chip Model	No longer supported	
E4692AS	Support Xtract MESFET Chip Model	Currently supported	
E4693A	Xtract Statz MESFET Model	No longer supported	
E4693AS	Support Xtract Statz MESFET Model	Currently supported	
E4694A	Xtract Curtice MESFET Model	No longer supported	
E4694AS	Support Xtract Curtice MESFET Model	Currently supported	
E4695A	Xtract MESFET Senior Model	No longer supported	
E4695AS	Support Xtract MESFET Senior Model	Currently supported	
E4696A	Xtract BJT Chip Model	No longer supported	
E4696AS	Support Xtract BJT Chip Model	Currently supported	
E4697A	Xtract RF Packaged BJT Model	No longer supported	
E4697AS	Support Xtract RF Packaged BJT Model	Currently supported	
E4698A	Xtract EEs of 3rd Generation MESFET Model	No longer supported	
E4698AS	Supp Xtract EEs of 3rd Gen MESFET Model	Currently supported	
E4699A	Xtract HEMT Model	No longer supported	
E4699AS	Support Xtract HEMT Model	Currently supported	
E4700A	Xtract MOSFET Model	No longer supported	
E4700AS	Support Xtract MOSFET Model	Currently supported	
E4701A	Xtract Engine & Model Package	No longer supported	
E4701AN	Xtract Engine & Model Package NLS	No longer supported	
E4701AS	Support Xtract Engine & Model Package	Currently supported	
E4701AX	Xtract Engine & Model Package	No longer supported	
E4701NS	Supp Xtract Engine & Model Package NLS	Currently supported	
E4701XS	E4701AX Software Support	No longer supported	E4701AS
E4710A	Sonnet em	No longer supported	
E4710AS	E4710A Software Support	No longer supported	no replacement
E4710M	Sonnet Family Media (Node-locked)	No longer supported	
E4710MU	E471x Sonnet Family Media Update	No longer supported	
E4711A	Sonnet xgeom	No longer supported	
E4711AS	E4711A Software Support	No longer supported	no replacement
E4712A	Sonnet emvu	No longer supported	
E4712AS	E4712A Software Support	No longer supported	no replacement
E4713A	Sonnet patvu	No longer supported	
E4713AS	E4713A Software Support	No longer supported	
E4714A	Sonnet em, xgeom and patvu	No longer supported	
E4714AS	E4714A Software Support	No longer supported	no replacement
E4715A	Sonnet em and xgeom	No longer supported	
E4715AS	E4715A Software Support	No longer supported	no replacement
E4716A	Sonnet em, xgeom and emvu	No longer supported	
E4716AS	E4716A Software Support	No longer supported	no replacement
E4717A	Sonnet em, xgeom emvu and patvu	No longer supported	
E4717AS	E4717A Software Support	No longer supported	no replacement
E4720A	MICKknife	No longer supported	
E4720B	Replacement MICKknife Tip	No longer supported	
E4721A	RE-Keying EEs of PC Hardware Key	Currently supported	
E4722A	Transfer Node-locked Prod. to X-Term.	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
E4723A	Series IV Platform Transfer	Currently supported	
E4730A	Touchstone (DOS)	No longer supported	E4740A
E4731A	Touchstone/LineCalc/E-Syn (DOS)	No longer supported	E4730A
E4732A	Touchstone DOS Upgrade	No longer supported	
E4732B	LineCalc DOS upgrade	No longer supported	no replacement
E4733A	Sonnet em/xgoem (1000) (DOS)	No longer supported	
E4734A	Sonnet em/xgeom (full) (DOS)	No longer supported	
E4735A	Sonnet emvu (DOS)	No longer supported	
E4736A	Sonnet patvu (DOS)	No longer supported	
E4740A	Touchstone for Windows	Currently supported	
E4741A	Touchstone Yield Analysis & Optimiztn.	Currently supported	
E4742A	MW/RF Transistor Library (Windows)	Currently supported	
E4743A	Libra for Windows	Currently supported	
E4744A	Libra Yield Analysis & Optimization	Currently supported	
E4745A	Analog Parts Libraries (Windows)	Currently supported	
E4746A	Touchstone for Windows Design Suite	Currently supported	
E4747A	Libra for Windows Design Suite	Currently supported	
E4747U	HP EEsof University Donation (Windows)	Currently supported	
E4748AD	Touchstone & Libra for Windows Doc.	Currently supported	
E4750A	CAD Data Store Service Account Advance	Currently supported	
E4751A	CAD Data Store Service Account Advance	Currently supported	
E4752A	CAD Data Store Service Account Advance	Currently supported	
E4753A	CAD Data Store Service Account Advance	Currently supported	
E4754A	CAD Data Store Service Account Advance	Currently supported	
E4755A	CAD Data Store Service Account Advance	Currently supported	
E4756A	CAD Data Store Service Account Advance	Currently supported	
E4757A	CAD Data Store Service Special	Currently supported	
E4772A-K10	RF & Microwave Entry Level LTP	Currently supported	
E4772A-K27	Interconnect/Signal Integrity HFSS LTP	Currently supported	
E4772AN-K10	RF & Microwave Entry Level LTP	Currently supported	
E4772AN-K27	Interconnect/Signal Integrity HFSS LTP	Currently supported	
E5774A-K01	#NAME?	Currently supported	
E5774AN-K01	DesignGuides LTP	Currently supported	
E4775A	Handset PA ValiFire Software Suite LTP	Currently supported	
E4775AN	Handset PA ValiFire Software Ste. LTP NL	Currently supported	
E4781A	Touchstone to Libra Upgrade	Currently supported	
E4781AN	Touchstone to Libra Upgrade NLS	Currently supported	
E4781NN	Touchstone to Libra Upgrade (Node-NetLS)	Currently supported	
E4782A	Touchstone to J-Omega Upgrade(Node-Node)	Currently supported	
E4782AN	Touchstone to J-Omega Upgrade NLS-NLS	Currently supported	
E4782NN	Touchstone to J-Omega Upgrade(Node-NetL)	Currently supported	
E4783A	Touchstone to CDS Upgrade (Node-Node)	Currently supported	
E4783AN	Touchstone to CDS Upgrade (NetLS-NetLS)	Currently supported	
E4783NN	Touchstone to CDS Upgrade (Node-NetLS)	Currently supported	
E4784A	Touchstone to MDS (mns) Node-Node	Currently supported	
E4784AN	Touchstone to MDS (nms) NetLS-NetLS	Currently supported	
E4784NN	Touchstone to MDS (mns) Node-NetLS	Currently supported	

Product	Description	Support Status	Replacement Information
E4785A	Libra to CDS Upgrade Node-Node	Currently supported	
E4785AN	Libra to CDS Upgrade NetLS-NetLS	Currently supported	
E4785NN	Libra to CDS Upgrade Node-NetLS	Currently supported	
E4786A	Libra to MDS (mns+Impulse) Node-Node	Currently supported	
E4786AN	Libra to MDS(mns+Impulse) NetLS-NetLS	Currently supported	
E4786NN	Libra to MDS(mns+Impulse) Node-NetLS	Currently supported	
E4787A	J-Omega to CDS Upgrade Node-Node	Currently supported	
E4787AN	J-Omega to CDS Upgrade NetLS-NetLS	Currently supported	
E4787NN	J-Omega to CDS Upgrade Node-NetLS	Currently supported	
E4788A	J-Omega to MDS(mns+Impulse) Node-Node	Currently supported	
E4788AN	J-Omega to MDS(mns+Impulse) NetLS-NetLS	Currently supported	
E4788NN	J-Omega to MDS(mns+Impulse) Node-NetLS	Currently supported	
E4789A	MDS (linear) to Libra Upgrade Node-Node	Currently supported	
E4789AN	MDS(linear)to Libra Upgrade NetLS-NetLS	Currently supported	
E4789NN	MDS(linear)to Libra Upgrade Node-NetLS	Currently supported	
E4790A	MDS(linear)to J-Omega Upgr Node-Node	Currently supported	
E4790AN	MDS(linear)to J-Omega Upgr NetLS-NetLS	Currently supported	
E4790NN	MDS(linear)to J-Omega Upgr Node-NetLS	Currently supported	
E4791A	MDS(linear)to CDS Upgrade Node-Node	Currently supported	
E4791AN	MDS(linear)to CDS Upgrade NetLS-NetLS	Currently supported	
E4791NN	MDS(linear)to CDS Upgrade Node-NetLS	Currently supported	
E4792A	Omnisys to CDS Upgrade Node-Node	Currently supported	
E4792AN	Omnisys to CDS Upgrade NetLS-NetLS	Currently supported	
E4792NN	Omnisys to CDS Upgrade Node-NetLS	Currently supported	
E4793A	ANACAT/XTRACT to HF ICCAP Upgrade	Currently supported	
E4793AN	ANACAT/XTRACT to HF ICCAP Upgrade NetLS	Currently supported	
E4794A	Ser IV Momentum for EMTB Owners Nodelock	Currently supported	
E4794AN	Series IV Momentum for EMTB owners NLS	Currently supported	
E4795A	TS Lite to Touchstone Unbundled Upgrade	Currently supported	
E4796A	TS Lite to Touchstone Des Ste Upgrade	Currently supported	
E4800S	System Reference Number	No longer supported	no replacement
E4821A	Parallel cell/traffic gen./analyzer mod.	Currently supported	
E4821AR	Parallel cell/traffic gen./analyzer mod.	Currently supported	
E4822A	8bit ATM/UTOPIA sw license for E4821A	Currently supported	
E4823A	16bit ATM/UTOPIA SW license for E4821A	Currently supported	
E4824A	8/16 bit MultiPHY sw license for E4821A.	Currently supported	
E4829A	Parallel cell/traffic gen./analyzer sys.	Currently supported	E4829B
E4831A	660MHz clock/data generator quote descr!	Currently supported	
E4836A	Two Single-Ended Anal.FEs 660 Msa/s.	No longer supported	
E4837A	Differential analyzer660Msa/s quote desc	Currently supported	
E4840A	81200 small frame. See quote descr.!	Currently supported	
E4842A	Generator front-end 330MHz	Currently supported	
E4843A	Generator 660 Mbit/s RZ/NRZ quote descr.	Currently supported	
E4844A	Single analyzer 660 Msa/s quote descr.	Currently supported	
E4845A	Dual analyzer 660Msa/s see quote descr.	Currently supported	
E4848A	Expander frame for 81200 quote descr.	Currently supported	
E4849A	Mainframe for 81200 see quote descr.	Currently supported	
E4849B	Mainframe for 81200 see quote descr!	Currently supported	
E4853A	Serial Cell Generator/Analyzer	Currently supported	
E4854A	Dual Serial Cell Generator	Currently supported	

Product	Description	Support Status	Replacement Information
E4860A	ParBERT 81250 Entry Bundle	No longer supported	
E4860B	High Speed Entry Bundle	No longer supported	
E4871A	User Software for E4821A and media	No longer supported	
E4871B	User Software for E4821A	Currently supported	
E4872A	User Software for E4853/4A and media	No longer supported	
E4872B	User software for E4859A	Currently supported	
E4876A	40G Fast Track ParBERT SW	No longer supported	
E4885A	UTOPIA level 2 TX POD for E4821A.	Currently supported	
E4886A	UTOPIA level 2 RX POD for E4821A.	Currently supported	
E4889A	Active TTL compatible POD for E4821A	Currently supported	
E4890A	ParBERT MUX/DEMUX Bundle.	Currently supported	
E4891A	High Speed Bundle, 2 Gen./2Ana.1,3 Gb/s.	No longer supported	
E4892A	Hight Speed Bundle, 2Gen./2Ana.2.6 Gb/s.	No longer supported	
E4893A	660 MHz Generators Bundle (8chn)	No longer supported	
E4915A	Crystal Impedance Meter	Currently supported	E5100A
E4915U	Upgrade Kit for E4915A.	No longer supported	no replacement
E4916A	Crystal Impedance /LCR Meter	Currently supported	E5100A
E4916U	Upgrade Kit for E4916A.	Currently supported	E5100A
E4925A	Low-cost LCR meter	Currently supported	4263B
E4925U	Upgrade Kit for the E4925A	No longer supported	no replacement
E5000A	PRML BIT ERROR ANALYZER	No longer supported	no replacement
E5000U	Upgrade kit for the E5000A.	No longer supported	no replacement
E5020A	System Software	No longer supported	no replacement
E5020B	System Software for HP E5021A	No longer supported	no replacement
E5020S	PRML Read/Write Analyzer	No longer supported	no replacement
E5021A	PRML Read/Write Analyzer	No longer supported	no replacement
E5022A	Hard Disk Read/Write Test System	Currently supported	E5022B, E5023A
E5030A	SS & DSP Modules	No longer supported	E5033A and E5034A
E5031A	Write Data Generation Module	No longer supported	no replacement
E5032A	Analog Interface Module	No longer supported	no replacement
E5033A	Synchronous Sampling Module	No longer supported	no replacement
E5034A	DSP Module	No longer supported	no replacement
E5039A	Bit Error Test Module	Currently supported	E5039B
E5050A	Colloid Dielectric Probe	No longer supported	no replacement
E5050AR	Colloid Dielectric Probe	No longer supported	
E5050U	Upgrade Kit for HP E5050A	No longer supported	no replacement
E5060A	B-H/Z ANALYZER	No longer supported	no replacement
E5060U	Upgrade kit for the HP E5060A	No longer supported	no replacement
E5090A	2-Port Transmission/Reflection Test Set	Currently supported	no replacement
E5100U	Upgrade Kit for E5100A/B	Currently supported	no replacement
E5115A	BSTS ATM Traffic Management Test Solut'n	No longer supported	
E5116A	BSTS ATM Signalling Test Station	No longer supported	
E5117A	BSTS 3G Wireless Test Solution	Currently supported	no replacement
E5118A	BSTS Switch-Router test Solution	No longer supported	
E5120A	Interface Pod, DS1/DS3	No longer supported	no replacement
E5120AR	Interface Pod, DS1/DS3.	Currently supported	
E5121A	Interface Pod, E3	No longer supported	no replacement
E5121AR	Interface Pod, E3	Currently supported	
E5122A	Interface Pod, OC-3/STM-1 SM Optical	No longer supported	no replacement
E5122AR	Interface Pod,OC-3/STM-1 SM Optical	Currently supported	
E5123A	Interface Pod STM-1 Electrical (Coax)	No longer supported	no replacement
E5124A	Interface Pod OC-3/STM-1 Optical (SC)	No longer supported	no replacement
E5125A	Interface Pod, E1	No longer supported	no replacement
E5126A	Interface Pod J2 6.3 Mb/s Electrical	No longer supported	no replacement
E5129A	Interface Pod, 25.6Mb/s	Currently supported	no replacement
E5135A	SC to ST Bundle	Currently supported	
E5135A	SC to ST Bundle	Currently supported	
E5136A	SC to FC/PC Bundle	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
E5136A	SC to FC/PC Bundle	Currently supported	
E5138A	ST multimode attenuator kit for E5122A	Currently supported	
E5139A	SC multimode attenuator kit for E5122A	Currently supported	
E5140A	B-ISDN UNI Signaling Test SW for E5200A	No longer supported	no replacement
E5141A	BGP-4 protocol s/w license	No longer supported	E7851B. Equivalent part N
E5142A	OSPF protocol s/w license	No longer supported	E7853A. Equivalent part N
E5143A	IS-IS protocol s/w license	No longer supported	E7856A. Equivalent part N
E5144A	SessionStorm TG s/w license	No longer supported	
E5145A	VB5 Signalling Test Software	No longer supported	no replacement
E5146A	AppStorm Software License	No longer supported	
E5147A	IP Impairment Software License	No longer supported	
E5148A	MPLS (RSVP) protocol SW license	No longer supported	E7857A. Equivalent part N
E5149A	MPLS (LDP/CR-LDP) Protocol SW License	No longer supported	E7858A. Equivalent part N
E5150A	SIP Protocol Software	No longer supported	
E5159A	1 yr sw update, exc conf test suites	No longer supported	no replacement
E5160A	UMTS W-CDMA Software	No longer supported	E5160B. Replaced by newer
E5161A	3G Port Bundle	Currently supported	
E5171A	Optical UNI RSVP Protocol Software	No longer supported	E5171B identical product.
E5180A	Broadband Launch Pad V1.0	No longer supported	no replacement
E5190A	Broadband Series UPE Conversion Toolkit	No longer supported	no replacement
E5200A	Broadband Service Analyzer	Currently supported	no replacement
E5200AR	Broadband Service Analyzer	Currently supported	
E5203A	OC-192c/STM-64c BER Test Module (1550nm)	Currently supported	
E5204A	OC-48c/STM-16c BER Test Module (1310nm)	Currently supported	no replacement
E5205A	OC-12c/STM-4c BER Test Module	Currently supported	no replacement
E5206A	OC-3c/STM-1 BER Test Module	Currently supported	no replacement
E5207A	OC-48c/STM-16c BER Test Module (850nm)	No longer supported	
E5212A	OC-192c/STM-64c BER Test Module (VSR)	Currently supported	
E5213A	OC-192c/STM-64c BER Test Module (1310nm)	Currently supported	
E5315A	240 pin PQFP Probe	No longer supported	
E5316A	Flexible adapter	No longer supported	
E5317A	240 pin PQFP adapter for 68360	No longer supported	
E5318A	208 pin PQFP probe.	No longer supported	
E5319A	160 pin PQFP probe.	No longer supported	
E5320A	MultiProbe,9-to-2, General-Purpose Pod	No longer supported	
E5321A	MultiProbe 240-to-2 High-Density Pod	No longer supported	
E5322A	Multiprobe 208-to-2 High-Density Pod	No longer supported	
E5330A	Rigid Adapter	No longer supported	
E5331A	304 pin PQFP Probe	No longer supported	
E5333A	Flexible Adapter for E5331A	No longer supported	
E5335A	160 pin PQFP adapter for 68F333/336.	No longer supported	
E5342A	Flexible Adapter Cable	Currently supported	
E5343A	184 Pin PQFP Probe	No longer supported	
E5344A	208 Pin PQFP Adapter for 80486	No longer supported	
E5345A	68040 Adapter	No longer supported	
E5346B	E5346B	No longer supported	
E5347A	Probe Adapter Kit	No longer supported	
E5352A	Transition Board for the 486SXSf	Currently supported	
E5353A	Probing Adapter Kit	Currently supported	
E5356A	Probing Adapter Kit for 64798F 68LC302	No longer supported	
E5357A	Emulator Adapter Kit for HP 64751A	No longer supported	
E5358A	Transition Board used w/ 64751 & E2424B	No longer supported	
E5359A	Probing Kit for 144p .5mm TQFP	Currently supported	

Product	Description	Support Status	Replacement Information
E5360A	Transition Board for the 64782J	No longer supported	
E5365A	Tip Network Adapter for E2474A	Currently supported	
E5367A	PGA adapter kit for use with the 64798C	No longer supported	
E5368A	100 pin 0.5 TQFP Elastomeric Probe	No longer supported	
E5369A	1/4 Flexible Adapter for use with E5368A	No longer supported	
E5400A	TestBook 5000 Computer	No longer supported	
E5470A	Signal simulation system	Currently supported	no replacement
E5515A	8960 Series 10 Wireless Comm Test Set	Currently supported	E5515C
E5515AU	Upgrades for the 8960 E5515A mainframe	No longer supported	no replacement
E5515T	8960 Series 10 IS-2000 Test Set	Currently supported	E5515C
E5527A	Controller Module	No longer supported	no replacement
E5529A	Alarm Relay Module	No longer supported	no replacement
E5530A	Filler Panel	No longer supported	no replacement
E5544A	OTDR 1310 nm Medium Performance	No longer supported	no replacement
E5551A	OTDR 1625 nm Medium Performance	No longer supported	no replacement
E5570A	Main Software License	Currently supported	no replacement
E5572A	Local Access Laptop Package	No longer supported	no replacement
E5574A	Optical Loss Analyzer	Currently supported	no replacement
E5579A	ATM Forum UNI 3.1 Test Suite SW Pkg.	No longer supported	E7830A, E7831A, E7832A, E
E5580A	ATM Forum UNI 3.0 Test Suite SW Pkg.	No longer supported	E7820A, E7821A, E7822A, E
E5581A	ATM Layer European Test Suite SW Pkg.	No longer supported	no replacement
E5583A	Bellcore Network Protocol Test Suite	No longer supported	no replacement
E5588A	TTCN Checker/Editor for PCs	No longer supported	no replacement
E5589B	One Year Support for 1 user of E5593B	No longer supported	E5593S #002.
E5593B	Broadband TTCN Tools 1 User License	No longer supported	E7310A #BST.
E5593C	TTCN Tools for HP9000 Series 700	No longer supported	E7310A #HPW.
E5593S	1 year support for 1 user for E5593A/B/C	No longer supported	E7310S.
E5600AN	DesignGuide Developers Studio (NLS)	Currently supported	
E5600AS	Support DsgnGde Developers Studio	Currently supported	
E5600NN	DsgnGuide Developers Studio Node-to-NLS	Currently supported	
E5600NS	Support DsgnGde Dev Studio (NLS)	Currently supported	
E5700A	Handset PA ValiFire System (nodelocked)	Currently supported	
E5700AN	Handset PA ValiFire System (networked)	Currently supported	
E5700AS	Upgrades and support for E5700A	Currently supported	
E5700NN	Handset PA ValiFire System Node-to-NLS	Currently supported	
E5700NS	Upgrades and support for E5700AN	Currently supported	
E5700S	Handset PA ValiFire System Reference	Currently supported	
E5710A	PA Design Director Software (nodelocked)	Currently supported	
E5710AN	PA Design Director Software (networked)	Currently supported	
E5710AS	Upgrades and support for E5710A	Currently supported	
E5710NN	PA Design Director Node-to-NLS	Currently supported	
E5710NS	Upgrades and support for E5710AN	Currently supported	
E5711A	Handset PA ValiFire EDGE SW Suite (node)	Currently supported	
E5711AN	Handset PA ValiFire EDGE SW Suite (NLS)	Currently supported	
E5711AS	Upgrades and support for E5711A	Currently supported	
E5711NN	Handset PA ValiFire EDGE SW Suite Node	Currently supported	
E5711NS	Upgrades and support for E5711AN	Currently supported	
E5712A	Handset PA ValiFire 3GPP SW Suite (node)	Currently supported	
E5712AN	Handset PA ValiFire 3GPP SW Suite (NLS)	Currently supported	
E5712AS	Upgrades and support for E5712A	Currently supported	
E5712NN	Handset PA ValiFire 3GPP SW Ste. Node-to	Currently supported	
E5712NS	Upgrades and support for E5712AN	Currently supported	

Product	Description	Support Status	Replacement Information
E5730A	Handset PA ValiFire Hardware Suite	Currently supported	
E5750A	Instrument Software Development Kit	No longer supported	
E5780A	Touchstone for Windows Upgrade	Currently supported	
E5781A	Touchstone for Windows Upgrade	Currently supported	
E5782A	Libra for Windows Design Suite Upgrade	Currently supported	
E5783A	Libra for Windows Upgrade	Currently supported	
E5784A	Touchstone to Libra for Windows Upgrade	Currently supported	
E5785A	Touchstone to Libra Design Suite Upgrade	Currently supported	
E5786A	LineCalc/DOS	No longer supported	
E5787A	E-Syn/DOS	No longer supported	
E5788A	TS/DOS to Touchstone for Windows Upgrade	Currently supported	
E5789A	TS/DOS to Touchstone Design Ste. Upgrade	Currently supported	
E5790A	TS/DOS to Libra for Windows Upgrade	Currently supported	
E5791A	TS/DOS to Libra Design Suite Upgrade	Currently supported	
E5792A	TS2ACAD Netlist to DXF Converter	Currently supported	
E5793A	Advanced Schematic Version 3.3	Currently supported	
E5794A	TS/Windows to Touchstone Lite Upgrade	Currently supported	
E5795A	TS-DS/Windows to Touchstone Lite Upgrade	Currently supported	
E5796A	TS-DS/Windows to Touchstone DS Upgrade	Currently supported	
E5797A	Libra/Windows to Libra DS Upgrade	Currently supported	
E5797B	Libra/Windows to J-Omega DS Upgrade	Currently supported	
E5798A	Libra-DS/Windows to Libra DS Upgrade	Currently supported	
E5798B	Libra-DS/Windows to J-Omega DS Upgrade	Currently supported	
E5970AR	Optical Power meter 800-1600nm	Currently supported	
E5972A	LED Source 1300nm	No longer supported	Related - N3974A
E5974AR	Dual Laser Source 1310/1550nm	Currently supported	
E6008A	1310/1550nm 40/39dB SM laser module	No longer supported	E6008B
E6110A	Remote Management Card for NT-Server	Currently supported	no replacement
E6115A	Remote Management Card for Server	No longer supported	deliveries of E6110A.
E6120A	Accessory Remote Management Card	No longer supported	deliveries of E6110A.
E6121A	RMC Evaluation Kit	Currently supported	no replacement
E6130A	Battery Module for Remote Mgmt.Card	Currently supported	no replacement
E6170A	HP TS-5450 Test System	No longer supported	E8786B
E6170B	TS-5450 Test System	Currently supported	E8786B
E6170G	TS-5450 Upgrade	Currently supported	E8786B
E6178A	8-Channel 30 Amp Load Card	No longer supported	E8786B
E6181A	E1328A DAC 4-ch + E1403B Adapter	Currently supported	E8786B
E6183A	E1429A Digitizer	No longer supported	8786B
E6185A	Additional System Load Box	Currently supported	E8786B
E6186A	6628A/908 Power Supply	No longer supported	E8786B
E6190A	Additional VXI Card Cage	No longer supported	E8786B
E6190B	Additional E1401B VXI Mainframe	Currently supported	E8786B
E6192A	TS-5000 Family Systems Spare Parts Kit	Currently supported	E8786B
E6195A	TS5400 Series I/II Test Action Dev Lic	No longer supported	E8786B
E6195B	TS-5400 Series I/II Test Action Dev Lic	Currently supported	E8786B
E6200A	Fixture Base	No longer supported	E8786B
E6202A	Instrument Fixture Block	No longer supported	E8786B
E6204A	Wires for Instrument Fixture Block	No longer supported	E8786B
E6205A	High Power Fixture Block	No longer supported	E8786B
E6206A	Wires for High Power Fixture Block	No longer supported	E8786B
E6207A	Blanks	No longer supported	E8786B
E6208A	Power Contacts	No longer supported	E8786B
E6209A	Housing for Receptacle Contact	No longer supported	E8786B
E6210A	Cable Hood	No longer supported	E8786B
E6211A	Receptacle Contacts	No longer supported	E8786B

Product	Description	Support Status as of 1 May	Replacement Information
E6212A	Crimp Tool Kit	No longer supported	E8786B
E6213A	Extracting Tool Kit	No longer supported	E8786B
E6227A	Customer Focused Solution Sets	Currently supported	no replacement
E6228A	Customer Focused Solution Sets	Currently supported	no replacement
E6229A	TS-5430 Accessories	No longer supported	N4041A/N4042A GS-8000
E6230A	TS-5430 Base System	No longer supported	E8780B
E6230B	TS-5430 Test System	Currently supported	E8780B
E6231A	6-slot to 13-slot conversion	No longer supported	
E6232AR	VXI Pentium PC Controller-WIN95/133MHz	No longer supported	
E6233A	VXI Pentium PC Controller WinNT/166MHz	No longer supported	no replacement
E6233AR	VXI Pentium PC Controller-WinNT/166MHz.	Currently supported	
E6236A	6654A Power supply	Currently supported	E8786B
E6241A	TS-5400 User Supplied ICA Connector Kit	Currently supported	E8786B
E6245A	16MB Add-on RAM for E6232/33/34/35/37	Currently supported	no replacement
E6246A	32MB Add-on RAM for E6232/33/34/35/37	No longer supported	no replacement
E6272A	LAN Emulation Protocol Viewer on CD ROM	No longer supported	E6272B
E6272B	LAN Emulation Test Software	No longer supported	
E6273A	ILMI Protocol Viewer on CD ROM	No longer supported	E6273B
E6275A	FUNI Test Software	No longer supported	
E6275A	FUNI Test Software	No longer supported	
E6276A	MPEGscope DVB	No longer supported	E6277A.
E6276AR	MPEGscope DVB	No longer supported	
E6277A	MPEGscope Plus	No longer supported	E6277B
E6277B	MPEGscope Plus	Currently supported	E6277C
E6277C	MPEGscope Plus	Currently supported	
E6278A	Frame Relay SVC Protocol Viewer	No longer supported	
E6278A	Frame Relay SVC Protocol Viewer	No longer supported	
E6279A	Frame Relay over HSSI Test Software	No longer supported	
E6279A	Frame Relay over HSSI Test Software	No longer supported	
E6280A	PNNI Test Software	No longer supported	no replacement
E6285A	Encoder Stress Test Patterns	No longer supported	no replacement
E6288A	MPEG Decoder Compliance Bitstreams on CD	No longer supported	no replacement
E6289A	ARIB Int'face Adapter for MPEGscope Plus	Currently supported	
E6290A	PerfecTV decode SW for MPEGscope Plus	No longer supported	no replacement
E6291A	ASI and Serial ECL (DHEI) Interface	No longer supported	
E6292A	SMPTE310M Interface for MPEGscope	Currently supported	
E6293A	IEEE 1394 Interface for MPEGscope	Currently supported	
E6295A	Transit Case for MPEGscope Plus Monitor	Currently supported	
E6296A	Transit Case for MPEGscope Plus Chassis	Currently supported	
E6297A	Hard Transit case for MPEGscope Portable	Currently supported	
E6299A	One-Time SW Update Kit for the E6277A/B	No longer supported	
E6300A	MPEGscope portable	Currently supported	
E6301A	MPEGscope Lite	Currently supported	
E6302A	MPEGscope Portable Lite	Currently supported	
E6305A	24GB External DAT Drive for MPEGscope	Currently supported	no replacement
E6306A	72 Gb/s capture hard drive for MPEGscope	Currently supported	
E6307A	Add CD-RW for MPEGscope	Currently supported	
E6309A	Audio Elementary Stream Analyzer	No longer supported	
E6310A	Video Elementary Stream Analyzer	No longer supported	

Product	Description	Support Status	Replacement Information
E6311A	Basic MPEG/DVB Compliance Verifier	No longer supported	
E6312A	Advanced MPEG/DVB Compliance Verifier	No longer supported	
E6313A	Upgrade to Advanced Compliance Verifier	No longer supported	
E6314A	ISDB Multiplex Software for MPEGscope	No longer supported	
E6315A	DSM-CC Software License Package	No longer supported	
E6325AR	T1 Test Advisor used with customer PC	Currently supported	
E6327AR	T1 Test Advisor(rugged),PC not included.	Currently supported	
E6334AR	T1 Test Advisor integrated w/PC	Currently supported	
E6358AR	DS3port Plus	No longer supported	
E6390A	PDC Signaling Tester	Currently supported	no replacement
E6391A	PDC 1.5GHz Signaling Tester	Currently supported	no replacement
E6449A	Custom accessory family for VXI comp.	Currently supported	no replacement
E6490Q	VXI switch matrix module	No longer supported	E6490A,B,C,D
E7290A	SMDS/CBDS Service over ATM Interop. TS	No longer supported	no replacement
E7293A	ATM Forum LANE 1.0 Service Testing ETS	No longer supported	
E7293B	ATMF LANE 1.0 Compl. Service Testing ETS	Currently supported	E7826A.
E7300A	QA Robot System Qstation OS license	Currently supported	high performance E7300B
E7300B	QA Robot (700MHz)CPU Pentium-3256MB RAM	Currently supported	E7300C
E7303A	OC3 ATM I/F card Single Port, 7PVCs	Currently supported	no replacement
E7304A	OC3 ATM I/F card Single Port, 54 PVCs	Currently supported	E7304B.
E7304B	155 Mb/s ATM I/F Card Single Port	Currently supported	
E7305A	Serial I/F card Dual Port, FR/PPP	No longer supported	
E7307A	622 Mb/s ATM I/F Card Single Port	Currently supported	
E7308A	OC12 POS I/F card Single port	Currently supported	
E7309A	OC48 POS I/F Card Single Port	Currently supported	
E7310S	1 year support for 1 user for E7310A	No longer supported	
E7311A	Protocol Test Execution Manager	No longer supported	no replacement
E7311S	1 year support for 1 user of E7311A	No longer supported	no replacement
E7312A	Protocol Test Automation Manager	No longer supported	no replacement
E7312S	1 year support for 1 user of E7312A	No longer supported	no replacement
E7313S	1 year support of HP-ITEX TTCN Editor	No longer supported	
E7328A.	Run Time Code to control add. Testers	No longer supported	no replacement
E7329A	Test Manager API	Currently supported	no replacement
E7416A	E7416A add-on modules	Currently supported	no replacement
E7500A	VXI Stimulus Subsystem	No longer supported	no replacement
E7501A	Arbitrary Analog Signal Generation Syst	No longer supported	http://www.agilent.com/find/psg
E7555A	7555A 36MHz Noise Defining filter	No longer supported	no replacement
E7556A	E7556A 44MHz Noise Defining filter	No longer supported	no replacement
E7686A	PDU Installation kit w/o bezel	No longer supported	E7685A
E7815A	ISDN CTR3 BRA TE Conformance Test Suite	No longer supported	no replacement
E7816A	ISDN CTR4 PRA TE Conformance Test Suite	No longer supported	no replacement
E7820A	ATMF UNI 3.0 ATM Layer CTS for Int. Sys.	Currently supported	
E7820A	ATMF UNI 3.0 ATM Layer CTS for Int. Sys.	Currently supported	
E7821A	ATMF UNI 3.0 Interop. TS for Int. Sys.	Currently supported	
E7821A	ATMF UNI 3.0 Interop. TS for Int. Sys.	Currently supported	
E7822A	ATMF UNI 3.0 ATM Layer CTS for End Sys.	Currently supported	
E7822A	ATMF UNI 3.0 ATM Layer CTS for End Sys.	Currently supported	
E7823A	ATMF UNI 3.0 Signal. CTS for Net. Side	Currently supported	
E7823A	ATMF UNI 3.0 Signal. CTS for Net. Side	Currently supported	

Product	Description	Support Status	Replacement Information
E7830A	ATMF UNI 3.1 ATM Layer CTS for Int. Sys.	Currently supported	
E7830A	ATMF UNI 3.1 ATM Layer CTS for Int. Sys.	Currently supported	
E7831A	ATMF UNI 3.1 Interop. TS for Int. Sys.	Currently supported	
E7831A	ATMF UNI 3.1 Interop. TS for Int. Sys.	Currently supported	
E7832A	ATMF UNI 3.1 ATM Layer CTS for End Sys.	Currently supported	
E7832A	ATMF UNI 3.1 ATM Layer CTS for End Sys.	Currently supported	
E7833A	ATMF UNI 3.1 Core Signal. CTS Net. Side	Currently supported	
E7833A	ATMF UNI 3.1 Core Signal. CTS Net. Side	Currently supported	
E7833B	ATMF UNI 3.1 Compl. Signa. CTS Net. Side	No longer supported	E7833C.
E7833C	ATMF UNI 3.1 Compl. Signa. CTS Net. Side	Currently supported	
E7833C	ATMF UNI 3.1 Compl. Signa. CTS Net. Side	Currently supported	
E7834A	ATMF UNI 3.1 Core Signal. CTS User Side	Currently supported	
E7834A	ATMF UNI 3.1 Core Signal. CTS User Side	Currently supported	
E7838A	ATMF PNNI Point to Point Signalling CTS	Currently supported	no replacement
E7840A	Bellcore FR/ATM Interworking Test Suite	Currently supported	
E7840A	Bellcore FR/ATM Interworking Test Suite	Currently supported	
E7842A	ATMF UNI 3.x ILMI Addr.Reg.TS User Side	Currently supported	
E7842A	ATMF UNI 3.x ILMI Addr.Reg.TS User Side	Currently supported	
E7843A	ATMF UNI 3.x ILMI Addr.Reg. TS Net.Side	Currently supported	
E7843A	ATMF UNI 3.x ILMI Addr.Reg. TS Net.Side	Currently supported	
E7843A	ATMF UNI 3.x ILMI Addr.Reg. TS Net.Side	Currently supported	
E7844A	ATMF UNI 4.0 Core Signal. CTS Net. Side	Currently supported	
E7844A	ATMF UNI 4.0 Core Signal. CTS Net. Side	Currently supported	
E7845A	ATMF UNI 4.0 Core Signal. CTS User Side	Currently supported	
E7845A	ATMF UNI 4.0 Core Signal. CTS User Side	Currently supported	
E7851A	RouterTester BGP-4 Emulation Software	No longer supported	E7851B.
E7854A	RouterTester MPLS Perf. Test SW License	No longer supported	E7850A.
E7869A	SIP Conformance Test Suite	No longer supported	
E7890A	RouterTester System Controller	No longer supported	
E7890-10300	Kayak XU 800 (D8022N) Win2K upgrade kit	No longer supported	E7890-10500
E7890-10301	Kayak XU 750 (D6348N) Win2K upgrade kit	No longer supported	E7890-10501
E7890-10302	XU 800 (D8010N/D8012N) Win2K upgrade kit	No longer supported	E7890-10502
E7891A	(HP) Laptop System Controller	Currently supported	E7891B
E7891-10302	OM 6000 (F2182K) Win2K upgrade kit	No longer supported	
E7891-10303	OM 6000 (F2182K) Win2K upgrade kit	No longer supported	
E7892A	High Perf. (HP) Rackmount Controller	Currently supported	E7892B
E7893A	(HP) Rackmount System Controller	Currently supported	E7893B
E7899A	Software Enhancement Service (SES)	No longer supported	E7899B
	Media		

Product	Description	Support Status as of 1 May	Replacement Information
E7901A	RouterTester P48/2 Test Module	Currently supported	http://www.agilent.com/find/routertester
E7901-69015	Calibration for E7901A, 02, 04, 05, 14	No longer supported	
E8021A	Kit to convert 16700A to 16702A	No longer supported	no replacement
E8034A	IA32 603pin Analysis Probe	No longer supported	
E8035A	PPGA 370S Interposer Probe	No longer supported	
E8123A	Motorola 68360 PQFP 240p Preprocessor	No longer supported	
E8285ART	Hardware Retrofit Kits for E8285A	No longer supported	no replacement
E8293A	GSM/DCS/PCS PoST Software for 8922	No longer supported	no replacement
E8394A	Std Rack Mnt Kit for 13-Slot Mainframes	Currently supported	E8400-60003
E8395A	Air Filter Kit for 13-Slot Mainframes	Currently supported	no replacement
E8396A	E8408A Carrying Strap & Accessory Pouch	No longer supported	no replacement
E8400A	13-slot, C-size VXI Mainframe	Currently supported	E8401A or E8403A.
E8431A	TS-5531 Mobile Phone Test System	Currently supported	
E8432A	TS-5532 Mobile Phone Test System	Currently supported	
E8452A	TS-5552 Mobile Phone Test System	Currently supported	
E8453A	TS-5553 Mobile Phone Test System	Currently supported	
E8454A	TS-5554 Mobile Phone Test System	Currently supported	
E8460AR	256-Channel Relay Multiplexer	Currently supported	
E8603A	HP Design Span 7670 Calibration Exec SW	Currently supported	
E8636A	HP Design Span 7470 APE S/W	Currently supported	
E8700A	40W Dynamic Measurement DC Source	Currently supported	663xx series
E8701A	Dual 40W Dynamic Measurement DC Source	Currently supported	663xx series
E8702A	100W Dynamic Measurement DC Source	Currently supported	663xx series
E8705A	TS-50 Final Test Fixture	No longer supported	
E8706A	TS-50 Board Test Fixture	No longer supported	E8421A
E8709A	GSM/8960 Test Set for TS-5500	No longer supported	E5515C
E8709B	GSM/8960B Test Set for TS-5500	Currently supported	
E8710A	GSM Test Set for TS-5500	Currently supported	
E8711A	GSM / PCS Test Set for TS-5500	Currently supported	
E8712A	CDMA Test Set for TS-5500	Currently supported	
E8713A	CDMA / PCS Test Set for TS-5500	Currently supported	E5515C
E8713B	CDMA/PCS/E8285A Test Set for TS-5500	Currently supported	
E8714A	TDMA Test Set for TS-5500	No longer supported	E5515C
E8715A	TDMA Test Set for TS-5500	No longer supported	E5515C
E8716A	Analog MS Test Set for TS-5500	No longer supported	
E8785A	TS-5400 Series II; Large Pin-Count	Currently supported	E8786B
E8789A	TS-5400 System Controller/SW Upgrade	No longer supported	E8786B
E8790A	Programming Station	No longer supported	E2235A
E8821AD	ADS DSP Documentation Set	Currently supported	
E8830A	DSP Synthesis PC Verilog	Currently supported	
E8830AN	DSP Synthesis PC Verilog NLS	Currently supported	
E8830AS	Support DSP Synthesis PC Verilog	Currently supported	
E8830NN	DSP Synthesis PC Verilog Node-to-NLS	Currently supported	
E8830NS	Support DSP Synthesis PC Verilog NLS	No longer supported	
E8831A	DSP Synthesis UNIX VHDL	Currently supported	
E8831AN	DSP Synthesis UNIX VHDL NLS	Currently supported	
E8831AS	Support DSP Synthesis UNIX VHDL	Currently supported	
E8831NN	DSP Synthesis UNIX VHDL Node-to-NLS	Currently supported	
E8831NS	Support DSP Synthesis UNIX VHDL NLS	Currently supported	
E8832A	DSP Synthesis UNIX Verilog	Currently supported	
E8832AN	DSP Synthesis UNIX Verilog NLS	Currently supported	
E8832AS	Support DSP Synthesis UNIX Verilog	Currently supported	
E8832NN	DSP Synthesis UNIX Verilog Node-to-NLS	Currently supported	
E8832NS	Support DSP Synthesis UNIX Verilog NLS	Currently supported	
E8835A	Verilog Models/Code Generation	Currently supported	
E8835AN	Verilog Models/Code Generation NLS	Currently supported	
E8835AS	Support Verilog Models/Code Generation	Currently supported	

Product	Description	Support Status	Replacement Information as of 1 May
E8835NN	Verilog Models/Code Generat.Node-to-NLS	Currently supported	
E8835NS	Supp Verilog Models/Code Generation NLS	Currently supported	
E8836A	Synthesis Engine	Currently supported	
E8836AN	Synthesis Engine NLS	Currently supported	
E8836AS	Support Synthesis Engine	Currently supported	
E8836NN	Synthesis Engine Node-to-NLS	Currently supported	
E8836NS	Support Synthesis Engine NLS	Currently supported	
E8838A	DSP Synthesis PC VHDL	Currently supported	
E8838AN	DSP Synthesis PC VHDL NLS	Currently supported	
E8838AS	Support DSP Synthesis PC VHDL	Currently supported	
E8838NN	DSP Synthesis PC VHDL Node-to-NLS	Currently supported	
E8838NS	Support DSP Synthesis PC VHDL NLS	No longer supported	
E8839A	DSP Synthesis PC VHDL + Verilog	Currently supported	
E8839AN	DSP Synthesis PC VHDL + Verilog NLS	Currently supported	
E8839AS	Support DSP Synthesis PC VHDL+Verilog	No longer supported	
E8839NN	DSP Synthesis PC VHDL+Vlog Node-to-NLS	Currently supported	
E8839NS	Supp DSP Synthesis PC VHDL+Verilog NLS	Currently supported	
E8840A	DSP Synthesis UNIX VHDL+Verilog	Currently supported	
E8840AN	DSP Synthesis UNIX VHDL+Verilog NLS	Currently supported	
E8840AS	Supp DSP Synthesis UNIX VHDL+Verilog	Currently supported	
E8840NN	DSP Synthesis UNIX VHDL+Verilog N-to-NLS	Currently supported	
E8840NS	Supp DSP Synthesis UNIX VHDL+Verilog NLS	Currently supported	
E8842A	DSP Upgrade for CommSys Pro/Premier	Currently supported	
E8842AN	DSP Upgrade for CommSys Pro/Premier NLS	Currently supported	
E8842AS	Support DSP Impl Upgrade	Currently supported	
E8842NN	DSP Impl Upgrade NodeToNLS	Currently supported	
E8842NS	Support DSP Impl Upgrade NLS	Currently supported	
E8844A	Vector Signal Analysis for EESof/ADS	No longer supported	
E8846A	W-CDMA and cdma2000 modulation analysis	No longer supported	
E8855A	W-CDMA Design Library	Currently supported	
E8855AN	W-CDMA Design Library NLS	Currently supported	
E8855AS	Support W-CDMA Design Library	Currently supported	
E8855NN	W-CDMA Des. Lib Node-to-NLS	Currently supported	
E8855NS	Support W-CDMA Design Library NLS	Currently supported	
E8861A	Photonic System Designer Short-Haul	Currently supported	
E8861AN	Photonic System Designer Short-Haul NLS	Currently supported	
E8861AS	Supp Photonic Sys Designer Short-Haul	Currently supported	
E8861NS	Supp Photonic Sys Designer Short-Haul NLS	Currently supported	
E8862A	Photonic System Designer Electro-Optic	Currently supported	
E8862AN	Photonic Sys Designer Electro-Optic NLS	Currently supported	
E8862AS	Supp Photonic Sys Designer Electro-Optic	Currently supported	
E8862NS	Supp Photonic Sys Designer Electro-Optic	Currently supported	
E8863A	Photonic System Designer Long-Haul	Currently supported	
E8863AN	Photonic System Designer Long-Haul NLS	Currently supported	
E8863AS	Supp Photonic System Designer Long-Haul	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
E8863NS	Supp Photonic Sys Designer Long-Haul NLS	Currently supported	
E8864A	Optical Library I	Currently supported	
E8864AN	Optical Library I NLS	Currently supported	
E8864AS	Support Optical Library I	Currently supported	
E8864NS	Support Optical Library I NLS	Currently supported	
E8865A	Optical Library II	Currently supported	
E8865AN	Optical Library II NLS	Currently supported	
E8865AS	Support Optical Library II	Currently supported	
E8865NS	Support Optical Library II NLS	Currently supported	
E8891A	SPICE Model Generator	Currently supported	
E8891AN	SPICE Model Generator NLS	Currently supported	
E8891AS	Support SPICE Model Generator	Currently supported	
E8891NN	SPICE Model Generator Node-to-NLS	Currently supported	
E8891NS	Support SPICE Model Generator NLS	Currently supported	
E8892A	RF Compiler	Currently supported	
E8892AN	RF Compiler NLS	Currently supported	
E8892AS	Support RF Compiler	Currently supported	
E8892NN	RF Compiler Node-to-Node	Currently supported	
E8892NS	Support RF Compiler NLS	Currently supported	
E8900X	Configured Computer for ADS Products	No longer supported	no replacement
E8908A	Graphical Cell Compiler	Currently supported	
E8908AN	Graphical Cell Compiler NLS	Currently supported	
E8908AS	Support Graphical Cell Compiler	Currently supported	
E8908NN	Graphical Cell Compiler Node-to-NLS	Currently supported	
E8908NS	Support Graphical Cell Compiler NLS	Currently supported	
E8921A-K04	High Speed Analog Designer Pro	Currently supported	
E8921A-K05	High Speed Analog Designer	Currently supported	
E8921A-K06	High Speed Analog-EM Designer	Currently supported	
E8921AN-K04	High Speed Analog Designer Pro	Currently supported	
E8921AN-K05	High Speed Analog Designer	Currently supported	
E8921AN-K06	High Speed Analog-EM Designer	Currently supported	
E8921AS-K04	High Speed Analog Designer Pro Support	Currently supported	
E8921AS-K05	High Speed Analog Designer Support	Currently supported	
E8921AS-K06	High Speed Analog-EM Designer Support	Currently supported	
E8921NS-K04	High Speed Analog Designer Pro Support	Currently supported	
E8921NS-K05	High Speed Analog Designer Support	Currently supported	
E8921NS-K06	High Speed Analog-EM Designer Support	Currently supported	
E8924A	HFSS Optimization Add-on	No longer supported	
E8924AN	HFSS Optimization Add-on NLS	No longer supported	
E8924AS	Support Optimization Add-on	No longer supported	
E8924M	HP HFSS Optimization Media	No longer supported	
E8924NS	Support Optimization Add-on NLS	No longer supported	
E8930A	HFSS Designer Pro	No longer supported	
E8930A-K05	EM Circuit Designer Bundle	No longer supported	
E8930AN	HFSS Designer Pro NLS	No longer supported	
E8930AN-K05	EM Circuit Designer Bundle	No longer supported	
E8930AS-K05	EM Circuit Designer Bundle Software	No longer supported	
E8930AS	Support HFSS Designer Pro	No longer supported	
E8930B	HFSS Upgrade	No longer supported	
E8930BN	HFSS Upgrade NLS	No longer supported	
E8930NN	HFSS Designer Pro Node-to-NLS	Currently supported	
E8930NS	Support HFSS Designer Pro NLS	No longer supported	
E8930NS-K05	EM Circuit Designer Bundle Software	No longer supported	
E8944A	Layout Basic	Currently supported	
E8944AS	Support Layout Basic	Currently supported	
E8945A	Layout Basic to Unbundled	Currently supported	
E8952A	Microwave Transistor Library	Currently supported	
E8952AN	Microwave Transistor Library NLS	Currently supported	
E8952AS	Support Microwave Transistor Library	Currently supported	
E8952NN	Microwave Transistor Library Node-to-NLS	Currently supported	

Product	Description	Support Status	Replacement Information
as of 1 May			
E8952NS	Support Microwave Transistor Library NLS	Currently supported	
E8953A	RF Transistor Library	Currently supported	
E8953AN	RF Transistor Library NLS	Currently supported	
E8953AS	Support RF Transistor Library	Currently supported	
E8953NN	RF Transistor Library Node-to-NLS	Currently supported	
E8953NS	Support RF Transistor Library NLS	Currently supported	
E8954A	High Frequency Diode Library	Currently supported	
E8954AN	High Frequency Diode Library NLS	Currently supported	
E8954AS	Support High Frequency Diode Library	Currently supported	
E8954NN	High Frequency Diode Library Node-to-NLS	Currently supported	
E8954NS	Support High Frequency Diode Library NLS	Currently supported	
E8955A	Analog Parts Library	Currently supported	
E8955AN	Analog Parts Library NLS	Currently supported	
E8955AS	Support Analog Parts Library	Currently supported	
E8955NN	Analog Parts Library Node-to-NLS	Currently supported	
E8955NS	Support Analog Parts Library NLS	Currently supported	
E8956A	RF Passive SMT Library	Currently supported	
E8956AN	RF Passive SMT Library NLS	Currently supported	
E8956AS	Support RF Passive SMT Library	Currently supported	
E8956NN	RF Passive SMT Library Node-to-NLS	Currently supported	
E8956NS	Support RF Passive SMT Library NLS	Currently supported	
E8957A	Murata SMT Library	Currently supported	
E8957AN	Murata SMT Library NLS	Currently supported	
E8957AS	Support Murata SMT Library	Currently supported	
E8957NN	Murata SMT Library Node-to-NLS	Currently supported	
E8957NS	Support Murata SMT Library NLS	Currently supported	
E8958A	RF System Library	Currently supported	
E8958AN	RF System Library NLS	Currently supported	
E8958AS	Support RF System Library	Currently supported	
E8958NN	RF System Library Node-to-NLS	Currently supported	
E8958NS	Support RF System Library NLS	Currently supported	
E8960X	Custom Agilent Training	Currently supported	
E9006A	HFSS Special Product Configuration	Currently supported	
E9006AS	Premium Support Special HFSS	Currently supported	
E9020BA	E-Link Programming Manuals for HP-UX	No longer supported	no replacement
E9021BA	E-Link User Manual for HP-UX	No longer supported	no replacement
E9022BA	E-Link CD-ROM for HP-UX	No longer supported	no replacement
E9023BA	E-Link Prog Manuals for Windows NT	No longer supported	no replacement
E9024BA	E-Link User Manual for Windows NT	No longer supported	no replacement
E9025BA	E-Link CD-ROM for Windows NT	No longer supported	no replacement
E9026AA	Visualizer Developer License	Currently supported	no replacement
E9027AA	Visualizer Runtime License	No longer supported	no replacement
E9028AA	Visualizer Media on CD-ROM	Currently supported	no replacement
E9260A	HP DS 7470 Rapid Prototyping Unit	Currently supported	
E9261A	HP Design Span 7470 APS RPU Crimping Kit	Currently supported	
E9263A	HP DS 7470 Algorithm Prototyping System	Currently supported	
E9405A	E9405A thickness meas. verif. device	No longer supported	no replacement
E9406A	E9406A thickness meas. verif device	No longer supported	no replacement
E9410A	E9410A stand-res. opt. thickness gauge	No longer supported	no replacement
E9411A	E9411A high res. opt. thickness gauge	No longer supported	no replacement
E9420A	E9420A hand held contact probe	No longer supported	no replacement
E9421A	E9421A hand held contact probe	No longer supported	no replacement
E9430A	E9430A non contact probe	No longer supported	no replacement
E9431A	E9431A non contact probe	No longer supported	no replacement
E9484B	PPC860 Emulation Solution	No longer supported	
E9488B	Do not order.	No longer supported	
E9491A	IBM PowerPC 403 Emulation Solution	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
E9513B	MPC7400 Emulation Solution	No longer supported	
E9514B	MPC7410/50 Emulation Solution	No longer supported	
E9591A	IBM PowerPC 403 Analysis Probe	No longer supported	
E9630A	BNC (m) to BNC (m); 50 Ohm Impedance	No longer supported	
E9637A	BNC (f) to Dual Banana (m)	No longer supported	
E9800B	HP DAC Express Setup/Data Viewer SW	Currently supported	no replacement
E9801A	HP DAC Express Data Recorder/Logger SW	product family sold	http://www.agilent.com/find/vxitechnologies
E9810A	HP DAC Express Integrated System	product family sold	http://www.agilent.com/find/vxitechnologies
E9810B	HP DAC Express Integrated System	Currently supported	no replacement
E9811B	HP DAC Express Multifunction Data Logger	Currently supported	no replacement
E9812A	HP DAC Express Analog Data Logger	product family sold	http://www.agilent.com/find/vxitechnologies
E9812B	HP DAC Express Analog Data Logger	Currently supported	no replacement
E9813B	HP DAC Express Data Recorder	Currently supported	no replacement
E9814A	HP DAC Express Recorder/Data Logger	product family sold	http://www.agilent.com/find/vxitechnologies
E9814B	HP DAC Express Recorder/Data Logger	Currently supported	no replacement
ENDC-2221FX	High Temp. Accelerometer, Charge Mode	No longer supported	no replacement
ENDC-2771XX	Charge to ICP Converter	No longer supported	no replacement
ENDC-3090CX	Low Noise Microdot Coax Cable	No longer supported	no replacement
ENDC-7221XX	High Output Accelerometer, Charge mode	No longer supported	no replacement
ENDC-7754XX	Ultra Low-Level Accelerometer	No longer supported	no replacement
ETN-60001	21X1-PQFP-PAS-AC	No longer supported	
ETN-60002	21X1-PQFP-PAS/A	No longer supported	
ETN-60003	21X1-PQFP-PAS/S	No longer supported	
ETN-60004	21X1-PQFP-PAS/T	No longer supported	
ETN-60005	Intel 80386SX PQFP analysis probe	No longer supported	
ETN-60006	386SX-PQFP-PAS-AC16540	No longer supported	
ETN-60007	386SX-PQFP-PAS/A	No longer supported	
ETN-60008	386SX-PQFP-PAS/A-16540	No longer supported	
ETN-60009	386SX-PQFP-PAS/S	No longer supported	
ETN-60010	386SX-PQFP-PAS/S-16540	No longer supported	
ETN-60011	386SX-PQFP-PAS/T	No longer supported	
ETN-60012	386SX-PQFP-PAS/T-16540	No longer supported	
ETN-60013	Motorola 68000/10 DIP analysis probe	No longer supported	
ETN-60014	Motorola 68000/10 PGA analysis probe	No longer supported	
ETN-60015	Motorola 68000/10 PLCC analysis probe	No longer supported	
ETN-60016	Motorola 68000/10 PLCC analysis probe	No longer supported	
ETN-60017	68000/10-PLCC-PAS-KIT (SMT&SKT)	No longer supported	
ETN-60018	Motorola 68000/10 SDIP analysis probe	No longer supported	
ETN-60019	Motorola 68008 DIP analysis probe	No longer supported	
ETN-60020	68020-PQFP-PAS-AC	No longer supported	
ETN-60021	68020-PQFP-PAS/A	No longer supported	
ETN-60022	68020-PQFP-PAS/S	No longer supported	
ETN-60023	68020-PQFP-PAS/T	No longer supported	
ETN-60024	68030-PQFP-PAS-AC	No longer supported	
ETN-60025	68030-PQFP-PAS/A	No longer supported	
ETN-60026	68030-PQFP-PAS/S	No longer supported	
ETN-60027	68030-PQFP-PAS/T	No longer supported	
ETN-60028	Motorola 68302 PGA analysis probe	No longer supported	
ETN-60029	Motorola 68302 PQFP analysis probe	No longer supported	
ETN-60030	68302-PQFP-PAS/A	No longer supported	
ETN-60031	68302-PQFP-PAS/S	No longer supported	
ETN-60032	68302-PQFP-PAS/T	No longer supported	
ETN-60033	68330-PQFP-PAS-AC	No longer supported	
ETN-60034	68330-PQFP-PAS/A	No longer supported	
ETN-60035	68330-PQFP-PAS/S	No longer supported	
ETN-60036	68330-PQFP-PAS/T	No longer supported	
ETN-60037	68332-PQFP-PAS-AC	No longer supported	
ETN-60038	68332-PQFP-PAS/A	No longer supported	
ETN-60039	68332-PQFP-PAS/S	No longer supported	

Product	Description	Support Status	Replacement Information
ETN-60040	68332-PQFP-PAS/T	No longer supported	
ETN-60041	68340-QFP-PAS-AC	No longer supported	
ETN-60042	68340-QFP-PAS/S	No longer supported	
ETN-60043	68EC000-PLCC-PAS	No longer supported	
ETN-60044	68EC000-PLCC-PAS-AC	No longer supported	
ETN-60045	68EC020-PGA-PAS	No longer supported	
ETN-60046	68EC020-PQFP-PAS-AC	No longer supported	
ETN-60047	68EC020-PQFP-PAS/S	No longer supported	
ETN-60048	68HC000/01-PGA-PAS	No longer supported	
ETN-60049	68HC000/01-PLCC-PAS	No longer supported	
ETN-60050	68HC000/01-PLCC-PAS-AC	No longer supported	
ETN-60051	68HC11F1-PCC1-PAS-AC	No longer supported	
ETN-60052	68HC16-QFP-AP/A	No longer supported	
ETN-60053	68HC16-QFP-AP/S	No longer supported	
ETN-60054	68HC16-QFP-AP/T	No longer supported	
ETN-60055	80186/88(XL)-QF47-AC	No longer supported	
ETN-60056	80186/88-LCC-PAS	No longer supported	
ETN-60057	80186/88-PCC1-PAS	No longer supported	
ETN-60058	80186/88-PCC1-PAS-AC	No longer supported	
ETN-60059	80186/88-PGA1-PAS	No longer supported	
ETN-60060	80186EC-PCC-UI	No longer supported	
ETN-60061	80186EB-PCC5-PAS	No longer supported	
ETN-60062	80186EB-PCC5-PAS-AC	No longer supported	
ETN-60063	80186EB-PQFP-PAS	No longer supported	
ETN-60064	80186EB-PQFP-PAS-AC	No longer supported	
ETN-60065	Intel 8031/51 DIP analysis probe	No longer supported	
ETN-60066	Intel 8031/51 PLCC analysis probe	No longer supported	
ETN-60067	Intel 8031/51 analysis probe	No longer supported	
ETN-60068	8031/51-PQFP-PAS/S	No longer supported	
ETN-60069	80386SL-PQFP-PAS-AC	No longer supported	
ETN-60070	80515/535-PLCC-PAS	No longer supported	
ETN-60071	80515/535-PLCC-PAS-AC	No longer supported	
ETN-60072	80960SA/SB-PCC5-PAS	No longer supported	
ETN-60073	80960SA/SB-PCC5-PAS-AC	No longer supported	
ETN-60074	Siemens 80C166 PQFP analysis probe	No longer supported	
ETN-60075	80C166-PQFP-PAS/A	No longer supported	
ETN-60076	80C166-PQFP-PAS/S	No longer supported	
ETN-60077	80C166-PQFP-PAS/T	No longer supported	
ETN-60078	Siemens 80C167 PQFP analysis probe	No longer supported	
ETN-60079	Siemens 80C167 PQFP analysis probe	No longer supported	
ETN-60080	80C451-PLCC-PAS-AC	No longer supported	
ETN-60081	80C517/537-PLCC-PAS	No longer supported	
ETN-60082	CX486-PQFP-PAS-AC1650/510	No longer supported	
ETN-60083	CX486-PQFP-PAS-AC16540/550	No longer supported	
ETN-60084	GENRC-40DIP-PAS	No longer supported	
ETN-60085	HPC46K-PLCC-PAS	No longer supported	
ETN-60086	HPC46K-PLCC-PAS-AC	No longer supported	
ETN-60087	HPC46K-PQFP-PAS-AC	No longer supported	
ETN-60088	HPC46K-PQFP-PAS/S	No longer supported	
ETN-60089	PENTIUM-HGA-UI 735/90 & 815/100 HW	No longer supported	
ETN-60090	PENTIUM-PGA14-UI	No longer supported	
ETN-60091	TMP96C141-PROBE MDDULE	No longer supported	
ETN-60092	V25-PLCC-PAS	No longer supported	
ETN-60093	V25-PLCC-PAS-AC	No longer supported	
ETN-60094	Zilog Z180 PLCC analysis probe	No longer supported	
ETN-60095	Zilog Z180 PLCC analysis probe	No longer supported	
ETN-60096	Zilog Z80 DIP analysis probe	No longer supported	
ETN-60097	Zilog Z80 PLCC analysis probe	No longer supported	
ETN-60098	Zilog Z80 PLCC analysis probe	No longer supported	
ETN-60099	Motorola 68HC12A4 TQFP analysis probe	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
ETN-60100	Motorola 68HC12B32 PQFP analysis probe	No longer supported	
EXTCD	External Desktop CD-ROM Drive	No longer supported	EXTDVD
FSI-60001	64 bit Futurebus+ PPI	No longer supported	
FSI-60002	64 bit Futurebus+ PPI w/ central arbit	No longer supported	
FSI-60003	128 bit Futurebus+ PPI	No longer supported	
FSI-60004	128 bit Futurebus+ PPI w/ central arbit	No longer supported	
FSI-60007	DECchip 21064 PPI	No longer supported	
FSI-60008	ISA bus analysis probe	No longer supported	
FSI-60009	MicroChannel Preprocessor	No longer supported	
FSI-60010	PCI Mezzanine (PMC) bus analysis probe	No longer supported	
FSI-60012	SIMM 72 pin bus analysis probe	No longer supported	
FSI-60013	PCI Logic Scope bus analysis probe	No longer supported	
FSI-60014	PCI Scope bus analysis probe	No longer supported	
FSI-60015	Personality Adapter for FSI60013/14	No longer supported	
FSI-60023	LVD SCSI bus analysis probe	No longer supported	
FSI-60029	PCI EIO bus analysis probe	No longer supported	
G347A	WG NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
G424A	WG DETECTOR	No longer supported	no replacement
G486A	THERMISTOR MOUNT	No longer supported	no replacement
G810B	SLOTTED SECTION	No longer supported	no replacement
G914A	MOVING LOAD	No longer supported	no replacement
GUN12AAX	Microphone Power Supply with gain	No longer supported	no replacement
GUN12ABX	Microphone Power Supply w/o gain	No longer supported	no replacement
GUN26ABX	Microphone preamplifier	No longer supported	no replacement
GUN26ACX	Microphone preamplifier w/cable	No longer supported	no replacement
GUN40AFX	Microphone, Free Field, High Sensitivity	No longer supported	no replacement
GUN40AKX	Matched pair 1/2" microphone	No longer supported	no replacement
GUN40APX	Microphone, Pressure, High Sensitivity	No longer supported	no replacement
GUN40BFX	Microphone, Free field, High Sensitivity	No longer supported	no replacement
GUN40BIX	Matched pair 1/4" microphone	No longer supported	no replacement
GUN40BPX	Microphone, Pressure, High Sensitivity	No longer supported	no replacement
GUN50AIX	Sound Intensity Probe w/mics and preamps	No longer supported	no replacement
GUN51ABX	Sound Intensity Cavity Calibrator	No longer supported	no replacement
GUNAA008	3m Extension Cable LEMO 7-pin to 7-pin	No longer supported	no replacement
GUNAA009	10m Extension Calbe LEMO 7-pin to 7-pin	No longer supported	no replacement
GUNAI001	Microphone Windscreen, Elliptical	No longer supported	no replacement
GUNAM069	Microphone Windscreen, spherical	No longer supported	no replacement
H347A	WG NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
H424A	WG DETECTOR	No longer supported	no replacement
H486A	THERMISTOR MOUNT	No longer supported	no replacement
H532A	FREQ METER	No longer supported	no replacement
H752A	WG COUPLER	No longer supported	no replacement
H752C	WG COUPLER	No longer supported	no replacement
H752D	WG COUPLER	No longer supported	no replacement
H810B	SLOTTED SECTION	No longer supported	no replacement
H910A	WG TERMINATION	No longer supported	no replacement
H914A	WG MOVING LOAD	No longer supported	no replacement
H920A	WG SLIDING SHORT	No longer supported	no replacement
H1300A	How to use an Oscilloscope Videotape	No longer supported	
H1301A	How to use a Digital V. Meter Videotape	No longer supported	
H1302A	How to use a Function/Arb Generator Vide	No longer supported	
H5260AU	T&M Custom Project Quote	No longer supported	H5260BS\SATLW\S\ABB\W
H5260EU	T&M Custom Project Quote	No longer supported	H5260BS\SATLW\S\ABB\W
H5260JU	T&M Custom Project Quote	No longer supported	H5260BS\SATLW\S\ABB\W
H5260PU	T&M Custom Project Quote	No longer supported	H5260BS\SATLW\S\ABB\W
H5264A	Amplitude Modulation Fundamentals CBT	No longer supported	
H5265A	Lightwave Fundamentals CBT	Currently supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
H5266A	Transmission-Line Fundamentals CBT	Currently supported	
H5267A	Frequency Modulation Fundamentals CBT	No longer supported	
H6237A	Tsutsuji STD. ENV. Response Ctr. 1 Month	No longer supported	no replacement
H6238A	Tsutsuji STD. ENV. SMS for 1 Month	No longer supported	no replacement
H6239A	Tsutsuji Mapper Response Center 1 Month	No longer supported	no replacement
H6240A	Tsutsuji Mapper SMS for 1 Month	No longer supported	no replacement
H6241A	Tsutsuji Pre-Study Consulting Service	No longer supported	no replacement
H6242A	Tsutsuji Training Course	No longer supported	no replacement
H6243A	Tsutsuji 1 Day Consulting Service	No longer supported	no replacement
H6244A	Tsutsuji 1 Project Unit	No longer supported	no replacement
H6245A	Tsutsuji Verilog link SMS service.	No longer supported	no replacement
H6246A	Tsutsuji VHDL link SMS Service	No longer supported	no replacement
HDHN-DBB110	Heidenhain DBB 110 Double Ball Bar	No longer supported	no replacement
HWP2355C	HP-UX 10.20 English Manuals on CD-ROM	No longer supported	no replacement
HWP2355P	HP-UX 10.20 English Man'ls(Paper Copies)	No longer supported	no replacement
HWPA4030	Localized Kit	No longer supported	no replacement
HWPA4575	19" Color Monitor	No longer supported	MON17
HWPA4576	21" Color Monitor	No longer supported	MON17
HWPB3782	HP-UX Media for Workstations	No longer supported	no replacement
HWPC1552	Desktop 8GB External DAT Drive	No longer supported	EXTDAT
HWPC4314	Desktop DVD / CD-ROM Drive	No longer supported	EXTDVD
HWPC6388	Desktop 4GB External Disk Module	No longer supported	EXTHD
HWPD8900	17" Color Monitor	No longer supported	MON17
HWPJ1519	Universal Monitor Rack Mount Kit	No longer supported	MONRACK
HX292B	Waveguide to Waveguide Adapter	No longer supported	no replacement
J347A	WG NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
J424A	WG DETECTOR	No longer supported	no replacement
J486A	THERMISTOR MOUNT	No longer supported	no replacement
J532A	FREQ METER	No longer supported	no replacement
J752A	WG COUPLER	No longer supported	no replacement
J752C	WG COUPLER	No longer supported	no replacement
J752D	WG COUPLER	No longer supported	no replacement
J810B	SLOTTED SECTION	No longer supported	no replacement
J885A	WG PHASE SHIFTER	No longer supported	no replacement
J910A	WG TERMINATION	No longer supported	no replacement
J914A	WG MOVING LOAD	No longer supported	no replacement
J920A	ADJUSTABLE SHORT	No longer supported	no replacement
J1420A	J1420A SpectralBER Short Reach Rx 10Gb	Currently supported	OmniBER XM
J1420B	SpectralBER Short Reach Rx-10Gb/s	Currently supported	OmniBER XM
J1421A	SpectralBER 10Gb/s clock source	Currently supported	OmniBER XM
J1422A	J1422A SpectralBER 1550nm Tx -10Gb/s	Currently supported	OmniBER XM
J1422B	SpectralBER 1550nm TX 10Gb/s	Currently supported	OmniBER XM
J1423A	J1423A 10G SpectralBER Manual Set	Currently supported	OmniBER XM
J1424A	J1424A 10G SpectralBER DWDM Mainframe	No longer supported	OmniBER XM
J1425A	SpectralBER 10Gb/s Mainframe	Currently supported	OmniBER XM
J1426A	MTS Clock Module for SpectralBER 10G	Currently supported	OmniBER XM
J1427A	Bits clock module for 10G SpectralBER	Currently supported	OmniBER XM
J2170AR	Network Advisor E/TR interface module	No longer supported	
J2171AR	N.A. Ethernet Interface Module	No longer supported	J2522B
J2173AR	N.A. FDDI Dual Attach Interface Module	No longer supported	
J2219AR	Network Advisor Series 486 Mainframe	No longer supported	
J2263AR	Handheld Cable Test Set	No longer supported	
J2300AR	WAN Advisor;V-series/64kbps	Currently supported	
J2301AR	T1 Advisor	No longer supported	J2301B
J2301BR	Internet advisor WAN T1	Currently supported	

Product	Description	Support Status as of 1 May	Replacement Information
J2302AR	E1 Advisor	No longer supported	J2302B
J2302BR	Internet advisor WAN E1	No longer supported	
J2303AR	T1/LAN Internet Advisor	No longer supported	
J2306AR	Ethernet interface for internet advisor	No longer supported	
J2306BR	Internet Advisor LAN Ethernet U/C	Currently supported	
J2309AR	Ether/TR Interface for Internet Advisor	No longer supported	
J2509AR	Upgrade kit-Internet Advisor DOS system	No longer supported	
J2522AR	Internet Advisor Ethernet	No longer supported	
J2523AR	Internet Advisor Ethernet/Token Ring.	No longer supported	
J2527AR	Internet Advisor TMS undercradle	Currently supported	
J2904AR	Internet Advisor WAN ISDN BRI S/T	No longer supported	J2904B
J2912AR	Internet Advisor ATM OC-3c/STM-1 Mod,S/W	Currently supported	
J3320AR	FDDI Probe/TP-PMD	Currently supported	
J3321AR	FDDI Probe/SAS	No longer supported	
J3321BR	FDDI/Probe/SAS with Telemetry	Currently supported	
J3322AR	FDDI Probe/DAS	No longer supported	
J3328AR	WanProbe 2048kbps 64 pvc	Currently supported	
J3329AR	WanProbe 2048kbps 106 pvc	Currently supported	
J3445AR	Internet Advisor LAN 100Base-FX I/F	Currently supported	
J3457AR	Quad Ethernet LanProbe	No longer supported	
J3504AR	Internet Wanprobe 2048 kbps 64 pvc	Currently supported	
J4221A	SpectralBER DWDM VXI Mainframe System	Currently supported	OmniBER XM
J4222A	SpectralBER DWDM VXI Mainframe System	Currently supported	OmniBER XM
J4225A	SpectralBER DWDM Short Reach Rx-2.5Gb/s	Currently supported	OmniBER XM
J4226A	SpectralBER DWDM Long Reach Rx-2.5Gb/s	Currently supported	OmniBER XM
J4227A	SpectralBER DWDM Short Reach Rx<2.5Gb/s	Currently supported	OmniBER XM
J4230A	SpectralBER DWDM 1310nm Tx-2.5Gb/s	Currently supported	OmniBER XM
J4231A	SpectralBER DWDM 1550nm Tx-2.5Gb/s	Currently supported	OmniBER XM
J4233A	SpectralBER DWDM 1310nm TX<2.5Gb/s	Currently supported	OmniBER XM
J4234A	SpectralBER DWDM 1550nm Tx<2.5Gb/s	Currently supported	OmniBER XM
J7251A	Multi-Port Tester 10GbE/1 (LW) module	No longer supported	no replacement
J7252A	Multi-Port Tester 10GbE/1 (ER) module	No longer supported	no replacement
J7253A	Multi-Port Tester 10GbE/1 (LR) module	No longer supported	no replacement
K362A	Waveguide Low Pass Filter.	No longer supported	no replacement
K422A	Waveguide Detector	No longer supported	K424C
K532A	Frequency Meter	No longer supported	5351B
K752A	Waveguide Coupler.	No longer supported	no replacement
K815B	SLOTTED SECTION	No longer supported	
K914B	Waveguide Moving Load.	No longer supported	no replacement
K920B	Waveguide Sliding Short	No longer supported	861/862 WL
K1020A-K11	1 GHz economy TDR probe	No longer supported	
K3485A-K31	Retrofit to install an OC-12 filter	No longer supported	
K8747A	TEST UNIT	No longer supported	
M362A	WG LPF.	No longer supported	no replacement
M424A	WG DETECTOR	No longer supported	no replacement
M486A	THERMISTOR MOUNT	No longer supported	no replacement
MANCD	HP-UX 10.2 English Manuals on CD-ROM	Currently supported	no replacement
MANPAP	HP-UX 10.2 English Manuals (Paper Copy)	Currently supported	no replacement
MICR-680001	68K/302/20/332/331 MRI Software Package	No longer supported	
MICR-680002	68k/20/302/332/331 MRI XRAY C Debug/Emul	No longer supported	
MICR-680003	68k/20/302/332/331 MRI XRAY C Debug/Sim	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
MICR-680004	68k/08/10/20/30/40/CPU32/302 C Compiler	No longer supported	
MICR-680005	68k/08/10/20/30/40/CPU32/302 Assembler	No longer supported	
MP292B	Waveguide to Waveguide Adapter	No longer supported	no replacement
MX292B	Waveguide to Waveguide Adapter	No longer supported	no replacement
N1020A-K02	20 GHz probe, 0.040-inch pitch	No longer supported	
N1020A-K03	20 GHz probe, 0.100-inch fixed pitch	No longer supported	
N1020A-K04	6 GHz probe, walking ground	No longer supported	
N1020A-K05	Calibration substrate	No longer supported	
N1020A-K06	6 GHz probe, .100-inch fixed spacing	No longer supported	
N1020A-K07	Resistive probe for the 54006A	No longer supported	
N1020A-K08	Firewire TDR cable	No longer supported	
N1020A-K09	Gigabit TDR cable (HSSDC)	No longer supported	
N1020A-K10	Gigabit TDR cable (DB-9)	No longer supported	
N1020A-K11	1 GHz Economy TDR Probe	No longer supported	
N1251A	High Performance 3 M Laser Head Cable	No longer supported	N1251B
N1310A	TestBook 5000 Computer	No longer supported	
N1321A	Trolley TestBook 5000/6000	Currently supported	no replacement
N1455A	TestBook Tablet Computer w/o Radio/LAN	No longer supported	
N1456A	TestBook Tablet Computer with Radio/LAN	No longer supported	
N1460A	Docking Station for Pen Computers	No longer supported	
N1470A	4 Bay Battery Charger for Pen Computer	No longer supported	
N1471A	Replacement Battery for Pen Computer	No longer supported	
N1473A	Cigarette Lighter Adapter	No longer supported	
N1474A	Replacement Pen Pack for Pen Computer	No longer supported	
N1477A	Replacement AC Adapter for Pen Computer	No longer supported	
N1478A	Wired LAN Kit for Pen Computer	No longer supported	
N1881A	Base Station Test Subsystem	No longer supported	no replacement
N2305A	1.5m Ribbon Cable for N2276B	No longer supported	no replacement
N2714A	Perf. Verification/Adj. SW for E4406 VSA	Currently supported	
N3180A	Video: Intro. to Mixer Simulation (ADS)	Currently supported	
N3181A	Video: PLL Simulation using Ckt Env(MDS)	Currently supported	
N3182A	Video: Intro to ADS Video (ADS)	Currently supported	
N3183A	ADS Designer's Application Guide	Currently supported	
N3184A	CBT: Introduction to ADS	Currently supported	
N3185A	CBT: Introduction to HFSS	Currently supported	
N3187A	ADS Quick Reference Guide	Currently supported	
N3188A	Video: Creating Analog Models in ADS	Currently supported	
N3200A	Advanced Design System Essentials	Currently supported	
N3200B	Advanced Design System Essentials	Currently supported	
N3201B	Using Adv Des Sys for RF/MW Ckt Des	No longer supported	new course
N3209A	Advanced Des Sys for W-CDMA Design	Currently supported	
N3209B	Advanced Des Sys for W-CDMA Design	Currently supported	
N3210A	Using Photonic System Designer	Currently supported	
N3210B	Using Photonic System Designer	Currently supported	
N3220A	Using Series IV for Circuit Design	Currently supported	
N3220B	Using Series IV for Circuit Design	Currently supported	
N3221A	OmniSys for System Design	Currently supported	
N3221B	OmniSys for System Design	Currently supported	
N3222A	Comms Design Suite for Board-Level Des	Currently supported	
N3222B	Comms Design Suite for Board-Level Des	Currently supported	
N3223A	Series IV Physical Design and Custom.	Currently supported	
N3223B	Series IV Physical Design and Custom.	Currently supported	
N3224A	Momentum for Series IV Users	Currently supported	
N3224B	Momentum for Series IV Users	Currently supported	
N3225A	AEL Programming for Series IV Users	Currently supported	

Product	Description	Support Status	Replacement Information as of 1 May
N3225B	AEL Programming for Series IV Users	Currently supported	
N3226A	MDS User Training	Currently supported	
N3226B	MDS User Training	Currently supported	
N3227A	Active Circuit Simulation	Currently supported	
N3227B	Active Circuit Simulation	Currently supported	
N3228A	MDS Circuit Envelope Simulation	Currently supported	
N3228B	MDS Circuit Envelope Simulation	Currently supported	
N3229A	Momentum for MDS Users	Currently supported	
N3229B	Momentum for MDS Users	Currently supported	
N3230A	HFSS Designer User's Course	No longer supported	
N3230B	HP HFSS Designer User's Course	No longer supported	
N3333A	Device Power Supply	Currently supported	
N3479A	Janus Special Solutions Configuration	Currently supported	
N3489A	SEEC Special Solutions Configuration	Currently supported	
N3500A	Adaptive Feedforward Linearization	Currently supported	
N3501A	Adaptive RF Predistortion	Currently supported	
N3502A	PA Design Small Signal Approach	Currently supported	
N3503A	RFIC MOS Gilbert Cell Mixer Design	Currently supported	
N3504A	Reducing Cross Modulation in CDMA Trans.	Currently supported	
N3505A	Fundamentals of Mixer Design	Currently supported	
N3506A	BER and Importance Sampling	Currently supported	
N3507A	Digital Predistortion Linearization-PA	Currently supported	
N3509A	IS-95 Transmitter Linearization	Currently supported	
N3510A	Quadrifiler Antenna Design	Currently supported	
N3511A	Fundamentals of Antenna Design	Currently supported	
N3630AA	CAD Data:0-8 pin,In Stock,Node Lic.	Currently supported	
N3630AG	CAD Data:0-8 pin,In Stock,Global Lic.	Currently supported	
N3630AN	CAD Data:0-8 pin,In Stock,Site License.	Currently supported	
N3630CG	CAD Data:0-8 pin,New 2 day,Global Lic.	Currently supported	
N3630CN	CAD Data:0-8 pin,New 2 day, Site Lic.	Currently supported	
N3630FG	CAD Data:0-8 pin,New 1 wk,Global Lic.	Currently supported	
N3630FN	CAD Data:0-8 pin,New 1 wk,Site Lic.	Currently supported	
N3630KG	CAD Data:0-8 pin,New 2 wk,Global Lic.	Currently supported	
N3630KN	CAD Data:0-8 pin,New 2 wk, Site Lic.	Currently supported	
N3630LG	CAD Data:0-8 pin,New 3 wk,Global Lic.	Currently supported	
N3630LN	CAD Data:0-8 pin,New 3 wk,Site Lic.	Currently supported	
N3630XG	CAD Data:0-8 pin,Node to Global Lic.	Currently supported	
N3630XH	CAD Data:0-8 pin,Site to Global Lic.	Currently supported	
N3630XN	CAD Data:0-8 pin,Node to Site Lic.	Currently supported	
N3631AA	CAD Data:9-16 pin,In Stock,Node Lic.	Currently supported	
N3631AG	CAD Data:9-16 pin,In Stock,Global Lic.	Currently supported	
N3631AN	CAD Data:9-16 pin, In Stock, Site Lic.	Currently supported	
N3631CG	CAD Data:9-16 pin,New 2 day,Global Lic.	Currently supported	
N3631CN	CAD Data:9-16 pin,New 2 day, Site Lic.	Currently supported	
N3631FG	CAD Data:9-16 pin, New 1 wk, Global Lic.	Currently supported	
N3631FN	CAD Data:9-16 pin,New 1 wk,Site Lic.	Currently supported	
N3631KG	CAD Data:9-16 pin,New 2 wk,Global Lic.	Currently supported	
N3631KN	CAD Data:9-16 pin, New 2 wk, Site Lic.	Currently supported	
N3631LG	CAD Data:9-16 pin, New 3 wk, Global Lic.	Currently supported	
N3631LN	CAD Data:9-16 pin, New 3 wk, Site Lic.	Currently supported	
N3631XG	CAD Data:9-16 pin,Node to Global Lic.	Currently supported	
N3631XH	CAD Data:9-16 pin,Site to Global Lic.	Currently supported	
N3631XN	CAD Data:9-16 pin,Node to Site Lic.	Currently supported	
N3632AA	CAD Data:17-32 pin,In Stock,Node Lic.	Currently supported	
N3632AG	CAD Data:17-32 pin,In Stock,Global Lic.	Currently supported	
N3632AN	CAD Data:17-32 pin,In Stock,Site Lic.	Currently supported	
N3632CG	CAD Data:17-32 pin,New 2 day,Global Lic.	Currently supported	
N3632CN	CAD Data:17-32 pin,New 2 day,Site Lic.	Currently supported	

Product	Description	Support Status	Replacement Information as of 1 May
N3632FG	CAD Data:17-32 pin,New 1 wk, Global Lic.	Currently supported	
N3632FN	CAD Data:17-32 pin,New 1 wk,Site Lic.	Currently supported	
N3632KG	CAD Data:17-32 pin,New 2 wk,Global Lic.	Currently supported	
N3632KN	CAD Data:17-32 pin,New 2 wk,Site Lic.	Currently supported	
N3632LG	CAD Data:17-32 pin,New 3 wk,Global Lic.	Currently supported	
N3632LN	CAD Data:17-32 pin,New 3 wk,Site Lic.	Currently supported	
N3632XG	CAD Data:17-32 pin,Node to Global Lic.	Currently supported	
N3632XH	CAD Data:17-32 pin,Site to Global Lic.	Currently supported	
N3632XN	CAD Data:17-32 pin,Node to Site Lic.	Currently supported	
N3633AA	CAD Data:33-50 pin,In Stock,Node Lic.	Currently supported	
N3633AG	CAD Data:33-50 pin,In Stock,Global Lic.	Currently supported	
N3633AN	CAD Data:33-50 pin,In Stock,Site Lic.	Currently supported	
N3633CG	CAD Data:33-50 pin,New 2 day,Global Lic.	Currently supported	
N3633CN	CAD Data:33-50 pin,New 2 day,Site Lic.	Currently supported	
N3633FG	CAD Data:33-50 pin,New 1 wk,Global Lic.	Currently supported	
N3633FN	CAD Data:33-50 pin,New 1 wk, Site Lic.	Currently supported	
N3633KG	CAD Data:33-50 pin,New 2 wk,Global Lic.	Currently supported	
N3633KN	CAD Data:33-50 pin, New 2 wk, Site Lic.	Currently supported	
N3633LG	CAD Data:33-50 pin,New 3 wk, Global Lic.	Currently supported	
N3633LN	CAD Data:33-50 pin, New 3 wk, Site Lic.	Currently supported	
N3633XG	CAD Data:33-50 pin,Node to Global Lic.	Currently supported	
N3633XH	CAD Data:33-50 pin,Site to Global Lic.	Currently supported	
N3633XN	CAD Data:33-50 pin,Node to Site Lic.	Currently supported	
N3634AA	CAD Data:51-100 pin, In Stock, Node Lic.	Currently supported	
N3634AG	CAD Data:51-100 pin,In Stock,Global Lic.	Currently supported	
N3634AN	CAD Data:51-100 pin, In Stock, Site Lic.	Currently supported	
N3634CG	CAD Data:51-100 pin,New 2 day,Globl Lic.	Currently supported	
N3634CN	CAD Data:51-100 pin,New 2 day,Site Lic.	Currently supported	
N3634FG	CAD Data:51-100 pin,New 1 wk,Global Lic.	Currently supported	
N3634FN	CAD Data:51-100 pin, New 1 wk, Site Lic.	Currently supported	
N3634KG	CAD Data:51-100 pin,New 2 wk,Global Lic.	Currently supported	
N3634KN	CAD Data:51-100 pin, New 2 wk, Site Lic.	Currently supported	
N3634LG	CAD Data:51-100 pin,New 3 wk,Global Lic.	Currently supported	
N3634LN	CAD Data:51-100 pin, New 3 wk, Site Lic.	Currently supported	
N3634XG	CAD Data:51-100 pin,Node to Global Lic.	Currently supported	
N3634XH	CAD Data:51-100 pin,Site to Global Lic.	Currently supported	
N3634XN	CAD Data:51-100 pin,Node to Site Lic.	Currently supported	
N3635AA	CAD Data:101-200 pin,In Stock, Node Lic.	Currently supported	
N3635AG	CAD Data:101-200 pin,In Stock,Globl Lic.	Currently supported	
N3635AN	CAD Data:101-200 pin,In Stock,Site Lic.	Currently supported	
N3635CG	CAD Data:101-200 pin,New 2day,Globl Lic.	Currently supported	
N3635CN	CAD Data:101-200 pin,New 2 day,Site Lic.	Currently supported	
N3635FG	CAD Data:101-200 pin,New 1 wk,Globl Lic.	Currently supported	
N3635FN	CAD Data:101-200 pin, New 1 wk,Site Lic.	Currently supported	
N3635KG	CAD Data:101-200 pin,New 2 wk,Globl Lic.	Currently supported	
N3635KN	CAD Data:101-200 pin,New 2 wk, Site Lic.	Currently supported	

Product	Description	Support Status	Replacement Information
N3635LG	CAD Data:101-200 pin,New 3 wk,Globl Lic.	Currently supported	
N3635LN	CAD Data:101-200 pin,New 3 wk,Site Lic.	Currently supported	
N3635XG	CAD Data:101-200 pin,Node to Global Lic.	Currently supported	
N3635XH	CAD Data:101-200 pin,Site to Global Lic.	Currently supported	
N3635XN	CAD Data:101-200 pin,Node to Site Lic.	Currently supported	
N3636AA	CAD Data:201-300 pin,In Stock,Node Lic.	Currently supported	
N3636AG	CAD Data:201-300 pin,In Stock,Globl Lic.	Currently supported	
N3636AN	CAD Data:201-300 pin,In Stock,Site Lic.	Currently supported	
N3636CG	CAD Data:201-300 pin,New 2day,Globl Lic.	Currently supported	
N3636CN	CAD Data:201-300 pin,New 2 day,Site Lic.	Currently supported	
N3636FG	CAD Data:201-300 pin,New 1 wk,Globl Lic.	Currently supported	
N3636FN	CAD Data:201-300 pin,New 1 wk,Site Lic.	Currently supported	
N3636KG	CAD Data:201-300 pin,New 2 wk,Globl Lic.	Currently supported	
N3636KN	CAD Data:201-300 pin,New 2 wk,Site Lic.	Currently supported	
N3636LG	CAD Data:201-300 pin,New 3 wk,Globl Lic.	Currently supported	
N3636LN	CAD Data:201-300 pin,New 3 wk,Site Lic.	Currently supported	
N3636XG	CAD Data:201-300 pin,Node to Global Lic.	Currently supported	
N3636XH	CAD Data:201-300 pin,Site to Global Lic.	Currently supported	
N3636XN	CAD Data:201-300 pin,Node to Site Lic.	Currently supported	
N3637AA	CAD Data:301-400 pin,In Stock,Node Lic.	Currently supported	
N3637AG	CAD Data:301-400 pin,In Stock,Globl Lic.	Currently supported	
N3637AN	CAD Data:301-400 pin,In Stock,Site Lic.	Currently supported	
N3637CG	CAD Data:301-400 pin,New 2day,Globl Lic.	Currently supported	
N3637CN	CAD Data:301-400 pin,New 2 day,Site Lic.	Currently supported	
N3637FG	CAD Data:301-400 pin,New 1 wk,Globl Lic.	Currently supported	
N3637FN	CAD Data:301-400 pin, New 1 wk,Site Lic.	Currently supported	
N3637KG	CAD Data:301-400 pin,New 2 wk,Globl Lic.	Currently supported	
N3637KN	CAD Data:301-400 pin, New 2 wk,Site Lic.	Currently supported	
N3637LG	CAD Data:301-400 pin,New 3 wk,Globl Lic.	Currently supported	
N3637LN	CAD Data:301-400 pin, New 3 wk,Site Lic.	Currently supported	
N3637XG	CAD Data:301-400 pin,Node to Global Lic.	Currently supported	
N3637XH	CAD Data:301-400 pin,Site to Global Lic.	Currently supported	
N3637XN	CAD Data:301-400 pin,Node to Site Lic.	Currently supported	
N3638AA	CAD Data:401-500 pin, In Stock,Node Lic.	Currently supported	
N3638AG	CAD Data:401-500 pin,In Stock,Globl Lic.	Currently supported	
N3638AN	CAD Data:401-500 pin,In Stock, Site Lic.	Currently supported	
N3638CG	CAD Data:401-500 pin,New 2day,Globl Lic.	Currently supported	
N3638CN	CAD Data:401-500 pin,New 2 day,Site Lic.	Currently supported	
N3638FG	CAD Data:401-500 pin,New 1 wk,Globl Lic.	Currently supported	
N3638FN	CAD Data:401-500 pin,New 1 wk,Site Lic.	Currently supported	

Product	Description	Support Status	Replacement Information
N3638KG	CAD Data:401-500 pin,New 2 wk,Globl Lic.	Currently supported	
N3638KN	CAD Data:401-500 pin, New 2 wk,Site Lic.	Currently supported	
N3638LG	CAD Data:401-500 pin,New 3 wk,Globl Lic.	Currently supported	
N3638LN	CAD Data:401-500 pin, New 3 wk,Site Lic.	Currently supported	
N3638XG	CAD Data:401-500 pin,Node to Global Lic.	Currently supported	
N3638XH	CAD Data:401-500 pin,Site to Global Lic.	Currently supported	
N3638XN	CAD Data:401-500 pin,Node to Site Lic.	Currently supported	
N3639AA	CAD Data:501-600 pin,In Stock, Node Lic.	Currently supported	
N3639AG	CAD Data:501-600 pin,In Stock,Globl Lic.	Currently supported	
N3639AN	CAD Data:501-600 pin,In Stock, Site Lic.	Currently supported	
N3639CG	CAD Data:501-600 pin,New 2day,Globl Lic.	Currently supported	
N3639CN	CAD Data:501-600 pin,New 2 day,Site Lic.	Currently supported	
N3639FG	CAD Data:501-600 pin,New 1 wk,Globl Lic.	Currently supported	
N3639FN	CAD Data:501-600 pin,New 1 wk,Site Lic.	Currently supported	
N3639KG	CAD Data:501-600 pin,New 2 wk,Globl Lic.	Currently supported	
N3639KN	CAD Data:501-600 pin, New 2 wk,Site Lic.	Currently supported	
N3639LG	CAD Data:501-600 pin,New 3 wk,Globl Lic.	Currently supported	
N3639LN	CAD Data:501-600 pin, New 3 wk,Site Lic.	Currently supported	
N3639XG	CAD Data:501-600 pin,Node to Global Lic.	Currently supported	
N3639XH	CAD Data:501-600 pin,Site to Global Lic.	Currently supported	
N3639XN	CAD Data:501-600 pin,Node to Site Lic.	Currently supported	
N3640AA	CAD Data:601-700 pin, In Stock,Node Lic.	Currently supported	
N3640AG	CAD Data:601-700 pin,In Stock,Globl Lic.	Currently supported	
N3640AN	CAD Data:601-700 pin, In Stock,Site Lic.	Currently supported	
N3640CG	CAD Data:601-700 pin,New 2day,Globl Lic.	Currently supported	
N3640CN	CAD Data:601-700 pin,New 2 day,Site Lic.	Currently supported	
N3640FG	CAD Data:601-700 pin,New 1 wk,Globl Lic.	Currently supported	
N3640FN	CAD Data:601-700 pin,New 1 wk,Site Lic.	Currently supported	
N3640KG	CAD Data:601-700 pin,New 2 wk,Globl Lic.	Currently supported	
N3640KN	CAD Data:601-700 pin,New 2 wk, Site Lic.	Currently supported	
N3640LG	CAD Data:601-700 pin,New 3 wk,Globl Lic.	Currently supported	
N3640LN	CAD Data:601-700 pin,New 3 wk,Site Lic.	Currently supported	
N3640XG	CAD Data:601-700 pin,Node to Global Lic.	Currently supported	
N3640XH	CAD Data:601-700 pin,Site to Global Lic.	Currently supported	
N3640XN	CAD Data:601-700 pin,Node to Site Lic.	Currently supported	
N3641AA	CAD Data:701-800 pin, In Stock,Node Lic.	Currently supported	
N3641AG	CAD Data:701-800 pin,In Stock,Globl Lic.	Currently supported	
N3641AN	CAD Data:701-800 pin,In Stock,Site Lic.	Currently supported	

Product	Description	Support Status	Replacement Information
N3641CG	CAD Data:701-800 pin,New 2day,Globl Lic.	Currently supported	
N3641CN	CAD Data:701-800 pin,New 2 day,Site Lic.	Currently supported	
N3641FG	CAD Data:701-800 pin,New 1 wk,Globl Lic.	Currently supported	
N3641FN	CAD Data:701-800 pin, New 1 wk,Site Lic.	Currently supported	
N3641KG	CAD Data:701-800 pin,New 2 wk,Globl Lic.	Currently supported	
N3641KN	CAD Data:701-800 pin,New 2 wk,Site Lic.	Currently supported	
N3641LG	CAD Data:701-800 pin,New 3 wk,Globl Lic.	Currently supported	
N3641LN	CAD Data:701-800 pin,New 3 wk,Site Lic.	Currently supported	
N3641XG	CAD Data:701-800 pin,Node to Global Lic.	Currently supported	
N3641XH	CAD Data:701-800 pin,Site to Global Lic.	Currently supported	
N3641XN	CAD Data:701-800 pin,Node to Site Lic.	Currently supported	
N3642AA	CAD Data:801-900 pin, In Stock,Node Lic.	Currently supported	
N3642AG	CAD Data:801-900 pin,In Stock,Globl Lic.	Currently supported	
N3642AN	CAD Data:801-900 pin,In Stock,Site Lic.	Currently supported	
N3642CG	CAD Data:801-900 pin,New 2day,Globl Lic.	Currently supported	
N3642CN	CAD Data:801-900 pin,New 2 day,Site Lic.	Currently supported	
N3642FG	CAD Data:801-900 pin,New 1 wk,Globl Lic.	Currently supported	
N3642FN	CAD Data:801-900 pin,New 1 wk,Site Lic.	Currently supported	
N3642KG	CAD Data:801-900 pin,New 2 wk,Globl Lic.	Currently supported	
N3642KN	CAD Data:801-900 pin, New 2 wk,Site Lic.	Currently supported	
N3642LG	CAD Data:801-900 pin,New 3 wk,Globl Lic.	Currently supported	
N3642LN	CAD Data:801-900 pin,New 3 wk,Site Lic.	Currently supported	
N3642XG	CAD Data:801-900 pin,Node to Global Lic.	Currently supported	
N3642XH	CAD Data:801-900 pin,Site to Global Lic.	Currently supported	
N3642XN	CAD Data:801-900 pin,Node to Site Lic.	Currently supported	
N3643AA	CAD Data:901-1000pin,In Stock,Node Lic.	Currently supported	
N3643AG	CAD Data:901-1000pin,In Stock,Globl Lic.	Currently supported	
N3643AN	CAD Data:901-1000pin, In Stock,Site Lic.	Currently supported	
N3643CG	CAD Data:901-1000pin,New 2day,Globl Lic.	Currently supported	
N3643CN	CAD Data:901-1000pin,New 2 day,Site Lic.	Currently supported	
N3643FG	CAD Data:901-1000pin,New 1wk,Globl Lic.	Currently supported	
N3643FN	CAD Data:901-1000pin, New 1wk,Site Lic.	Currently supported	
N3643KG	CAD Data:901-1000pin,New 2 wk,Globl Lic.	Currently supported	
N3643KN	CAD Data:901-1000pin, New 2 wk,Site Lic.	Currently supported	
N3643LG	CAD Data:901-1000pin,New 3 wk,Globl Lic.	Currently supported	
N3643LN	CAD Data:901-1000pin, New 3 wk,Site Lic.	Currently supported	
N3643XG	CAD Data:901-1000pin,Node to Global Lic.	Currently supported	

Product	Description	Support Status	Replacement Information
N3643XH	CAD Data:901-1000pin,Site to Global Lic.	Currently supported	
N3643XN	CAD Data:901-1000pin,Node to Site Lic.	Currently supported	
N3644AA	CAD Data:1001+pin, In Stock, Node Lic.	Currently supported	
N3644AG	CAD Data:1001+pin, In Stock, Globl Lic.	Currently supported	
N3644AN	CAD Data:1001+pin,In Stock, Site Lic.	Currently supported	
N3644CG	CAD Data:1001+pin, New 2 day,Global Lic.	Currently supported	
N3644CN	CAD Data:1001+pin, New 2 day,Site Lic.	Currently supported	
N3644FG	CAD Data:1001+pin, New 1 wk,Global Lic.	Currently supported	
N3644FN	CAD Data:1001+pin, New 1 wk,Site Lic.	Currently supported	
N3644KG	CAD Data:1001+pin,New 2 wk,Global Lic.	Currently supported	
N3644KN	CAD Data:1001+pin, New 2 wk,Site Lic.	Currently supported	
N3644LG	CAD Data:1001+pin, New 3 wk,Global Lic.	Currently supported	
N3644LN	CAD Data:1001+pin, New 3 wk,Site Lic.	Currently supported	
N3644XG	CAD Data:1001+pin,Node to Global Lic.	Currently supported	
N3644XH	CAD Data:1001+pin,Site to Global Lic.	Currently supported	
N3644XN	CAD Data:1001+pin,Node to Site Lic.	Currently supported	
N4201A	Flat pnl mon & kybd 1ru s All rack models	Currently supported	no replacement
NK292A	Waveguide to Waveguide Adapter	No longer supported	no replacement
NP292A	Waveguide to Waveguide Adapter	No longer supported	no replacement
P347A	WG NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
P362A	Waveguide Low Pass Filter.	No longer supported	no replacement
P375A	Waveguide Variable Attenuator.	No longer supported	no replacement
P382AR	Variable attenuator.	Currently supported	
P424A	Waveguide Detector	No longer supported	P424C
P487B	THERMISTOR MOUNT	No longer supported	no replacement
P532A	Frequency Meter.	No longer supported	no replacement
P752A	Waveguide Coupler.	No longer supported	no replacement
P752CR	Waveguide coupler.	Currently supported	
P810B	Slotted Section.	No longer supported	no replacement
P870A	Waveguide Tuner.	No longer supported	no replacement
P8747A	TEST UNIT	No longer supported	
P885A	Waveguide Phase Shifter.	No longer supported	no replacement
P914A	Waveguide Moving Load.	No longer supported	no replacement
P920B	Waveguide Sliding Short.	No longer supported	no replacement
P932A	Harmonic Mixer.	No longer supported	no replacement
PCBI-039AXX	IDC Installation Tool	No longer supported	no replacement
PCBI-209AXX	High Frequency Dynamic Load Cell, ICP	No longer supported	no replacement
PCBI-002C15	BNC/Microdot Accelerometer Cable	No longer supported	no replacement
PCBI-070A18	Insulation Displacement Connector Set	No longer supported	no replacement
PCBI-080A55	Flexcell Accelerometer Triax Base	No longer supported	no replacement
PCBI-080A99	Flexcell Adhesive Mounting Socket	No longer supported	no replacement
PCBI-208A02	General Purpose Dynamic Load Cell, ICP	No longer supported	no replacement
PCBI-291M54	Hammer Kit 0.3 pound, ICP	No longer supported	no replacement
PCBI-291M55	Hammer kit 3.0 Pound, ICP	No longer supported	no replacement
PCBI-336A04	Structural Accelerometer, 8 Channel, ICP	No longer supported	no replacement
PCBI-336C34	Structural Accelerometer, ICP	No longer supported	no replacement
PCBI-336M32	Tri-axial Accelerometer, ICP	No longer supported	no replacement
PCBI-408B02	ICP Power Supply	No longer supported	no replacement
PCBI-80A104	Adapter Head for Calibrator	No longer supported	no replacement
PZT288C1	Driving Point Sensor, ICP	No longer supported	no replacement
PZT291M6	Hammer Kit 1.0 Pound, ICP	No longer supported	no replacement
PZT333AK	Structural Acceslerometer Kit	No longer supported	no replacement
PZT333AX	Structural Accelerometer, ICP	No longer supported	no replacement
PZT422E3	In-line Charge Converter	No longer supported	no replacement
PZT80A14	Modal Accelerometer Adhesive Mount	No longer supported	no replacement
PZT80B40	Adhesive Accelerometer Mount	No longer supported	no replacement
PZT8A114	Modal Triax Adapter	No longer supported	no replacement

Product	Description	Support Status	Replacement Information
Q347BR	Q-band noise source, solid-state	Currently supported	
Q370A	Waveguide Fixed Attenuator.	No longer supported	no replacement
Q370B	Waveguide Fixed Attenuator.	No longer supported	no replacement
Q370C	Waveguide Fixed Attenuator.	No longer supported	no replacement
Q373D	Attenuator, Fixed, Q-Band, 20dB	No longer supported	no replacement
Q373G	Attenuator, Fixed, Q-Band, 50dB	No longer supported	no replacement
Q382A	Precision Variable Attenuator.	No longer supported	no replacement
Q422A	Waveguide Detector.	No longer supported	no replacement
Q532A	Waveguide Frequency Meter.	No longer supported	no replacement
Q752A	Waveguide Single Directional Coupler.	No longer supported	no replacement
Q880A	E-H TUNERS	No longer supported	no replacement
Q894D	Q-Band Std. Mismatch-.25 Reflection	No longer supported	no replacement
Q896B	Precision Standard Section	No longer supported	no replacement
Q896D	Precision Standard Section.	No longer supported	no replacement
Q897A	90 Degree Bends.	No longer supported	no replacement
Q897B	90 Degree Bends.	No longer supported	no replacement
Q898A	90 DEGREE TWIST	No longer supported	no replacement
Q898B	90 Degree Twist.	No longer supported	no replacement
Q899A	Straight Piece.	No longer supported	no replacement
Q899B	Straight Piece.	No longer supported	no replacement
Q914C	Sliding Load.	No longer supported	no replacement
Q920A	Sliding Short.	No longer supported	no replacement
Q920C	Sliding Short	No longer supported	no replacement
Q921A	Waveguide Fixed Short	No longer supported	no replacement
Q8486AR	Power sensor, 33-50 GHz	Currently supported	
QU292A	Waveguide.	No longer supported	no replacement
Q11643A	WR-22 Test Set Kit (33 50 GHz)	No longer supported	Q85104A
R362A	Waveguide Low Pass Filter.	No longer supported	no replacement
R373D	Attenuator, Fixed, R-B, 20dB	No longer supported	no replacement
R373G	Attenuator, Fixed, R-Band, 50dB	No longer supported	no replacement
R382AR	Precision variable attenuator, R-band	Currently supported	
R422A	Waveguide Crystal Detector	No longer supported	R422C
R532A	Frequency Meter.	No longer supported	no replacement
R752A	Waveguide Coupler.	No longer supported	no replacement
R752AS	Coupler, R-Band waveguide, 3dB coupling	No longer supported	no replacement
R815B	SLOTTED SECTION	No longer supported	no replacement
R894D	R-Band std mismatch, .25 reflection	No longer supported	no replacement
R896B	Precision Standard Section	No longer supported	no replacement
R896D	Precision Standard Section.	No longer supported	no replacement
R897A	WAVEGUIDE BEND	No longer supported	no replacement
R897B	Waveguide Bend.	No longer supported	no replacement
R898A	Waveguide Twist.	No longer supported	no replacement
R898B	Waveguide Twist.	No longer supported	no replacement
R899A	Waveguide Straight.	No longer supported	
R899B	Waveguide Straight.	No longer supported	no replacement
R899D	Waveguide Straight.	No longer supported	no replacement
R914B	Waveguide Moving Load.	No longer supported	no replacement
R914C	Sliding Load.	No longer supported	no replacement
R920B	Waveguide Sliding Short.	No longer supported	no replacement
R920C	MM-Wave WG Sliding Short	No longer supported	no replacement
R921A	Waveguide Fixed Short	No longer supported	no replacement
R8747A	TEST UNIT	No longer supported	
R8747B	TEST UNIT	No longer supported	
R11643A	WR-28 Test Set Kit	No longer supported	8516A
R11644AR	WR-28 calibration kit, 26.5 to 40 GHz	Currently supported	
RADEPCDV	Data Acq development sw upgrade	No longer supported	no replacement
RADEPCRT	Data Acq run-only sw upgrade	No longer supported	no replacement
RADEPCSW	EPConnect software upgrade	No longer supported	no replacement
RADEPC7A	VXI C-size PC Embedded Controller, 486DX	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
RADEPC7B	VXI C-size PC embedded controller,100MHz	No longer supported	no replacement
RADEPC7BR	VXI C-size PC embedded controller,100MHz	No longer supported	
RADEPC8A	VXI B-size PC Embedded Controller 486DX2	No longer supported	no replacement
RADEPC8B	VXI B-size PC embedded controller, 66MHz	No longer supported	no replacement
RADEPC8BR	VXI B-size PC embedded controller, 66MHz	No longer supported	
RADEPC95	Upgrade EPCconnect for MS-Win95	No longer supported	no replacement
RADI-AM00	One short form 8-bit PC/XT ISA slot	No longer supported	no replacement
RADI-BP20	2-slot wide VME/VXI subplane (RADEPC8A)	No longer supported	no replacement
RADI-BP3A	3-slot wide VME/VXI subplane (RADEPC8A)	No longer supported	no replacement
RADI-BP4A	4-slot wide VME/VXI subplane (RADEPC8A)	No longer supported	no replacement
RADI-EPC7	VXI C-size PC embedded controller	No longer supported	RADEPC7A
RADI-EPC8	VXI B-size PC embedded controller	No longer supported	RADEPC8A
RADI-EPCA	EPCconnect development S/W (version 4.0)	No longer supported	no replacement
RADI-EPCB	Upgrade to EPCconnect dev. S/W (Ver. 4.0)	No longer supported	no replacement
RADI-EX04	GPIB for SICL for DOS, NI GPIB-PCII S/W	No longer supported	no replacement
RADI-EX07	Two-channel RS-232 interface, EXM module	Currently supported	no replacement
RADI-EX10	Thick/Thin LAN Ethernet Port	Currently supported	no replacement
RADI-EX16	External SCSI-2 I/O w/ floppy controller	No longer supported	no replacement
RADI-EX22	GPIB for SICL for Windows and HP VEE	Currently supported	no replacement
RADI-EX24	8-channel RS-232 intelligent serial I/O	No longer supported	no replacement
RADI-EX26	4-chan RS-232 non-intelligent serial I/O	No longer supported	no replacement
RADI-EX29	2-channel RS-422/485 serial I/O	No longer supported	no replacement
RADI-FDM3	3.5" floppy disk drive for RADEPC8A	No longer supported	no replacement
RADI-MC00	2-slot EXM module carrier for RADEPC8A	No longer supported	no replacement
RADI-SSD1	10 MB solid-state HD w/floppy controller	No longer supported	no replacement
RADI-SSD4	40 MB solid-state HD w/floppy controller	No longer supported	no replacement
RADIS-EXM24	8-Ch Intelligent Serial I/O for E6237A	No longer supported	no replacement
RQ292A	Waveguide to Waveguide Adapter.	No longer supported	no replacement
S382C	Variable Attenuator.	No longer supported	no replacement
S424A	WG DETECTOR	No longer supported	no replacement
S486A	THERMISTOR MOUNT	No longer supported	no replacement
TASC-429	ARINC-429 interface VXI card bundle	No longer supported	no replacement
TASC-429R	ARINC-429 VXI card right-to-use bundle	No longer supported	no replacement
U370A	Waveguide Fixed Attenuator.	No longer supported	no replacement
U370B	Waveguide Fixed Attenuators	No longer supported	no replacement
U370C	Waveguide Fixed Attenuator	No longer supported	no replacement
U373D	Attenuator,Fixed, U-Band, 20dB	No longer supported	no replacement
U373G	Attenuator, Fixed, U-Band, 50dB	No longer supported	no replacement
U382A	Precision Variable Attenuator	No longer supported	no replacement
U422A	Waveguide Detector	No longer supported	no replacement
U532A	Waveguide Frequency Meter	No longer supported	no replacement
U752A	Waveguide Single Directional Coupler.	No longer supported	no replacement
U880A	E-H TUNERS	No longer supported	no replacement
U894D	U-Band Std. Mismatch. .25 Reflection	No longer supported	no replacement
U896B	Precision Standard Section	No longer supported	no replacement
U896D	Precision Standard Section	No longer supported	no replacement
U897A	90 Degree Bends	No longer supported	no replacement
U897B	90 Degree Bends	No longer supported	no replacement
U898A	90 Degree Twist	No longer supported	no replacement

Product	Description	Support Status as of 1 May	Replacement Information
U898B	90 Degree Twist	No longer supported	no replacement
U899A	Straight Piece	No longer supported	no replacement
U899B	Straight Piece	No longer supported	no replacement
U914C	Sliding Load	No longer supported	no replacement
U920A	Tunable Short	No longer supported	no replacement
U920C	Sliding Short	No longer supported	no replacement
U921A	Waveguide Fixed Short	No longer supported	no replacement
UIKIT	HP-UX User Interface Kit	Currently supported	no replacement
UV292A	Waveguide to Waveguide Adapter.	No longer supported	no replacement
UXMEDIA	HP-UX 10.2 Media & C/ANSI C Dev. Bundle	Currently supported	no replacement
U11643A	WR-19 Test Set Kit	No longer supported	U85104A
V373D	Attenuator, Fixed, V-Band, 20dB	No longer supported	no replacement
V373G	Attenuator, Fixes, V-Band, 50dB	No longer supported	no replacement
V894B	V-Band Std Mismatch, .25Reflection	No longer supported	no replacement
V896B	Standard Section	No longer supported	no replacement
V897A	Waveguide Bend	No longer supported	no replacement
V897B	Waveguide Bend	No longer supported	no replacement
V898A	Waveguide Twist	No longer supported	no replacement
V898B	Waveguide Twist	No longer supported	no replacement
V899A	Waveguide Straight	No longer supported	no replacement
V899B	Waveguide Straight	No longer supported	no replacement
V910C	Precision Fixed Termination	No longer supported	no replacement
V11643A	WR-15 V-Band (50 to 75 GHz) test set kit	No longer supported	V85104A
W85104AR	WR-15 test set modules, 50 to 75GHz.	Currently supported	
W1109AS	Upgrades and support for W1109A	Currently supported	
W1109AT	Janus Special Training Configuration	Currently supported	
W1109B	Janus Special Consulting Configuration	Currently supported	
W1119A	SEEC Special Solutions Configuration	Currently supported	
W1119AS	Upgrades and support for W1119A	Currently supported	
W1119AT	SEEC Special Training Configuration	Currently supported	
W1119B	SEEC Special Consulting Configuration	Currently supported	
W1129AS	SEEC Special Support Configuration	Currently supported	
W11643A	WR-10 W-Band (75 110 GHz) test set kit	No longer supported	W85104A
W373D	Attenuator, Fixed, W-Band, 20dB	No longer supported	no replacement
W373G	Attenuator,Fixed, W-Band, 50dB	No longer supported	no replacement
W894B	W-Band Std Mismatch, .25 Reflection	No longer supported	no replacement
W896B	Standard Section	No longer supported	no replacement
W897A	Waveguide Bend	No longer supported	no replacement
W897B	Waveguide Bend	No longer supported	no replacement
W898A	Waveguide Twist	No longer supported	no replacement
W898B	Waveguide Twist	No longer supported	no replacement
W899A	Waveguide Straight	No longer supported	no replacement
W899B	Waveguide Straight	No longer supported	no replacement
WILC-973XXX	Vibration Measurement Accelerometer, ICP	No longer supported	no replacement
WILC-HV8XXX	Handheld Velocity Probe, ICP	No longer supported	no replacement
WJC9119L	HF Tuner (LO section)	Currently supported	WJC9119M
WJC9119R	HF Tuner (RF section)	Currently supported	WJC9119S
X281B	Coaxial to Waveguide Adapter.	No longer supported	X281C
X347A	WG NOISE SOURCE	No longer supported	http://www.agilent.com/find/noise-source
X362A	Waveguide Low Pass Filter.	No longer supported	no replacement
X375A	Waveguide Variable Attenuator.	No longer supported	X382A
X424A	Waveguide Crystal Detector	No longer supported	no replacement
X485B	TUNABLE DETECTOR	No longer supported	
X487B	THERMISTOR MOUNT	No longer supported	
X532B	Frequency Meter	No longer supported	5350B
X752A	Waveguide Coupler	No longer supported	no replacement
X810B	Slotted Section	No longer supported	
X870A	Waveguide Tuner.	No longer supported	Maury X353
X8747A	TEST UNIT	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
X885A	Phase Shifter	No longer supported	no replacement
X923A	Waveguide Sliding Short.	No longer supported	661/662 WL
X930A	Waveguide Switch	No longer supported	no replacement
Z1001A	Ford Sbds	No longer supported	
Z1063B	Volvo Diagnostic Bench Top System	No longer supported	
Z1067A	Volvo DVOM PCA	No longer supported	
Z1080C	JDVision Std Server, 15" Mon, Prn.	No longer supported	
Z1080D	JDVision Server w/17" Monitor & Printer	No longer supported	
Z1080E	JDVision Std Server	No longer supported	
Z1081C	JDVision Std Client with 15" Monitor	No longer supported	
Z1081D	JDVision Std Client with 17" Monitor	No longer supported	
Z1081E	JDVision Std Client	No longer supported	
Z1081F	JD Vision Client	No longer supported	
Z1081G	JD Vision Client	No longer supported	
Z1084E	JDVision Multimedia Client	No longer supported	
Z1089A	JDVision Add-on Client Printer	No longer supported	no replacement
Z1089B	JDVision Add-on Client Printer LJ4ML	No longer supported	no replacement
Z1089C	JDVision Add-on Client Printer LJ5MP	No longer supported	no replacement
Z1090A	INST-TECH 2 GM NO TRADE SALES	No longer supported	
Z1092A	Tech 2 GM Kit	No longer supported	
Z2320A	Engineering Unit, Customer Training	No longer supported	no replacement
Z3801A	GPS Receiver 24V BTS	product family sold	http://www.agilent.com/find/symmetricom
Z3803A	1 to 12 Distribution Amp	product family sold	http://www.agilent.com/find/symmetricom
Z3804A	Ref Clk & Dist. Outputs	product family sold	http://www.agilent.com/find/symmetricom
Z3805A	GPS Time & Freq Rcvr	product family sold	http://www.agilent.com/find/symmetricom
Z3806A	GPS Time & Freq Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z3807A	Mounting Shelf	product family sold	http://www.agilent.com/find/symmetricom
Z3809A	Cable	product family sold	http://www.agilent.com/find/symmetricom
Z3810AS	GPS Timing System	product family sold	http://www.agilent.com/find/symmetricom
Z3811A	Reference Module	product family sold	http://www.agilent.com/find/symmetricom
Z3812A	Reference Module	product family sold	http://www.agilent.com/find/symmetricom
Z3813A	GPS Timing Receiver.	product family sold	http://www.agilent.com/find/symmetricom
Z3815A	GPS Time Receiver.	product family sold	http://www.agilent.com/find/symmetricom
Z3817A	Remote High Stability Oscillator	product family sold	http://www.agilent.com/find/symmetricom
Z3822A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z3825A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z3833A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z3834A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z3835A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z3837A	GPS Time & Frequency Reference Receiver	product family sold	http://www.agilent.com/find/symmetricom
Z5003B	Ford EPS Car / Light Truck Server	No longer supported	
Z5004B	Ford EPS Car Light Truck Client, ROW	No longer supported	
Z5006B	Ford EPS LaserJet 4 Plus Printer	No longer supported	no replacement
Z5009B	Ford EPS Car Light Truck Server US	No longer supported	
Z5010B	Ford EPS Car Light Truck Client, US	No longer supported	
Z5014A	Ford EPS Heavy Truck Server US	No longer supported	
Z5014E	US Heavy Truck Server	No longer supported	
Z5020A	Ford EPS Heavy Truck Server Non US	No longer supported	
Z5020E	ROW Heavy Truck Server	No longer supported	
Z5021A	Ford EPS Heavy Truck Client Non US	No longer supported	
Z5022A	Ford EPS Heavy Truck Client US	No longer supported	
Z5023U	Ford EPS Heavy Truck Server Upgrd Non US	No longer supported	
Z5024A	Mexico Car/Light Truck Server	No longer supported	

Product	Description	Support Status	Replacement Information
Z5040A	Tech 2 NAO 12,19 Adapter	No longer supported	
Z5041A	Tech 2 Opel 10,19 Adapter	No longer supported	
Z5042A	Tech 2 Saab 10,19 Adapter	No longer supported	
Z5043A	Tech 2 Yazaki 3,19 Adapter	No longer supported	
Z5044A	Tech 2 3-T 3,19 Adapter	No longer supported	
Z5045A	Tech 2 GMB 12,19 Adapter	No longer supported	
Z5046A	Tech 2 Power Module	No longer supported	
Z5047A	Tech 2 Universal Power Module	No longer supported	
Z5048A	Tech 2 US Power Cable	No longer supported	
Z5049A	Tech 2 European Power Cable	No longer supported	
Z5050A	Tech 2 Israel Power Cable	No longer supported	
Z5051A	Tech 2 Japan Power Cable	No longer supported	
Z5052A	Tech 2 Australia Power Cable	No longer supported	
Z5053A	Tech 2 UK Power Cable	No longer supported	
Z5054A	Tech 2 DLC Cable	No longer supported	
Z5055A	Tech 2 Cigarette Lighter Power Cable	No longer supported	
Z5056A	Tech 2 Battery Power Cable	No longer supported	
Z5057A	Tech 2 SAE 16,19 Adapter	No longer supported	
Z5058A	Tech 2 DLC Loopback Adapter	No longer supported	
Z5059A	Tech 2 RS-232 Cable	No longer supported	
Z5060A	Tech 2 RS-232 DB9 Adapter	No longer supported	
Z5061A	Tech 2 RS-232 Loopback Connector	No longer supported	
Z5062A	Tech 2 Storage Case	No longer supported	
Z5063A	Tech 2 Software Card Programmable	No longer supported	
Z5064A	Tech 2 Switzerland Power Cable	No longer supported	
Z5065A	Tech 2 Denmark Power Cable	No longer supported	
Z5066A	Tech 2 South Africa/India Power Cable	No longer supported	
Z5067A	Tech 2 Hand Strap	No longer supported	
Z5068A	Saturn Adapter	No longer supported	
Z5080B	Fiat Examiner Test System	No longer supported	
Z5081A	Fiat Examiner DVOM Upgrade	No longer supported	
Z5082B	Fiat Examiner Test System with DVOM	No longer supported	
Z5151A	RMH 12 Inputs W/O Modem	No longer supported	no replacement
Z5152A	RMH 6 Inputs W/O Modem	No longer supported	no replacement
Z5200FB	Kyocera Supplemental System	No longer supported	
Z5230A	JD Vision LH+	No longer supported	
Z5230B	JD Vision LH Pro	No longer supported	
Z5245A	Tsubasa TestBook	No longer supported	
Z5260A	Rover TestBook	No longer supported	
Z5480A	CAN/FVCI UpgradeKit-Fiat Examiner	Currently supported	no replacement
Z5480B	CAN/FVCI Upgrade Kit-Fiat Examiner	Currently supported	no replacement
Z5481A	Fiat Examiner Plus	Currently supported	no replacement
Z5481B	Fiat Examiner + system, 350MHz, Italian	Currently supported	no replacement
Z5483A	Fiat Examiner 350MHz Upgrade Kit	Currently supported	no replacement
Z5484A	Kit-Fiat CAN Combo FDVOM PCAs Cables	Currently supported	no replacement
Z5600A	Custom accessory family for ESA	No longer supported	
Z5601A	Custom accessory family for VSA	No longer supported	
Z5602A	Custom acc. family for Spectrum Analyzer	No longer supported	
Z5603A	Custom accessory family for 856x series	No longer supported	
Z5604A	Custom accessory family for 859x series	No longer supported	
Z5640A	Custom accessory family for ESG	No longer supported	http://www.agilent.com/find/esg
Z5670A	Custom accessory family for MTA products	Currently supported	
Z6008A	Royal Navy Drvr Disk	No longer supported	
Z6041B	Crowd Monitor for NYSE	No longer supported	
Z8461B	CON1 to PIA1 Cable 4M Extended Temp	No longer supported	no replacement
ZTR-0015E	POCSAG encoder for testing pagers	No longer supported	8648x with Opt. 1EP.
ZTR-0015U	POCSAG encoder for testing pagers	No longer supported	8648x with Opt. 1EP.
5783-6570	Remote Management Card	No longer supported	

Product	Description	Support Status as of 1 May	Replacement Information
5961-7526	BHS GUIDEBOOK EUROPEAN TELECOM APPROVERS	No longer supported	no replacement
5961-7527	BHS GUIDEBOOK PACRIM TELECOM APPROVERS	No longer supported	no replacement
5964-8106	66111A/66311B User's Guide	Currently supported	
5964-8120	Users' Guide	Currently supported	
8120-3445	HP-IB Cable 1 meter	No longer supported	10833A
8120-3446	GPIB CABLE: 2 METER	No longer supported	10833B
8120-3447	GPIB CABLE: 4 METER	No longer supported	10833C
8120-3448	GPIB CABLE: 6 METER	No longer supported	10833F
8120-3449	GPIB CABLE: 8 METER	No longer supported	10833G
05060-6090	Cesium Beam Tube	No longer supported	no replacement
05060-6122	High Performance Cesium Tube	No longer supported	no replacement
05061-6072	Cesium Beam Tube	No longer supported	
05065-6071	Rubidium Vapor Frequency Reference	No longer supported	no replacement
00085-15001	Mass Storage ROM	No longer supported	no replacement
00085-15002	Plotter/Printer ROM	No longer supported	no replacement
00085-15003	Input/Output ROM	No longer supported	no replacement
00085-15004	Matrix ROM	No longer supported	no replacement
00085-15005	Advanced Programming ROM	No longer supported	no replacement
00085-15007	ASSEMBLER ROM	No longer supported	no replacement
00085-15013	Extended Mass Storage ROM	No longer supported	no replacement
00085-15101	MASS STOR/FRENCH	No longer supported	no replacement
00085-15102	PLTR/PRTR FRENCH	No longer supported	no replacement
00085-15104	MATRIX ROM FR	No longer supported	no replacement
00085-15105	ADV PRG ROM FR	No longer supported	no replacement
00085-15201	MASS STOR-GERMAN	No longer supported	no replacement
00085-15202	PLTR/PRTR GER	No longer supported	no replacement
00085-15204	MATRIX ROM GER	No longer supported	no replacement
00085-15205	ADV PRG ROM -GER	No longer supported	no replacement
00085-15301	MASS ST-ITALIAN	No longer supported	no replacement
00085-15302	PLTR/PRTR ITAL	No longer supported	no replacement
00085-15304	MATRIX ROM -ITAL	No longer supported	no replacement
00085-15401	MASS ST -SPANISH	No longer supported	no replacement
00085-15402	PLTR/PTR-SPANISH	No longer supported	no replacement
00087-15002	Plotter ROM	No longer supported	no replacement
00087-15003	Input/Output ROM	No longer supported	no replacement
00087-15004	Matrix ROM	No longer supported	no replacement
00087-15005	Advanced Programming ROM	No longer supported	no replacement
00087-15007	ASSEMBLER ROM	No longer supported	no replacement
00087-15011	MIKSAM ROM	No longer supported	no replacement
00087-15012	ELEC DISC ROM	No longer supported	no replacement
00087-15013	Extended Mass Storage ROM	No longer supported	no replacement
03724-10101	V-CURVE ANALYSIS	No longer supported	no replacement
03724-10102	V-CURVE ANALYSIS	No longer supported	no replacement
05062-60500	Cesium Beam Tube	No longer supported	5071A
05501-69030	New Replacement 5501A Laser Tube	No longer supported	no replacement
05517-60255	New Rplcmnt 5517C Laser Tube, Hi Power.	No longer supported	05517-60225
11886-90001	User's manual for 11886A SMF cable kit	No longer supported	