

**Software Release Date:** Nov, 2016

**System Requirements:** Keysight i3070 test system or test development workstation

**Controller Requirements:** Windows PC

**Operating System:** Microsoft Windows 7 or Microsoft Windows XP

**Software Requirement:** Keysight i3070 09.01p

This software patch should only be installed on systems with i3070 09.01p software release. It can be installed on i3070 test system or i3070 test development workstation.

The 09.01pa software patch addresses following change requests.

Change Request	Description
462398	08.40p: Allow use of two same model of power supplies for utility card
503911	09.00p: Ability to disable Probe verification during AutoAdjust and DGN
522184	09.00p: Enhanced DGN T2349 for RoHS ASRU N Revision
522202	09.00p: Enhanced DGN for New N6701C DUT power supplies RoHS frame
522207	09.00p: NISTCAL updated for RoHS ASRU N Revision

The software patch must be installed using the administrator login (or a login with administrator privileges).

### Installing the 09.01pa software patch

Follow these steps to install the 09.01pa software patch:

1. Save the **Keysighti3070\_0901pa.exe** file to your hard disk.
2. Close all open programs.
3. Double-click **Keysighti3070\_0901pa.exe**
4. Follow the on-screen instructions for installation.
5. To validate that the software was installed correctly:
  - a. On the **Start** menu, select **Programs > Agilent ICT > Korn Shell**
  - b. In the Korn Shell window, type **version** and press **Enter**.  
The following software revision should be displayed:  
**Keysight i3070 09.01pa 1116 WN.**

© Keysight Technologies, Inc. 2017  
Printed in Malaysia 07/2017



E9901-90038

