# Keysight True IR Analysis and Reporting Tool 2.0 Readme

# **System Requirements**

Before installing the Keysight TrueIR Analysis and Reporting Tool, ensure that your PC meets the following minimum system requirements for installation and operation.

Hardware requirements	Minimum specifications	
Processor	1.6 GHz or higher	
Operating system	<ul> <li>Windows 10 32-bit and 64-bit</li> <li>Windows 8.1 32-bit and 64-bit</li> <li>Windows 8 32-bit and 64-bit</li> <li>Windows 7 32-bit and 64-bit</li> </ul>	
Screen resolution	1024×768 and above	
Available RAM	4 GB and above	
Hard disk space	10 GB free disk space at runtime	

Software requirements	Minimum specifications	
Microsoft .NET Framework	Runtime version 4.0	
Microsoft Office	Microsoft Office 2007 SP3 and above	

# What's new in 2.0

- Real time thermal image streaming via USB
- Record and playback thermal recording
- · Select thermal images from recording and add them to the report
- Change thermal camera settings via USB

# What's been fixed in 2.0

Descriptions	Broken	Resolution
	in	
Fail to generate report for non-English OS.	1.2	Fixed report generation for non-English OS.
Fail to open image with Alarm on and gray color	1.2	Fixed open image with Alarm on by setting the
palette in the software.		color palette to rainbow.

# What's been fixed in 1.0.1.0

Descriptions	Broken	Resolution
	in	
Microsoft Word 2007 SP3 (higher than Version	1.0	Error dialogue Microsoft Word 2007 SP3 (Version
12.0.6612) is installed but when Report is clicked,		12.0.6612) and above is removed.
an error dialogue mentioning Microsoft Word 2007		
SP3 or higher is needed appears.		

Descriptions in this document are subject to change without notice.

Last updated: May 2016.

© Keysight Technologies 2015-2016