

## E5061B Network Analyzer Firmware Software Revision History

Rev. 20170901

---

**Note:**

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

---

**Revision B.04.88** ... Released September 2017

1. Supported PERSONA commands

**Revision B.04.86** ... Released March 2017

2. Fixed potential failure of User Characterization by N7554A/N7555A

**Revision B.04.84** ... Released September 2016

1. Fixed the bug related to the measurement when selecting 16198A from fixture selection softkey.

**Revision B.04.80** ... Released June 2016

1. Supported new ECal (N7554A, N7555A)

**Revision B.04.50** ... Released May 2016

1. Supported new touch screen driver

**Revision B.04.10** ... Released July 2015

1. Supports Option-006 Wireless Power Transfer Analysis

**Revision B.04.00** ... Released October 2014

1. Rebranding from Agilent to Keysight
2. Enhanced the licensing management

**Revision B.03.03** ... Released July 2014

1. Bug Fix: LAN connection failure with Telnet/Socket.

**Revision B.03.02** ... Released July 2014

1. Initial version of Windows 7.

**Revision A.02.22** ... Released December 2013

1. Bug fixes. The previous reading of marker is output after format change. This occurs only when Display update is turned off.
2. The query of :SENSe:CORRection:COLLect:ECAL:INFormation? is not the same as the E5071C.

**Revision A.02.21** ... Released August 2013

1. Minor Enhancement
2. Bug Fix

**Revision A.02.12** ... Released October 2012

1. Bug Fix

**Revision A.02.11** ... Released August 2012

1. Fixed bugs related to firmware boot up

**Revision A.02.09** ... Released June 2012

1. Fixed minor bugs on system recovery issues

**Revision A.02.06** ... Released October 2011

1. Added the system error correction ON/OFF capability

**Revision A.02.04** ... Released May 2011

1. Added Touch Panel Driver check functions
2. Enhanced Firmware Revision dialog design

**Revision A.02.00** ... Released Jan 2011

1. Added RF NA options
2. Added Impedance analysis option for LF-RF NA
3. The return values of VBA query commands on instrument setting has been changed from full spelling to abbreviation for compatibility with other ENA series products.  
e.g. LINear -> LIN, PHASe -> PHAS

**Revision A.01.14** ... Released Jun 2010

1. Improved of overload protection function
2. Fixed a bug related to the system exit function

**Revision A.01.12** ... Released Apr 2010

1. Fixed a bug related to internal ranging operation

**Revision A.01.10** ... Released Dec 2009

1. Customer first release

**Revision A.09.41** ... Released Sep 2009

1. Demo use only